

Case No. 19006558 / Ksd322

Kenneth

ASSIGNMENT (Office)

Report of Instruction

191804/Person

Jas Tan

at

ASM(CAXA)

Date/Time

11/4/2019

Estimated Cost

Bill to

☒

TP / WS / TP RPT / OD RPT / RYA / INV / MY / C

To Inspect Vehicle No.

SLT7205H

Insured

at Workshop no.

Ah Lim Motor

Tel

64831244

at

10 Amk Ind. park 2A # 01-09

Policy No.

Claim No.

S9M01JPM

Sum Insured

Excess

\$700.00

Make of Veh

D.O.A

07/04/2019

(Client's Record)

☒

CA / REV / RPT / REV 24 HRS

R.O.D. Incident

Date/Time

10:00am @ 12/4/19

Person Contacted

Zila

Vehicle

☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLT7205H - x

15/04/19

@ 13:43 pm revised PA to Jas Tan via email.
Smart claim Can't login.

ASS. REC. BY:

REF: ANA/

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: 700

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 865k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lum Sum: 1-B.1%

3 Val.: Yes or No

CA REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SUT 7005HYr Regn: 09/08Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyotac.c. 2362Colour: M. P. White

A/C: Insured / Std / NI / NA

Sp. Reading: 15741P

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACU 300082056Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / SR / STD A/Rim or

Tyre Size: F: _____

R: 245/45 ZR20BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 7/4/19D.O.I. 11/4/19

Survey held at _____

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

09/09/19

Confirmed PIP \$ 4,335.03 @ 4 days with Kenneth
(\$ 2,992.21 Ret - 41%)

RECEIVED 12 SEP 2019

Date/Time, File Pass to?

12/09/19

11

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I. / S

4,335.03 P/P700700



Service Request Details

Claim

S9M01JPU

Reference

None 

Loss Date

April 7, 2019

Report Date

Apr 9, 2019 12:00:00 AM

Request Date

April 11, 2019

Due Date

April 18, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLT7205H



HARRIER

HARRIER 2.4

Service Address

...

Primary Contact/Insured

TAY SU YONG DEREK

01-23, 25 Punggol Field Walk, 828751, Singapore

97952097

DEREKTAY@SINGNET.COM.SG

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

AH LIM OD XS \$700

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 2857F

Vehicle Details

Vehicle No.: SLT7205H
Vehicle to be Exported: Yes
Intended Deregistration Date: 09 Apr 2019
Vehicle Make: TOYOTA
Vehicle Model: HARRIER 2.4GL A
Primary Colour: White
Manufacturing Year: 2008
Engine No.: 2AZB343962
Chassis No.: ACU300092056
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$27,628.00
Original Registration Date: 16 Sep 2008
First Registration Date: 16 Sep 2008
Transfer Count: 5
Actual ARF Paid: \$27,628.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 15 Sep 2028
COE Category: E - Open Category
COE Period(Years): 10
PQP Paid: \$33,377.00
COE Rebate Amount: \$31,485.00
Total Rebate Amount: \$31,485.00

The information contained herein is correct as at 09 Apr 2019

OK



Re:SUPPLEMENTARY - SLT 7205H

Type

🔗 Question

Message

please proceed

Reply



SUPPLEMENTARY - SLT 7205H

Type

🔗 Question

Message

Damages consistent, repair cost economical. Kindly let us have your approval of supplementary amount is \$ 90,20. We have not authorize repair. Thanks. From : Shirley Hiew

Reply



IA - SLT 7205H

Type

🔗 Question

Message

Damages consistent, repair cost economical. We have authorize repair. IA uploaded. Thanks : From : Shirley Hiew

Reply

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 15 April 2019 1:43 PM
To: 'jas'
Subject: SLT 7205H OD (AXA) CLAIM NO - S9M01JPU
Attachments: Immediate Advice .pdf; ESTIMATE .pdf

Hi Jas,

Enclosed IA of the vehicle no SLT 7205H.

We will uploaded in smart claim after can login smart claim system.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408903 TEL : (065) 62563961 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 23/04/2019

Survey Details:

Date of loss	7-Apr-19
Date of appointment	11-Apr-19
Date of survey	11-Apr-19
Location of survey	NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLT 7205H
Make and Model	TOYOTA HARRIER 2.4GL A
Date of registration	30-Aug-13
Excess	\$700
Market Value	\$65,000
Parf Rebate	\$31,485
Nett Loss	\$33,515

Repair details:

Initial Estimate	7,367.44	(inclusive supplementary)
------------------	----------	---------------------------

Proposed/Revised repair cost:

Parts	\$3,241.50	(inclusive supplementary)
Check items (estimate)	\$1,956.10	
Labour	\$1,263.03	
Total	\$6,460.63	
Lump Sum(if applicable)	\$	

Number of days for repair	<u>4 DAYS</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563361 FAX : (065) 62564311

Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL.
KINDLY LET US HAVE YOUR APPROVAL OF
SUPPLEMENTARY AMOUNT IS \$ 90.20. WE HAVE NOT
AUTHORIZE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Auto
Consultants
Pte Ltd

Company Registration No. 199407188R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 15/04/2019

Survey Details:

Date of loss	7-Apr-19
Date of appointment	11-Apr-19
Date of survey	11-Apr-19
Location of survey	10 Ang Mo Kio Ind. Park 2A, #01-09 S568047

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLT 7205H
Make and Model	TOYOTA HARRIER 2.4GL A
Date of registration	30-Aug-13
Excess	\$700
Market Value	\$65,000
Part Rebate	\$31,485
Nett Loss	\$33,515

Repair details:

Initial Estimate	7,277.24
------------------	----------

Proposed/Revised repair cost:

Parts	\$3,151.30
Check items (estimate)	\$1,956.10
Labour	\$1,263.03
Total	\$6,370.43
Lump Sum(if applicable)	\$

Number of days for repair	<u>4 DAYS</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 198607198R

81 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE
HAVE AUTHORIZED REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/04/2019 17:32
Date Of Accident	07/04/2019 08:30
Exact Location Of Accident	ALONG SENGKANG E AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT7205H
Insured/Policyholder	
Name Of Registered Owner	TAY SU YONG DEREK
NRIC No	S7902857F
Email Address	DEREKTAY@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-97952097
Alternative Phone No	OTHERS-97952097

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER 2.4GL A

Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
--	-------------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA396706
Cover Note Number	06/09/2018 - 15/09/2019

Driver

Name of Driver	TAY SU YONG DEREK
NRIC No	S7902857F
Date Of Birth	28/01/1979
Occupation	INDOOR
Date Of Driving Pass	30/11/2001
Driving Experience	17 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97952097
Fax Number	
Contact Number	OTHERS-97952097
Email Address	DEREKTAY@SINGNET.COM.SG

Address	25 PUNGGOL FIELD WALK #01-23
Postcode	828751
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GLENNA QUEK GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBF7966L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	LUQMAN HAKIM BIN ABDURRAHMAN
NRIC/Passport Number	S9701560J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

Date of accident: 7th APR 2019 Time: 0830hrs Location: SENG KANG E AVE
 My Vehicle A: SLT 7205H Vehicle B: FBF 7966L Vehicle C: _____
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight and motorbike in front stop due to traffic light junction. I did not anticipate that the motorbike will stop and am expecting the motorbike to cross the traffic light junction. The motorbike stop after the first stop line of the traffic light junction.

Veh B: Jughman Hakim Bin Abdurrahman
 S9201560J

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :
 Email address :
 & myself :
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7902857F



Name

TAY SU YONG, DEREK
(ZHENG XURONG, DEREK)

鄭序榮

Race

CHINESE

Date of birth

28-01-1979

Sex

M

Country of birth

SINGAPORE

S7902857F

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S7902857F

Name

TAY SU YONG, DEREK
(ZHENG XURONG, DEREK)

Birth Date: 28 Jan 1979

Issue Date: 15 Feb 2011



Sp: 9795 2097

Email: derektay@singnet.com.sg



4840392

NRIC No: S7902857F



Date of issue

01-10-2010

25 PUNGGOL FIELD WALK #01-23
SINGAPORE 828751

NRIC No: S7902857F

Date: 28/01/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B	Motorcycles <= 200 cc	03 Nov 1999
Class 2A	Motorcycles between 201 cc and 400 cc	05 Dec 2000
Class 2	Motorcycles > 400 cc	19 Mar 2007
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg	30 Nov 2001



N7 425A

passenger
Glenna Quek (P)

Sp: No
ca: No

Total: 2



redefining / insurance

AXA Insurance Pte Ltd
1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
(65) 6880 4740
customer.care@axa.com.sg
www.axa.com.sg

Certificate of Insurance

Account number
04066

Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third Party Risks and Compensation) Rules, 1960 (Road Transport Act, 1987 (Malaysia))
Motor Vehicles (Third Party Risks) Rules, 1960 (Malaysia)

Policy details

Policyholder name	TAY SU YONG DEREK	Certificate number	GA396706 / 1
Cover	Comprehensive	Chassis number	ACU300090056
Plan name	Essential	Engine number	2A2B343962
NCD applicable	0%		
Vehicle registration number	SLT720SH		
Period of Insurance	from 06/09/2018 to 15/09/2019 (both dates inclusive)		
Finance loan company	TOKYO CENTURY LEASING (S) PTE LTD		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Section 85 of the Road Transport Act, 1987 (Malaysia), and not to be included under these headings.

EXCESS	Basic Own Damage Excess	S\$0 700.00
	Windscreen Excess	S\$0 100.00

An Additional Excess is applicable as follows:

- S\$500 for unlicensed Authorized Driver
- S\$500 for declared Young and Inexperienced Driver
- S\$5,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

(We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).)

AXA Insurance Pte Ltd

Authorized signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate and endorsement etc.

AXA Insurance Pte Ltd (199903512M)
8 Shenton Way, #24-01, AXA Tower,
Singapore 068811
Customer Centre, #B1-01

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: 002091
 Version: 1810
 Date calculated: 04/11/2019 03:35 PM

Full Report
 Registration: SLT7205H
 Printed: 11/04/2019 3:35 PM

Code	Description	WU	Price SGD
NO NUMBER	RENEW L/BONNET HINGE (BONNET AND L/F WING REMOVED)	1.0	4.50
NO NUMBER	RENEW R/BONNET HINGE (BONNET AND R/F WING REMOVED)	1.0	4.50
NO NUMBER	R + R L/SILL MOULDING	2.0	9.00
NO NUMBER	R + R R/SILL MOULDING	2.0	9.00
NO NUMBER	RENEW CONDENSER	2.0	9.00 ✓
NO NUMBER	REFILL AIR CONDITIONING	7.0	31.50 ✓
NO NUMBER	RENEW RADIATOR	22.0	99.00
NO NUMBER	R + R AIR CLEANER	3.0	13.50
NO NUMBER	R + R ENGINE PROTECTION	2.0	9.00 ✓
NN	BUMP LWR SPOILER R&R / NEW PARTS	~ 30.0*	135.00 ✗
Labour Cost		Hrs	WU
Panel / Mechanical Labour		12.90	129.0
Total of Labour			580.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	23.0
	INNER FRT PANEL CPL SURFACE PAINT	6.0
	FRONT BUMPER NEW PART PAINT K1G/P	24.0
	L/F WING SURFACE PAINT	6.0
	R/F WING SURFACE PAINT	6.0
	BUMP LWR SPOILER 1	~ 150.00* ✗

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	72.76
1009	INNER FRT PANEL CPL SURFACE PAINT	13.45
0283	FRONT BUMPER NEW PART PAINT K1G/P	93.60
0741	L/F WING SURFACE PAINT	10.21
0742	R/F WING SURFACE PAINT	10.21

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: 002091
 Version: 1810
 Date calculated: 04/11/2019 03:35 PM

Full Report
 Registration: SLT7205H
 Printed: 11/04/2019 3:35 PM

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		65.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.80	8.0	36.00
Total	10 WU/h	98.0	591.00

Material Cost - Paint	Price SGD
New Part Painting	72.76
New Part Painting - Plastic K1G/PUR	93.60
Surface-/Blend Paint	33.87
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	241.53

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Supplier	Price SGD	
0260	FRT NO PLATE BRKT	52114 48052		CM	50.00 ✓
0277	L/F BUMPER COVER	52128 48010A0		Sm	15.00 X
0278	R/F BUMPER COVER	52127 48020A0		Sm	15.00 X
0283	FRONT BUMPER	52119 4D915		Bu	255.00 ✓
0321	L/INN BUMPER BRACKET	52115 48060		Sm	40.00 X
0322	R/INN BUMPER BRACKET	52115 48060		Sm	40.00 X
0340	FRT BUMPER REINF	52131 48051			270.00 ?
0344	FRT IMPACT ABSORBER	52611 48030			58.00 ?
0410	GRILLE	53101 48201		CM	185.00 ✓
0431	RAD GRILLE BADGE	75311 48051		Sm	38.00 ✓
0471	BONNET	53301 48060		Bu	580.00 ✓
0475	L/F HINGE	53420 48030		R	25.00 X
0476	R/F HINGE	53410 48030		R	25.00 X
0481	BONNET INSULATION	53341 48050		Sm	180.00 X
0493	BONNET LOCK	53510 48060			50.00 ?
0494	SAFETY LATCH	53550 48020			0.00
0561	LEFT HEADLAMP ASSY	81150 48220		MgCM	580.00 ✓
0562	RIGHT HEADLAMP ASSY	81110 48220		MgCM	580.00 ✓
0988	LOCK CARRIER STRUT	53208 48030		Bu	50.00 ✓
1009	INNER FRT PANEL CPL	53201 48041			490.00 ?
1016	UPPER AIR GUIDE	53295 48010		Sm	70.00 X
4465	CONDENSER	88460 48041		Poc	490.00 ✓
7761	RADIATOR	16041 28381			430.00 ?

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: 002091

Version: 1810

Date calculated: 04/11/2019 03:35 PM

Full Report

Registration: SLT7205H

Printed: 11/04/2019 3:35 PM

Code	Description	Part Number	Supplier	Price SGD
7767	RADIATOR SHROUD	16711 28261		80.00 ?
7789	L/FAN MOTOR	16363 21030		160.00 ?
7790	R/FAN MOTOR	16363 28380		160.00 X
7793	L/BLOWER FAN	16361 28161		75.00 ?
7794	R/BLOWER FAN	16361 74162		48.00 ?
9645	LOW TONE HORN	86520 48030		45.00 ?
9646	HIGH TONE HORN	86510 48050		45.00 ?
1000	INSULATOR CLIPS (10)	1		10.00 ✓
1001	BUMP CLIPS (15)	1		15.00 ✓
1002	BUMP LWR SPOILER	1		0.01 X
1004	GARNISH CLIPS (8)	1		8.00 X
1005	RAD SIDE AIR GUIDEX2	1		110.00 X
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 5,272.01
u: Used parts				Addition(+10.00%) 527.20
Total				5,799.21

Extras

Code	Description	Price SGD
1006	NUMBER PLATE	35.00* ✓
1007	RADIATOR COOLANT	30.00* ?
Total Extras		65.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
Assessment number: MC1900295
Version: 1810
Date calculated: 24/07/2019 11:25 AM

Full Report
Registration: SLT7205H
Printed: 24/07/2019 11:25 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:		Date of Incident:	07/04/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA		
Model:	HARRIER		
Sub Model:	BASE MODEL		
Model Sheet Number:	70 MH 01		
Registration:	SLT7205H		
VIN number:			
Odometer:			
Model Specs			
FROM 09/2008	2.4 LTR 120 KW	TWO COAT METALLIC	PREPARE OFF VEHICLE

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900295
 Version: 1810
 Date calculated: 24/07/2019 11:25 AM

Full Report
 Registration: SLT7205H
 Printed: 24/07/2019 11:25 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R BONNET LANDING PANEL BRACKET		4.0	18.00
NO NUMBER	R + R FRONT BUMPER		4.0	18.00
NO NUMBER	RENEW FRONT BUMPER (REMOVED)		2.0	9.00
NO NUMBER	R + R BOTH HEADLAMPS (BUMPER REMOVED)		2.0	9.00
	NOT INCLUDED: ADJUST HEADLAMPS			
NO NUMBER	RENEW BOTH HEADLAMPS (REMOVED)		1.0	4.50
NO NUMBER	ADJUST HEADLAMPS		2.0	9.00
NO NUMBER	R + R L/F AND R/F WHEELHOUSE LINER		2.0	9.00
NO NUMBER	R + R LEFT FRONT WHEELHOUSE SHELL		1.0	4.50
NO NUMBER	R + R RIGHT FRONT WHEELHOUSE SHELL		1.0	4.50
NO NUMBER	R + R BONNET		3.0	13.50
NO NUMBER	RENEW BONNET		3.0	13.50
	INCLUDES: R + R OR RENEW ATTACHED PARTS			
NO NUMBER	R + R LOCK CARRIER		2.0	9.00
NO NUMBER	RENEW CONDENSER		2.0	9.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900295

Version: 1810

Date calculated: 24/07/2019 11:25 AM

Full Report

Registration: SLT7205H

Printed: 24/07/2019 11:25 AM

Code	Description	WU	Price SGD
NO NUMBER	REFILL AIR CONDITIONING	7.0	31.50
NO NUMBER	CONDENSER AND ADD RADIATOR R + R. INCLUDES: DRAIN + REFILL COOLANT	7.0	31.50
NO NUMBER	R + R LEFT FRONT WHEEL	1.0	4.50
NO NUMBER	R + R RIGHT FRONT WHEEL	1.0	4.50
NO NUMBER	R + R ENGINE PROTECTION	2.0	9.00
1009	INNER FRT PANEL CPL REPAIR	10.0*	45.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		5.70	57.0
Total of Labour			256.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	23.0
	FRONT BUMPER NEW PART PAINT K1G/P	24.0
	L/F WING SURFACE PAINT	6.0
	R/F WING SURFACE PAINT	6.0
	INNER FRT PANEL CPL SURFACE PAINT	6.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	72.76
0283	FRONT BUMPER NEW PART PAINT K1G/P	93.60
0741	L/F WING SURFACE PAINT	10.21
0742	R/F WING SURFACE PAINT	10.21
1009	INNER FRT PANEL CPL SURFACE PAINT	13.45

Labour Cost - Paint

	45.00 SGD/h	Hrs	WU	Price SGD
Factor			65.0	
Time Paint				
Preparation Main Work Metal		2.50	25.0	112.50
Preparation Comp. Work Plastic		0.80	8.0	36.00
Total	10 WU/h	9.80	98.0	441.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900295
 Version: 1810
 Date calculated: 24/07/2019 11:25 AM

Full Report
 Registration: SLT7205H
 Printed: 24/07/2019 11:25 AM

Material Cost - Paint

New Part Painting	Price SGD
	72.76
New Part Painting - Plastic K1G/PUR	93.60
Surface-/Blend Paint	33.87
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	241.53

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0260	FRT NO PLATE BRKT	52114 48052		50.00
0283	FRONT BUMPER	52119 4D915		255.00
0410	GRILLE	53101 48201		185.00
0431	RAD GRILLE BADGE	75311 48051		38.00
0471	BONNET	53301 48060		580.00
0493	BONNET LOCK	53510 48060		50.00
0561	LEFT HEADLAMP ASSY	81150 48220		580.00
0562	RIGHT HEADLAMP ASSY	81110 48220		580.00
0988	LOCK CARRIER STRUT	53208 48030		50.00
4465	CONDENSER	88460 48041		490.00
9646	HIGH TONE HORN	86510 48050		45.00
1000	INSULATOR CLIPS (10)	1		10.00
1001	BUMP CLIPS (15)	1		15.00
1008	BONNET SEAL	1		35.00
1009	BONNET CABLE	1		35.00
1010	HEADLAMP CLIPSX2	1		12.00
f: OEM Parts				0.00
n: Non-OEM Parts				3,010.00
u: Used parts				301.00
Savings				
Subtotal				
Addition(+10.00%)				
Total				3,311.00

Extras

Code	Description	Price SGD
1006	NUMBER PLATE	35.00
1007	RADIATOR COOLANT	30.00
1011	AIR CON GAS	50.00
Total Extras		115.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900295
 Version: 1810
 Date calculated: 24/07/2019 11:25 AM

Full Report
 Registration: SLT7205H
 Printed: 24/07/2019 11:25 AM

Code	Description	Price SGD	
Final Calculation			
		SGD	SGD
Parts		3,010.00	
Addition(+10.00%)		301.00	
Total Parts			3,311.00
Labour Time Base 10 WU/h			
Total 57.0 WU X 45.00 SGD/h		256.50	
Total of Labour			256.50
Total Of Extras			115.00
Paint Work Time Base 10 WU/h			
Labour Cost 98.0 WU X 45.00 SGD/h		441.00	
Material Cost		241.53	
Total Paint Including Material			682.53
Repair Cost Excludes GST			4,365.03
GST (+7.0%)			305.58
Repair Cost Included GST			4,670.58

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
GST:M9-0009639-E RCB NO:064703008

DRAFT FINALISATION

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288
ATTN: Motor Claim Department

FAX: 63382522

Claim No: MC1900295
Ref No: MF1900461
Date: 23 Jul 2019
Policy No: GA396706
Veh Reg-No: SLT7205H
Make/Model: TOYOTA HARRIER
2.4GL A

DRAFT FINALISATION

Your Ref No: -
Claim Type: Own Damage
Accident Date: 07/04/2019

Repair Cost to Vehicle No (For Finalization):SLT7205H

Description	U/Price	Quantity	Cost SS	Amount SS
SPARE PARTS				
1 BONNET SEAL		1 PC	35.00	
2 BONNET CABLE		1 PC	35.00	
3 HEADLAMP CLIPS		2 PC	12.00	
4 FRT NO. PLATE BRKT		1 PC	50.00	
5 FRONT BUMPER		1 PC	255.00	
6 GRILLE		1 PC	185.00	
7 RAD GRILLE BADGE		1 PC	38.00	
8 BONNET		1 PC	580.00	
9 BONNET LOCK		1 PC	50.00	
10 LEFT HEADLAMP ASSY		1 PC	580.00	
11 RIGHT HEADLAMP ASSY		1 PC	580.00	
12 LOCK CARRIER STRUT		1 PC	50.00	
13 CONDENSER		1 PC	490.00	
14 HIGH TONE HORN		1 PC	45.00	
15 INSULATOR CLIPS		10 PC	10.00	
16 BUMPER CLIPS		15 PC	15.00	
			3,010.00	
	Add 10%		301.00	3,311.00
Special Nett				
17 NUMBER PLATE		1 PC	35.00	
18 RADIATOR COOLANT		1 PC	30.00	
				65.00
LABOUR				
19 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR RADIATOR SUPPORT PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	256.50	
20 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL.		1 PC	682.53	
21 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	50.00	

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

989.03

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC1900295

Ref No: MF1900461

Date: 23 Jul 2019

Policy No: GA396706

Veh Reg No: SLT7205H

Make/Model: TOYOTA HARRIER
2.4GL A

Your Ref No: -

Claim Type: Own Damage

Accident Date: 07/04/2019

Repair Cost to Vehicle No (For Finalization):SLT7205H

Amount Before Excess	S\$ 4,365.03
Less Excess	S\$ 700.00
Amount Before GST	S\$ 3,665.03
Add GST @ 7%	256.55
Total Amount payable	S\$ 3,921.58

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED TWENTY ONE AND CENTS FIFTY EIGHT ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 12/04/2019

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 - ext 6483 6170
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK, Singapore 569047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST: M9-0009639-E RCB NO:664703000

M/S: AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC1900295

Date: 15 Apr 2019

Policy No: GA396706

Veh Reg No: SLT7205H

Make/Model: TOYOTA HARRIER
 2.4GL A

Your Ref No: -

Claim Type: Own Damage

Accident Date: 07/04/2019

Estimate Repair Cost to Vehicle No :SLT7205H

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts to Repair				
SPARE PARTS				
1 BONNET SEAL		1 PC	35.00	
2 BONNET CABLE		1 PC	35.00	
3 HEADLAMP CLIPS		2 PC	12.00	
			82.00	
	Add 10%		8.20	90.20
Amount Before Excess				S\$ 90.20
GST Amount				S\$ 6.31
Total Amount payable				S\$ 96.51

The above vehicle was surveyed by KENNETH KONG -LKK on 12/04/2019

For AH LIM MOTOR COMPANY
AH LIM MOTOR CO.
 BLK 10, ANG MO KIO INDUSTRIAL PARK 2A
 #01-09, AMK, SINGAPORE 569047

AUTHORISED SIGNATURE

Let the insurance company notify the insured of the following:

- To ensure proper spray painting
- To ensure damaged part(s) during resurvey
- To ensure proper subject to confirmation
- To ensure the survey is on a "Without Prejudice" basis
- To ensure the survey is allowed
- To ensure the survey must be resurveyed and approved from insurance company

Signature of the Insured

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

SURVEYOR COPY

Claim Reference:
Assessment number: 002091
Version: 1810
Date calculated: 04/11/2019 03:35 PM

Full Report
Registration: SLT7205H
Printed: 11/04/2019 3:35 PM

89M017PU

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:		Date of Incident:	2019-04-07
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	HARRIER
Sub Model:	BASE MODEL
Model Sheet Number:	70 MH 01
Registration:	SLT7205H
VIN number:	
Odometer:	

Model Specs

FROM 09/2008	2.4 LTR 120 KW	TWO COAT METALLIC	PREPARE OFF VEHICLE
--------------	----------------	-------------------	---------------------

Authorise
Repair B4 paint
4 days
Ex 8 Foot

LKK Auto Consultants hence notify the Repairer of the following:

- To return before/after spray painting
- To notify damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary parts must be resurveyed and be subject to final approval from Insurance Company

Authorised by Repairer:
Signature:
Date:

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: 002091
 Version: 1810
 Date calculated: 04/11/2019 03:35 PM

Full Report
 Registration: SLT7205H
 Printed: 11/04/2019 3:35 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R LEFT FRONT WING (FRT BUMPER AND L/HEADLAMP ASSY REMOVED)	4.0	18.00	✓
NO NUMBER	R + R RIGHT FRONT WING (FRT BUMPER AND R/HEADLAMP ASSY REMOVED)	4.0	18.00	✓
NO NUMBER	RENEW FRONT PANEL CPL	31.0	139.50	✓
NO NUMBER	R + R FRONT BUMPER	4.0	18.00	✓
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT	1.0	4.50	✓
NO NUMBER	RENEW FRONT BUMPER (REMOVED)	2.0	9.00	✓
NO NUMBER	R + R BOTH HEADLAMPS (BUMPER REMOVED)	2.0	9.00	✓
NO NUMBER	NOT INCLUDED: ADJUST HEADLAMPS			
NO NUMBER	RENEW BOTH HEADLAMPS (REMOVED)	1.0	4.50	✓
NO NUMBER	ADJUST HEADLAMPS	2.0	9.00	✓
NO NUMBER	R + R BONNET	3.0	13.50	✓
NO NUMBER	RENEW BONNET	3.0	13.50	✓
	INCLUDES: R + R OR RENEW ATTACHED PARTS			

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: 002091
 Version: 1810
 Date calculated: 04/11/2019 03:35 PM

Full Report
 Registration: SLT7205H
 Printed: 11/04/2019 3:35 PM

Code	Description	WU	Price SGD
NO NUMBER	RENEW L/BONNET HINGE (BONNET AND L/F WING REMOVED)	1.0	4.50 ✓
NO NUMBER	RENEW R/BONNET HINGE (BONNET AND R/F WING REMOVED)	1.0	4.50 ✓
NO NUMBER	R + R L/SILL MOULDING	2.0	9.00 ✓
NO NUMBER	R + R R/SILL MOULDING	2.0	9.00 ✓
NO NUMBER	RENEW CONDENSER	2.0	9.00 ✓
NO NUMBER	REFILL AIR CONDITIONING	7.0	31.50 ✓
NO NUMBER	RENEW RADIATOR	22.0	99.00 ✓
NO NUMBER	R + R AIR CLEANER	3.0	13.50 ✓
NO NUMBER	R + R ENGINE PROTECTION	2.0	9.00 ✓
NN	BUMP LWR SPOILER R&R / NEW PARTS	~ 30.0*	135.00 X
Labour Cost		Hrs	WU
Panel / Mechanical Labour		12.90	129.0
Total of Labour			580.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	23.0
	INNER FRT PANEL CPL SURFACE PAINT	6.0
	FRONT BUMPER NEW PART PAINT K1G/P	24.0
	L/F WING SURFACE PAINT	6.0
	R/F WING SURFACE PAINT	6.0
	BUMP LWR SPOILER 1	~ 150.00* X

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	72.76
1009	INNER FRT PANEL CPL SURFACE PAINT	13.45
0283	FRONT BUMPER NEW PART PAINT K1G/P	93.60
0741	L/F WING SURFACE PAINT	10.21
0742	R/F WING SURFACE PAINT	10.21

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: 002091

Version: 1810

Date calculated: 04/11/2019 03:35 PM

Full Report

Registration: SLT7205H

Printed: 11/04/2019 3:35 PM

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		65.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.80	8.0	36.00
Total	10 WU/h	98.0	591.00

Material Cost - Paint	Price SGD
New Part Painting	72.76
New Part Painting - Plastic K1G/PUR	93.60
Surface-/Blend Paint	33.87
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	241.53

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Supplier	Price SGD	
0260	FRT NO PLATE BRKT	52114 48052		CM 50.00	✓
0277	L/F BUMPER COVER	52128 48010A0		Sm 15.00	X
0278	R/F BUMPER COVER	52127 48020A0		Sm 15.00	X
0283	FRONT BUMPER	52119 4D915		Bu 255.00	✓
0321	L/INN BUMPER BRACKET	52115 48060		Sm 40.00	X
0322	R/INN BUMPER BRACKET	52115 48060		Sm 40.00	X
0340	FRT BUMPER REINF	52131 48051		Sm 270.00	X
0344	FRT IMPACT ABSORBER	52611 48030		Sm 58.00	X
0410	GRILLE	53101 48201		CM 185.00	✓
0431	RAD GRILLE BADGE	75311 48051		Sm 38.00	✓
0471	BONNET	53301 48060		Bu 580.00	✓
0475	L/F HINGE	53420 48030		R 25.00	X
0476	R/F HINGE	53410 48030		R 25.00	X
0481	BONNET INSULATION	53341 48050		Sm 180.00	X
0493	BONNET LOCK	53510 48060		DIT 50.00	✓
0494	SAFETY LATCH	53550 48020		Sm 0.00	✓
0561	LEFT HEADLAMP ASSY	81150 48220		Mg CM 580.00	✓
0562	RIGHT HEADLAMP ASSY	81110 48220		Mg CM 580.00	✓
0988	LOCK CARRIER STRUT	53208 48030		Bu 50.00	✓
1009	INNER FRT PANEL CPL	53201 48041	- Repair	R 490.00	X
1016	UPPER AIR GUIDE	53295 48010		Sm 70.00	X
4465	CONDENSER	88460 48041		Puc 490.00	✓
7761	RADIATOR	16041 28381		Sm 430.00	X

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: 002091
 Version: 1810
 Date calculated: 04/11/2019 03:35 PM

Full Report
 Registration: SLT7205H
 Printed: 11/04/2019 3:35 PM

Code	Description	Part Number	Supplier	Price SGD	
7767	RADIATOR SHROUD	16711 28261		80.00	✓
7789	L/FAN MOTOR	16363 21030		160.00	✓
7790	R/FAN MOTOR	16363 28380		160.00	✓
7793	L/BLOWER FAN	16361 28161		75.00	✓
7794	R/BLOWER FAN	16361 74162		48.00	✓
9645	LOW TONE HORN	86520 48030		45.00	✓
9646	HIGH TONE HORN	86510 48050		45.00	✓
1000	INSULATOR CLIPS (10)	1		10.00	✓
1001	BUMP CLIPS (15)	1		15.00	✓
1002	BUMP-LWR SPOILER	1		0.01	✓
1004	GARNISH CLIPS (8)	1		8.00	✓
1005	RAD-SIDE AIR GUIDEX2	1		110.00	✓

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	5,272.01
u: Used parts	Addition(+10.00%)	527.20
	Total	5,799.21

Extras

Code	Description	Price SGD	
1006	NUMBER PLATE	35.00*	✓
1007	RADIATOR COOLANT	30.00*	✓
	Total Extras	65.00	

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: 002091
 Version: 1810
 Date calculated: 04/11/2019 03:35 PM

Full Report
 Registration: SLT7205H
 Printed: 11/04/2019 3:35 PM

Final Calculation

	SGD	SGD
Parts	5,272.01	
Addition(+10.00%)	527.20	
Total Parts		5,799.21
Labour Time Base 10 WU/h		
Total 129.0 WU X 45.00 SGD/h	580.50	356.50
Total of Labour		580.50
Total Of Extras		65.00
Paint Work Time Base 10 WU/h		
Labour Cost 98.0 WU X 45.00 SGD/h	441.00	
Material Cost	241.53	
Total Paint Including Material		832.53
Repair Cost Excludes GST		7,277.24
GST (+7.0%)		509.41
Repair Cost Included GST		7,786.65

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

2417.44

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC1900295

Date: 15 Apr 2019

Policy No: GA396706

Veh Reg No: SLT7205H

Make/Model: TOYOTA HARRIER
2.4GL A

Your Ref No: -

Claim Type: Own Damage

Accident Date: 07/04/2019

Estimate Repair Cost to Vehicle No :SLT7205H

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
SPARE PARTS				
1 BONNET SEAL		1 PC	35.00	
2 BONNET CABLE		1 PC	35.00	
3 HEADLAMP CLIPS		2 PC	12.00	
			82.00	
	Add 10%		8.20	90.20

Amount Before Excess S\$ 90.20

GST Amount S\$ 6.31

Total Amount payable S\$ 96.51

The above vehicle was surveyed by KENNETH KONG -LKK on 12/04/2019

For AH LIM MOTOR COMPANY
AH LIM MOTOR CO.
BLK 10, ANG MO KIO INDUSTRIAL PARK 2A
#01-09, AMK AUTOPPOINT
SINGAPORE 568047

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Time:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlime@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC1900295

Date: 27 Aug 2019

Policy No: GA396706

Veh Reg No: SLT7205H

Make/Model: TOYOTA HARRIER
2.4GL A

Your Ref No: -

Claim Type: Own Damage

Accident Date: 07/04/2019

Estimate Repair Cost to Vehicle No :SLT7205H

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts to Repair				
LABOUR				
1 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	50.00	50.00

Amount Before Excess	S\$ 50.00
GST Amount	S\$ 3.50
Total Amount payable	S\$ 53.50

The above vehicle was surveyed by KENNETH KONG -LKK on 12/04/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlime@singnet.com.sg
AUTHORISED SIGNATURE

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: MC1900295
Date calculated: 09/09/2019 10:34 AM
Summary Information

Full Report
Registration: SLT7205H
Printed: 09/09/2019 10:35 AM

Claim			
Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	07/04/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle			
Manufacturer:	TOYOTA		
Model:	HARRIER		
Sub Model:	BASE MODEL		
Model Sheet Number:	70 MH 01		
Registration:	SLT7205H		
VIN number:			
Odometer:			
Model Specs			
FROM 09/2008	2.4 LTR 120 KW	TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 45.00 SGD/h

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:

Repairer Reference: MC1900295

Date calculated: 09/09/2019 10:34 AM

Full Report

Registration: SLT7205H

Printed: 09/09/2019 10:35 AM

Code	Description	WU	Price SGI
NO NUMBER	R + R BONNET LANDING PANEL BRACKET	4.0	18.00
NO NUMBER	R + R FRONT BUMPER	4.0	18.00
NO NUMBER	RENEW FRONT BUMPER (REMOVED)	2.0	9.00
NO NUMBER	R + R BOTH HEADLAMPS (BUMPER REMOVED)	2.0	9.00
	NOT INCLUDED: ADJUST HEADLAMPS		
NO NUMBER	RENEW BOTH HEADLAMPS (REMOVED)	1.0	4.50
NO NUMBER	ADJUST HEADLAMPS	2.0	9.00
NO NUMBER	R + R L/F AND R/F WHEELHOUSE LINER	2.0	9.00
NO NUMBER	R + R LEFT FRONT WHEELHOUSE SHELL	1.0	4.50
NO NUMBER	R + R RIGHT FRONT WHEELHOUSE SHELL	1.0	4.50
NO NUMBER	R + R BONNET	3.0	13.50
NO NUMBER	RENEW BONNET	3.0	13.50
	INCLUDES: R + R OR RENEW ATTACHED PARTS		
NO NUMBER	R + R LOCK CARRIER	2.0	9.00
NO NUMBER	RENEW CONDENSER	2.0	9.00
NO NUMBER	REFILL AIR CONDITIONING	7.0	31.50
NO NUMBER	CONDENSER AND ADD RADIATOR R + R	7.0	31.50
	INCLUDES: DRAIN + REFILL COOLANT		
NO NUMBER	R + R LEFT FRONT WHEEL	1.0	4.50
NO NUMBER	R + R RIGHT FRONT WHEEL	1.0	4.50
NO NUMBER	R + R ENGINE PROTECTION	2.0	9.00
1009	INNER FRT PANEL CPL REPAIR	10.0*	45.00

Labour Cost

Panel / Mechanical Labour

Hrs

WU

5.70

57.0

256.50

Total of Labour

256.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGI
	BONNET NEW PART PAINTING	23.0
	FRONT BUMPER NEW PART PAINT K1G/P	24.0
	L/F WING SURFACE PAINT	6.0
	R/F WING SURFACE PAINT	6.0
	INNER FRT PANEL CPL SURFACE PAINT	6.0

Paint Material Per Part

Code	Description	Price SGI
0471	BONNET NEW PART PAINTING	72.7
0283	FRONT BUMPER NEW PART PAINT K1G/P	93.6
0741	L/F WING SURFACE PAINT	10.2

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: MC1900295
Date calculated: 09/09/2019 10:34 AM
Paint Material Per Part

Full Report
Registration: SLT7205H
Printed: 09/09/2019 10:35 AM

Code	Description	Price SGD
0742	R/F WING SURFACE PAINT	10.21
1009	INNER FRT PANEL CPL SURFACE PAINT	13.45

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			45.00 SGD/h
Time Paint		65.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.80	8.0	36.00
Total	10 WU/h	98.0	441.00

Material Cost - Paint

	Price SGD
New Part Painting	72.70
New Part Painting - Plastic K1G/PUR	93.60
Surface-/Blend Paint	33.80
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	241.50

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/0	Price SGD
0260	FRT NO PLATE BRKT	52114 48052			50.00
0283	FRONT BUMPER	52119 4D915			255.00
0410	GRILLE	53101 48201			185.00
0431	RAD GRILLE BADGE	75311 48051			38.00
0471	BONNET	53301 48060			580.00
0493	BONNET LOCK	53510 48060			50.00
0561	LEFT HEADLAMP ASSY	81150 48220			580.00
0562	RIGHT HEADLAMP ASSY	81110 48220			580.00
0988	LOCK CARRIER STRUT	53208 48030			50.00
4465	CONDENSER	88460 48041			490.00
9646	HIGH TONE HORN	86510 48050			45.00
1000	INSULATOR CLIPS (10)	1			10.00
1001	BUMP CLIPS (15)	1			15.00
1008	BONNET SEAL	1			35.00
1009	BONNET CABLE	1			35.00
1010	HEADLAMP CLIPSX2	1			12.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal

0.0
3,010.0

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
 Repairer Reference: MC1900295
 Date calculated: 09/09/2019 10:34 AM
 Addition(+10.00%)

Full Report
 Registration: SLT7205H
 Printed: 09/09/2019 10:35 AM
 301.00

Total **3,311.00**

Extras

Code	Description	Price SGD
1006	NUMBER PLATE	35.00
1011	AIR CON GAS	50.00
Total Extras		85.00

Final Calculation

	SGD	SGD
Parts	3,010.00	
Addition(+10.00%)	301.00	
Total Parts		3,311.00
Labour Time Base 10 WU/h		
Total 57.0 WU X 45.00 SGD/h	256.50	
Total of Labour		256.50
Total Of Extras		85.00
Paint Work Time Base 10 WU/h		
Labour Cost 98.0 WU X 45.00 SGD/h	441.00	
Material Cost	241.53	
Total Paint Including Material		682.53
Repair Cost Excludes GST		4,335.03
GST (+7.0%)		303.41
Repair Cost Included GST		4,638.44
Deductions (Excludes GST)		
Deduction For Excess	-700.00	
Total Of Deductions (Excludes GST)		-700.00
Grand Total Excludes GST		3,635.03
GST (+7.0%)		254.41
Grand Total Included GST		3,889.44

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: MC1900295
Date calculated: 09/09/2019 10:34 AM

Full Report
Registration: SLT7205H
Printed: 09/09/2019 10:35 AM

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6417 8794

Dept Direct: 6417 8795

Dept Direct: 6417 8796

Dept Direct: 6417 8797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

Page 1

TAX INVOICE : AR201904-07225
DATE : 12/04/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SLT7205H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T53301-48050/60 RX300-MCU35	FRT BONET	CC CC12-E-01A	1	580.00	580.00
2.	T90467-T0014/09050 ZSU60 ZRE171	FRT BONET INSULATOR CLIP	CC GC12-N-03B4	10	1.00	10.00
3.	T75311-48051 ACU30	FRT LOGO <i>secure GR</i>	CC CC12-P-03B3	1	38.00	38.00
4.	T81145-48192 RX300-MCU35	HEAD LAMP RH	CC CC12-F-10C	1	580.00	580.00
5.	T81185-48190/1/2 ACU30	HEAD LAMP LH	CC CC12-F-07C	1	580.00	580.00
6.	T53208-48030/20 HARRIER-ACU30	BRACE PANEL	CC CC12-I-01B2	1	50.00	50.00
7.	T53510-48060 MCU35	BONNET LOCK	CC NEW	1	50.00	50.00

CONTINUE NEXT PAGE

[P] 12/04/2019 4:48:52PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[B] 12/04/2019 4:35:46PM

[Signature]



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 8781 / 8745 9939



Dept Direct: 6417 9794

Dept Direct: 6417 8780

Dept Direct: 6417 8780

Dept Direct: 6417 8780

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201904-07225
DATE : 12/04/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SLT7205H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR : SGD

Page 1

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
PA 8.	T53101-48150/48201 ACU30	RAD GRILLE	CC NEW	1	185.00	185.00
PA 9.	T52119-4D915 ACU30	FRT BUMPER	CC NEW	1	255.00	255.00
PA 10.	T52161-16010/16011 ALL MODEL	BUMPER CLIP	CC NEW	15	1.00	15.00
PA 11.	T52114-48050/1/2 MCU35 RX300	FRT NO PLATE GARNISH	CC NEW	1	50.00	50.00

SUB-TOTAL : 2,393.00
ADD GST 7.00 % 167.51

E. & O.E TOTAL AMOUNT SGD : 2,560.51

[P] 12/04/2019 4:48:52PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 12/04/2019 4:35:46PM

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 301B UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9035



Dept Direct: 6309 9610

Dept Direct: 6305 9011

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: HWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY

10 ANG MO KIO PARKS 2A

#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL : 64831244 FAX : 64836170

ATTN : SIMON 96205405

Page 2

TAX INVOICE : AR201904-07235

DATE : 12/04/2019

CUSTOMER ID : AHL008

VEH REG. NO. : SLT7205H

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	T53381-48030/1 MCU35 RX300	BONNET SEAL	PA PL2-D1-04D	1	35.00	35.00

SUB-TOTAL : 35.00

ADD GST 7.00% 2.45

E & O E

TOTAL AMOUNT SGD : 37.45

[P] 12/04/2019 4:53:58PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 12/04/2019 4:50:01PM

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.
No signature is required.



AR201904-07235

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPER/SCREEN GLASS
Dept Direct: 6417 8291 / 6745 9229



Dept Direct: 6305 9010

Dept Direct: 6305 9011

Dept Direct: 6417 8782



Dept Direct: 6417 8784

Dept Direct: 6417 8785

Dept Direct: 6417 8786

Dept Direct: 6417 8787

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY

10 ANG MO KIO PARKS 2A

#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL: 64831244 FAX: 64836170

ATTN: SIMON 96205405

TAX INVOICE : AR201904-07294

DATE : 13/04/2019

CUSTOMER ID : AHL008

VEH REG. NO. : SLT7205H

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

Page 3

SO STOCKID

Y. T88460-48041J

ACU30

DESCRIPTION

A/C CONDENSER

StkLoc

U1

SUPPLIER

QTY

1

U/PRICE

490.00

AMOUNT

490.00

SUB-TOTAL : 490.00

ADD GST 7.00 % 34.30

E & O E

TOTAL AMOUNT SGD : 524.30

[P] 13/04/2019 8:08:04AM

[E] 13/04/2019 8:05:41AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : STEVEN



* A R 2 0 1 9 0 4 - 0 7 2 9 4 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 8745 9039



Dept Direct: 6417 8794

Dept Direct: 6417 8795

Dept Direct: 6417 8796

Dept Direct: 6417 8797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201904-07324
DATE : 13/04/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SLT7205H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

Page 4

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53630-48030 ACU30	BONNET CABLE	PA PL2-K1-03S	1	35.00	35.00

SUB-TOTAL : 35.00
ADD GST 7.00 % 2.45

E. & O.E TOTAL AMOUNT SGD : 37.45

[P] 13/04/2019 9:23:14AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 13/04/2019 9:22:23AM

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8781 / 6745 9020



Dept Direct: 6308 9010

Dept Direct: 6305 9811

Dept Direct: 6417 8782



Dept Direct: 6417 9704

Dept Direct: 6417 8785

Dept Direct: 6417 9790

Dept Direct: 6417 9711

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

5

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

Page 5

TAX INVOICE : AR201904-07323
DATE : 13/04/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SLT7205H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	T86510-48150 GYL15	HORN ASSY	CC CC12-O-03B11	1	45.00	45.00

SUB-TOTAL : 45.00
ADD GST 7.00 % 3.15

E. & O.E TOTAL AMOUNT SGD : 48.15

[P] 13/04/2019 9:22:40AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 13/04/2019 9:21:32AM

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 0791 / 6745 0639



Dept Direct: 6417 0794

Dept Direct: 6417 0795

Dept Direct: 6417 0796

Dept Direct: 6417 0797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

Page 6

TAX INVOICE : AR201904-07439
DATE : 13/04/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SLT7205H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1.	T53271-12060/0B010 KR42,AT210'98	H/LAMP CLIP	PA PL2-K1-06M	2	6.00	12.00

supp

SUB-TOTAL : 12.00
ADD GST 7.00 % 0.84

E. & O.E TOTAL AMOUNT SGD : 12.84

[P] 13/04/2019 10:54:24AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[P] 13/04/2019 10:53:44AM

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

HYDROSCREEN GLASS
Dept Direct: 6417 9781 / 6745 0639



Dept Direct: 6417 9754

Dept Direct: 6417 9756

Dept Direct: 6417 9758

Dept Direct: 6417 9752

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL : 64831244 FAX : 64836170

ATTN : SIMON 96205405

TAX INVOICE : AR201904-07411
DATE : 13/04/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SLI7205H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

Page 7

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T75311-48070	GRILLE LOGO	PA	1	38.00	38.00
MCU35 LEXUS		PL2-J1-08K			

SUB-TOTAL : 38.00
ADD GST 7.00 % 2.66

E. & O.E TOTAL AMOUNT SGD : 40.66

[P] 13/04/2019 10:31:59AM

[E] 13/04/2019 10:30:17AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.

No signature is required.



* A R 2 0 1 9 0 4 - 0 7 4 1 1 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date