

Case No. 19006559 / Ksd3¹² Report Instruction
Assigned to Kennedy follow
CWS Karen Tan of PCI Date/Time 9:11am 12/4/19
Estimated Cost: Bill to:

OD TP WS/TP RES / OI RES / EVA / INV / MV / CS

To Inspect Vehicle No. GBB 1734A Insured 84C 2356A

at Workshop no. K. Kim Hin Tel: 6452 7018

of 160 Sin Ming Drive #02-20

Policy No. Claim No. D19002454MPSH

Sum Insured: Excess:

Make of Veh: D.O.A. 8/4/2019
(Client's Record)

CA / REV / RRP / REV 24 HRS lup

Date/Time: 10:35am 12/4/19 Person Contacted: Jendren H.O.D. Endorsement:
Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBB 1734A-X</u>
	<u>84C 2356A - C03/FCI 15016/44 / Kvd1</u> <u>DOT: 21/9/15</u>
<u>15/04/19</u>	<u>@ 17:20 p.m. revised PA to Karen via email.</u>
	<u>6/1 Sep 816501 confirmed</u>
	<u>C\$ 739.50 Red - 31%)</u>

ASS. REC. BY:

REF: 1021

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 827K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBB1734A Yr Regn: 08, 08Type: M.Car / M.Cycle / Bus / Van / Corry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Dyno c.c. 2982Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 167988 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFA T354.303001988Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim orTyre Size: F: mic 195R15X8
R: Yoko 155R12X8(11)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 3 mmL/Bal. 3 mmD.O.A. 8/4/19

Survey held at

Rear

R/Bal. 99 mmL/Bal. 99 mmD.O.I. 11/4/19Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / File pass to
11/4 Est not readyMV - \$ 271K
LTA - \$ 13,596.00
Nett - \$ 13,404.00

RECEIVED 23 APR 2019

Date/Time, File Pass to?

23/04/19

☐ : Prell. Report☒ : Final Report1) Typist

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fixings

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 1,650/- HS)

230



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002454MFSH

Date: 15 April 2018

Our Ref: CS/FCI19006559/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBB 1734A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/04/2019 at the premises of M/s K.Kim Hin Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,621.00</u> .
Revised Estimate Amount	: S\$ <u>2,561.00</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	10-04-2019	Our Ref No. D19002454MFSH
Accident Date	08-04-2019	Claim Type. Third Party
Insured Vehicle	SHC2356A	Third Party Vehicle. GBB1734A
Survey Location	160 SIN MING DRIVE #02-20SIN MING AUTOCITY	
Contact Person.	SANDRA	
Contact No.	64527018/ 96222116	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	K. KIM HIN AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 15 April 2019 5:20 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19002454MFSH/1
Attachments: GBB 1734A - Preli Advise.pdf

Dear Karen,

Enclosed preliminary revised of vehicle GBB 1734A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 12 April 2019 10:46 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002454MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 12 April 2019 9:11 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002454MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2109H
Vehicle Details	
Vehicle No.:	GBB1734A
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL 3SEATER
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	1KD1855615
Chassis No.:	JTFAT35Y303001998
Maximum Power Output:	-
Open Market Value:	\$24,243.00
Original Registration Date:	21 Aug 2008
First Registration Date:	21 Aug 2008
Transfer Count:	3
Actual ARF Paid:	\$1,213.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Aug 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$15,582.00
COE Rebate Amount:	\$13,596.00
Total Rebate Amount:	\$13,596.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 09 Apr 2019

OK

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S665500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MKKH 1904442 Vehicle Registration No: GBB 1734 A
Name (as shown in NRIC) : SUHADAK BIN SOPAEMO NRIC/FIN/Passport No : S 1317796 A
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : 86195687
Email Address : _____
Date of Accident : 8.4.19 Time of Accident : 13:20 HRS
Place of Accident : CHANGI ROAD
Insurance Company: TMIS

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

THIRD PARTY VEHICLE SHOULD BE SHE 2352 A.
SORRY FOR TYPE.

[Signature]
Policyholder / Driver's Signature
Date: 11/4/19

[Signature]
Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____
Date: _____

EG. NUMBER:

MAKE/MODEL:**HASSIS MEMBER:**

GBB 1734A

Toyota Dyna

JTFAT35Y303001998

[illegible]

LIST
40

95

255N

220x2
195

2205W

60 N

4505N

450

400

50

~~2561~~
2621

LKK (Kenneth)

Ks



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30416

Date : 13-Apr-2019

Vehicle Insured : SHC 2356 A
Accident Date : 08-Apr-2019

PAGE : 1

Our Ref : 190186 (FIRST) / SANDRA

CDS CAR RENTAL PTE LTD
Singapore

Not Notarised
11 Rm @ 1650
Resurvey After Paint

ESTIMATED COST OF REPAIR FOR TOYOTA DYNA 150 3.0 (2008) GBB1734A

1 pc rear end panel 'Dyna' sticker	<i>m</i>	95.00	✓
1 pc tailgate 'Toyota' sticker	<i>m</i>	196.00	✓
2 pcs taillamp assy (LH & RH)	@ S\$220.00 <i>m</i>	440.00	✓
1 pc n/s taillamp bracket	<i>n</i>	195.00	X
		926.00	
	Less 25% :	-231.50	

694.50

- 1 pc rear number plate
- 1 pc tailgate '70km/h' sticker
- 1 pc reverse sensor assy
- 1 pc reverse sensor bracket
- 1 pc rear lower step member

<i>m</i>	40.00	sn	✓
<i>m</i>	25.00	sn	✓
<i>n</i>	220.00	sn	✓ <i>2000</i>
<i>n</i>	60.00	sn	X
<i>m</i>	450.00	sn	✓

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

To putty and respray on affected
portions.

To focus taillamps. To check rear
wiring and lighting operation.

<i>731.00</i>	
<i>-25%</i>	
<i>548.25 s/parts</i>	450.00 400
<i>735.00 sn</i>	
<i>+780.00 Labour</i>	400.00 360
<i>2063.25</i>	
<i>-20%</i>	50.00 20
Total :	S\$ 2,389.50
<i>1650.60</i>	

Singapore Dollars Two Thousand Three Hundred
and Eighty Nine and Cents Fifty Only

L/Sum \$1650/-

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants has advised the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: *Shay*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19006559/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 25-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2356A	Veh. Inspected	GBB 1734A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002454MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	12/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JTFAT35Y303001998	Colour	BLUE	
Odometer	167968	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	MICHELIN	3 mm	
L/H Front Tyre	195 R15X8	MICHELIN	3 mm	
R/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	9/9 mm	
L/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	9/9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/04/2019	Inspection Date	11/04/2019	
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 1734A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR END PANEL "DYNA" STICKER	NECESSARY	95.00	95.00
1	TAILGATE "TOYOTA" STICKER	NECESSARY	196.00	196.00
2	TAILLAMP ASSY (LH & RH) @\$220.00	CRACKED	440.00	440.00
1	N/S TAILLAMP BRACKET	TO REPAIR SEE LABOUR	195.00	-
	LESS 25% DISCOUNT		-231.50	-182.75
			694.50	548.25
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	BENT	40.00	40.00
1	TAILGATE "70KM/H" STICKER (SN)	NECESSARY	25.00	25.00
1	REVERSE SENSOR ASSY (SN)	DENTED	220.00	200.00
1	REVERSE SENSOR BRACKET (SN)	TO REPAIR SEE LABOUR	60.00	-
1	REAR LOWER STEP MEMBER (SN)	BENT	450.00	450.00
			795.00	715.00
LABOUR				
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF N/S TAILLAMP BRACKET AND REVERSE SENSOR BRACKET.		450.00	400.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		400.00	360.00
	TO FOCUS TAILLAMPS.TO CHECK REAR WIRING AND LIGHTING OPERATION.		50.00	20.00
			900.00	780.00
GRAND TOTAL			2,389.50	2,043.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00

Report Ref No. CS/FCI19006559/Ksd3n2

MARKET VALUE: \$27,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$13,596.00=NETT VALUE: \$13,404.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.