

Ke

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0021969
Yusuf Ali

Page 1 of 2
Your ref. TP-SFW 8999Z EQ
Job No 70385
Our ref. 19.04.08
Payment
Date 12/4/2019

Attn

Vehicle No SGG 295X
Vehicle Model BMW 328i
Accident on 6/4/2019

Not Authorized

Reserv B4 paint

3 days

83733.00

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts					
1.00	Pc	Front door RH	310.00		310.00 ✓
1.00	Pc	Front door weatherstrip RH	105.00		105.00 ✓
1.00	Pc	Rear door RH	1,200.00		1,200.00 ✓
1.00	Pc	Rear door weatherstrip RH	105.00		105.00 ✓
Total amount of parts supplied - S\$2220.00					
1.00		15% of parts supplied	333.00		333.00
Labour & Misc					
1.00		To check/erase fault codes	80.00		80.00 ✓
1.00		To apply anti rust chemical	80.00		80.00 ✓
1.00		To straighten body, to dismantle + renew above parts	500.00		500.00 440 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0021969
Yusuf Ali

Page 2 of 2
Your ref. TP-SFW 8999Z EQ
Job No 70385
Our ref 19.04.08
Payment
Date 12/4/2019

Attn

Vehicle No SGG 295X
Vehicle Model BMW 328i
Accident on 6/4/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To spray paint	800.00		800.00

(Bad part fed in and new fed in RT)

800

Sub-Total 4,013.00
GST 7.00% 280.91
Total S\$ 4,293.91

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO