



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

### ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JIANG JUN  BLK 334C YISHUN STREET 31 #09-123 SINGAPORE 763334  Contact No	Cust No/Name	KCV09940/JIANG JUN
	Reg No/Reg Date	SMG8553C / 02/01/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0600388
	Engine No	4J11AB7593
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KCV09940	CRDVCH	23/01/2019/ 14:12	TLC	442 / CocoLu	35541		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000		RENEW REAR BUMPER, TAILGATE, REPAIR REAR END PANEL			1100		2200.00
E PNT88000		REMOVE & INSTALL TAILGATE GLASS			260		300.00
E PNT88000		REMOVE & INSTALL REAR COMPARTMENT TRIMS AND TAILGATE TRIMS			840		300.00
E PNT98000		SPRAY PAINT FOR REAR BUMPER, TAILGATE, REAR END PANEL					1680.00
E PNT88000		REMOVE & INSTALL PARKING SENSOR			60		100.00
M SUNDRY		SUPPLY PARKING SENSOR					220.00
M SUNDRY		APPLY SEALANT FOR ACCIDENT PORTION					80.00
M SUNDRY		APPLY SEALANT FOR ACCIDENT PORTION					40.00
M SUNDRY		C&C LOGO					40.00
A 54900099		CHECK WIRING & ELECTRICAL SYSTEM			20		30.00
A 54900099		CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM					200.00
M SUNDRY		Sundry					20.00
M		PANEL ASSY, TAILGATE	1.00	924.00	00.00		924.00
M		FACE, RR BUMPER	1.00	799.00	00.00		799.00
M		EXTENSION, RR BUMPER	1.00	224.00	00.00		224.00
M		REINFORCEMENT, RR BUMPER, RH	1.00	78.00	00.00		78.00
M		REINFORCEMENT, RR BUMPER, LH	1.00	78.00	00.00		78.00
M		BRKT, R/BMPR FACE SIDE, LH	1.00	12.00	00.00		12.00
M		BRKT, R/BMPR FACE SIDE, RH	1.00	12.00	00.00		12.00
M		MOULDING, RR BUMPER, LH	1.00	105.00	00.00		105.00
M		W/STRIP, TAILGATE OPENING	1.00	211.00	00.00		211.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

### ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JIANG JUN  BLK 334C YISHUN STREET 31 #09-123 SINGAPORE 763334  Contact No	Cust No/Name	KCV09940/JIANG JUN
	Reg No/Reg Date	SMG8553C / 02/01/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0600388
	Engine No	4J11AB7593
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV09940	CRDVCH	23/01/2019/ 14:12	TLC	442 / CocoLu	35541

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M DAM, TAILGATE, UPR	1.00	12.00	00.00	12.00
M DAM, TAILGATE SIDE	1.00	27.00	00.00	27.00
M STOPPER, WINDSHIELD GLASS	1.00	3.00	00.00	3.00
M DAM, TAILGATE, LWR	1.00	41.00	00.00	41.00
M GLASS, TAILGATE WINDOW	1.00	743.00	00.00	743.00
M FASTENER, WINDSHIELD	2.00	6.00	00.00	12.00
M LATCH, TAILGATE	1.00	379.00	00.00	379.00
M MOULDING, RR BUMPER, LH	1.00	105.00	00.00	105.00
M TRIM, RR END	1.00	112.00	00.00	112.00
M MARK, OUTLANDER	1.00	94.00	00.00	94.00
M REFLECTOR, TAIL LAMP, LH	1.00	99.00	00.00	99.00
M REFLECTOR, TAIL LAMP, RH	1.00	99.00	00.00	99.00

# Estimate

5 Days.

before paint photos.

Guo Qianf - 8880282

29/1/19.

Confirm & accepted by LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and Authorized signatory and company stamp		
	7% GST on	9379.00
	Nett	9,379.00
	Total Payable	10,035.53

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.