

Kancha

Survey & report
16.05 @ 10am
LKK VIC

BMW Dealer

Performance Motors LimitedA Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

12 APR 2019

E S T I M A T EEstimate No. : b1 50825
Date Estimated : 11/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Manokaran S/O Mookkayyah
290G Bukit Batok Street 24
#05-91

Singapore 656290

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR406M	0V44791	03/07/2017	X4 xDrive20i	0

DESCRIPTION

To replace front bumper, fender right and attachments.

Painting front bumper and fender right.

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.To carry out body cavity preservation.
(Per panel).

To replace right headlight.

To carry out body cavity preservation.
(Per panel).

Sundries.

VALUE

1700 2,580.00

1996 2,218.00

150 177.00

100 118.00

408 481.00

nn repeated X 118.00

80.00

Total Labour 1: 5,742.00

DESCRIPTION

CLIP BEIGE 1. X 1.10

RH GRILLE SIDE CLOSED 1. X 107.75

GRID LATERAL RH (X LINE) 1. X 112.90

CLADDING BUMPER FRT (PDC/SCHWARZ) 1. X 315.70

CLIP 6. X 2.00

FRT RH WHEEL ARCH COVER 1. X 179.75

RH BI XENON HEADLIGHT 1. X 2,437.65

Super (Prined) 1. X

QTYPRICVALUE

6 1.10 6.60

1 107.75 107.75

1 112.90 112.90

1 315.70 315.70

6 2.00 12.00

1 179.75 179.75

1 2,437.65 2,437.65

Total Parts : 3,172.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 50825**
Date Estimated : **11/04/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR406M	0V44791	03/07/2017	X4 xDrive20i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured Losses / Direct Settlement	
Regh No.	Claim No.
Date&Time 16/05/19 @ 1410	Excess S\$
Surveyor's Name Rasul	Sign
Surveyor's Tel 90010068	Authorised Yes / No
Authorised Date	Time
PLS SURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M. Yes / No	
Company's Email	
No. of Working Days Recommend 5 days	

Labour 1	:	5,742.00
Parts	:	3,172.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	624.00
Grand Total	:	9,538.35

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****

**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50825
Date Estimated : 11/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Manokaran S/O Mookkayyah
290G Bukit Batok Street 24
#05-91

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 656290

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR406M	0V44791	03/07/2017	X4 xDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

To replace front bumper and attachments, front RH fender, front RH wheel arch cover include knocking out dents caused by the accident	1700.00		1,700.00 ✓
---	---------	--	------------

To spray paint front bumper and front RH fender	1996.00		1,996.00 ✓
---	---------	--	------------

To check electrical wiring systems at the front section for proper function	150.00		150.00 ✓
---	--------	--	----------

To carry out body cavity preservation (Per panel)	100.00		100.00 ✓
---	--------	--	----------

To replace RH bi xenon headlight include programming and conducting tests for proper function	408.00		408.00 ✓
---	--------	--	----------

Sundries	80.00		80.00 ✓
----------	-------	--	---------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# FRT RH FENDER *	804.50	1.00		804.50 (✓)
CLADDING BUMPER FRT (PDC/SCHWARZ)	315.70	1.00		315.70 ✓
# FRT BUMPER PANEL PRIMED *	1,362.10	1.00		1,362.10 (✓)
CLIP	2.00	6.00		12.00 ✓
# EXPANDING RIVET *	1.35	20.00		27.00 (✓)
FRT RH WHEEL ARCH COVER	179.75	1.00		179.75 ✓
RH BI XENON HEADLIGHT	2,437.65	1.00		2,437.65 ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,434.00
Total Parts :	5,138.70
Total Labour & Parts :	9,572.70
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,572.70
GST @7%:	670.09
Grand Total :	10,242.79

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 50825
Date Estimated : 11/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Manokaran S/O Mookkayyah
290G Bukit Batok Street 24
#05-91

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 656290

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR406M	0V44791	03/07/2017	X4 xDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT RH FENDER * <i>bt</i> ✓	804.50	1.00		804.50
# FRT BUMPER PANEL PRIMED * <i>sent</i> ✓	1,362.10	1.00		1,362.10
# EXPANDING RIVET * <i>rm</i> ✓	1.35	20.00		27.00

Total Labour :	0.00
Total Parts :	2,193.60
Total Labour & Parts :	2,193.60