



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKX2785Z

Sta Inter-Global Pte.Ltd.

2 Jalan Jamal
Singapore 457594

Vehicle & Document Information

WIP No **32459**
Reg No/Reg Date **SKX2785Z / 02/12/2015**
Date In/Mileage **/ 0**
Chassis No **WDD2462422J365887**
Engine No **27091030802448**
Make/Model **MB/B 180 SEDAN (W246) "STYLE**
Colour/Trim **029 990 Orientbraun/ 041 111 Black**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WCV21390	CRDVCH	12/04/2019/ 09:15	AQ	305 / Alan Quek Ai Lun					
<p>M BPNSUN POLICY NO/ACC DATE : // 09-04-2019 TOW IN:09-04-2019 // TP CAR NO:SFS8822X (AXA INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :</p>									
A BPILAB									
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT								0.10	380.00
A BPILAB									
CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT									120.00
S BPNSUB									
SUPPLY & TRANSFER 1PC FRONT RIGHT RIM PURCHASE ORDER NO:									60.00
A BPILAB									
INSPECT & CONDUCT WHEEL ALIGNMENT.NETT									540.00
A BPILAB									
REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.									3360.00
A BPIRES									
RESPRAY FRONT BUMPER, FRONT BONNET, FRONT RIGHT FENDER & FRONT RIGHT DOOR								0.02	2800.00
M	RH/F HEADLAMP	1.00	2578.52	00.00	2578.52				
M	RH/F HEADLAMP CONTROL UNIT	1.00	922.93	00.00	922.93				
M	FRT CROSS MEMBER	1.00	319.85	00.00	319.85				
M	FRT END SUPPORT MEMBER	1.00	643.80	00.00	643.80				
M	RH/F FENDER	1.00	659.41	00.00	659.41				
M	RH/F INTERMEDIATE LAYER	1.00	9.35	00.00	9.35				
M	RH/F BUMPER BRACKET	1.00	12.11	00.00	12.11				
M	RH/F WHEEL ARCH	1.00	188.53	00.00	188.53				
M	FRT BUMPER	1.00	1387.61	00.00	1387.61				
M	RH/F BOTTOM GRILLE	1.00	47.59	00.00	47.59				
M	FRT UNDER CARRIAGE COVER	1.00	286.38	00.00	286.38				
M	FRT IMPACT ABSORBER	1.00	131.95	00.00	131.95				

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKX2785Z

Sta Inter-Global Pte.Ltd.

2 Jalan Jamal
Singapore 457594

Vehicle & Document Information

WIP No **32459**
Reg No/Reg Date **SKX2785Z / 02/12/2015**
Date In/Mileage **0**
Chassis No **WDD2462422J365887**
Engine No **27091030802448**
Make/Model **MB/B 180 SEDAN (W246) "STYLE**
Colour/Trim **029 990 Orientbraun/ 041 111 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WCV21390	CRDVCH	12/04/2019/ 09:15	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RH/F PARKING SENSOR	1.00	177.22	00.00	177.22
M RH/F PARKING SENSOR SEAL	1.00	6.42	00.00	6.42
M RH/F BOTTOM GRILLE GARNISH	1.00	75.02	00.00	75.02
M RH/F DISC WHEEL	1.00	509.20	00.00	509.20

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
OID: 6771 437 IP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **15,215.89**
7% GST on **15215.89** **1065.11**

Authorized signatory and company stamp

Total Payable **16,281.00**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg