



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKX2785Z

Sta Inter-Global Pte.Ltd.

2 Jalan Jamal
Singapore 457594

Vehicle & Document Information

WIP No 32459
Reg No/Reg Date SKX2785Z / 02/12/2015
Date In/Mileage / 0
Chassis No WDD2462422J365887
Engine No 27091030802448
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 029 990 Orientbraun/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator				
WCV21390	CRDVCH	15/04/2019/ 08:56	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 5096846404 // 09-04-2019 TOW IN: 09-04-2019 // TP CAR NO: SFS8822X (AXA INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :								
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT					0.10			380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT								120.00
S BPNSUB SUPPLY & TRANSFER IPC FRONT RIGHT RIM PURCHASE ORDER NO:								60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								540.00
A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.					2400	3368.00		3368.00
A BPIRES RESPRAY FRONT BUMPER, FRONT BONNET, FRONT RIGHT FENDER & FRONT RIGHT DOOR					0.02	2400		2800.00
S BPNTOW ACCIDENT TOWING FROM 32 DEFU LANE TO PLSC USING STRAIGHT TOWING WO: 161887								120.00
M RH/F HEADLAMP					1.00	2578.52	00.00	2578.52
M RH/F HEADLAMP CONTROL UNIT					1.00	922.93	00.00	922.93
M FRT CROSS MEMBER					1.00	319.85	00.00	319.85
M FRT END SUPPORT MEMBER					1.00	643.80	00.00	643.80
M RH/F FENDER					1.00	659.41	00.00	659.41
M RH/F INTERMEDIATE LAYER					1.00	9.35	00.00	9.35
M RH/F BUMPER BRACKET					1.00	12.11	00.00	12.11
M RH/F WHEEL ARCH					1.00	188.53	00.00	188.53

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 195400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKX2785Z

Sta Inter-Global Pte.Ltd.

2 Jalan Jamal
Singapore 457594

Vehicle & Document Information

WIP No 32459
Reg No/Reg Date SKX2785Z / 02/12/2015
Date In/Mileage / 0
Chassis No WDD2462422J365887
Engine No 27091030802448
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 029 990 Orientbraun/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WCV21390	CRDVCH	15/04/2019/ 08:56	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M FRT BUMPER	1.00	1387.61	00.00	1387.61
M RH/F BOTTOM GRILLE	1.00	47.59	00.00	47.59
M FRT UNDER CARRIAGE COVER	1.00	286.38	00.00	286.38
M FRT IMPACT ABSORBER	1.00	131.95	00.00	131.95
M RH/F PARKING SENSOR	1.00	177.22	00.00	177.22
M RH/F PARKING SENSOR SEAL	1.00	6.42	00.00	6.42
M RH/F BOTTOM GRILLE GARNISH	1.00	75.02	00.00	75.02
M RH/F DISC WHEEL	1.00	509.20	00.00	509.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Alan Quek

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Handwritten notes:
Hq 90010068
8 days
P/P
15/04/19 @ 1535
Resy before paint

Confirmed & accepted by

7% GST on 15335.89
Total Payable 16,409.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

ESTIMATE FOR SKX2785Z

STA Inter-Global Pte. Ltd

C/O AXA INSURANCE PTE LTD
MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811
63387283

Rasul

Vehicle & Document Information

WIP No 32459
Reg No/Reg Date SKX2785Z / 02/12/2015
Date In/Mileage 15/04/2019/42619
Chassis No SWDD2462422J365887
Engine No 27091030802448
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 029 990 Orientbraun/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator	
CSI00001	Cash	29/04/2019/ 19:35	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M. BPNSUN

POLICY NO/ACC DATE : 5096846404 // 09-04-2019
TOWIN: 09-04-2019 // TPA CAR NO: SFS8822X (AXA INSURANCE)
DATE IN/DATE SURVEY: 15-04-2019 // LKK RASUL
BY/AUTHORIZED ON : LKK ASHER // 30-04-2019

OFFICIAL TAX INVOICE

A BPILAB	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT	0.10			380.00 ✓
A BPILAB	CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT				120.00 ✓
S BPNSUB	LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN ELAP) WHEEL BALANCE AND INSTALL NEW VALVE HEAD				60.00 ✓
A BPILAB	INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00 ✓
A BPILAB	REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				2400.00 ✓
A BPIRES	RESPRAY FRONT BUMPER, FRONT BONNET, FRONT RIGHT FENDER & FRONT RIGHT DOOR				2400.00 ✓
S BPNTOW	ACCIDENT TOWING FROM 32 DEFU LANE TO PLSC USING STRAIGHT TOWING WO: 161887				120.00 ✓
X RH/F HEADLAMP		1.00	2578.52	00.00	2578.52 ✓
X CONTROL UNIT		1.00	922.93	00.00	922.93 ✓
X RH/F FENDER		1.00	659.41	00.00	659.41 ✓
X RH/F WHEEL ARCH		1.00	188.53	00.00	188.53 ✓
X FRT BUMPER		1.00	1387.61	00.00	1387.61 ✓
X RH/F DISC WHEEL		1.00	509.20	00.00	509.20 ✓
X RH/F BUMPER BRACKET		1.00	12.11	00.00	12.11 ✓
X PLUG		1.00	4.96	00.00	4.96 (S)

Also Quick

Cycle & Carriage Industries Pte Ltd

Confirmed & accepted by

Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Nett 12,283.27
7% GST on 12283.27 859.83

Authorized signatory and company stamp

Total Payable 13,143.10

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8368
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

SUPPLEMENTARY

ESTIMATE FOR SKX2785Z

STA Inter-Global Pte. Ltd

C/O AXA INSURANCE PTE LTD
MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811
63387288

Vehicle & Document Information

WIP No 32459
Reg No/Reg Date SKX2785Z / 02/12/2015
Date In/Mileage 16/04/2019/42619
Chassis No SWB2462422J365887
Engine No 27091030802448
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 029 990 Orientbraun/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator	
CS100001	Cash	29/04/2019/ 19:35	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M_BPNSUN

POLICY NO/ACC DATE : 5096846404 // 09-04-2019
TOWN IN: 09-04-2019 // TPA CAR NO: SFS8822X (AXA INSURANCE)
DATE IN/DATE SURVEY: 15-04-2019 // LKK RASUL
BY/AUTHORIZED ON : LKK ASHER // 30-04-2019
X PLUG

1.00 4.96 00.00

4.96

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on Nett 4.96 0.35

Authorized signatory and company stamp

Total Payable 5.31

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg