



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
ADEL TRANSPORTATION SERVICES  287 BUKIT BATOK EAST AVENUE 3 #09-405 SINGAPORE 650287  Contact No	Cust No/Name	KCV08900/ ADEL TRANSPORTATION SERVICES
	Reg No/Reg Date	SGH2020D / 31/07/201
	Date In/Mileage	/ 0
	Chassis No	JMAXTGK1WJZ002787
	Engine No	4B40DR0442
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS SU
	Colour/Trim	P26 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KCV08900	CRDVCH	08/04/2019/ 18:47		465 / Tay Jian Ye	38456		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW REAR BUMPER, REAR AIR DAM, TAILGATE, REPAIR END PANEL , REAR RH FENDER							<del>2200.00</del> 1650
E PNT88000 TO TRANSFER TAILGATE TRIM, MECHANISM TO NEW PART							<del>300.00</del> 250
E PNT88000 TO TRANSFER REAR PARKING SENOR TO NEW PART							<del>80.00</del>
E PNT88000 TO REMOVE AND REFIT REAR WINDSCREEN							<del>240.00</del>
E PNT98000 PAINT WORK SPRAY REAR BUMPER, TAILGATE . REAR RH FENDER END PANEL, REAR AIR DAM							<del>2520.00</del> 1260
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							<del>50.00</del> 30
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							<del>200.00</del>
M SUNDRY TO APPLY ANTI COROSSION							<del>80.00</del>
M SUNDRY TO APPLY BODY SEALANT							<del>120.00</del> 80
M SUNDRY TO APPLY WINDSCREEN SEALANT							<del>80.00</del>
M SUNDRY TO SUPPLY C&C LOGO							<del>50.00</del>
M SUNDRY TO SUPPLY MIVEC LOGO							<del>50.00</del>
M SUNDRY SUNDRIES							<del>50.00</del> 20
M	REAR BUMPER GARNISH	DE		1.00	443.00	00.00	443.00
M	REAR CORNER EXTENSION	X		1.00	266.00	00.00	266.00
M	TAIL GATE GARNISH	SEA		1.00	111.00	00.00	111.00
M	REAR BUMPER PROTECTOR	NEW		1.00	181.00	00.00	181.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
<b>ADEL TRANSPORTATION SERVICES</b>  287 BUKIT BATOK EAST AVENUE 3 #09-405 SINGAPORE 650287  <b>Contact No</b>	<b>Cust No/Name</b>	KCV08900/ ADEL TRANSPORTATION SERVICES
	<b>Reg No/Reg Date</b>	SGH2020D / 31/07/201
	<b>Date In/Mileage</b>	/ 0
	<b>Chassis No</b>	JMAXTGK1WJZ002787
	<b>Engine No</b>	4B40DR0442
	<b>Make/Model</b>	MIT/ECLIPSE CROSS 1.5 T/C SPORTS SU
	<b>Colour/Trim</b>	P26 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KCV08900	CRDVCH	08/04/2019/ 18:47		465 / Tay Jian Ye	38456	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
M	REINFORCEMENT,RR BUMPER		1.00	489.00	00.00	489.00
M	FACE,RR BUMPER	DE	1.00	548.00	00.00	548.00
M	BRKT,R/BMPR FACE SIDE,LH	X	1.00	25.00	00.00	25.00
M	BRKT,R/BMPR FACE SIDE,RH	ne	1.00	25.00	00.00	25.00
M	EXTENSION,RR BUMPER	scu	1.00	150.00	00.00	150.00
M	COVER,RR BUMPER,LH	X	1.00	116.00	00.00	116.00
M	COVER,RR BUMPER,RH	ne	1.00	116.00	00.00	116.00
M	CLIP,ENG ROOM COVER	ne	10.00	2.00	00.00	20.00
M	SENSOR,BACK DISTANCE WARN	scu	1.00	326.00	00.00	326.00
M	SENSOR,BACK DISTANCE WARN	X	1.00	326.00	00.00	326.00
M	SENSOR,CORNER CLEARANCE	?	1.00	326.00	00.00	326.00
M	PANEL ASSY,TAILGATE	9A	1.00	969.00	00.00	969.00
M	SPACER,QTR WINDOW	ne	4.00	8.00	00.00	32.00
M	STOPPER,WINDSHIELD GLASS	ne	2.00	3.00	00.00	6.00
M	FASTENER,WINDSHIELD	ne	8.00	6.00	00.00	48.00
M	SPACER,TAILGATE	ne	2.00	8.00	00.00	16.00
M	SPACER,TAILGATE	ne	2.00	8.00	00.00	16.00
M	PIN,TAILGATE WINDOW	ne	1.00	4.00	00.00	4.00
M	DAM,TAILGATE,LWR	ne	1.00	13.00	00.00	13.00
M	CLIP,TAILGATE	ne	2.00	3.00	00.00	6.00
M	W/STRIP,TAILGATE OPENING	9B?	1.00	192.00	00.00	192.00
M	LATCH,TAILGATE	X	1.00	379.00	00.00	379.00
M	MARK,ECLIPSE CROSS	ne	1.00	86.00	00.00	86.00
M	GLASS,TAILGATE WINDOW	?	1.00	696.00	00.00	696.00
M	GLASS,TAILGATE WINDOW	?	1.00	516.00	00.00	516.00

Estimate

SURVEYOR NAME: Pasne - (tp 90010068)

SURVEYOR SIGNATURE: [Signature]

DATE: 18/04/19 @ 1530

REMARKS: 7 days  
Ream before paint

SURVEYOR NAME: Pasue - Hp 90010068

SURVEYOR SIGNATURE: [Signature]

DATE: 18/04/19 @ 1530

REMARKS: 7 days

Ready before paint

Confirm & accepted by

<b>Nett</b>	<b>12,467.00</b>
7% GST on	12467.00
<b>Total Payable</b>	<b>13,339.69</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.