



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKN8118M

Sharon Huang Si Min

Blk 410A Fernvale Road
#13-110
Singapore 791410

Mobile: 91910733

Vehicle & Document Information

WIP No **32524**
Reg No/Reg Date **SKN8118M / 09/03/2017**
Date In/Mileage **0**
Chassis No **WDD2130422A201001**
Engine No **27492030956950**
Make/Model **MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 042 201 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	11/04/2019/ 15:24	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request				
M BPNSUN POLICY NO/ACC DATE : GA370443 // 10-4-2019 DRIVE IN/TP VEH NUMBER : 11-4-2019 // SGY4452M - AXA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				1920 4800.00
A BPIRES RESPRAY FRONT BUMPER & BONNET & RH/FRONT FENDER				1800 2160.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00 /
A BPILAB TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT				120.00 /
S BPNSUB SUPPLY 1 SET NUMBER PLATE WITH HOUSING. NETT				60.00 /
M RH FRONT FENDER	1.00	1005.14	00.00	1005.14
M RH/FENDER INTERMEDIATE LAYER	1.00	10.71	00.00	10.71
M FRONT BUMPER	1.00	1248.31	00.00	1248.31
M BUMPER CHROME ORNAMENTAL MOLDING	1.00	279.67	00.00	279.67
M LOWER BASIC MOUNTING FOR BUMPER	1.00	82.27	00.00	82.27
M FRT BUMPER BOTTOM	1.00	115.17	00.00	115.17
M BUMPER LOWER CHROME ORNAMENTAL MOLDING	1.00	115.17	00.00	115.17
M CTR COVER BUMPER AREA	1.00	98.70	00.00	98.70
M LICENSE PLATE MOLDING	1.00	115.17	00.00	115.17
M RADAR SENSOR	1.00	1579.51	00.00	1579.51
M ELECTRICAL WIRING HARNESS	1.00	447.58	00.00	447.58
M PRESSURE SENSOR	1.00	191.24	00.00	191.24
M RH/COVER BUMPER AREA	1.00	62.56	00.00	62.56
M RH/BUMPER BRACKET	1.00	49.37	00.00	49.37

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKN8118M

Sharon Huang Si Min
Blk 410A Fernvale Road
#13-110
Singapore 791410
Mobile: 91910733

Vehicle & Document Information

WIP No 32524
Reg No/Reg Date SKN8118M / 09/03/2017
Date In/Mileage / 0
Chassis No WDD2130422A201001
Engine No 27492030956950
Make/Model MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE
Colour/Trim 029 992 Selenite Gr/ 042 201 Black

Table with 5 columns: Account No, Terms, Date/Time Printed, CSE, Operator. Row 1: CSI00001, Cash, 11/04/2019/ 15:24, CH, 371 / Go Chee Han

Main items table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like INNER DISTANCE SENSOR, OUTER DISTANCE SENSOR, BONNET, RADIATOR GRILLE, STAR CARRIER SILVER BEAM, etc.

Large diagonal watermark text: 'ESTIMATE' and 'THIS IS NOT AN OFFICIAL TAX INVOICE'

Handwritten notes: Steve (LKK) with P/P, 9/5/19 12.10pm, 8322 8813, 5 days, P/P, Ry beL spy

Summary table with 3 columns: Description, Amount, Total. Rows: Confirmed & accepted by, LKK Auto Consultants hence notify the Repairer of the following, Net 22,512.80, 7% GST on 22512.80, Total Payable 24,088.70

Authorized signatory and company stamp box with fields for Signature and Date. Includes text: 'LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting'.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg