



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKN8118M

Sharon Huang Si Min

Blk 410A Fernvale Road
#13-110
Singapore 791410

Mobile: 91910733

Vehicle & Document Information

WIP No **32524**
Reg No/Reg Date **SKN8118M / 09/03/2017**
Date In/Mileage **SKN8118M / 0**
Chassis No **WDD2130422A201001**
Engine No **27492030956950**
Make/Model **MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 042 201 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	11/04/2019/ 15:24	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : GA370443 // 10-4-2019 DRIVE IN/TP VEH NUMBER : 11-4-2019 // SGY4452M - AXA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				4800.00
A BPILAB STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				2160.00
A BPIRES RESPRAY FRONT BUMPER & BONNET & RH/FRONT FENDER			0.10	380.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				120.00
A BPILAB TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT				60.00
S BPNSUB SUPPLY 1 SET NUMBER PLATE WITH HOUSING-NETT				
M RH FRONT FENDER	1.00	1005.14	00.00	1005.14
M RH/FENDER INTERMEDIATE LAYER	1.00	10.71	00.00	10.71
M FRONT BUMPER	1.00	1248.31	00.00	1248.31
M BUMPER CHROME ORNAMENTAL MOLDING	1.00	279.67	00.00	279.67
M LOWER BASIC MOUNTING FOR BUMPER	1.00	82.27	00.00	82.27
M FRT BUMPER BOTTOM	1.00	115.17	00.00	115.17
M BUMPER LOWER CHROME ORNAMENTAL MOLDING	1.00	115.17	00.00	115.17
M CTR COVER BUMPER AREA	1.00	98.70	00.00	98.70
M LICENSE PLATE MOLDING	1.00	115.17	00.00	115.17
M RADAR SENSOR	1.00	1579.51	00.00	1579.51
M ELECTRICAL WIRING HARNESS	1.00	447.58	00.00	447.58
M PRESSURE SENSOR	1.00	191.24	00.00	191.24
M RH/COVER BUMPER AREA	1.00	62.56	00.00	62.56
M RH/BUMPER BRACKET	1.00	49.37	00.00	49.37

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKN8118M

Sharon Huang Si Min

Blk 410A Fernvale Road
#13-110
Singapore 791410

Mobile: 91910733

Vehicle & Document Information

WIP No **32524**
Reg No/Reg Date **SKN8118M / 09/03/2017**
Date In/Mileage **SKN8118M / 0**
Chassis No **WDD2130422A201001**
Engine No **27492030956950**
Make/Model **MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 042 201 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	11/04/2019/ 15:24	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M INNER DISTANCE SENSOR	2.00	177.22	00.00	354.44
M OUTER DISTANCE SENSOR	1.00	177.22	00.00	177.22
M BONNET	1.00	2277.67	00.00	2277.67
M RADIATOR GRILLE	1.00	186.72	00.00	186.72
M STAR CARRIER SILVER BEAM	1.00	291.34	00.00	291.34
M TOP LEFT CHROME GRILLE	1.00	62.84	00.00	62.84
M TOP RIGHT CHROME GRILLE	1.00	62.84	00.00	62.84
M BOTTOM LEFT CHROME GRILLE	1.00	62.84	00.00	62.84
M BOTTOM RIGHT CHROME GRILLE	1.00	62.84	00.00	62.84
M STAR CARRIER BEAM	1.00	73.49	00.00	73.49
M MERCEDES STAR	1.00	139.39	00.00	139.39
M CROSSMEMBER	1.00	508.61	00.00	508.61
M CONSOLE MOUNTING	1.00	210.75	00.00	210.75
M FRONT SUPPORT PANEL	1.00	822.01	00.00	822.01
M RIGHT HEADLAMP UNIT	1.00	3352.04	00.00	3352.04
M HEADLAMP RANGE CONTROL UNIT	1.00	650.76	00.00	650.76
M COVER F ENGINE COMP. BM	1.00	233.55	00.00	233.55
M RH/COVER F ENGINE COMP. BM	1.00	62.88	00.00	62.88

THIS IS NOT AN OFFICIAL TAX INVOICE
ESTIMATE

Confirmed & accepted by

Nett 22,512.80
7% GST on 22512.80 1575.90

Authorized signatory and company stamp

Total Payable 24,088.70

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg