



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Asher

ESTIMATE FOR SKN8118M

Sharon Huang Si Min
Blk 410A Fernvale Road
#13-110
Singapore 791410
Mobile: 91910733

Vehicle & Document Information	
WIP No	32524
Reg No/Reg Date	SKN8118M / 09/03/2017
Date In/Mileage	09/05/2019 / 26249
Chassis No	WBD10022A201001
Engine No	27492030956950
Make/Model	MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE
Colour/Trim	029 992 Selenite Gr/ 042 201 Black

SKN8118M

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
CSI00001	Cash	16/05/2019/ 08:35	CH	371 / Go Chee Han				

Z REQUEST
Customer Request
M BRNSON

THIS IS NOT AN OFFICIAL TAX INVOICE

POLICY NO/ACC DATE : GA370443 // 10-4-2019
DRIVE IN/TP VEH NUMBER : 11-4-2019 // SGY4452M - AXA
DATE IN/DATE SURVEY: 9-5-2019 1210 // Steve - LKK
BY/AUTHORIZED ON : 8-5-2019 0954 // Asher Sng - LKK

- ①
- ②
- ③
- ④
- ⑤
- ⑥
- ⑦
- ⑧
- ⑨
- ⑩
- ⑪
- ⑫
- ⑬
- ⑭

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A BPILAB STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH				1920.00
A BPIRES RESPRAY FRONT BUMPER & BONNET & RH/FRONT FENDER			0.10	380.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				120.00
A BPILAB TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT				60.00
S BPNSUB SUPPLY 1 PC NO PLATE	1.00	1005.14	00.00	1005.14
X RH FRONT FENDER	1.00	2277.67	00.00	2277.67
X BONNET	1.00	62.88	00.00	62.88
X RH/COVER F ENGINE COMP. BM	1.00	1248.31	00.00	1248.31
X FRONT BUMPER	1.00	279.67	00.00	279.67
X BUMPER CHROME ORNAMENTAL MOLDING	1.00	82.27	00.00	82.27
X LOWER BASIC MOUNTING FOR BUMPER	1.00	115.17	00.00	115.17
X FRT BUMPER BOTTOM	1.00	115.17	00.00	115.17
X BUMPER LOWER CHROME ORNAMENTAL MOLDING	1.00	98.70	00.00	98.70
X CTR COVER BUMPER AREA	1.00	115.17	00.00	115.17
X LICENSE PLATE MOLDING	1.00	62.56	00.00	62.56
X RH/COVER BUMPER AREA	1.00	49.37	00.00	49.37
X RH/BUMPER BRACKET	1.00	177.22	00.00	177.22
X INNER DISTANCE SENSOR	1.00	186.72	00.00	186.72
X RADIATOR GRILLE				

ESTIMATE

Finalization

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, so signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKN8118M

Sharon Huang Si Min

Bik 410A Fernvale Road
#13-110
Singapore 791410

Mobile: 91910733

Vehicle & Document Information

WIP No **32524**
Reg No/Reg Date **SKN8118M / 09/03/2017**
Date In/Mileage **09/05/2019 / 26249**
Chassis No **WDD2130422A201001**
Engine No **27492030956950**
Make/Model **MB/MB E 200 2.0 SEDAN (W213) *AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 042 201 Black**

SKN8118M

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	16/05/2019/ 08:35	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X TOP RIGHT CHROME GRILLE	1.00	62.84	00.00	62.84
X BOTTOM RIGHT CHROME GRILLE	1.00	62.84	00.00	62.84
X MERCEDES STAR	1.00	189.89	00.00	189.89
X CONSOLE MOUNTING	1.00	210.75	00.00	210.75
X RIGHT HEADLAMP UNIT	1.00	3352.04	00.00	3352.04
X COVER F ENGINE COMP. BM	1.00	233.55	00.00	233.55
X CTR . IMPACT ABSORBER	1.00	148.07	00.00	148.07
X INFORMATION LABEL	1.00	35.86	00.00	35.86

- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Go Chee Han
DID: 6771 4336 HP: 9181 7717
Email: cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Finalization

Confirmed & accepted by

Nett	14,401.36
7% GST on	14401.36
	1008.10

Authorized signatory and company stamp

Total Payable 15,409.46

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKN8118M

Sharon Huang Si Min
Blk 410A Fernvale Road
#13-110
Singapore 791410
Mobile: 91910733

Vehicle & Document Information

WIP No	32524
Reg No/Reg Date	SKN8118M / 09/03/2017
Date In/Mileage	09/05/2019 / 26249
Chassis No	WBD2130422A201001
Engine No	27492030956950
Make/Model	MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE
Colour/Trim	029 992 Selenite Gr/ 042 201 Black

SKN8118M

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	16/05/2019/ 08:35	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN
 POLICE NO/ACC DATE : 10570445 / 10-5-2019
 DRIVE IN/APP VER NUMBER : 1144-2019 / 136Y4452M AXA
 DATE IN/DATE SURVEY : 9-5-2019 1210 // Steve - LKK
 BY/AUTHORIZED ON : 8-5-2019 0954 // Asher Sng - LKK
 X CTR . IMPACT ABSORBER - BR
 X INFORMATION LABEL - NEC

THIS IS NOT AN OFFICIAL TAX INVOICE				
	1.00	148.07	00.00	148.07
	0.00	35.86	00.00	35.86

Go Chee Han
 DID : 6771 4336 HP : 9181 7717
 Email : cheehan.go@cyclecarriage.com.sg
 Cycle & Carriage Industries Pte Ltd
 Customer Service Centre - Pandan Loop

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

	Nett	183.93
7% GST on	183.93	12.88
Total Payable		196.81

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
 188 Pandan Loop
 Singapore 128378
 Tel: 6777 8388
 Fax: 6779 5383
 www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKN8118M

Sharon Huang Si Min

Blk 410A Fernvale Road
#13-110
Singapore 791410

Mobile: 91910733

Vehicle & Document Information

WIP No 32524
Reg No/Reg Date SKN8118M / 09/03/2017
Date In/Mileage / 0
Chassis No WDD2130422A201001
Engine No 27492030956950
Make/Model MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE
Colour/Trim 029 992 Selenite Gr/ 042 201 Black

SKN8118M

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	11/04/2019/ 15:24	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE : GA370443 // 10-4-2019				
DRIVE IN/TP VEH NUMBER : 11-4-2019 // SGY4452M - AXA				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
A BPILAB				1920 4800.00
STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. 910 x 2				
A BPIRES				1800 2160.00
RESPRAY FRONT BUMPER & BONNET & RH/FRONT FENDER				
A BPILAB			0.10	380.00 /
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
A BPILAB				120.00 /
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT				
S BPNSUB				60.00 /
SUPPLY 1 SET NUMBER PLATE WITH HOUSING. NETT				
M RH FRONT FENDER	1.00	1005.14	00.00	1005.14
M RH/FENDER INTERMEDIATE LAYER X NN	1.00	10.71	00.00	10.71
M FRONT BUMPER BR	1.00	1248.31	00.00	1248.31
M BUMPER CHROME ORNAMENTAL MOLDING BR	1.00	279.67	00.00	279.67
M LOWER BASIC MOUNTING FOR BUMPER ? BR	1.00	82.27	00.00	82.27
M FRT BUMPER BOTTOM MIS	1.00	115.17	00.00	115.17
M BUMPER LOWER CHROME ORNAMENTAL MOLDING MIS	1.00	115.17	00.00	115.17
M CTR COVER BUMPER AREA CUT	1.00	98.70	00.00	98.70
M LICENSE PLATE MOLDING CUT ON	1.00	115.17	00.00	115.17
M RADAR SENSOR X NN	1.00	1579.51	00.00	1579.51
M ELECTRICAL WIRING HARNESS ? X NN	1.00	447.58	00.00	447.58
M PRESSURE SENSOR X AIAI	1.00	191.24	00.00	191.24
M RH/COVER BUMPER AREA CUT	1.00	62.56	00.00	62.56
M RH/BUMPER BRACKET BR	1.00	49.37	00.00	49.37

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKN8118M

Sharon Huang Si Min
Blk 410A Fernvale Road
#13-110
Singapore 791410
Mobile: 91910733

Vehicle & Document Information

WIP No: 32524
Reg No/Reg Date: SKN8118M / 09/03/2017
Date In/Mileage: / 0
Chassis No: WDD2130422A201001
Engine No: 27492030956950
Make/Model: MB/MB E 200 2.0 SEDAN (W213) *AVANTGARDE
Colour/Trim: 029 992 Selenite Gr/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	11/04/2019/ 15:24	CH	371 / Go Chee Han

	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
③	M INNER DISTANCE SENSOR / IC	2.00	177.22	00.00	354.44
	M OUTER DISTANCE SENSOR X NN	1.00	177.22	00.00	177.22
②	M BONNET X R NN DO	1.00	2277.67	00.00	2277.67
④	M RADIATOR GRILLE / BR	1.00	186.72	00.00	186.72
	M STAR CARRIER SILVER BEAM X NN	1.00	291.34	00.00	291.34
	M TOP LEFT CHROME GRILLE X NAI	1.00	62.84	00.00	62.84
⑤	M TOP RIGHT CHROME GRILLE / CH	1.00	62.84	00.00	62.84
	M BOTTOM LEFT CHROME GRILLE X NN	1.00	62.84	00.00	62.84
⑥	M BOTTOM RIGHT CHROME GRILLE / CH	1.00	62.84	00.00	62.84
	M STAR CARRIER BEAM X NAI	1.00	73.49	00.00	73.49
⑦	M MERCEDES STAR / CH	1.00	139.39	00.00	139.39
	M CROSSMEMBER X NAI	1.00	508.61	00.00	508.61
⑧	M CONSOLE MOUNTING / BR	1.00	210.75	00.00	210.75
	M FRONT SUPPORT PANEL X NN	1.00	822.01	00.00	822.01
⑨	M RIGHT HEADLAMP UNIT / CH	1.00	3352.04	00.00	3352.04
	M HEADLAMP RANGE CONTROL UNIT X NN	1.00	650.76	00.00	650.76
⑩	M COVER F ENGINE COMP. BM / CRU	1.00	233.55	00.00	233.55
③	M RH/COVER F ENGINE COMP. BM / BR	1.00	62.88	00.00	62.88

Steve (LKK) with print 8 9/5/19 12.10pm
8322 8813 5 days
P/P
By brk spy

Confirmed & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

Nett	22,512.80
7% GST on	22512.80
Total Payable	24,088.70

Validity of this estimate is only valid on the vehicle's computer generated document, no signature is required. Estimated costs quoted are based on our initial inspection and does not include any additional parts or labour which may be required after work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Acknowledged by Repairer

Signature:

Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg