

11th APR 2019

ERGO Insurance Pte Ltd

5 Temasek boulevard, #04-05, suntec Tower Fire Singapore 038985

Attention : Motor Vehicle Claim Department

Dear Sir / Mdm,

Third Party Claim

We are currently assisting SMA9010C to make accident claims

Against vehicle number GBB4245A which eventuated on 10/04/2019

This vehicle is insured by ERGO Insurance

We seek your co-operation to get the vehicle surveyed by your
Accredited surveyors.

Once arrangement is being made, please do notify us to let us have the
Ample time to get things arranged for the surveyor.

Your Faithfully,

Wega Engineering Pte Ltd



Leong Chee Kwong

Claims Advisor

Mobile No: 84917768

WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

ERGO Insurance Pte Ltd

Date : 11/4/2019

5 Temasek boulevard, #04-05, suntec Tower Fire Singapore 038985

Vehicle No : SMA9010C
Chassis No : ZSU600081234
Make/Model : TOYOTA HARRIER PREMIUM 2.0 CVT
Year : 2016

S/N	Qty	Description	Unit Price	Amount
Estimate Cost Of Repair				
1	1pc	REAR TAIL GATE ASSY	\$ 1,590.00	\$ 1,590.00
2	1pc	TAILGATE LOCK	\$ 360.00	\$ 360.00
3	1pc	TAILGATE LOCK COVER	\$ 49.00	\$ 49.00
4	1pc	TAILGATE GAS ABSORBER LH	\$ 1,150.00	\$ 1,150.00
5	1pc	TAILGATE GAS ABSORBER RH	\$ 1,150.00	\$ 1,150.00
6	1pc	TAIL GATE DOOR WEATHERSTRIP	\$ 328.00	\$ 328.00
7	1pc	TAIL GATE INNER BOARD ASSY	\$ 690.00	\$ 690.00
8	1pc	TAIL GATE LAMP LH	\$ 530.00	\$ 530.00
9	1pc	TAILAMP LH	\$ 580.00	\$ 580.00
10	1pc	TAIL GATE LAMP RH	\$ 530.00	\$ 530.00
11	1pc	TAILAMP RH	\$ 580.00	\$ 580.00
12	1pc	NAME PLATE (HARRIER)	\$ 75.00	\$ 75.00
13	1pc	EMBLEM REAR	\$ 55.00	\$ 55.00
14	1pc	CAMERA ASSY REVERSE	\$ 1,185.00	\$ 1,185.00
15	1pc	REAR BUMPER	\$ 1,460.00	\$ 1,460.00
16	1pc	REAR BUMPER RENTANNER LH	\$ 110.00	\$ 110.00
17	1pc	REAR BUMPER RENTANNER RH	\$ 110.00	\$ 110.00
18	1pc	REAR BUMPER ABSORBER	\$ 93.00	\$ 93.00
19	1pc	REVERSE SENSOR	\$ 220.00	\$ 220.00
20	1pc	REAR END PANAL	\$ 670.00	\$ 670.00
21	1pc	REAR END PANAL COVER	\$ 400.00	\$ 400.00
22	1pc	REAR BUMPER LOWER COVER	\$ 420.00	\$ 420.00
23	1pc	NUMBER PLATE SET	\$ 60.00	\$ 60.00
24	2pc	WINDSCREEN SILLANT	\$ 35.00	\$ 70.00

Labour Charges

1	To check wiring & system function	\$ 100.00
2	To apply rust proofing on affected area	\$ 150.00
3	To transfer rear tail gate mechanism	\$ 120.00
4	To remove & refix rear windscreen	\$ 200.00
5	To replace sundry parts	\$ 100.00
6	To replace , repair & knocking accident rear portion rear bumper , rear tailgate , rear bumper lower cover and rear end panal	\$ 1,300.00
7	To respray rear bumper , rear tail gate rear end panal , rear fender RH & LH	\$ 1,500.00

Grand Total

\$ 15,935.00

Wega Engineering Pte Ltd

Authorised Signature
Leong Chee Kwong
Mobile No: 84917768