

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

Number : EBK0000268
Date : 13/04/2019
Case No : ADK0000341
Vehicle No : SJU7372B
Chassis: JHMF1D16039S203257
Year of Mfr 2009
Policy No
Model : HONDA CIVIC

Term:		DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	RR BUMPER	1.0	638.00	20	510.40	
2	RR BUMPER SIDE RETAINER LH RH	2.0	17.60	20	28.16	
3	RR BUMPER CLIPS	12.0	3.70	20	35.52	
4	RR BOOTLID	1.0	610.70	20	488.56	
5	RR BOOTLID LOGO CIVIC	1.0	24.30	20	19.44	
6	RR BOOTLID LOGO 1.8 I-VTEC	1.0	21.70	20	17.36	
7	RR BOOTLID EMBLEM	1.0	24.10	20	19.28	
8	RR BOOTLID INNER RUBBER	1.0	95.80	20	76.64	
9	RR END PANEL	1.0	300.60	20	240.48	
List Price - Parts Sub Total					1,435.84	
10	RR REVERSE SENSOR LH RH	1.0	300.00	0	300.00	
Special Nett Price - Parts Sub Total					300.00	
Parts Total					1,735.84	
11	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	800.00	0	800.00	
12	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00	
Labour 1 Sub Total					1,600.00	
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To do any damaged part(s) during resurvey - Parts price are subject to confirmation - Third party survey is on a "Without Prejudice" basis - The repair completion must be allowed - Quote the cost to be resurveyed and is subject to the approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					1363.2 209 109056 228056 302 1603.	
SINGAPORE DOLLARS: THREE THOUSAND FIVE HUNDRED SIXTY-NINE AND CENTS THIRTY-FIVE ONLY				Less Excess	0.00	
				SUBTOTAL	3,335.84	
				GST 7.00%	233.51	
				TOTAL	3,569.35	

* N = Item not subjected to GST