

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

11/02/19

A/C

TO : S7413164F
LOW WEI WEI
BLK 763 BEDOK RESERVOIR VIEW
12-291
SINGAPORE 470763
TEL : FAX :
PH : 98588868
ATTN :

not Adhorm
Hock
narrow
1st 8/19
Hdy. 4/5
The ph. After repair

ESTIMATE BILL

Number : EBK0000268
Date : 13/04/2019
Case No : ADK0000341
Vehicle No : SJU7372B
Chassis : JHMFD16039S203257
Year of Mfr : 2009
Policy No :
Model : HONDA CIVIC

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	RR BUMPER	1.0	638.00	20	510.40
2	RR BUMPER SIDE RETAINER LH RH	2.0	17.60	20	28.16
3	RR BUMPER CLIPS	12.0	3.70	20	35.52
4	RR BOOTLID	1.0	610.70	20	488.56
5	RR BOOTLID LOGO CIVIC	1.0	24.30	20	19.44
6	RR BOOTLID LOGO 1.8 I-VTEC	1.0	21.70	20	17.36
7	RR BOOTLID EMBLEM	1.0	24.10	20	19.28
8	RR BOOTLID INNER RUBBER	1.0	95.80	20	76.64
9	RR END PANEL	1.0	300.60	20	240.48
List Price - Parts Sub Total					1,435.84
10	RR REVERSE SENSOR LH RH	1.0	300.00	0	300.00
Special Nett Price - Parts Sub Total					300.00
Parts Total					1,735.84
11	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	800.00	0	800.00
12	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
Labour 1 Sub Total					1,600.00
SINGAPORE DOLLARS : THREE THOUSAND FIVE HUNDRED SIXTY-NINE AND CENTS THIRTY-FIVE ONLY					0.00
Less Excess					0.00
SUBTOTAL					3,335.84
GST 7.00%					233.51
TOTAL					3,569.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date of accident : 19/02/2019 09:40 AM. Place : ALONG RD 1 MOULMEIN RD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE