

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

SHD 59R

AAD1904-126

Not Authored
1/1/2016 83350/1

Vehicle No.:	SHD 59R
Chassis No.:	VF1ABL15AUC282639
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	10.4.2019
Third Party Insurer :	TOKIO MARINE
Date of Registration :	4/2/2016

PART	LIST
1 FENDER PANEL REAR RH	\$ <i>B1</i> 3,299.13
1 FENDER PANEL INNER TRIM REAR	\$ <i>Sn</i> 671.45
1 WHEELARCH REAR RH	\$ <i>Sn</i> 543.47
1 BUMPER COVER REAR	\$ <i>R</i> 1,108.46
1 BUMPER LOWER REAR	\$ <i>Sn</i> 768.84
1 BUMPER BRACKET CTR REAR	\$ <i>Sn</i> 113.47
1 BUMPER BRACKET SIDE RH REAR	\$ <i>Sn</i> 135.97
1 BUMPER RETAINER RH REAR	\$ <i>Sn</i> 44.99
1 REAR TAILAMP RH	\$ <i>Sn</i> 552.55
	<hr/>
	\$ 7,238.33
	10% \$ 723.83
	<hr/>
	\$ 6,514.50

Special Nett

1SET PARKING AID	\$ <i>Sn</i> 700.00
1SET REAR BUMPER CLIP	\$ <i>nn</i> 66.00
1SET BUMPER BRACKET CTR CLIP	\$ <i>nn</i> 33.00
1SET BUMPER BRACKET SIDE CLIP RH RR	\$ <i>nn</i> 10.00
1SET BUMPER RETAINER RH CLIP RR	\$ <i>nn</i> 20.00
1SET BUMPER BRACKET SIDE CLIP LH RR	\$ <i>nn</i> 10.00
1SET BUMPER RETAINER CLIP LH RR	\$ <i>nn</i> 20.00
1SET BUMPER LOWER REAR RIVET	\$ <i>nn</i> 22.00
1SET BUMPER LOWER REAR CLIP	\$ <i>nn</i> 66.00

TOTAL \$ 947.00

Trans-cab Auto Services Pte Ltd

AAD1904-126

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 59R

TOTAL PARTS \$ 7,461.50

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	<i>600</i>
Putty and spray painting of the affected portion.	\$	3,000.00	<i>440</i>
To rust-proofing of the affected areas.	\$	170.00	<i>30</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>100</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>na X</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>na X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>20</i>
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	380.00	<i>na X</i>

TOTAL \$ 7,490.00

Over All Total \$ 14,951.50

LUMP SUM (REPAIR DAY)

10 DAYS

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____