

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0448/2019/DY/GW
Date : 6-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : **SKT 4614 S**

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Motor Claims Dept

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr. Tan Siew Ming Jeffrey
Address : 32 Mount Vernon Road
#17-07
Singapore 368056
Telephone : 97429517
Type of Claim : Third Party Claims
Policy No. : 1800109467
Vehicle No : **SME 2989 D**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Sep-18
Engine No : CVK068515
Chassis No : WAUZZZ48JA229658
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Apr-19
Place of Accident : Along Upper Aljunied

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 2989 D

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	s/n	\$ 360.00	✓
2	To dismantle and renew rear bumper. Re-organize crash management components. Reinstall all parts removed.		\$ 900.00 600	
3	To respray rear bumper.		\$ 800.00 600	
4	To carry out diagnostic check.	s/n	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	\$ <u>2,252.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2989 D

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	\$	2,015.00 <i>+</i>
2	REAR BUMPER SECURING STRIP <i>new</i>	\$	203.00 <i>+</i>
3	REAR BUMPER SPOILER <i>new</i>	\$	227.00 <i>+</i>
4	REAR BUMPER REINFORCEMENT BEAM <i>new</i>	\$	819.00 <i>+</i>
5	REAR BUMPER SEAL <i>3 new</i>	2 \$	25.00 <i>+</i>
6	REAR BUMPER GUIDE SECTION-LH/RH	2 \$	40.00 <i>+</i>
7	REAR SENSOR <i>3 new</i>	2 \$	462.00 <i>+</i>
8	REAR SENSOR SEAL RING	4 \$	12.00 <i>+</i>
9	SUNDRIES <i>new</i>	\$	400.00 <i>+</i>
TOTAL SPARE PARTS		:	\$ 4,203.00
TOTAL LABOUR CHARGES		:	\$ 2,252.00
GRAND TOTAL		:	\$ 6,455.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Addan King
Surveyed Date : 12/04/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant