

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT19001624	Page	1
	3 ANSON ROAD #16-00	Date	: 11. Apr 2019		
	SPRINGLEAF TOWER	Customer No.	: WC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SKW629K	Engine No	: K24W71011552		
Chassis No	: JHMRC1890FC203162	Date Time	: 11. Apr 2019 9:50:16 AM		
Model	: ODYSSEY 2.4 EXV-S 15YM	Surveyor Name	: DID : +65 6846 5673		
Owner's Name	: NG DJONI	Survey Date	: HP : +65 8109 6306		
Ins Policy No.	:	Authorisation Date	: Email : arychua@honda.com.sg		
Date of Accident	: 10/4/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: 72527						
	POLICY/CLAIMS NO: DMPCSN1669891802						
	OWNER: NG DJONI						
	ACC DATE: 10-04-2019@12.15PM						
	ACC: SENGKANG EAST RD (L/P 119)@TRAFFIC JUNCTION						
	SURVEYED BY:						
	AUTHORIZED ON:						
	REF NO:						
54206	EXTERNAL LABOUR SALES - INS. EXCESS		1000.00				
			Sum G/L Account		0.00	0.00	0.00
TOW-SPEEDWAY	TOWING SERVICE - B24022	1	60.00		60.00	4.20	64.20
BO-V-KOOL-FWS	SUPPLY & INSTALL SOLAR FILM ON FRONT WINDSCREEN.	1	300.00		300.00	21.00	321.00
			Sum Ext. Service		360.00	25.20	385.20
60400-T6A-310ZZ	BULKHEAD COMPFR. / Buc	1	460.80	15	391.68	27.42	419.10
60433-T6A-300ZZ	SUPPORTR.FR.BULKHEAD UPP SIDE = BT	1	35.30	15	30.00	2.10	32.10
60483-T6A-300ZZ	SUPPORT,L.FR.BULKHEAD UPP SIDE = BT	1	35.30	15	30.00	2.10	32.10
60210-T6A-300ZZ	FENDER COMPR.FR. / Buc	1	548.60	15	466.31	32.64	498.95
60260-T6A-300ZZ	FENDER COMPL.FR. / Buc	1	548.60	15	466.31	32.64	498.95
74150-T6A-000	FENDER ASSYL.FR INNER = Re	1	120.70	15	102.59	7.18	109.77
74100-T6A-000	FENDER ASSYR.FR INNER = M's	1	120.70	15	102.59	7.18	109.77
72415-T6A-003	MOLDING ASSYR.FR.CORNER = Re.	1	87.70	15	74.54	5.22	79.76
72465-T6A-003	MOLDING ASSYL.FR.CORNER = Re.	1	87.70	15	74.54	5.22	79.76
60100-T6A-000ZZ	HOOD COMP / Buc	1	671.40	15	570.69	39.95	610.64
60120-T6A-000ZZ	HINGE COMPR.HOOD = BT	1	47.40	15	40.29	2.82	43.11
60170-T6A-000ZZ	HINGE COMPL.HOOD = BT	1	47.40	15	40.29	2.82	43.11

Printed on 12/4/2019 3:27:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SKW629K

Chassis No : JHMRC1890FC203162

Model : ODYSSEY 2.4 EXV-S 15YM

Owner's Name : NG DJONI

Ins Policy No. :

Date of Accident : 10/4/2019

Document No. : SQT19001624 Page 2

Date : 11. Apr 2019

Customer No. : WC008

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W71011552

Date | Time : 11. Apr 2019 9:50:16 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
74120-T6A-003	LOCK ASSYHOOD / BT	1	106.20	15	90.27	6.32	96.59
74141-T6A-010	INSULATORHOOD / BT	1	94.40	15	80.24	5.62	85.86
80111-T6A-003	CONDENSER COMP / BT	1	681.90	15	579.61	40.57	620.18
80341-T6A-003	PIPE COMPRECEIVER ?	1	176.70	15	150.19	10.51	160.70
80311-T6A-003	HOSE COMPSUCTION ?	1	184.30	15	156.65	10.97	167.62
80315-T6A-003	HOSE COMPDISCHARGE ?	1	160.20	15	136.17	9.53	145.70
19010-5X6-J02	RADIATOR COMP / BT	1	1347.30	15	1145.20	80.16	1225.36
19015-5X6-J01	SHROUD COMP ?	1	108.30	15	92.05	6.44	98.49
19020-5A4-H02	FAN COMPCOOLING ?	1	55.50	15	47.17	3.30	50.47
19030-5X6-J01	MOTORCOOLING FAN ?	1	298.40	15	253.64	17.75	271.39
38611-5A4-H02	FAN COMPCOOLING ?	1	54.20	15	46.07	3.22	49.29
38615-5X6-J01	SHROUD COMP ?	1	83.80	15	71.23	4.99	76.22
38616-5X6-J02	MOTOR, COOLING FAN ?	1	322.60	15	274.21	19.19	293.40
38619-5X6-J01	HEAT PROTECTORFAN MOTOR ?	1	8.60	15	7.31	0.51	7.82
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED = CRA	1	2281.90	15	1939.61	135.77	2075.38
33150-T6A-Q11	HEADLIGHT ASSY,L.WITH LED = CRA	1	2281.90	15	1939.61	135.77	2075.38
71104-T6A-921	GARNISHR.FR.BUMPER =	1	46.10	15	39.18	2.74	41.92
71109-T6A-921	GARNISHL.FR.BUMPER =	1	46.10	15	39.18	2.74	41.92
71121-T6A-003	BASEFR.GRILLE = DIS	1	169.00	15	143.65	10.06	153.71
71122-T6A-003	MOLDINGFR.GRILLE =	1	263.30	15	223.80	15.67	239.47
75700-TA0-A00	EMBLEMFR. =	1	26.70	15	22.69	1.59	24.28
90301-ST0-003	NUTPUSH 3MM =	2	2.10	15	3.57	0.25	3.82
36560-T6A-J01	CAMERA ASSY,MVC FR. = NB	1	520.00	15	442.00	30.94	472.94
36561-T6A-N01	COVERMVC FR.CAMERA = NB	1	8.30	15	7.05	0.49	7.54
04711-T6A-900ZZ	FACE,FR.BUMPER =	1	700.00	15	595.00	41.65	636.65
71105-T6A-901	GRILLEFR.BUMPER LOWER = CRA	1	67.10	15	57.03	3.99	61.02
71130-T6A-310ZZ	BEAM COMP,FR.BUMPER =	1	291.80	15	248.03	17.36	265.39
71140-T6A-003	BEAMR.FR.BUMPER UPPER = BT	1	34.90	15	29.66	2.08	31.74
71151-T6A-911	BASEMID GRILLE = DIS	1	186.50	15	158.52	11.10	169.62

Printed on 12/4/2019 3:27:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SKW629K

Chassis No : JHMRC1890FC203162

Model : ODYSSEY 2.4 EXV-S 15YM

Owner's Name : NG DJONI

Ins Policy No. :

Date of Accident : 10/4/2019

Document No. : SQT19001624 Page 3

Date : 11. Apr 2019

Customer No. : WC008

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W71011552

Date | Time : 11. Apr 2019 9:50:16 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71152-T6A-921	UPPER MOLDINGMID GRILLE	1	153.60	15	130.56	9.14	139.70
71153-T6A-921	MID MOLDINGMID GRILLE	1	147.10	15	125.03	8.75	133.78
71154-T6A-921	LOWER MOLDINGR.MID GRILLE	1	39.50	15	33.57	2.35	35.92
71159-T6A-921	LOWER MOLDINGL.MID GRILLE	1	39.50	15	33.57	2.35	35.92
71190-T6A-003	BEAML.FR.BUMPER UPPER	1	34.90	15	29.66	2.08	31.74
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	11.80	15	10.03	0.70	10.73
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	11.80	15	10.03	0.70	10.73
71117-T6A-921ZE	SPOILER ASSYL.FR.SIDE	1	94.40	15	80.24	5.62	85.86
71112-T6A-921ZE	SPOILER ASSYR.FR.SIDE	1	94.40	15	80.24	5.62	85.86
91505-TM8-003	CLIP,BUMPER	10	2.30	15	19.55	1.37	20.92
91578-T0A-003	CLIPFR.GRILLE	4	2.30	15	7.82	0.55	8.37
73111-T6A-U01	GLASS SET,FR.WINDSHIELD	1	2365.30	15	2010.50	140.74	2151.24
73126-SYY-000	RUBBER BFR W/SHIELD	3	3.70	15	9.43	0.66	10.09
73150-T6A-003	MOLDINGFR.WINDSHIELD	1	19.60	15	16.66	1.17	17.83
77466-TL0-G01	SEALFR.INSTRUMENT	1	13.50	15	11.47	0.80	12.27
17201-5X6-J00	CASE SETAIR CLEANER	1	94.40	15	80.24	5.62	85.86
17210-5X6-J00	COVER COMPAIR CLEANER	1	82.80	15	70.38	4.93	75.31
17220-5X6-J00	ELEMENT ASSYAIR CLEANER	1	70.30	15	59.75	4.18	63.93
17230-5X6-J00	CHAMBER ASSYRESONATOR	1	109.70	15	93.24	6.53	99.77
17252-5X6-J00	TUBE ASSY AAIR INTAKE	1	75.50	15	64.17	4.49	68.66
17253-5X6-J00	TUBE ASSY BAIR INTAKE	1	66.00	15	56.10	3.93	60.03
19101-5X6-J00	TANKRESERVE	1	56.60	15	48.11	3.37	51.48
19501-5X6-J00	HOSEWATER UPPER	1	26.30	15	22.35	1.56	23.91
32200-T6A-U41	WIRE HARNESS ENGINE ROOF	1	3182.00	15	2704.70	189.33	2894.03
38100-T6A-J01	HORN ASSYLOW	1	45.70	15	38.84	2.72	41.56
38150-T6A-J01	HORN ASSYHIGH	1	45.70	15	38.84	2.72	41.56
38251-T6A-010	BRACKETRELAY BOX	1	37.90	15	32.21	2.25	34.46
77930-T6A-J21	SENSOR ASSYFR.CRASH	2	131.70	15	223.89	15.67	239.56
77960-T6A-J12	UNIT ASSY,SRS	1	968.00	15	822.80	57.60	880.40

Printed on 12/4/2019 3:27:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT19001624	Page	4
	3 ANSON ROAD #16-00	Date	: 11. Apr 2019		
	SPRINGLEAF TOWER	Customer No.	: WC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SKW629K	Engine No	: K24W71011552		
Chassis No	: JHMRC1890FC203162	Date Time	: 11. Apr 2019 9:50:16 AM		
Model	: ODYSSEY 2.4 EXV-S 15YM	Surveyor Name	:		
Owner's Name	: NG DJONI	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 10/4/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
77100-T6A-000ZA	PANEL COMPINSTRUMENT UPPER - <i>CR1</i>	1	879.80	15	747.83	52.35	800.18
77820-T6A-N80	MODULE ASSYPASSENGER - <i>CR1</i>	1	2785.60	15	2367.76	165.74	2533.50
04814-T6A-M00ZA	TONGUE SETR.FR.SEATBELT OUTER - <i>CR1</i>	1	408.70	15	347.39	24.32	371.71
76841-T6A-003	TANKWASHER ?	1	70.90	15	60.26	4.22	64.48
76812-T6A-003	HOSE ?	1	21.30	15	18.10	1.27	19.37
18120-5B0-Y00	COVER COMPCHAMBER <i>R - cut</i>	1	42.20	15	35.87	2.51	38.38
18121-5B0-Y10	COVER COMPPRIMARY CONVERTER - <i>CR1</i>	1	74.60	15	63.41	4.44	67.85
31100-5X6-J01	AC GENERATOR ASSY ?	1	1859.80	15	1580.83	110.66	1691.49
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 - <i>WCL</i>	6	23.20	15	118.32	8.28	126.60
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) - <i>BT</i>	1	45.00		45.00	3.15	48.15
BO-WS-SEALANT	WINDSCREEN SEALANT (N) - <i>WCL</i>	2	60.00		120.00	8.40	128.40
Sum Item					23877.17	1,671.41	25,548.58

BOSUN	SUNDRIES	1	100.00		<i>40</i> 100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		<i>140</i> 180.00	12.60	192.60
BOJSE	BODY JOINT SEALANT.	1	200.00		<i>150</i> 200.00	14.00	214.00
BOBC	BODY UNDERSIDE COATING (N)	1	250.00		<i>150</i> 250.00	17.50	267.50
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	280.00		<i>250</i> 280.00	19.60	299.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	350.00		<i>300</i> 350.00	24.50	374.50
BG01R	REPLACE FR. WINDSCREEN.(N)	1	350.00		<i>300</i> 350.00	24.50	374.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	400.00		<i>350</i> 400.00	28.00	428.00
BC011R	REMOVE INSTALL & CALIBRATE FRONT VIEW CAMERA	1	450.00		<i>400</i> 450.00	31.50	481.50
BMS00R	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU &	1	2240.00		<i>1680</i> 2240.00	156.80	2396.80
BMI00D	REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL	1	2240.00		<i>1120</i> 2240.00	156.80	2396.80
BKBH11M	RENEW BULKHEAD, WHEELHOUSE ASSY & ALIGN CHASSIS	1	3360.00		<i>2800</i> 3360.00	235.20	3595.20
BP01R	SPRAY PAINT ON REPAIRED/REPLACED AREAS.(7PX \$450)	1	3500.00		<i>3150</i> 3500.00	245.00	3745.00
Sum Labor					13900.00	973.00	14,873.00

Printed on 12/4/2019 3:27:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT19001624	Page	5
	3 ANSON ROAD #16-00	Date	: 11. Apr 2019		
	SPRINGLEAF TOWER	Customer No.	: WC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SKW629K	Engine No	: K24W71011552		
Chassis No	: JHMRC1890FC203162	Date Time	: 11. Apr 2019 9:50:16 AM		
Model	: ODYSSEY 2.4 EXV-S 15YM	Surveyor Name	:		
Owner's Name	: NG DJONI	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 10/4/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	<u>Eno Q. Yap. 82880282</u>						
Date & Time	<u>15/4/19</u>				Total Amount	38,137.17	2,669.61 40,806.78
Excess	<u>\$1000</u>				Total (Inclusive of GST)		<u>40,806.78</u>
Status	<u>Not Authorised.</u>						
Signature							

12-14 Days.

refuel paint photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/4/2019 3:27:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.