

CS/CTI/19006623/Grd302

Merimen

Person (Person)

Estimated Cost

TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To inspect Vehicle No.

at Workshop no.

of

Policy No.

Sum Insured

Make of Veh.

(Client's Record)

CA / RCV / REP / RRV 24 HRS

Date/Time

Person Contacted

ROD Endorsement

Vehicle IN / OUT

Date/Time

Action/Instructon (✓) Estimate

SKW 629K - CS/CTI/19006623/Klea3

DOA: 4/4/19

16/4/19

@404pm Any request repair cost \$37000f

16/4/19

Revert via Merimen. - Repairer asking for repair cost \$37000f

23/4/19

Rate approved \$35,067.17 from Alfred via Merimen

23/4/19

Informed Any c/A not exceeding \$35000f ex \$1000 by email

GR

Elaine Cheong

ASSIGNMENT (Office)

CTI

Date/Time 15/4/19 @ 11:24am

Bill to

SKW 629K

Insured

Kah Motor
15 Ubi Rd 4

Tel

81006306

Claim No.

SNM19020165301

Excess

\$1,000.00

DOA

10/04/2019

Any

Date/Time 12:34pm @ 15/4/19

ASSIGNMENT

From:
 Date: 15/4/19
 Estimated Cost:
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKW629K
 at Workshop m/s: Kiah Motor
 of: 15 Ubi Rd 4
 Insured: 8100 6306
 Policy No: 6846 5673
 Claims No:
 Sum Insured:
 Excess: \$1,000.00
 (Client's Record)
 Make of Veh: pls check market value & consistency of damages.
 (Policy Condition) Any.
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$96k.
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 12 days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No
 CA / (REV) / REP. / 24 HRS
 Date:
 Person Contacted:
 Vehicle: IN / OUT

Veh No: SKW629K Yr Regn: 15 Oct 2015
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda odyssey 2.4 cc .2356
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 23/29 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: JHM RC 1890 FC 203162
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215 / 55 R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or MAXXIS
 Front Rear
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. D.O.I. 15-04-19
 Survey held at w/s 5:30pm
 Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
15/4	It's consistent to the accident.
16/4	Inform Any limit \$96k.
14/5/19	Final fig \$ 32,146.91 confirmed by email (Ref 8031.60, 2019)

RECEIVED 10 MAY 2019

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
 Date/Time, File Return to?
 14/5 - typist
 Report Format: meimen
 Lump Sum / I.B.I. (\$) 32,146.91
 Days Of Repair: 12
 Resurvey No. of Trip: 1
 Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)
 Survey Fee: 220
 Transportation: 3 + RS 31
 Photos
 Others
 TOTAL 220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Apr 2019		15 Apr 2019 11:24 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	NG DJONI, ID: S72765543, Tel: +6591813344, Email: NGDJONI@GMAIL.COM		
Vehicle Reg. No.:	SKW629K	Date of Loss:	10/04/2019 12:00 - :59
Claim Type:	OD / SNM19D201653C01	Policy/Cover Note No.:	DMPCSN1669891802 (Comprehensive)
Vehicle Reg. No. (TP):	GX8306G	Policy No. (TP):	
		Excess:	S\$1,000.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/04/2019]		
Driver/Custodian:	NG DJONI (46 / Male) , NRIC: S72765543, Tel: +6591813344 Email: NGDJONI@GMAIL.COM		
Adj Asg. Remarks:	Please check market value & consistency of damages		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SKW629K (SNM19D201658C01)**

OD

Apr 10 2019 12:00PM

[NG DJONI]

Kah Motor Co Sdn Bhd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 14/05/2019 16:02 PM.
To claimsdept@sg.cntaiping.com; elaine.cheong@sg.cntaiping.com
Subject SKW 629K-SUPPLEMENTARY

Dear Elaine,

Please be informed that we have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident is economical to repair and within authorise limit.

Kindly refer supplementary uploaded.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Ary Chua <arychua@honda.com.sg>
Sent: Tuesday, 23 April 2019 11:52 AM
To: Veron Chen (LKKAUTO); SUR; Guo Qiang (LKKAUTO)
Cc: Liew Thye Wui; Faeaz
Subject: RE: SKW 629K-DOA: 10/4/2019 (CHINA TAIPING)

Hi Veron Chen,
We accept this Limit Repair \$35000.00 for Vehicle: SKW629K

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor **Kah Motor Co.Sdn.Bhd.** Address:15 Ubi Road 4 Singapore 408610
E-mail: arychua@honda.com.sg H/P:81006306 DID:68465673 Fax: 67480770

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Tuesday, 23 April, 2019 11:29 AM
To: SUR <sur@lkkauto.com>; Ary Chua <arychua@honda.com.sg>
Subject: SKW 629K-DOA: 10/4/2019 (CHINA TAIPING)

Dear Ary,

As instructed by our client , please proceed to repair the **insured vehicle SKW 629K Not exceeding repair cost \$35,000/- or which ever lower (Excess \$1000/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 23 April 2019 11:29 AM
To: SUR; Ary Chua
Subject: SKW 629K-DOA: 10/4/2019 (CHINA TAIPING)

Dear Ary,

As instructed by our client , please proceed to repair the **insured vehicle SKW 629K Not exceeding repair cost \$35,000/- or which ever lower (Excess \$1000/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKW629K (SNM19D201658C01)
[GX8306G]**

OD
Apr 10 2019 12:00PM
[NG DJONI]
Kah Motor Co Sdn Bhd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **23/04/2019 11:12 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$35067.17) - SKW629K - Claim Handler: Elaine Cheong

Approved:35067.17:Proceed to authorize repairs NO MORE THAN \$35,773.00 before Excess of \$1,000.00. RE-INSPECTION of vehicle REQUIRED.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Elaine Cheong	Date:	16 Apr 2019
Preliminary Advice			

Vehicle No	: SKW629K	Accident Date	: 10/04/2019
Make	: HONDA ODYSSEY	Policy No.	: DMPCSN1669891802
Assignment Date	: 15/04/2019	Excess	: S\$1,000.00
Date of Inspection	: 15/04/2019	Est. Duration of Repair	: 14.00
Inspection At	: KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,137.17
Revised Amount	:S\$	29,304.89
Check Items (Estimated)	:S\$	5,762.28
Total	:S\$	35,067.17
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	60,227.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,773.00

Brake System : In Order
Steering System : In Order
Tyre Condition (Front) : 6/6 mm
Tyre Condition (Rear) : 6/6 mm

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(X)	Other comments :Repairer asking for repair cost \$37,000/-

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6554J
Vehicle Details	
Vehicle No.:	SKW629K
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	K24W71011552
Chassis No.:	JHMRC1890FC203162
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$27,090.00
Original Registration Date:	15 Oct 2015
First Registration Date:	15 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$29,926.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2025
PARF Rebate Amount:	\$22,444.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$37,783.00
Total Rebate Amount:	\$60,227.00

The information contained herein is correct as at 16 Apr 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6554J
Vehicle Details	
Vehicle No.:	SKW629K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	K24W71011552
Chassis No.:	JHMRC1890FC203162
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$27,090.00
Original Registration Date:	15 Oct 2015
First Registration Date:	15 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$29,926.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2025
PARF Rebate Amount:	\$22,444.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$37,800.00
Total Rebate Amount:	\$60,244.00

The information contained herein is correct as at 15 Apr 2019

OK

NG DJONI
260B SENGKANG EAST WAY
#13-442
SINGAPORE, 542260
SINGAPORE

KF012
DBS BANK LTD
6 SHENTON WAY
DBS BUILDING TOWER ONE
SINGAPORE, 068806
SINGAPORE

Regn. No.: SKW629K
Sales Exec: 0304

Customer No: ****6554J
Registration Date: 15. October 2015

Vehicle: ODYSSEY 2.4 EXV-S 15YM
Model: RC189FJN-NH788P
Color: NH788P WHITE ORCHID P.

Engine: K24W71011552
Chassis: JHMRC1890FC203162

FOC LIMITED EDITION CASHCARD, PETROL VOUCHER,
BLACK VUE 1 CH, 6 MTHS RD TAX

SPECIAL DISCOUNT	-10,000.00
KM DISCOUNT	-1,000.00
FINANCE DISCOUNT	-1,000.00
FLOOR MAT, BLACK W HEAT DUCT	
STEP ILLUMI, NH900L WITH LED	
DVR, BLACKVUE 1 CHANNEL	

TOTAL SGD INCL GST 163,979.49

DOWNPAYMENT BY CUSTOMER	NG DJONI	1,980.49
AMOUNT FINANCED BY	DBS BANK LTD	161,999.00

VALUE OF OTHER SUPPLIES	91,607.49
VALUE OF STANDARD RATE SUPPLIES (SRS)	67,637.39
GST 7% ON STANDARD RATE SUPPLIES	4,734.61
	163,979.49

CUSTOMER'S SRS AMOUNT	1,850.93	G.S.T	129.56
FINANCE CO'S SRS AMOUNT	65,786.46	G.S.T	4,605.05

REMARKS:

FOC 6 MONTHS RD TAX
EXTENDED WARRANTY TO 60 MTHS/UNLIMITED MILEAGE
FOC 1K,10K,20K,30K,40K,50K,60K SERVICING*
IN-HOUSE INSURANCE AND LOAN
3 YRS SVC APPLIED TO 1ST OWNER, NON-TRANSFERABLE
INCOMPLETION USAGE WILL BE FORFEITED

NG DJONI
260B SENGKANG EAST WAY
#13-442
SINGAPORE, 542260
SINGAPORE

KF012
DBS BANK LTD
6 SHENTON WAY
DBS BUILDING TOWER ONE
SINGAPORE, 068806
SINGAPORE

Regn. No.: SKW629K
Sales Exec: 0304

Customer No *****6554J
Registration Date: 15. October 2015

Vehicle ODYSSEY 2.4 EXV-S 15YM
Model RC189FJN-NH788P
Color : NH788P WHITE ORCHID P.

Engine : K24W71011552
Chassis : JHMRC1890FC203162

NETT ARF PRICE (including ARF, COE, ARF, Road Tax, GST, Reg Fee, Aircon, Std Sound Sys, IU,
NO-Plates, Petrol, Carpets, Key-chains, Accessories, And *CVT Oil Change For Civic CVT Models Only)

173,999.00

OPTIONAL ACCESSORIES: *warranty terms and conditions apply

OPT-ODYSSEY-VKOOLE83-FOC
REAR 4PCS ACTIVE SENSORS
ODYSSEY 15 FLR MAT W HEATDUCT

ODYSSEY 14 STEP ILLUMI BLACK

▶ Odyssey Used Vehicle List (10 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Honda Odyssey 2.4A Absolute	\$108,000	\$13,460 /yr	04-Dec-2015	2,356 cc	79,500 km	Maximus Automobile Pte Ltd	Available
Complete Genuine Mugen Bodykit, Came Factory Painted, With Mugen Wheels. Interior Matched With Honda Genuine Modulo Lighting Kits And Mugen Floor Mats. Total Upgrades Over \$25,000. 1 Owner Only. Comes ...							
Office No. - 62501198 Daphne Tan - 96382477 James Lee - 98569774							
Honda Odyssey 2.4A Absolute	\$106,800	\$13,530 /yr	22-Oct-2015	2,356 cc	37,000 km	ST Carz Pte Ltd	Available
1 Owner Only! Cheapest In The Market! Super Low Mileage Clocked! Comes With 19" Sports Rims! 100% Accident Free! STA Evaluation Welcome! Comes With 6 Months Warranty! Buy With A Peace Of Mind! Low Int...							
Office No. - 64654747 Chris Liao - 83565566 Ryan - 90778009							
Honda Odyssey 2.4A EXV-S Sunroof	\$98,800	\$12,710 /yr	16-Oct-2015	2,356 cc	66,399 km	Cosmo Automobiles	Available
Purchase From An Award Winning Dealership! STA Certified Accident Free Quality Pre-Owned With Agent Service History For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing Options. ...							
Office No. - 64651090 Dennis - 92234854 Derrick - 91012525 Andy - 98502116 Alan - 92325665							
Honda Odyssey 2.4A EXV-S Sunroof	\$98,800	\$12,760 /yr	09-Oct-2015	2,356 cc	53,000 km	Prime Car Traders Pte Ltd	Available
One Owner. Well Maintained By Kah Motor Agent. Immaculate Condition. Low Interest Rate. Call/SMS For More Details.							
Office No. - 63166000 Jason - 93881975 Nicolas Lim - 96849675 Jessy - 91690999							
Honda Odyssey 2.4A EXV-S Navi Res Sunroof	\$99,800	\$13,270 /yr	03-Aug-2015	2,356 cc	80,000 km	Dickson Automobile	Available
Highest Spec Honda Odyssey With Factory Fitted Navigation And Res! Low Interest Rate From 1.99% For Limited Period Only! In-House Loan Available! 1 Owner Only! Agent Maintain Unit With Ongoing Agent W...							
Office No. - 68447667 Beatrice Teo - 81287619 Ricky Eng - 91853390 Tank Ong - 85265670							
Honda Odyssey 2.4A Absolute	\$105,000	\$14,510 /yr	21-May-2015	2,356 cc	105,400 km		Available
Direct 1 Owner. Pre Loved, Well Maintained And Prompt Servicing. Accident Free. Call To Arrange To View Or Test Drive In West Area. Negotiable.							
Office No. - - Musrin Marof - 90493994							
Honda Odyssey 2.4A EXV-S Sunroof	\$95,800	\$13,180 /yr	19-May-2015	2,356 cc	50,775 km	Dickson Automobile	Available
Low Interest Rates From 1.99%, In House Loan Available. Low Mileage, Superd Well Maintained & Keep By Previous Careful One Owner With On Going Warranty From Kah Motor Till 5/2020. Buy It From Us With A...							
Office No. - 68447667 Ricky Eng - 91853390 Beatrice Teo - 81287619 Ting Ting - 83946026							
Honda Odyssey 2.4A EXV-S Sunroof	\$93,666	\$12,840 /yr	10-Apr-2015	2,356 cc	93,000 km	Privilege Group Pte Ltd	Available
1 Owner, Warranty From Kah Motor. 100% Accident Free, 100% Loan Available, From 2.28%. Priv Loan Available Too. Very Well Maintained! Most Luxurious MPV! High End Model! Clean And Neat Interior! Call No...							
Office No. - 64755115 Francis - 96358298 Hong - 88223339 Desmond Ang - 83821155 Jackson - 84799696							
Honda Odyssey 2.4A EX-S	\$84,800	\$12,130 /yr	19-Mar-2015	2,356 cc	69,600 km	Hanns Auto	Available
1 Owner With Full Servicing At Agent Kah Motor. Fresh Paintwork, Like New. Decent Mileage Used. Luxurious Full Size MPV That Carry 7 People Comfortably Anywhere. Need No Further Introduction. Honda Be...							
Office No. - 62712252							

Desmond Chan - 91717808

Honda Odyssey 2.4A EXV-S **\$92,800** **\$13,330 /yr** **13-Feb-2015** **2,356 cc** **59,633 km** **Dickson Automobile** **Available**
Sunroof

Low Interest Of 1.98%, In House Loan Available, Well Maintained MPV That Is As Good As Brand New And Smell Like Brand New! Fully Agent (Kah Motor) Maintained With On-going Warranty! 1 Owner! STA Evalu...

Office No. - 68447667

Tank Ong - 85265670 | Ricky Eng - 91853390 | Eric Lee - 91827304

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/04/2019 16:32
Date Of Accident	10/04/2019 12:15
Exact Location Of Accident	SENGKANG EAST RD (LP119)@TRAFFIC JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW629K
Insured/Policyholder	
Name Of Registered Owner	NG DJONI
NRIC No	S7276554J
Email Address	NGDJONI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91813344
Alternative Phone No	OFFICE-91813344

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 EX-S (RC1) (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1669891802
Cover Note Number	

Driver

Name of Driver	NG DJONI
NRIC No	S7276554J
Date Of Birth	19/05/1972
Occupation	INDOOR
Date Of Driving Pass	14/06/1996
Driving Experience	22 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91813344
Fax Number	
Contact Number	OFFICE-91813344
Email Address	NGDJONI@GMAIL.COM

Address	BLK 260B SENGKANG EAST WAY #13-442
Postcode	S542260
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

NOBODY INJURY DURING THE ACCIDENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX8306G
Vehicle Make/Model/Colour	TOYOTA/LORRY/SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

File Number: STW629K
SW8 LRT Renjong Station
 SKETCH PLAN
 ← Sengkang East
Ave ←

A = STW629K
 B = GX8306G



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10/4/19 around 12:17pm, when I was driving home along Sengkang East road. The traffic light was green and I presume that the front vehicle had move. I couldn't stop in time when I realised that the front vehicle did not move even though it was green light.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

10:10am
 11 APR 2019
 Reporting Centre Personnel's Signature
 Name: ARY CHUA
 NRIC/FIN No.:

Sketch Plan Pg. 2

Vehicle Number: SEW 69K

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

10:10am
11 APR 2019

Reporting Centre Personnel's Signature
Name: **ARY CHUA**
NRIC/FIN No.:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT19001624	Page	1
	3 ANSON ROAD #16-00	Date	: 11. Apr 2019		
	SPRINGLEAF TOWER	Customer No.	: WC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SKW629K	Engine No	: K24W71011552		
Chassis No	: JHMRC1890FC203162	Date Time	: 11. Apr 2019 9:50:16 AM		
Model	: ODYSSEY 2.4 EXV-S 15YM	Surveyor Name	: DID : +65 6846 5673		
Owner's Name	: NG DJONI	Survey Date	: HP : +65 8109 5306		
Ins Policy No.	:	Authorisation Date	: Email : anychua@honda.com.sg		
Date of Accident	: 10/4/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	OWN DAMAGE CLAIMS-J/NO: 72527						
	POLICY/CLAIMS NO: DMPCSN1669891802						
	OWNER: NG DJONI						
	ACC DATE: 10-04-2019@12.15PM						
	ACC: SENGKANG EAST RD (L/P 119)@TRAFFIC JUNCTION						
	SURVEYED BY:						
	AUTHORIZED ON:						
	REF NO:						
54206	EXTERNAL LABOUR SALES - INS. EXCESS		1000.00				
			Sum G/L Account		0.00	0.00	0.00
TOW-SPEEDWAY	TOWING SERVICE - B24022 ✓	1	60.00		60.00	4.20	64.20
BO-V-KOOL-FWS	SUPPLY & INSTALL SOLAR FILM ON FRONT WINDSCREEN. ✓ <i>mc</i>	1	300.00		300.00	21.00	321.00
			Sum Ext. Service		360.00	25.20	385.20
60400-T6A-310ZZ	BULKHEAD COMPFR. ✓ <i>Buc</i>	1	460.80	15	391.68	27.42	419.10
60433-T6A-300ZZ	SUPPORTR.FR.BULKHEAD UPP SIDE ✓ <i>SOT</i>	1	35.30	15	30.00	2.10	32.10
60483-T6A-300ZZ	SUPPORT.L.FR.BULKHEAD UPP SIDE ✓ <i>SOT</i>	1	35.30	15	30.00	2.10	32.10
60210-T6A-300ZZ	FENDER COMPR.FR. ✓ <i>Buc</i>	1	548.60	15	466.31	32.64	498.95
60260-T6A-300ZZ	FENDER COMPL.FR. ✓ <i>Buc</i>	1	548.60	15	466.31	32.64	498.95
74150-T6A-000	FENDER ASSYL.FR INNER ✓ <i>Re</i>	1	120.70	15	102.59	7.18	109.77
74100-T6A-000	FENDER ASSYR.FR INNER ✓ <i>Mis</i>	1	120.70	15	102.59	7.18	109.77
72415-T6A-003	MOLDING ASSYR.FR.CORNER ✓ <i>Re.</i>	1	87.70	15	74.54	5.22	79.76
72465-T6A-003	MOLDING ASSYL.FR.CORNER ✓ <i>Re.</i>	1	87.70	15	74.54	5.22	79.76
60100-T6A-000ZZ	HOOD COMP ✓ <i>Buc</i>	1	671.40	15	570.69	39.95	610.64
60120-T6A-000ZZ	HINGE COMPR.HOOD ✓ <i>SOT</i>	1	47.40	15	40.29	2.82	43.11
60170-T6A-000ZZ	HINGE COMPL.HOOD ✓ <i>SOT</i>	1	47.40	15	40.29	2.82	43.11

Printed on 12/4/2019 3:27:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SKW629K

Chassis No : JHMRC1890FC203162

Model : ODYSSEY 2.4 EXV-S 15YM

Owner's Name : NG DJONI

Ins Policy No. :

Date of Accident : 10/4/2019

Document No. : SQT19001624

Date : 11. Apr 2019

Customer No. : WC008

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W71011552

Date | Time : 11. Apr 2019 9:50:16 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
74120-T6A-003	LOCK ASSYHOOD / BT	1	106.20	15	90.27	6.32	96.59
74141-T6A-010	INSULATORHOOD / R	1	94.40	15	80.24	5.62	85.86
80111-T6A-003	CONDENSER COMP / BT	1	681.90	15	579.61	40.57	620.18
80341-T6A-003	PIPE COMPRECEIVER / X	1	176.70	15	150.19	10.51	160.70
80311-T6A-003	HOSE COMPSUCTION / X	1	184.30	15	156.65	10.97	167.62
80315-T6A-003	HOSE COMPDISCHARGE / X	1	160.20	15	136.17	9.53	145.70
19010-5X6-J02	RADIATOR COMP / BT	1	1347.30	15	1145.20	80.16	1225.36
19015-5X6-J01	SHROUD COMP / CRA	1	108.30	15	92.05	6.44	98.49
19020-5A4-H02	FAN COMPCOOLING / R	1	55.50	15	47.17	3.30	50.47
19030-5X6-J01	MOTORCOOLING FAN / R	1	298.40	15	253.64	17.75	271.39
38611-5A4-H02	FAN COMPCOOLING / R	1	54.20	15	46.07	3.22	49.29
38615-5X6-J01	SHROUD COMP / CRA	1	83.80	15	71.23	4.99	76.22
38616-5X6-J02	MOTOR COOLING FAN / R	1	322.60	15	274.21	19.19	293.40
38619-5X6-J01	HEAT PROTECTORFAN MOTOR / X	1	8.60	15	7.31	0.51	7.82
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED / CRA	1	2281.90	15	1939.61	135.77	2075.38
33150-T6A-Q11	HEADLIGHT ASSY,LWITH LED / CRA	1	2281.90	15	1939.61	135.77	2075.38
71104-T6A-921	GARNISHR.FR.BUMPER /	1	46.10	15	39.18	2.74	41.92
71109-T6A-921	GARNISHL.FR.BUMPER /	1	46.10	15	39.18	2.74	41.92
71121-T6A-003	BASEFR.GRILLE /	1	169.00	15	143.65	10.06	153.71
71122-T6A-003	MOLDINGFR.GRILLE /	1	263.30	15	223.80	15.67	239.47
75700-TA0-A00	EMBLEMFR. /	1	26.70	15	22.69	1.59	24.28
90301-ST0-003	NUTPUSH 3MM /	2	2.10	15	3.57	0.25	3.82
36560-T6A-J01	CAMERA ASSY,MVC FR. /	1	520.00	15	442.00	30.94	472.94
36561-T6A-N01	COVERMVC FR.CAMERA /	1	8.30	15	7.05	0.49	7.54
04711-T6A-900ZZ	FACE,FR.BUMPER /	1	700.00	15	595.00	41.65	636.65
71105-T6A-901	GRILLEFR.BUMPER LOWER / CRA	1	67.10	15	57.03	3.99	61.02
71130-T6A-310ZZ	BEAM COMP,FR.BUMPER /	1	291.80	15	248.03	17.36	265.39
71140-T6A-003	BEAMR.FR.BUMPER UPPER / BT	1	34.90	15	29.66	2.08	31.74
71151-T6A-911	BASEMID GRILLE /	1	186.50	15	158.52	11.10	169.62

Printed on 12/4/2019 3:27:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SKW629K

Chassis No : JHMR1890FC203162

Model : ODYSSEY 2.4 EXV-S 15YM

Owner's Name : NG DJONI

Ins Policy No. :

Date of Accident : 10/4/2019

Document No. : SQT19001624

Date : 11. Apr 2019

Customer No. : WC008

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W71011552

Date | Time : 11. Apr 2019 9:50:16 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71152-T6A-921	UPPER MOLDINGMID GRILLE	1	153.60	15	130.56	9.14	139.70
71153-T6A-921	MID MOLDINGMID GRILLE	1	147.10	15	125.03	8.75	133.78
71154-T6A-921	LOWER MOLDINGR.MID GRILLE	1	39.50	15	33.57	2.35	35.92
71159-T6A-921	LOWER MOLDINGL.MID GRILLE	1	39.50	15	33.57	2.35	35.92
71190-T6A-003	BEAM LFR.BUMPER UPPER	1	34.90	15	29.66	2.08	31.74
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	11.80	15	10.03	0.70	10.73
71198-T6A-003	SPACERLFR.BUMPER SIDE	1	11.80	15	10.03	0.70	10.73
71117-T6A-921ZE	SPOILER ASSYL.FR.SIDE	1	94.40	15	80.24	5.62	85.86
71112-T6A-921ZE	SPOILER ASSYR.FR.SIDE	1	94.40	15	80.24	5.62	85.86
91505-TM8-003	CLIP,BUMPER	10	2.30	15	19.55	1.37	20.92
91578-T0A-003	CLIPFR.GRILLE	4	2.30	15	7.82	0.55	8.37
73111-T6A-U01	GLASS SET,FR.WINDSHIELD	1	2365.30	15	2010.50	140.74	2151.24
73126-SYY-000	RUBBER BFR W/SHIELD	3	3.70	15	9.43	0.66	10.09
73150-T6A-003	MOLDINGFR.WINDSHIELD	1	19.60	15	16.66	1.17	17.83
77466-TL0-G01	SEALFR.INSTRUMENT	1	13.50	15	11.47	0.80	12.27
17201-5X6-J00	CASE SETAIR CLEANER	1	94.40	15	80.24	5.62	85.86
17210-5X6-J00	COVER COMPAIR CLEANER	1	82.80	15	70.38	4.93	75.31
17220-5X6-J00	ELEMENT ASSYAIR CLEANER	1	70.30	15	59.75	4.18	63.93
17230-5X6-J00	CHAMBER ASSYRESONATOR	1	109.70	15	93.24	6.53	99.77
17252-5X6-J00	TUBE ASSY AAIR INTAKE	1	75.50	15	64.17	4.49	68.66
17253-5X6-J00	TUBE ASSY BAIR INTAKE	1	66.00	15	56.10	3.93	60.03
19101-5X6-J00	TANKRESERVE	1	56.60	15	48.11	3.37	51.48
19501-5X6-J00	HOSEWATER UPPER	1	26.30	15	22.35	1.56	23.91
32200-T6A-U41	WIRE HARNESS ENGINE ROOF	1	3182.00	15	2704.70	189.33	2894.03
38100-T6A-J01	HORN ASSYLOW	1	45.70	15	38.84	2.72	41.56
38150-T6A-J01	HORN ASSYHIGH	1	45.70	15	38.84	2.72	41.56
38251-T6A-010	BRACKETRELAY BOX	1	37.90	15	32.21	2.25	34.46
77930-T6A-J21	SENSOR ASSYFR.CRASH	2	131.70	15	223.89	15.67	239.56
77960-T6A-J12	UNIT ASSY,SRS	1	968.00	15	822.80	57.60	880.40

Printed on 12/4/2019 3:27:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SKW629K

Chassis No : JHMRC1890FC203162

Model : ODYSSEY 2.4 EXV-S 15YM

Owner's Name : NG DJONI

Ins Policy No. :

Date of Accident : 10/4/2019

Document No. : SQT19001624

Date : 11. Apr 2019

Customer No. : WC008

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W71011552

Date | Time : 11. Apr 2019 9:50:16 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 4

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
77100-T6A-000ZA	PANEL COMPINSTRUMENT UPPER - CMA	1	879.80	15	747.83	52.35	800.18
77820-T6A-N80	MODULE ASSYPASSENGER - SACT	1	2785.60	15	2367.76	165.74	2533.50
04814-T6A-M00ZA	TONGUE SETR.FR SEATBELT OUTER - SACT	1	408.70	15	347.39	24.32	371.71
76841-T6A-003	TANKWASHER - SNN	1	70.90	15	60.26	4.22	64.48
76812-T6A-003	HOSE - SNN	1	21.30	15	18.10	1.27	19.37
18120-5B0-Y00	COVER COMPCHAMBER - SNN	1	42.20	15	35.87	2.51	38.38
18121-5B0-Y10	COVER COMPPRIMARY CONVERTER - SNN	1	74.60	15	63.41	4.44	67.85
31100-5X6-J01	AC GENERATOR ASSY - BR	1	1859.80	15	1580.83	110.66	1691.49
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 - BT	6	23.20	15	118.32	8.28	126.60
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) - BT	1	45.00		45.00	3.15	48.15
BO-WS-SEALANT	WINDSCREEN SEALANT (N) - MCL.	2	60.00		120.00	8.40	128.40
Sum Item					23877.17	1,671.41	25,548.58

BOSUN	SUNDRIES	1	100.00		✓ 40 100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		✓ 140 180.00	12.60	192.60
BOJSE	BODY JOINT SEALANT	1	200.00		✓ 150 200.00	14.00	214.00
BOBC	BODY UNDERSIDE COATING (N)	1	250.00		✓ 150 250.00	17.50	267.50
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS	1	280.00		✓ 250 280.00	19.60	299.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	1	350.00		✓ 300 350.00	24.50	374.50
BG01R	REPLACE FR. WINDSCREEN.(N)	1	350.00		✓ 300 350.00	24.50	374.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	400.00		✓ 350 400.00	28.00	428.00
BC011R	REMOVE INSTALL & CALIBRATE FRONT VIEW CAMERA	1	450.00		✓ 400 450.00	31.50	481.50
BMS00R	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU &	1	2240.00		✓ 1680 2240.00	156.80	2396.80
BMI00D	REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL	1	2240.00		✓ 1120 2240.00	156.80	2396.80
BKBH11M	RENEW BULKHEAD, WHEELHOUSE ASSY & ALIGN CHASSIS	1	3360.00		✓ 2800 3360.00	235.20	3595.20
BP01R	SPRAY PAINT ON REPAIRED/REPLACED AREAS (7PX \$450)	1	3500.00		✓ 3150 3500.00	245.00	3745.00
Sum Labor					13900.00	973.00	14,873.00

Printed on 12/4/2019 3:27:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SKW629K

Chassis No : JHMRC1890FC203162

Model : ODYSSEY 2.4 EXV-S 15YM

Owner's Name : NG DJONI

Ins Policy No. :

Date of Accident : 10/4/2019

Document No. : SQT19001624 Page 5

Date : 11. Apr 2019

Customer No. : WC008

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W71011552

Date | Time : 11. Apr 2019 9:50:16 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

Survey By Ene Qap. 82880282

Date & Time 15/4/19

Excess \$1000

Status Not Authorised.

Signature _____

Total Amount 38,137.17 2,669.61 40,806.78

Total (Inclusive of GST) 40,178.51

12-14 Days.
refue paint photos.

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/4/2019 3:27:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WC008 / CHINA TAIPING
Chassis No: JHMRC1890FC203162
License No: SKW629K
Mileage: 23130
Engine No: K24W71011552

Document No: SVO19025611
Printed By: ARYCHUA
Order Date: 23. April 2019
Order Time: 12:01:48 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	OWN DAMAGE CLAIMS-J/NO: 72527 POLICY/CLAIMS NO: DMPCSN1669891802 OWNER: NG DJONI ACC DATE: 10-04-2019@12.15PM ACC: SENGKANG EAST RD (L/P 119)@TRAFFIC JUNCTION SURVEYED BY: GUO QIANG(LKKAUTO)15/04/2019@17.17PM AUTHORIZED ON: VERON CHEN(LKK)23/04/2019@11.52AM REF NO:						
54206	EXTERNAL LABOUR SALES - INS. EXCESS	-1	1,000.00		-1,000.00	-70.00	-1,070.00
54600	84101-T6A-J91ZA - GARNISH ASSY,R.FR.PILLAR	1	82.80	15	70.38	4.93	75.31
	SUM EXCESS:				-929.62	-65.07	-994.69
60400-T6A-310ZZ	BULKHEAD COMPFR.	1	460.80	15	391.68	27.42	419.10
60433-T6A-300ZZ	SUPPORTR.FR.BULKHEAD UPP SIDE	1	35.30	15	30.00	2.10	32.10
60483-T6A-300ZZ	SUPPORT,L.FR.BULKHEAD UPP SIDE	1	35.30	15	30.00	2.10	32.10
60210-T6A-300ZZ	FENDER COMPR.FR.	1	548.60	15	466.31	32.64	498.95
60260-T6A-300ZZ	FENDER COMPL.FR.	1	548.60	15	466.31	32.64	498.95
74150-T6A-000	FENDER ASSYL.FR INNER	1	120.70	15	102.59	7.18	109.77
74100-T6A-000	FENDER ASSYR.FR INNER	1	120.70	15	102.59	7.18	109.77
72415-T6A-003	MOLDING ASSYR.FR CORNER	1	87.70	15	74.54	5.22	79.76
72465-T6A-003	MOLDING ASSYL.FR CORNER	1	87.70	15	74.54	5.22	79.76
60100-T6A-000ZZ	HOOD COMP	1	671.40	15	570.69	39.95	610.64
60120-T6A-000ZZ	HINGE COMPR.HOOD	1	47.40	15	40.29	2.82	43.11
60170-T6A-000ZZ	HINGE COMPL.HOOD	1	47.40	15	40.29	2.82	43.11
74120-T6A-003	LOCK ASSYHOOD	1	106.20	15	90.27	6.32	96.59
74141-T6A-010	INSULATORHOOD	1	94.40	15	80.24	5.62	85.86
80111-T6A-003	CONDENSER COMP	1	681.90	15	579.61	40.57	620.18
19010-5X6-J02	RADIATOR COMP	1	1,347.30	15	1,145.20	80.16	1,225.36
19015-5X6-J01	SHROUD COMP	1	108.30	15	92.05	6.44	98.49
19020-5A4-H02	FAN COMPCOOLING	1	55.50	15	47.17	3.30	50.47
19030-5X6-J01	MOTORCOOLING FAN	1	298.40	15	253.64	17.75	271.39
38611-5A4-H02	FAN COMPCOOLING	1	54.20	15	46.07	3.22	49.29
38615-5X6-J01	SHROUD COMP	1	83.60	15	71.23	4.99	76.22
38616-5X6-J02	MOTOR,COOLING FAN	1	322.60	15	274.21	19.19	293.40
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED	1	2,281.90	15	1,939.61	135.77	2,075.38
33150-T6A-Q11	HEADLIGHT ASSY,L.WITH LED	1	2,281.90	15	1,939.61	135.77	2,075.38
71104-T6A-921	GARNISHR.FR BUMPER	1	46.10	15	39.18	2.74	41.92
71109-T6A-921	GARNISHL.FR BUMPER	1	46.10	15	39.18	2.74	41.92
71121-T6A-003	BASEFR.GRILLE	1	169.00	15	143.65	10.06	153.71
71122-T6A-003	MOLDINGFR.GRILLE	1	263.30	15	223.80	15.67	239.47
75700-TA0-A00	EMBLEMFR.	1	26.70	15	22.69	1.59	24.28
90301-ST0-003	NUTPUSH 3MM	2	2.10	15	3.57	0.25	3.82
36560-T6A-J01	CAMERA ASSY,MVC FR.	1	520.00	15	442.00	30.94	472.94
36561-T6A-N01	COVERMVC FR.CAMERA	1	8.30	15	7.05	0.49	7.54
04711-T6A-900ZZ	FACE,FR.BUMPER	1	700.00	15	595.00	41.65	636.65
71105-T6A-901	GRILLEFR.BUMPER LOWER	1	67.10	15	57.03	3.99	61.02
71130-T6A-310ZZ	BEAM COMP,FR.BUMPER	1	291.80	15	248.03	17.36	265.39
71140-T6A-003	BEAMR.FR.BUMPER UPPER	1	34.90	15	29.66	2.08	31.74
71151-T6A-911	BASEMID GRILLE	1	186.50	15	158.52	11.10	169.62

WD=12

1 ct

(A)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WC008 / CHINA TAIPING
Chassis No: JHMRC1890FC203162
License No: SKW629K
Mileage: 23130
Engine No: K24W71011552

Document No: SVO19025611
Printed By: ARYCHUA
Order Date: 23. April 2019
Order Time: 12:01:48 PM
Service Advisor: ARY CHUA WAI NGEE

71152-T6A-921	UPPER MOLDINGMID GRILLE	1	153.60	15	130.56	9.14	139.70
71153-T6A-921	MID MOLDINGMID GRILLE	1	147.10	15	125.03	8.75	133.78
71154-T6A-921	LOWER MOLDINGR.MID GRILLE	1	39.50	15	33.57	2.35	35.92
71159-T6A-921	LOWER MOLDINGL.MID GRILLE	1	39.50	15	33.57	2.35	35.92
71190-T6A-003	BEAML.FR.BUMPER UPPER	1	34.90	15	29.66	2.08	31.74
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	11.80	15	10.03	0.70	10.73
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	11.80	15	10.03	0.70	10.73
71117-T6A-921ZE	SPOILER ASSYL.FR.SIDE	1	94.40	15	80.24	5.62	85.86
71112-T6A-921ZD	SPOILER ASSYR.FR.SIDE	1	94.40	15	80.24	5.62	85.86
91505-TM8-003	CLIP,BUMPER	10	2.30	15	19.55	1.37	20.92
91578-T0A-003	CLIPFR.GRILLE	4	2.30	15	7.82	0.55	8.37
73111-T6A-U01	GLASS SET,FR.WINDSHIELD	1	2,365.30	15	2,010.50	140.74	2,151.24
73126-SYY-000	RUBBER BFR W/SHIELD	3	3.70	15	9.43	0.66	10.09
73150-T6A-003	MOLDINGFR.WINDSHIELD	1	19.60	15	16.66	1.17	17.83
77466-TL0-G01	SEALFR.INSTRUMENT	1	13.50	15	11.47	0.80	12.27
17201-5X6-J00	CASE SETAIR CLEANER	1	94.40	15	80.24	5.62	85.86
17210-5X6-J00	COVER COMPAIR CLEANER	1	82.80	15	70.38	4.93	75.31
17220-5X6-J00	ELEMENT ASSYAIR CLEANER	1	70.30	15	59.75	4.13	63.93
17230-5X6-J00	CHAMBER ASSYRESONATOR	1	109.70	15	93.24	6.53	99.77
17252-5X6-J00	TUBE ASSY AAIR INTAKE	1	75.50	15	64.17	4.49	68.66
17253-5X6-J00	TUBE ASSY BAIR INTAKE	1	66.00	15	56.10	3.93	60.03
19501-5X6-J00	HOSEWATER UPPER	1	26.30	15	22.35	1.56	23.91
38100-T6A-J01	HORN ASSYLOW	1	45.70	15	38.84	2.72	41.56
38150-T6A-J01	HORN ASSYHIGH	1	45.70	15	38.84	2.72	41.56
38251-T6A-010	BRACKETRELAY BOX	1	37.90	15	32.21	2.25	34.46
77930-T6A-J21	SENSOR ASSYFR.CRASH	2	131.70	15	223.89	15.67	239.56
77960-T6A-J12	UNIT ASSY,SRS	1	968.00	15	822.80	57.60	880.40
77100-T6A-000ZA	PANEL COMPINSTRUMENT UPPER	1	879.80	15	747.83	52.35	800.18
77820-T6A-N80	MODULE ASSYPASSENGER	1	2,785.60	15	2,367.76	165.74	2,533.50
04814-T6A-M00ZA	TONGUE SETR.FR.SEATBELT OUTER	1	408.70	15	347.39	24.32	371.71
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	6	23.20	15	118.32	8.28	126.60
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
31100-5X6-J01	AC GENERATOR ASSY	1	1,859.80	15	1,580.83	110.66	1,691.49
15650-5A2-A03	GAUGE COMPOIL LEVEL	1	15.00	15	12.75	0.89	13.64
80315-T6A-003	HOSE COMPDISCHARGE	1	160.20	15	136.17	9.53	145.70
31521-T6A-J00	BOXBATTERY	1	15.60	15	13.26	0.93	14.19
19101-5X6-J00	TANKRESERVE	1	56.60	15	48.11	3.37	51.48
74130-T6A-003	WIRE ASSYHOOD	1	36.60	15	31.11	2.18	33.29
19103-5X6-J00	TUBE ARESERVE TANK	1	5.50	15	4.67	0.33	5.00
19106-R5A-G00	JOINTRESERVE TANK	1	7.10	15	6.03	0.42	6.45
84151-T6A-J91ZA	GARNISH ASSY,L.FR.PILLAR	1	82.80	15	70.38	4.93	75.31
38232-T6A-J11	FUSEMULTI BLOCK	1	13.40	15	11.39	0.80	12.19
74201-T6A-000	GARNISHR.FR.FENDER	1	33.10	15	28.13	1.97	30.10
74206-T6A-000	GARNISHL.FR.FENDER	1	33.10	15	28.13	1.97	30.10
		SUM PARTS:			20,888.53	1,462.07	22,348.60
BOSUN	0760	1	40.00		40.00	2.80	42.80
		SUNDRIES					
BML01I	1864	1	140.00		140.00	9.80	149.80
		INSPECT FR LIGHTING MECHANISMS & FOCUS					

Rept

sepl
(A)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WC008 / CHINA TAIPING
Chassis No: JHMRC1890FC203162
License No: SKW629K
Mileage: 23130
Engine No: K24W71011552

Document No: SVO19025611
Printed By: ARYCHUA
Order Date: 23. April 2019
Order Time: 12:01:48 PM
Service Advisor: ARY CHUA WAI NGEE

	HEADLIGHTS.(N)					
BOJSE	0760	1	150.00	150.00	10.50	160.50
	BODY JOINT SEALANT.					
BOBC	0760	1	150.00	150.00	10.50	160.50
	BODY UNDERSIDE COATING (N)					
BMC01D	1864	1	250.00	250.00	17.50	267.50
	REMOVE & INSTALL RADIATOR WITH FITTINGS.					
	PRESSURE TEST COOLING SYSTEM.(N)					
BMA01D	1864	1	300.00	300.00	21.00	321.00
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.					
	VACUUM & RECHARGE A/C GAS.(N)					
BG01R	1864	1	300.00	300.00	21.00	321.00
	REPLACE FR. WINDSCREEN.(N)					
BC012R	0760	1	350.00	350.00	24.50	374.50
	RESET VEHICLE SMART ENTRY SYSTEM					
BC011R	0760	1	400.00	400.00	28.00	428.00
	REMOVE INSTALL & CALIBRATE FRONT VIEW CAMERA					
BMI00D	0760	1	1,120.00	1,120.00	78.40	1,198.40
	REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL					
	AUDIO WIRING HARNESS & ETC.(N)					
BM500R	0760	1	1,680.00	1,680.00	117.60	1,797.60
	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU & RESET SRS SYSTEM.(N)					
BKBH11M	1864	1	2,800.00	2,800.00	196.00	2,996.00
	RENEW BULKHEAD, WHEELHOUSE ASSY & ALIGN CHASSIS INCLUDING FITTINGS ON ATTACHMENT ITEMS.					
BP01R	1865	1	3,150.00	3,150.00	220.50	3,370.50
	SPRAY PAINT ON REPAIRED/REPLACED AREAS.(7PX\$450)					
	SUM LABOUR:			10,830.00	758.10	11,588.10
TOW-SPEEDWAY	TOWING SERVICE - B24022	1	60.00	60.00	4.20	64.20
BO-V-KOOL-FWS	SUPPLY & INSTALL SOLAR FILM ON FRONT WINDSCREEN.	1	300.00	300.00	21.00	321.00
	SUM EXT SERVICE:			360.00	25.20	385.20
	TOTAL SGD			31,146.91	2,180.30	33,327.21

Total Payable (SGD)

33,327.21

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: ****6554J / NG DJONI
Chassis No: JHMRC1890FC203162
License No: SKW629K
Mileage: 23130
Engine No: K24W71011552

Document No: SVO19025611
Printed By: ARYCHUA
Order Date: 23, April 2019
Order Time: 12:01:48 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incld GST
	SUPPLIMENTARY ITEM PARTS & LABOR						
54600	84101-T6A-J91ZA - GARNISH ASSY,R.FR.PILLAR <i>cut</i>	1	82.80	15	70.38	4.93	75.31
	SUM EXCESS:				70.38	4.93	75.31
31100-5X6-J01	AC-GENERATOR ASSY <i>PR</i>	1	1,859.80	15	1,580.83	110.66	1,691.49
15650-5A2-A03	GAUGE COMPOIL LEVEL <i>BR</i>	1	15.00	15	12.75	0.89	13.64
80315-T6A-003	HOSE COMPDISCHARGE <i>BT</i>	1	160.20	15	136.17	9.53	145.70
31521-T6A-J00	BOXBATTERY <i>re</i>	1	15.60	15	13.26	0.93	14.19
19101-5X6-J00	TANKRESERVE <i>cut</i>	1	56.60	15	48.11	3.37	51.48
74130-T6A-003	WIRE ASSYHOOD <i>cut</i>	1	36.60	15	31.11	2.18	33.29
19103-5X6-J00	TUBE ARESERVE TANK <i>4abc.</i>	1	5.50	15	4.67	0.33	5.00
19106-RSA-G00	JOINTRESERVE TANK	1	7.10	15	6.03	0.42	6.45
84151-T6A-J91ZA	GARNISH ASSY,L.FR.PILLAR <i>cut</i>	1	82.80	15	70.38	4.93	75.31
38232-T6A-J11	FUSEMULTI BLOCK <i>NW</i>	1	13.40	15	11.39	0.80	12.19
74201-T6A-000	GARNISHR.FR.FENDER <i>4mis</i>	1	33.10	15	28.13	1.97	30.10
74206-T6A-000	GARNISHL.FR.FENDER	1	33.10	15	28.13	1.97	30.10
	SUM PARTS:				1,970.96	137.98	2,108.94
	TOTAL SGD				2,041.34	142.91	2,184.25

Total Payable (SGD)

2,184.25

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: ****6554J / NG DJONI
Chassis No: JHMRC1890FC203162
License No: SKW629K
Mileage: 23130
Engine No: K24W71011552

Document No: SVO19025611
Printed By: ARYCHUA
Order Date: 23. April 2019
Order Time: 12:01:48 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Includ Amount	GST
SUPPLIMENTARY ITEM PARTS & LABOR							
54600	84101-T6A-J91ZA - GARNISH ASSY,R.FR.PILLAR <i>cut</i>	1	82.80	15	70.38	4.93	75.31
SUM EXCESS:					70.38	4.93	75.31
31100-5X6-J01	AC GENERATOR ASSY <i>Rept</i>	1	1,859.80	15	1,580.83	110.66	1,691.49
15650-5A2-A03	GAUGE COMPOIL LEVEL <i>BR</i>	1	15.00	15	12.75	0.89	13.64
80315-T6A-003	HOSE COMPDISCHARGE <i>BT</i>	1	160.20	15	136.17	9.53	145.70
31521-T6A-J00	BOXBATTERY <i>DE</i>	1	15.60	15	13.26	0.93	14.19
19101-5X6-J00	TANKRESERVE <i>Rept</i>	1	56.60	15	48.11	3.37	51.48
74130-T6A-003	WIRE ASSYHOOD <i>cut</i>	1	36.60	15	31.11	2.18	33.29
19103-5X6-J00	TUBE ARESERVE TANK <i>NEC</i>	1	5.50	15	4.67	0.33	5.00
19106-RSA-G00	JOINTRESERVE TANK <i>NEC</i>	1	7.10	15	6.03	0.42	6.45
84151-T6A-J91ZA	GARNISH ASSY,L.FR.PILLAR <i>cut</i>	1	82.80	15	70.38	4.93	75.31
38232-T6A-J11	FUSEMULTI BLOCK <i>NW</i>	1	13.40	15	11.39	0.80	12.19
74201-T6A-000	GARNISHR.FR.FENDER <i>MIS</i>	1	33.10	15	28.13	1.97	30.10
74206-T6A-000	GARNISHL.FR.FENDER <i>MIS</i>	1	33.10	15	28.13	1.97	30.10
SUM PARTS:					1,970.96	137.96	2,108.94
TOTAL SGD					2,041.34	142.91	2,184.25

Total Payable (SGD)

2,184.25

GST Amount is calculated from individual line(s)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 14 May 2019 4:12 PM
To: Ary Chua; Guo Qiang (LKKAUTO); Admin A
Cc: Yeo Thiam Swee; Liew Thye Wui; Faeaz; SUR
Subject: RE: Finalise OD-CT: SKW629K DOA: 10-04-2019@12.15PM

Dear Ary,

Confirmed amount \$32,146.91 before excess \$1000 and GST @ 12 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ary Chua <arychua@honda.com.sg>
Sent: Wednesday, 8 May 2019 10:28 AM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: Yeo Thiam Swee <tsyeo@honda.com.sg>; Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: Finalise OD-CT: SKW629K DOA: 10-04-2019@12.15PM

Hi Guo Qiang,
Kindly Finalise OD-CT: SKW629K DOA: 10-04-2019@12.15PM

Final Repair Costs (include GST)	\$31,146.91(-EXCESS\$1000) + (\$2,180.30) = \$33,327.21
Repair Period* (Working Day)	12

Please examine the above information carefully. If no discrepancy is reported within 7 days (*Exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor **Kah Motor Co.Sdn.Bhd.** Address:15 Ubi Road 4 Singapore 408610

E-mail: aychua@honda.com.sg H/P:81006306 DID:68465673 Fax: 67480770



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Apr 2019		15 Apr 2019 11:24 Edit Adj Rpt	S\$32,146.91 Edit Estimates	S\$32,146.91 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: NG DJONI , ID: S7276554J, Tel: +6591813344, Email: NGDJONI@GMAIL.COM									
Vehicle Reg. No.: SKW629K		Date of Loss: 10/04/2019 12:00 - :59 [41 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM19D201658C01		Policy/Cover Note No.: DMPCSN1669891802 (Comprehensive)							
		Excess: S\$1,000.00							
Repairer: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/04/2019]									
Driver/Custodian: NG DJONI (46 / Male) , NRIC: S7276554J, Tel: +6591813344 Email: NGDJONI@GMAIL.COM									
Adj Asg. Remarks: Please check market value & consistency of damages									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (23/04/2019): Alert - Adj Mandate Approved (S\$35067.17) - SKW629K - Claim Handler: Elaine Cheo...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW629K (SNM19D201658C01)

OD

Apr 10 2019 12:00PM

[NG DJONI]

Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Video									1 per page		☒			
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)								Thumbnail	Print			
1	11/04/19 17:20	Video - Accident [Linked Accident Report Documents]								Load MP4				
Assessment Reports									1 per page		☒			
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)								Thumbnail	Print			
1	11/04/19 17:21	Accident Statement								Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	16/04/19 16:08	Adjuster Immediate Advice								Load HTM				
2	16/04/19 16:12	Adjuster Immediate Advice								Load HTM				
Photos/Images									3 per page		☒			
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)								Thumbnail	Print			
1	11/04/19 17:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
2	11/04/19 17:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
3	11/04/19 17:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
4	11/04/19 17:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
5	11/04/19 17:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
6	11/04/19 17:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
7	11/04/19 17:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
8	11/04/19 17:21	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	16/04/19 14:51	General View								Load PDF				
2	14/05/19 15:52	Reinspection Photo								Load PDF				
Documentation									1 per page		☒			
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print			
1	15/04/19 11:25	OD ESTIMATE								Load PDF				
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)								Thumbnail	Print			
1	11/04/19 17:20	Sketch Plan [Linked Accident Report Documents]								Load TIF				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	16/04/19 14:51	MARK ESTIMATE								Load PDF				
2	14/05/19 16:03	SUPPLEMENTARY								Load PDF				

Linked Accident Report Documents

										View	View in Browser	
Video										1 per page		☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)							Thumbnail	Print		
1	11/04/19 17:20	Video - Accident								Load MP4		

Video			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	11/04/19 17:21	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	11/04/19 17:21	Accident Photo	 Load JPG	☒
2	11/04/19 17:21	Accident Photo	 Load JPG	☒
3	11/04/19 17:21	Accident Photo	 Load JPG	☒
4	11/04/19 17:21	Accident Photo	 Load JPG	☒
5	11/04/19 17:21	Accident Photo	 Load JPG	☒
6	11/04/19 17:21	Accident Photo	 Load JPG	☒
7	11/04/19 17:21	Accident Photo	 Load JPG	☒
8	11/04/19 17:21	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	11/04/19 17:20	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19006623/GVD3E2

Date: 04/06/2019

REFERENCE

Insured/Claimant: NG DJONI Policy No: DMPCSN1669891802
Date of Loss: 10/04/2019 Nature of Claim: OD Claim No: SNM19D201658C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW629K**
Make & Model: HONDA ODYSSEY, 2.4 EX-S (RC1) (A) Engine No: K24W71011552
Reg. Date: 15/10/2015 (Man. Year: 2015) Chassis No: JHMRC1890FC203162
Colour: White Odometer: 23129 km
Engine Capacity: 2356 cc
Market Value/New Car Price: S\$96,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55Z R17 Rear Tyre Size: 215/55Z R17
Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,018.51	20,996.91	5,021.60	19.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,160.00	11,150.00	3,010.00	21.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,178.51	32,146.91	8,031.60	19.99
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	39,178.51	31,146.91	8,031.60	20.50
+ GST 7.00/7.00% (S\$)	2,742.50	2,180.28	562.22	20.50
Nett Amount (S\$)	41,921.01	33,327.19	8,593.82	20.50

INSPECTION

Date of Assignment: 15/04/2019
Date Inspected: 15/04/2019 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610
Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2019)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 EX-S (RC1) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW629K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BULKHEAD COMPFR	Buckled	391.68 FS	*391.68 FS
2	1		*SUPPORTR.FR.BULKHEAD UPP SIDE	Bent	30.00 FS	*30.00 FS
3	1		*SUPPORT,L.FR.BULKHEAD UPP SIDE	Bent	30.00 FS	*30.00 FS
4	1		*FENDER COMPR.FR.	Buckled	466.31 FS	*466.31 FS
5	1		*FENDER COMPL.FR.	Buckled	466.31 FS	*466.31 FS
6	1		*FENDER ASSYL.FR.INNER	Deformed	102.59 FS	*102.59 FS
7	1		*FENDER ASSYR.FR.INNER	Missing	102.59 FS	*102.59 FS
8	1		*MOLDING ASSYR.FR.CORNER	Deformed	74.54 FS	*74.54 FS
9	1		*MOLDING ASSYL.FR.CORNER	Deformed	74.54 FS	*74.54 FS
10	1		*HOOD COMP	Buckled	570.69 FS	*570.69 FS
11	1		*HINGE COMPR.HOOD	Bent	40.29 FS	*40.29 FS
12	1		*HINGE COMPL.HOOD	Bent	40.29 FS	*40.29 FS
13	1		*LOCK ASSYHOOD	Bent	90.27 FS	*90.27 FS
14	1		*INSULATORHOOD	Deformed	80.24 FS	*80.24 FS
15	1		*CONDENSER COMP	Bent	579.61 FS	*579.61 FS
16	1		*PIPE COMPRECEIVER	Not Necessary	150.19 FS	*- FS
17	1		*HOSE COMPSUCTION	Not Necessary	156.65 FS	*- FS
18	1		*HOSE COMPDISCHARGE	Not Necessary	136.17 FS	*- FS
19	1		*RADIATOR COMP	Bent	1,145.20 FS	*1,145.20 FS
20	1		*SHROUD COMP	Cracked	92.05 FS	*92.05 FS
21	1		*FAN COMPCOOLING	Deformed	47.17 FS	*47.17 FS
22	1		*MOTORCOOLING FAN	Not Working	253.64 FS	*253.64 FS
23	1		*FAN COMPCOOLING	Deformed	46.07 FS	*46.07 FS
24	1		*SHROUD COMP	Cracked	71.23 FS	*71.23 FS
25	1		*MOTOR, COOLING FAN	Not Working	274.21 FS	*274.21 FS
26	1		*HEAT PROTECTORFAN MOTOR	Not Necessary	7.31 FS	*- FS
27	1		*HEADLIGHT ASSYR.WITH LED	Cracked	1,939.61 FS	*1,939.61 FS
28	1		*HEADLIGHT ASSY,L.WITH LED	Cracked	1,939.61 FS	*1,939.61 FS
29	1		*GARNISHR.FR.BUMPER	Distorted	39.18 FS	*39.18 FS
30	1		*GARNISHL.FR.BUMPER	Distorted	39.18 FS	*39.18 FS
31	1		*BASEFR.GRILLE	Distorted	143.65 FS	*143.65 FS
32	1		*MOLDINGFR.GRILLE	Distorted	223.80 FS	*223.80 FS
33	1		*EMBLEMFR.	Necessary	22.69 FS	*22.69 FS
34	1		*NUTPUSH 3MM (2PCS)	Necessary	3.57 FS	*3.57 FS
35	1		*CAMERA ASSY, MVC FR.	Missing	442.00 FS	*442.00 FS
36	1		*COVERMVC FR.CAMERA	Necessary	7.05 FS	*7.05 FS
37	1		*FACE,FR.BUMPER	Deformed	595.00 FS	*595.00 FS
38	1		*GRILLEFR.BUMPER LOWER	Cracked	57.03 FS	*57.03 FS
39	1		*BEAM COMP,FR.BUMPER	Bent	248.03 FS	*248.03 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*BASEMID GRILLE	Distorted	158.52 FS	*158.52 FS
41	1		*UPPER MOLDING MID GRILLE	Missing	130.56 FS	*130.56 FS
42	1		*MID MOLDING MID GRILLE	Missing	125.03 FS	*125.03 FS
43	1		*LOWER MOLDING MID GRILLE	Missing	33.57 FS	*33.57 FS
44	1		*LH BEAML.FR.BUMPER UPPER	Bent	29.66 FS	*29.66 FS
45	1		*SPACERR.FR.BUMPER SIDE	Necessary	10.03 FS	*10.03 FS
46	1		*SPACERL.FR.BUMPER SIDE	Necessary	10.03 FS	*10.03 FS
47	1		*SPOILER ASSYL.FR.SIDE	Cut	80.24 FS	*80.24 FS
48	1		*SPOILER ASSYR.FR.SIDE	Cut	80.24 FS	*80.24 FS
49	1		*CLIP, BUMPER (10PCS)	Necessary	19.55 FS	*19.55 FS
50	1		*CLIPFR.GRILLE (4PCS)	Necessary	7.82 FS	*7.82 FS
51	1		*GLASS SET, FR.WINDSHIELD	Cracked	2,010.50 FS	*2,010.50 FS
52	1		*RUBBER BFR W/SHIELD (3PCS)	Necessary	9.43 FS	*9.43 FS
53	1		*MOLDINGFR.WINDSHIELD	Necessary	16.66 FS	*16.66 FS
54	1		*SEALFR.INSTRUMENT	Necessary	11.47 FS	*11.47 FS
55	1		*CESE SETAIR CLEANER	Necessary	80.24 FS	*80.24 FS
56	1		*COVER COMPAIR CLEANER	Necessary	70.38 FS	*70.38 FS
57	1		*ELEMENT ASSYAIR CLEANER	Necessary	59.75 FS	*59.75 FS
58	1		*CHAMBER ASSYRESONATOR	Cracked	93.24 FS	*93.24 FS
59	1		*TUBE ASSY AAIR INTAKE	Cracked	64.17 FS	*64.17 FS
60	1		*TUBE ASSY BAIR INTAKE	Cracked	56.10 FS	*56.10 FS
61	1		*TANKRESERVE	Cut	48.11 FS	*48.11 FS
62	1		*HOSEWATER UPPER	Twisted	22.35 FS	*22.35 FS
63	1		*WIRE HARNESS ENGINE ROOF	Not Necessary	2,704.70 FS	*- FS
64	1		*HORN ASSYLOW	Cracked	38.84 FS	*38.84 FS
65	1		*HORN ASSYHIGH	Cracked	38.84 FS	*38.84 FS
66	1		*BRACKETRELAY BOX	Bent	32.21 FS	*32.21 FS
67	1		*SENSOR ASSYFR.CRASH (2PCS)	Activated	223.89 FS	*223.89 FS
68	1		*UNIT ASSY, SRS	Activated	822.80 FS	*822.80 FS
69	1		*PANEL COMPINSTRUMENT UPPER	Cracked	747.83 FS	*747.83 FS
70	1		*MODULE ASSYPASSENGER	Activated	2,367.76 FS	*2,367.76 FS
71	1		*TONGUE SETR.FR.SEATBELT OUTER	Activated	347.39 FS	*347.39 FS
72	1		*TANKWASHER	Not Necessary	60.26 FS	*- FS
73	1		*HOSE	Not Necessary	18.10 FS	*- FS
74	1		*COVER COMPCHAMBER	Not Necessary	35.87 FS	*- FS
75	1		*COVER COMPPRIMARY CONVERTER	Not Necessary	63.41 FS	*- FS
76	1		*AC GENERATOR ASSY	Broken	1,580.83 FS	*1,580.83 FS
77	6		*COOLANT ANTI-FREEZE TYPE 2	Necessary	118.32 FS	*118.32 FS
78	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
79	1		*SUNDRIES	Necessary	100.00 FS	*40.00 FS
80	1		*84101-T6A-J91ZA-GARNISH ASSY,R.FR.PILLAR	Cut	70.38 FS	*70.38 FS
81	1		*AC GENERATOR ASSY	Repeated	1,580.83 FS	*- FS
82	1		*GAUGE COMPOIL LEVEL	Broken	12.75 FS	*12.75 FS
83	1		*HOSE COMPDISCHARGE	Bent	136.17 FS	*136.17 FS
84	1		*BOXBATTERY	Deformed	13.26 FS	*13.26 FS
85	1		*TANKRESERVE	Repeated	48.11 FS	*- FS
86	1		*WIRE ASSYHOOD	Cut	31.11 FS	*31.11 FS
87	1		*TUBE ARESERVE TANK	Necessary	4.67 FS	*4.67 FS
88	1		*JOINTRESERVE TANK	Necessary	6.03 FS	*6.03 FS
89	1		*GARNISH ASSY,L.FR.PILLAR	Cut	70.38 FS	*70.38 FS
90	1		*FUSEMULTI BLOCK	Not Working	11.39 FS	*11.39 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
91	1		*GARNISHR.FR.FENDER	Missing	28.13 FS	*28.13 FS
92	1		*GARNISHL.FR.FENDER	Missing	28.13 FS	*28.13 FS
93	1		*RH BEAMR.FR.BUMPER UPPER	Bent	29.66 FS	*29.66 FS
94	1		*LOWER MOLDINGL.MID GRILLE	Missing	33.57 FS	*33.57 FS
95	1		*NUMBER PLATE WITH CASING	Bent	45.00 FS	*45.00 FS
Total Parts (\$\$)					26,018.51	20,996.91

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING SERVICE - B24022	New	60.00	60.00
2	SUPPLY & INSTALL SOLAR FILM ON FRONT WINDSCREEN	New	300.00	300.00
3	INSPECT FR LIGHTING MECHANISM & FOCUS	New	180.00	140.00
4	BODY JOINT SEALANT	New	200.00	150.00
5	BODY UNDERSIDE COATING	New	250.00	150.00
6	REMOVE & INSTALL RADIATOR WITH FITTINGS	New	280.00	250.00
7	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	New	350.00	300.00
8	REPLACE FR.WINDSCREEN	New	350.00	300.00
9	RESET VEHICLE SMART ENTRY SYSTEM	New	400.00	350.00
10	REMOVE INSTALL & CALIBRATE FRONT VIEW CAMERA	New	450.00	400.00
11	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU &	New	2,240.00	1,680.00
12	REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL	New	2,240.00	1,120.00
13	RENEW BULKHEAD, WHEELHOUSE ASSY & ALIGN CHASSIS	New	3,360.00	2,800.00
14	SPRAY PAINT ON REPAIRED / REPLACED AREAS. (7PX\$450)	New	3,500.00	3,150.00
Gross Labour Cost (\$\$)			14,160.00	11,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >