CITY CAB PTE LTD REPAIR ESTIMATE*

YEHICLE NO : SHB 2352R

MAKE

: HYUNDAI i40 MODEL

China Taiping

DATE 12/4/2019 CPTP

LKK-Kalvin

Qty	Parts Description/ Labour	Type	Unit Price		mount
21	Boot Lid Xrysin			\$	2,174.90
	Boot Lid Lock Upper X			\$	102.60
	Boot Lid Lock Lower X			\$	31.70
	Boot Lid 'H' Emblem			\$	28.70
	Boot Lid CRDI Plate			\$	27.90
	Bootlid Moulding			\$	85.00
	Bootlid i40 Emblem			\$	27.90
	Bootlid Lower Garnish X			\$	227.90
	Rear Bumper Aubub		RT LEST	\$	553.00
	Rear Bumper Reinforcement			\$	428.40
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 80.30	\$	160.60
				\$	22.00
	Rear Bumper Clip 10 pcs		\$ 35.60	\$	71.20
	Rear Bumper Bracket		33.00	\$	103.50
	Rear Bumper Sponge			\$	228.00
	Rear Bumper Under Cover			\$	526.70
	Rear Panel			\$	57.70
	Rear Panel Garnish	Consultani		\$	89.40
	Rear Panel Garnish Rear Panel Lower Panel LKK Anto	alter s		Φ	100000000000000000000000000000000000000
	SUB TOTAL			\$	4,947.10
	LESS 20%	Subject to	Terring resurvey	\$	989.42
	DISCOUNTED TOTAL	must approval fro		\$	3,957.68
	Boot Lid Comfort Logo & Tel No. Sticker Signature:	Repairer	Campany	\$	30.00
	Rear Bumper Reverse Sensor			\$	135.70
	Rear Bumper Rubber Mat			\$	50.00
	Rear Bumper Advertisement Logo — M			\$	50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$	200.00
	Labour Charge Panel Beating Spray Painting Charge Wiring Charge Tuff Kote Remove/Refix Reverse Sensor TOW FRE (Not accides some to TOTAL LABOUR)	14		\$	465.70
	Labour Charge		,		600
	Panel Beating // 12/	4/19	1:45%	\$	800.00
	Spray Painting Charge	2		\$	900.00
	Wiring Charge 3 V	4/2		\$	50.00
	Tuff Kote	100	Paid whater	\$	50.00
	Remove/Refix Reverse Sensor	eson	1 2177	\$	80.00
	TOW FRE. (Not accident scene +	1-)			60. No
	TOTAL LABOUR			\$	1,880.00
	ESTIMATE TOTAL			\$	6,303.38
		*			
		12	+		

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

pti Brusses Cart Bittander (161) 1945 (1777) 19 Hi vyrtus Reput Languagus (1612) 1945 (1777) 1971 (1777) 1 Burgai (1800) (1895) 1985 (1897) 1975 (1777) 1970 (1777)





JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition				
1. Date: U, H, G Time Receiv		4.	Type of Towing: Normal Tow	
2. New SPARK Kaki	Private Taxi (CTP	L/CCPL)	King Dolly	
Name of Customer : NO ONG	Fleet	DOOP L)	Flat Bed	
	STK (Boot	n Lay)	Crane-up	
Contact No. : Q79526	386			
Vehicle No. : SHB335	5. Nature of Serv	ice: 6.	Parts Replaced/Remarks:	
	Jumpstan			
Make/Model/Colour: 140	Recovery			
Email :	Change T	yre / Battery		
7. Location:	11 0	8. Vehicle Tow - I		
Dret sino	ndoon voryp bac			
9. Preferred Workshop:	,	Overheati		
Braddell Loyang	Pandan	Starting F		
Sin Ming Sungei Kadut	Ubi	[A!-		
Senoko Komoco (UBI /	Leng Kee)	Return Ta		
Others:				
10. Odometer Reading :	11. Rad	dio / CD Player	FROIT	
To. Odomoto Hodding		OK		
Fuel Level : F 1	/4 1/2 3/4 E	Faulty		
ruei Levei		Not tested	E SOU	
Job Attended			BIDE THOUSAND	
10 Taux Tausk / Beacoupt Von	S QA GAO TZ YIS	SHUN OTHERS	040	
12. Tow Truck / Recovery Van : VR		WING		
Name of Driver			REAR CONTRACTOR	
Vehicle No. :	52268 I		#: Cracked X: Dented	
Time Dispatch :			/ : Scatched O : Missing	
Time of Arrival :			(A)	
Time Completed :			Signature of Customer	
Cash Invoice Details (if applicable)				
13. Cash Invoice No. :				
Customer Acknowledgement				
a. I have been advised to remove all valuable ite	ms in my vehicle, including Global Positionin	g System (GPS), audio comp	pact disk, thumbdrive, carpark coupo	
cash cards, spectacles, pen, etc. b. I understand that any items left behind are at	my own risk and SPARK Car Care™ will not	be held liable for such losse	s.	
c. Surcharge: Towing fee will be levied if the cus	stomer decides neither to tow nor proceed w	ith the repairs in SPARK Car	Care™,	
19-4-91	1845		Clar.	
		Signed	turn of Customer	
Date	Time	Signat	ture of Cystomer	
14. WORKSHOP				
Name of Attending Staff/Guard	Date & Time of Arrival	Signature of	f Attending Staff/Guard	
Ivaille of Attending Stall/Guard	Dato & Tillo Olivalitai		CUSTOMER'S C	