

INS: CASE OWNER: LEE HING YAO

CC4 / ALH1900 6638, B97A32

LKK:
IDAC:

Surveyor:

Mr Lim

DOI:

ASSIGNMENT

18/4/19

Date / Time:

18/4/19

Registered in Merimen:

18/4/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

CKG 1963Y

Name of Insured:

Remichelle Pam Charles

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

17/4/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

186200880890

Policy No.:

200509349-01

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLT 102



INSRS:

WSP:

Tel:

Liability:

RMKS:

Team
Autopro.

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SLT102-X; CKG1963Y-X

Pending surveyor's assignment sheet.

26/07/19

- FILE REVIEWED. OLD RATE-ENDED TP.
SEND LETTER BY EMAIL TO OI TO
NOTIFY TP CLAIM & NCB ISSUES.
- FINALISED
- TP LOD IN BY EMAIL

27/08/19

- TYPE REPORT FOR MANDATE APPROVAL
- REPORT DONE

23/10/19

- SEND MANDATE APPROVAL TO MC

07/11/19

- AG APPROVED MANDATE @ MAX \$10 & \$3,500.00

30/11/19

- SEND 1ST OFFER TO TP

13/11/19

- TP REQUESTED OFFER. PROPOSED @ \$ & \$4K (MIN)

17/11/19

- TP ACCEPTED OFFER.

- ALL LOGS IN ORDER.

- TO CLOSE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 23/07/19-VIC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

\$S 40,000.00 (18 days) Reduction: 37 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

\$S 40,000.00

COI (END-ENDED TP)

Loss of Rental (LOR):

\$S (days)

Loss of Use (LOU):

\$S 4,680.00 x 26 days

Loss of Income (LOI):

\$S (\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$S 36.45

Medical:

\$S 180.00

Disbursement: TOWING

\$S 180.00

(e.g. Tow/ Independent)

Legal Cost

\$S

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320.00

Total:

\$S 44,896.45

Global Sum \$S:

43,560.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$S 43,560.00

Name 1:

TEAM AUTOPRO PDS LTD

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

Surveyor

REF: AIG

ASSIGNMENT

From:

Date:

15/4/2019

Estimated Cost:

OD ☒ TPY WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLT 10Z

at Workshop m/s

Team Auto pro

of 160 Sin Ming Drive #01-14

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

18 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLT 10Z

Yr Regn: 2/1/2014

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Porsche Cayenne GTS V8

C.C. 4806 cc

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

32150

T/Radio: Insured / Std / NI / NA

Eng/No:

M4802GE04078

C/No:

WP1ZXX92ZELA72087

Gen. Cond: Good / Fair / ☒ Poor / Burnt (Engine not startable)Steering: Inorder / ☒ Jammed / Leaked / Burnt orBrake: Inorder / ☒ Jammed / Leaked / Burnt orModi: Nil / ☒ R/Rim / STD A/Rim or

Tyre Size:

F: 295/35R21

R: 295/35R21

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

12/4/19

D.O.I.

15/4/2019

Survey held at

Team Auto pro

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

HS 40,000/2 TRIM line
16/7/19
CRV: \$24,103.94/57%.

MV 227,000/2

PV 178,894/2

NV 48,106/2

TRIM line
28/5/19

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$))

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

SJE : _____
Date of Survey : _____
Date of ReSurvey : _____ After-Paint: _____
Contacts : _____

Vehicle Nos : **SLT 10Z**
Model : **PORSCHE CAYENNE GTS**
Year : _____
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	TAILGATE	1	\$ 4,420.00	\$ 3750.00 ✓ 4,420.00
2	TAILGATE EMBLEM 'PORSCHE'	1	\$ 150.00	\$ 62.00 ✓ 150.00
3	TAILGATE EMBLEM 'CAYENNE'	1	\$ 185.00	\$ ✓ 185.00
4	TAILGATE 'GTS'	1	\$ 188.00	\$ ✓ 188.00
5	TAILGATE CHROME MOULDING	1	\$ 389.00	\$ 350.00 ✓ 389.00
6	TAILGATE OUTER MOULDING	1	\$ 300.00	\$ 260.00 ✓ 300.00
7	TAILGATE REFLECTOR	✓ 2	\$ 420.00 450.00	\$ 840.00 900.00
8	TAILGATE WINDSCREEN	1	\$ 3,000.00	\$ 2,970.00 3,000.00
9	TAILGATE INNER TRIM	1	\$ 985.00	\$ 700.00 985.00
10	TAILGATE MOTORIZED DAMPER	2	\$ 350.00	\$ 700.00
11	TAILGATE LOCK MECHANISM	1	\$ 1,350.00	\$ ✓ 1,350.00
12	TAILGATE WEATHER STRIP	1	\$ 480.00	\$ ✓ 480.00
13	TAILGATE RUBBER	1	\$ 276.00	\$ ✓ 276.00
14	REAR BUMPER	1	\$ 1,200.00	\$ ✓ 1,200.00
15	REAR BUMPER COVER	1	\$ 195.90	\$ ✓ 195.90
16	REAR BUMPER LOWER	1	\$ 650.00	\$ ✓ 650.00
	REAR BUMPER LOWER SIDE GARNISH	✓ 2	\$ 300.00	\$ ✓ 600.00
17	REAR BUMPER DEFUSER	1	\$ 650.00	\$ ✓ 650.00
18	REAR BUMPER DEFUSER BRACKET	1	\$ 102.80	\$ ✓ 102.80
19	REAR BUMPER RETAINER	✓ 12	\$ 188.50	\$ 188.50 377.00
20	REAR BUMPER REFLECTOR	2	\$ 180.00	\$ ✓ 360.00
21	REAR BUMPER REINFORCEMENT	1	\$ 600.00	\$ ✓ 600.00
22	REAR BUMPER BRACKET	1	\$ 171.60	\$ ✓ 171.60
23	REAR BUMPER ARCH GARNISH	2	\$ 160.00	\$ ✓ 320.00
24	REAR BUMPER INSULATOR RH	1	\$ 38.00	\$ ✓ 38.00
25	REAR BUMPER INSULATOR LH	1	\$ 38.00	\$ ✓ 38.00
26	REAR BUMPER PARK ASSIST	1	\$ 1,500.00	\$ 884.40 1,500.00
27	REVERSE SENSOR	✓ 2	\$ 350.00	\$ 750.00 1,400.00
28	REVERSE CAMERA	1	\$ 500.00	\$ 500.00
29	REVERSE SENSOR WIRE HARNESS	1	\$ 160.00	\$ ✓ 160.00
30	REAR END PANEL	1	\$ 1,688.00	\$ 1450.00 1,688.00
31	REAR END PANEL TOP GARNISH	1	\$ 663.00	\$ ✓ 663.00
32	TAIL LAMP	2	\$ 1,683.00	\$ ✓ 3,366.00
33	BATTERY REGULATOR	1	\$ 1,680.00	\$ 900.00 1,680.00
34	REAR AIRBAG SENSOR	1	\$ 230.00	\$ ✓ 230.00
35	REAR SAFETY BELT	2	\$ 871.00 879.00	\$ 1742.00 1,758.00
36	FRONT SAFETY BELT	2	\$ 871.00 899.00	\$ 1742.00 1,798.00
37	REAR SAFETY BELT ECU	1	\$ 3,000.00	\$ 2500.00 3,000.00
38	FRONT SAFETY BELT ECU	1	\$ 3,000.00	\$ 2,500.00 3,000.00
39	COLLISION SENSOR	1	\$ 2,800.00	\$ 2,000.00 2,800.00
40	REAR FENDER LH	1	\$ 3,800.00	\$ ✓ 3,800.00
41	ANTI ROLL BAR	1	\$ 860.00	\$ 860.00
42	EXHAUST PIPE	1	\$ 5,000.00	\$ 2,500.00 5,000.00

DDV ✓
NECV ✓
BR ✓
BR ✓
NECV ✓
BR ✓
NNX ✓
BT ✓
CUT ✓
NECV ✓
DD ✓
DIS ✓
BR ✓
NIS / BR ✓
BR ✓
NECV ✓
NECV ✓
BR ✓
BT ✓
BR ✓
BR ✓
? ✓ BR ✓
? ✓ BR ✓
SC ✓
DL ✓
NNX ✓
CUT ✓
DD ✓
DL ✓
BR ✓
SC ✓
SC ✓
NECV ✓
NECV ✓
ACT ✓ active
DD ✓
NNX ✓
BT ✓

43	EXHAUST MUFFLER VALVE	1	\$ 3,650.00	\$ 3,650.00	DIS ✓
44	EXHAUST MUFFLER MOUNTING	6	\$ 105.00 110.00	\$ 630.00 708.00	NEC
45	EXHAUST HEAT SHIELD	1	\$ 680.00	\$ 450.00 680.00	DIS ✓
Parts Sub Total :				\$ 56,867.30	46443.30
5% Discount				\$ 2,843.37	2322.17
PARTS TOTAL :				\$ 54,023.94	44121.14

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	TAILGATE OUTER MOULDING CLIPS	1	\$ 50.00	\$ 30.00 50.00	NEC ✓
2	TAILGATE REFLECTOR CLIPS	2	\$ 50.00	\$ 60.00 100.00	NEC ✓
3	TAILGATE REFLECTOR SEAL	2	\$ 100.00	\$ 200.00	NNX
4	TAILGATE WINDSCREEN INNER SEAL	1	\$ 250.00	\$ 250.00	NEC ✓
5	TAILGATE WINDSCREEN SEALANT	1	\$ 100.00	\$ 100.00	NEC ✓
6	TAILGATE INNER TRIM CLIPS	1	\$ 50.00	\$ 30.00 50.00	✓ nec
7	REAR BUMPER ARCH GARNISH CLIPS	1	\$ 50.00	\$ 30.00 50.00	✓ } nec
8	REAR END PANEL SEALANT	1	\$ 100.00	\$ 60.00 100.00	✓ }
9	REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$ 30.00 50.00	✓ }
10	SUNDRIES	1	\$ 100.00	\$ 100.00	NNX
SPECIAL NETT TOTAL :				\$ 1,050.00	590.00

Nos.	LABOUR	S\$	
1	R&R TAILGATE COMPONENT	\$ 100.00 150.00	✓
2	R&R REVERSE SENSOR	\$ 60.00 100.00	✓
3	R&R EXHAUST PIPE + Axle	\$ 180.00 200.00	✓
4	CONDUCT 4 WHEEL ALIGNMENT	\$ 80.00	✓
5	PANEL BEAT	\$ 1400.00 1,800.00	✓
6	RUST PROOFING	\$ 100.00 200.00	✓
7	SPRAY PAINTING	\$ 1200.00 1,800.00	✓
8	RESET FAULT CODE	\$ 500.00 1,000.00	✓
9	R&R REAR SEAT BELT & TENSIONER (FRONT & REAR)	\$ 500.00 800.00	✓
10	R&R AIRBAG CONTROL MODULE	\$ 700.00 1,000.00	✓
11	R&R UNDERCARRIAGE	\$ 500.00 1,000.00	✓
12	CHECK WIRING	\$ 80.00 100.00	✓
13	MOUNT WORK BENCH	\$ 300.00	NNX
14	CHASSIS ALIGNMENT	\$ 300.00	NNX
15	R&R UPHOLSTERY	\$ 200.00 500.00	NNX
LABOUR TOTAL :		\$ 9,330.00	5400.00

PARTS TOTAL :	\$ 54,023.94	44121.14
SPECIAL NETT TOTAL :	\$ 1,050.00	590.00
LABOUR TOTAL :	\$ 9,330.00	5400.00
GRAND TOTAL :	\$ 64,403.94	50111.14

@ 20% 10022.23
40088.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

? Photo

Resurvey on 23/5/19

hump saw repair

TGCim lhm

Repair days 18

1727

L/S 40,000/2

(1) Deformed (6) Shifted (9) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)
(4) Not Compliant (X)

Vehicle No: SLT108

Rear Portion

NAC	INC	Item	CON	ACQ	QTY
1137	993626	Rear Number Plate	BT	✓	
1138	993627	Rear Number Plate Base	BR	✓	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	DL	✓	
1141	992958	Rear Bumper	BR	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	BR	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	MIS		
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket	BR	✓	1
1148	993068	Rear Bumper Side Retainer	NEC	✓	
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad	BR	✓	2
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	BR	✓	2
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DL	✓	2
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	DL	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	BR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	BR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	3
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding	BR	✓	
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	BR	✓	2
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass	NEC	✓	
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock	BT	✓	
1198	994651	Tailgate Rubber	NEC	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	BR	✓	

NAC	INC	Item	CON	ACQ	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy	BT	✓	
1211	990532	Centre Exhaust Mounting	NEC	✓	
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe	DD	✓	4
1214	993361	Rear Exhaust Mounting	NEC	✓	
1215	993358	Rear Exhaust Heat Shield	DIS	✓	
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	DD	✓	
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1195	990247	Sticker			
		Ext seat belt		NEC	✓
		Rear seat belt		NEC	✓
		Rear Bumper Arch Garnish	BR	✓	2
		Rear Bumper Park Assist	GL	✓	
		Reverse Sensors wire harness	CUT	✓	
		Battery Regulator	SC	✓	
		Rear air bag sensor	SC	✓	
		Ext & Rear Safety belt	NEC	✓	4
		Ext & Rear seat belt ecu	AG	✓	2

No of Items: 41

Assessor: J. G. Lim

29/5/19

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8068J
Vehicle Details	
Vehicle No.:	SLT10Z
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Apr 2019
Vehicle Make:	PORSCHE
Vehicle Model:	CAYENNE GTS V8
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	M4802GE04078
Chassis No.:	WP1ZZZ92ZELA72087
Maximum Power Output:	309.0 kW (414 bhp)
Open Market Value:	\$129,240.00
Original Registration Date:	02 Jan 2014
First Registration Date:	02 Jan 2014
Transfer Count:	1
Actual ARF Paid:	\$204,632.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jan 2024
PARF Rebate Amount:	\$143,242.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jan 2024
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$75,700.00
COE Rebate Amount:	\$35,652.00
Total Rebate Amount:	\$178,894.00

The information contained herein is correct as at 16 Apr 2019

OK

MV 227,000/2

PV 178,894/2

NV 48,106/2

TAM
16/4/19

PRE-REPAIR INSPECTION REQUEST – SLT10Z vs SKG1963Y (OI) on D.O.A.: 12/04/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com'; Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Abu Kassim, Noor Mariesa; Chan, Yoke Shi
Sent: 15/4/2019 8:59:14 AM
Attachments: SC454e (Sj19041311260.pdf) draft.pdf

Hi,

Please refer to the enclosed request from **Team AutoPro Pte Ltd.**

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

From: TeamAutoPro North [mailto:teamautopl@gmail.com]

Sent: Saturday, April 13, 2019 11:50 AM

To: Chan, Yoke Shi; Chin, Lee-Ying; Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Abu Kassim, Noor Mariesa; Supramaniam, Darshene; Tan, Lily (AIG)

Subject: [EXTERNAL] Re: 2 Days Notice SLT 10 Z (Our Ref) and SKG 1963 Y (Your Ref) Dated 12rd April 2019

Caution: External Email

Dear Sirs,

With reference to your list of surveyors, we are agreeable with the appointment of **Mr Lim - LKK** as the SJE for subject claim.

Kindly note our personnel in charge for the survey as follows:-

Contact Person	Alan Koh	9092 7279
	Frederick Lim	9674 6635
Email	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Singapore 575722	

Thank you for your kind attention to our request.

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Michelle Lim

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

385 Sin Ming Drive

#01-02 Vicom Inspection Centre

Singapore 575718

On Sat, Apr 13, 2019 at 11:25 AM TeamAutoPro North <teamautopl@gmail.com> wrote:

Dear Sir/Madam,

Road Traffic Accident Involving SLT 10 Z (Our Ref) and SKG 1963 Y (Your Ref)

Dated 12th April 2019, Time around 17:30

@ Woodland Ave 3 turning towards BKE

9:35am @ 15/4/19
vehicle in
person Adelle
sur @ Mr Lim

We represent our client; Chen Yen Yeo, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SLT 10 Z and your insured's vehicle registration number: SKG 1963 Y.

Enclosed herewith a copy of our 2 Days Notice Letter and the relevant Singapore Accident Statement filed for your reference.

Please let us know within **2 working days** from today, your list of at least **ten (10) motor surveyors**, via email to the following personnel:-

Contact Person	Alan Koh Frederick Lim	9092 7279 9674 6635
Email Address	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722	

Thank you for your attention to this email and we look forward to your earliest reply.

--

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Michelle Lim

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

385 Sin Ming Drive

#01-02 Vicom Inspection Centre

Singapore 575718

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Print Received Message

This mail is associated with :

***SLT10Z (9362003868SG)
[SKG1963Y]**

TP

CHEN YEN YEO

Apr 12 2019 5:00PM

[DEMICHELE PAUL CHARLES]

Team Autopro Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 07/11/2019 11:24 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$43560.00) - SLT10Z - Claim Handler: Lee, Ming-Yao

Approved:43560.00:Pls do your utmost to negotiate at best from: \$43.3k to \$43.56k (All-in) Above mandate subject to Final Repair Bill, GIA/LTA Bill in order

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Apr 2019 Edit Reg		15 Apr 2019 00:00 Edit Adj Rpt	S\$40,000.00 Edit Estimates	S\$40,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured:	DEMICHELE PAUL CHARLES, ID: G5408669K								
Main Claimant:	CHEN YEN YEO, ID: S7718068J								
Vehicle Reg. No.:	SLT10Z	Date of Loss:	12/04/2019 17:00 - :59 [63 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9362003868SG	Policy/Cover Note No.:	2100509349-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKG1963Y	Policy No. (Claimant):	PNPV2018-00008649						
		Excess:							
Repairer:	Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 25/04/2019]								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
AIG_SG_EXPRESS (07/11/2019): Alert - Adj Mandate Approved (S\$43560.00) - SLT10Z - Claim Handler: Lee, Ming-Ya...									
ALL ASSOCIATED TASKS ☐			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLT10Z (9362003868SG)**
[SKG1963Y]
TP
CHEN YEN YEO
Apr 12 2019 5:00PM
[DEMICHELE PAUL CHARLES]
Team Autopro Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/07/19 09:17	Chassis Number	Load JPG	☒
2	23/07/19 09:17	Odometer Reading	Load JPG	☒
3	23/07/19 09:17	General View	Load JPG	☒
4	23/07/19 09:17	General View	Load JPG	☒
5	23/07/19 09:17	General View	Load JPG	☒
6	23/07/19 09:17	General View	Load JPG	☒
7	23/07/19 09:17	General View	Load JPG	☒
8	23/07/19 09:17	General View	Load JPG	☒
9	23/07/19 09:17	General View	Load JPG	☒
10	23/07/19 09:17	General View	Load JPG	☒
11	23/07/19 09:17	General View	Load JPG	☒
12	23/07/19 09:17	General View	Load JPG	☒
13	23/07/19 09:17	General View	Load JPG	☒
14	23/07/19 09:17	General View	Load JPG	☒
15	23/07/19 09:17	General View	Load JPG	☒
16	23/07/19 09:17	General View	Load JPG	☒
17	23/07/19 09:17	General View	Load JPG	☒
18	23/07/19 09:17	General View	Load JPG	☒
19	23/07/19 09:17	General View	Load JPG	☒
20	23/07/19 09:17	General View	Load JPG	☒
21	23/07/19 09:17	General View	Load JPG	☒
22	23/07/19 09:17	General View	Load JPG	☒
23	23/07/19 09:17	General View	Load JPG	☒
24	23/07/19 09:17	General View	Load JPG	☒
25	23/07/19 09:17	General View	Load JPG	☒
26	23/07/19 09:17	General View	Load JPG	☒
27	23/07/19 09:17	General View	Load JPG	☒
28	23/07/19 09:17	General View	Load JPG	☒
29	23/07/19 09:17	General View	Load JPG	☒
30	23/07/19 09:17	General View	Load JPG	☒
31	23/07/19 09:17	General View	Load JPG	☒
32	23/07/19 09:17	General View	Load JPG	☒
33	23/07/19 09:17	General View	Load JPG	☒
34	23/07/19 09:17	General View	Load JPG	☒
35	23/07/19 09:17	General View	Load JPG	☒
36	23/07/19 09:17	General View	Load JPG	☒
37	23/07/19 09:17	General View	Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/07/19 09:17	General View	 Load JPG	☒
39	23/07/19 09:17	General View	 Load JPG	☒
40	23/07/19 09:17	General View	 Load JPG	☒
41	23/07/19 09:17	General View	 Load JPG	☒
42	23/07/19 09:17	General View	 Load JPG	☒
43	23/07/19 09:17	General View	 Load JPG	☒
44	23/07/19 09:17	General View	 Load JPG	☒
45	23/07/19 09:17	General View	 Load JPG	☒
46	23/07/19 09:17	General View	 Load JPG	☒
47	23/07/19 09:17	General View	 Load JPG	☒
48	23/07/19 09:17	General View	 Load JPG	☒
49	23/07/19 09:17	General View	 Load JPG	☒
50	23/07/19 09:17	General View	 Load JPG	☒
51	23/07/19 09:17	General View	 Load JPG	☒
52	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
53	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
54	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
55	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
56	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
57	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
58	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
59	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
60	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
61	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
62	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
63	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
64	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
65	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
66	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
67	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
68	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
69	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
70	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
71	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
72	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
73	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
74	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
75	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
76	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
77	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
78	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
79	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
80	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
81	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
82	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
83	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
84	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
85	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
86	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
87	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
88	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
89	23/07/19 09:18	Reinspection Photo	 Load JPG	☒
90	23/07/19 09:18	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	23/07/19 09:18	Reinspection Photo	Load JPG	☒
92	23/07/19 09:18	Reinspection Photo	Load JPG	☒
93	23/07/19 09:18	Reinspection Photo	Load JPG	☒
94	23/07/19 09:18	Reinspection Photo	Load JPG	☒
95	23/07/19 09:18	Reinspection Photo	Load JPG	☒
96	23/07/19 09:18	Reinspection Photo	Load JPG	☒
97	23/07/19 09:18	Reinspection Photo	Load JPG	☒
98	23/07/19 09:18	Reinspection Photo	Load JPG	☒
99	23/07/19 09:18	Reinspection Photo	Load JPG	☒
100	23/07/19 09:18	Reinspection Photo	Load JPG	☒
101	23/07/19 09:18	Reinspection Photo	Load JPG	☒
102	23/07/19 09:18	Reinspection Photo	Load JPG	☒
103	23/07/19 09:18	Reinspection Photo	Load JPG	☒
104	23/07/19 09:18	Reinspection Photo	Load JPG	☒
105	23/07/19 09:18	Reinspection Photo	Load JPG	☒
106	23/07/19 09:19	Reinspection Photo	Load JPG	☒
107	23/07/19 09:19	Reinspection Photo	Load JPG	☒
108	23/07/19 09:19	Reinspection Photo	Load JPG	☒
109	23/07/19 09:19	Reinspection Photo	Load JPG	☒
110	23/07/19 09:19	Reinspection Photo	Load JPG	☒
111	23/07/19 09:19	Reinspection Photo	Load JPG	☒
112	23/07/19 09:19	Reinspection Photo	Load JPG	☒
113	23/07/19 09:19	Reinspection Photo	Load JPG	☒
114	23/07/19 09:19	Reinspection Photo	Load JPG	☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/04/19 14:37	EMAIL FROM AIG DD 15.04.2019	Load PDF	
2	15/04/19 14:37	ACKNOWLEDGEMENT EMAIL TO AIG DD 15.04.2019	Load PDF	
3	15/04/19 14:37	NOTIFICATION FROM WORKSHOP	Load PDF	
4	15/04/19 14:37	NOTIFICATION FROM WORKSHOP +TP GIA REPORT	Load PDF	
5	29/05/19 20:46	TP ESTIMATE - MARKED	Load PDF	
6	23/07/19 09:08	TP ESTIMATE - FINALIZED	Load PDF	
7	23/07/19 09:27	EMAIL TO OI	Load PDF	
8	23/07/19 09:27	LETTER TO OI	Load PDF	
9	23/10/19 17:45	LOD	Load PDF	
10	23/10/19 17:45	GIA LTA SEARCH	Load PDF	
11	23/10/19 17:45	TOWING FEE	Load PDF	
12	22/11/19 16:13	AUTHORISATION TO ACT	Load PDF	
13	22/11/19 16:13	RELEASE VOUCHER	Load PDF	
14	22/11/19 16:13	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/04/19 08:41	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKG1963Y (Insd veh)	Model:	PORSCHE CAYENNE 4.8 GTS
	SLT10Z (TP veh)		V8 (A)
Date of Accident:	12/04/2019		

Global Sum Settlement	: [X]	Yes	[]	No	
Repair Estimate	:	\$		64,403.93	
Final Repair Cost	:	\$		43,560.00	
Loss of Use	:	\$			26.00 days at \$180.00 per day
Rental (if any)	:	\$			days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (GLOBAL SUM)	:	\$		43,560.00	
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)					
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)			
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown

1)	Team Autopro Pte Ltd	:	\$	43,560.00
2)		:	\$	
3)		:	\$	
4)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

22 Nov
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19006638/BHA3S2

Date: 22/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100509349-01
 Claimant Vehicle No: SLT10Z Insured Vehicle No: SKG1963Y
 Date of Loss: 12/04/2019 Nature of Claim: TP Claim No: 9362003868SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT10Z Engine No: M4802GE04078
 Make & Model: PORSCHE CAYENNE, 4.8 GTS V8 (A) Chassis No: WP1ZZZ92ZELA72087
 Reg. Date: 02/01/2014 (Man. Year: 2013) Odometer: 32150 km
 Colour: Black
 Engine Capacity: 4806 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Poor Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/35 R21 Rear Tyre Size: 295/35 R21
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	55,073.93	44,711.13	10,362.80	18.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,330.00	5,400.00	3,930.00	42.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	64,403.93	50,111.13	14,292.80	22.19
Approved Total (Overridden) (\$\$)		40,000.00		
Nett Amount (\$\$)	64,403.93	40,000.00	24,403.93	37.89
+ Loss of Use (26.0 x S\$180.00/day) (\$\$)		4,680.00		
+ Doc/Search Fee (\$\$)		36.45		
+ Other Costs (\$\$)		180.00		
Nett Liability (\$\$)		44,896.45		
Global Sum Settlement (\$\$)		43,560.00		

INSPECTION

Date of Assignment: 15/04/2019
 Date Inspected: 15/04/2019 Inspected At: Team Autopro Pte Ltd (Sin Ming)
 385 Sin Ming Drive, #01-02 Vicom Inspection
 Centre
 Singapore 575718
 Estimated Period of Repair: 18.0 days

Adjuster: Lim Teow Guan

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=812700&extid=300836&CFID=629122... 1/5

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	4,420.00 FL	*3,750.00 FL
2	1		*TAILGATE EMBLEM PORSCHE	Necessary	150.00 FL	*62.00 FL
3	1		*TAILGATE EMBLEM CAYENNE	Necessary	185.00 FL	*185.00 FL
4	1		*TAILGATE GTS	Necessary	188.00 FL	*188.00 FL
5	1		*TAILGATE CHROME MOULDING	Broken	389.00 FL	*350.00 FL
6	1		*TAILGATE OUTER MOULDING	Broken	300.00 FL	*260.00 FL
7	2		*TAILGATE REFLECTOR	Broken	900.00 FL	*840.00 FL
8	1		*TAILGATE WINDSCREEN	Necessary	3,000.00 FL	*2,970.10 FL
9	1		*TAILGATE INNER TRIM	Broken	985.00 FL	*700.00 FL
10	2		*TAILGATE MOTORIZED DAMPER	Not Necessary	700.00 FL	*- FL
11	1		*TAILGATE LOCK MECHANISM	Bent	1,350.00 FL	*1,350.00 FL
12	1		*TAILGATE WEATHERSTRIP	Cut	480.00 FL	*480.00 FL
13	1		*TAILGATE RUBBER	Necessary	276.00 FL	*276.00 FL
14	1		*REAR BUMPER	Dented	1,200.00 FL	*1,200.00 FL
15	1		*REAR BUMPER COVER	Distorted	195.90 FL	*195.90 FL
16	1		*REAR BUMPER LOWER	Broken	650.00 FL	*650.00 FL
17	2		*REAR BUMPER LOWER SIDE GARNISH	Missing / Broken	600.00 FL	*600.00 FL
18	1		*REAR BUMPER DEFUSER	Broken	650.00 FL	*650.00 FL
19	1		*REAR BUMPER DEFUSER BRACKET	Necessary	102.80 FL	*102.80 FL
20	2		*REAR BUMPER RETAINER	Necessary 1pc Only	377.00 FL	*188.50 FL
21	2		*REAR BUMPER REFLECTOR	Broken	360.00 FL	*360.00 FL
22	1		*REAR BUMPER REINFORCEMENT	Bent	600.00 FL	*600.00 FL
23	1		*REAR BUMPER BRACKET	Broken	171.60 FL	*171.60 FL
24	2		*REAR BUMPER ARCH GARNISH	Broken	320.00 FL	*320.00 FL
25	1		*REAR BUMPER INSULATOR RH	Broken	38.00 FL	*38.00 FL
26	1		*REAR BUMPER INSULATOR LH	Broken	38.00 FL	*38.00 FL
27	1		*REAR BUMPER PARK ASSIST	Short Circuit	1,500.00 FL	*884.40 FL
28	4		*REVERSE SENSOR	Dislodged 2pcs Only	1,400.00 FL	*750.00 FL
29	1		*REVERSE CAMERA	Not Necessary	500.00 FL	*- FL
30	1		*REVERSE SENSOR WIRE HARNESS	Cut	160.00 FL	*160.00 FL
31	1		*REAR END PANEL	Dented	1,688.00 FL	*1,450.00 FL
32	1		*REAR END PANEL TOP GARNISH	Dislodged	663.00 FL	*663.00 FL
33	2		*TAIL LAMP	Broken	3,366.00 FL	*3,366.00 FL
34	1		*BATTERY REGULATOR	Short Circuit	1,680.00 FL	*900.00 FL
35	1		*REAR AIRBAG SENSOR	Short Circuit	230.00 FL	*230.00 FL
36	2		*REAR SAFETY BELT	Necessary	1,758.00 FL	*1,742.00 FL
37	2		*FRONT SAFETY BELT	Necessary	1,798.00 FL	*1,742.00 FL
38	1		*REAR SAFETY BELT ECU	Necessary	3,000.00 FL	*2,500.00 FL
39	1		*FRONT SAFETY BELT ECU	Necessary	3,000.00 FL	*2,500.00 FL
40	1		*COLLISION SENSOR	Activated	2,800.00 FL	*2,000.00 FL
41	1		*REAR FENDER LH	Dented	3,800.00 FL	*3,800.00 FL
42	1		*ANTI ROLL BAR	Not Necessary	860.00 FL	*- FL
43	1		*EXHAUST PIPE	Bent	5,000.00 FL	*2,500.00 FL
44	1		*EXHAUST MUFFLER	Distorted	3,650.00 FL	*3,650.00 FL
45	6		*EXHAUST MUFFLER MOUNTING	Necessary	708.00 FL	*630.00 FL
46	1		*EXHAUST HEAT SHIELD	Distorted	680.00 FL	*450.00 FL
47	1		*TAILGATE OUTER MOULDING CLIPS	Necessary	50.00 FS	*30.00 FS
48	2		*TAILGATE REFLECTOR CLIPS	Necessary	100.00 FS	*60.00 FS
49	2		*TAILGATE REFLECTOR SEAL	Not Necessary	200.00 FS	*- FS
50	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	250.00 FS	*250.00 FS
51	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*100.00 FS
52	1		*TAILGATE INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
53	1		*REAR BUMPER ARCH GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
54	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
55	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SUNDRIES	Not Necessary	100.00 FS	*-FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					57,917.30	47,033.30
- List Item Discount on L Items 5.00/5.00% (\$)					2,843.37	2,322.17
Total Parts (\$)					55,073.93	44,711.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT.	New	150.00	100.00
2	R&R REVERSE SENSOR.	New	100.00	60.00
3	R&R EXHAUST PIPE.	New	200.00	180.00
4	CONDUCT 4 WHEEL ALIGNMENT.	New	80.00	80.00
5	PANEL BEAT.	New	1,800.00	1,400.00
6	RUST PROOFING.	New	200.00	100.00
7	SPRAY PAINTING.	New	1,800.00	1,200.00
8	RESET FAULT CODE.	New	1,000.00	500.00
9	R&R REAR SEAT BELT & TENTIONER (FRONT & REAR)	New	800.00	500.00
10	R&R AIRBAG CONTROL MODULE.	New	1,000.00	700.00
11	R&R UNDERCARRIAGE.	New	1,000.00	500.00
12	CHECK WIRING.	New	100.00	80.00
13	MOUNT WORK BENCH.	New	300.00	0.00
14	CHASSIS ALIGNMENT.	New	300.00	0.00
15	R&R UPHOLSTERY.	New	500.00	0.00
Gross Labour Cost (\$\$)			9,330.00	5,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >