



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLH 4382 L
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU303537376

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	\$97.70		X
2	Rear windscreen sealant	1	\$50.00	S.N	X
3	Rear number plate	1	\$45.00	S.N	X
4	Reverse sensor	1	\$200.00	S.N	✓
5	Rear bumper	1	\$497.50		✓
6	Rear bumper clip	10	\$40.00		✓
7	Rear bumper side retainer LH	1	\$112.70		✓
8	Rear bumper side retainer RH	1	\$112.70		X
9	Rear bumper reinforcement	1	\$398.90		✓
10	Rear bumper lower garnish centre	1	\$582.60		✓
11	Rear bumper lower garnish LH	1	\$149.70		✓
12	Rear bumper lower garnish RH	1	\$149.70		?
13	Rear bumper tow cover	1	\$31.70		✓
14	Rear bumper under cover	1	\$355.20		✓
15	Rear bumper under cover LH	1	\$187.60		✓
16	Rear bumper under cover RH	1	\$187.60		X
17	Rear bumper under cover clip	4	\$14.00		✓
18	Tail door	1	\$1,122.50		X
19	Tail door lock	1	\$487.70		X
20	Tail door emblem	1	\$61.70		X
21	Wording "PRIUS"	1	\$51.90		X
22	Wording "HYBRID"	1	\$55.47		X
23	Tail door plate garnish	1	\$782.50		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLH 4382 L
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU303537376

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door inner trim <i>Sn</i>	1	\$278.90		X
25	Tail door inner trim clip <i>Sn</i>	10	\$28.00		X
26	Taildoor spoiler <i>Sn</i>	1	\$1,567.83		X
27	Tail end panel <i>R</i>	1	\$596.60		?
28	Tail end panel garnish	1	\$151.60		?
29	Tail end panel garnish clip	10	\$35.00		?
30	Antenna Electrical key	1	\$155.45		?
31	Boot weatherstrip <i>Sn</i>	1	\$353.10		X
32	Spare tyre well panel <i>R</i>	1	\$793.15		X
33	Spare tyre board <i>Sn</i>	1	\$566.79		X
34	Spare tyre compartment sponge LH <i>Sn</i>	1	\$297.67		X
35	Spare tyre compartment sponge RH <i>Sn</i>	1	\$297.67		X
36	Spare tyre compartment centre <i>Sn</i>	1	\$251.70		X
37	Tail lamp LH - UPPER <i>Sn</i>	1	\$498.75		X
38	Tail lamp RH - UPPER <i>Sn</i>	1	\$498.75		X
39	Tail lamp LH - LOWER	1	\$511.60		?
40	Tail lamp RH - LOWER <i>Sn</i>	1	\$511.60		X
41	Taildoor glass sealant <i>Sn</i>	1	\$50.00	S.N	X
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Labour

Vehicle No. : SLH 4382 L Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER)	\$1,400.00	400-600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER)	\$1,400.00	500
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
6	To remove & refit rear windscreen. <i>na</i>	\$120.00	X
7	To tuff coat.	\$250.00	?
8	To transfer boot mechanism to new boot <i>na</i>	\$150.00	X
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	?
10	To remove & refit Taildoor glass <i>na</i>	\$120.00	X
11	Towing	\$60.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.