

ASS. REC. BY:

REF:

CS/FCI 1900 6669 / Ktd3

n2

Special Instruction:

SW/Ven/ty

Kenneth

ASSIGNMENT (Office)

cus

From (Person): Penny Kao

of FCI

Date/Time: 12:56pm@15/4/14

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 39004

Insured:

SHC 7756X

at Workshop in/s

Ah Lim Motor

Tel:

64831244

of

No. 10 AMK Ind. Park 2A # 01-09

Policy No:

Claim No:

D19002514MF84

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/10/2019

CA / REV / REP. / REV 24 HRS

'DS'

16/4/19@10am

H.O.D. Endorsement:

Date/Time:

1:35pm@15/4/14

Person Contacted:

Zila

Vehicle-IN/

☒ OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 39004 - CCG / AIG / 8008060 / Aua3s2

DUA: 26/4/18

SHC 7756x - CCG / AIG / 7021350 / K1hb3y2

DUA: 4/1/2017

17/4@4:14pm - Revised preli advise via email.

26/6 11 Lnp 8 245d Confirm (led: 3886.24; 61%)

Surveyor


REF: FCI

ASSIGNMENT

From: _____ Date: 16/4/2019
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: STK 3900H
 at Workshop m/s Ah Lim Motor
 of No. 10 Amk Ind. park 2A #01-09
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$55k
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 0.4 days Res.: Yes or No
 Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (DS)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STK 3900H Yr Regn: 01, 17
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mazda 2 C.C. 1496
 Colour: M.P. White A/C: Insured / Std / NI / NA
 Sp. Reading: 45649 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MM 60.2 23-4AGW191121
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 4 mm R/Bal. 5 mm
 L/Bal. 4 mm L/Bal. 5 mm
 D.O.A. 10/4/18 D.O.I. 16/4/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/5 8222P.08 email

RECEIVED 27 JUN 2019

Date/Time, File Pass to?

1) 27/6 Typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: (\$ 2450)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

145
50
50+50
19
314



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002514MFSH

Date: 17/4/2019

Our Ref: CS/FCI19006669/Ktd3


The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLK 3900H
Please be informed that we had conducted the inspection of the abovementioned vehicle
16/4/2019 at the premises of M/s Ah Lim Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>6,211.76</u>
Revised Estimate Amount	: S\$ <u>1,304.60</u>
"Check" Items Amount	: S\$ <u>2,339.60</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:
The vehicle sustained damages at the
rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	12-04-2019	Our Ref No. D19002514MFSH
Accident Date	10-04-2019	Claim Type. Third Party
Insured Vehicle	SHC7756X	Third Party Vehicle. SLK3900H
Survey Location	NO. 10 ANG MO KIO IND PARK 2A #01-09 AMK AUTOPOINT	
Contact Person.	EILEEN CHUA	
Contact No.	64831244/ 0	Fax No. 64836170
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AH LIM MOTOR COMPANY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 17 April 2019 4:14 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002514MFSH/1
Attachments: PRELI ADVISED SLK 3900H.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLK 3900H**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 15 April 2019 1:41 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002514MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 15 April 2019 12:56 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002514MFSH/1

Dear Sir/Mdm,

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	2651H

Vehicle Details

Vehicle No.:	SLK3900H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Apr 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SEDAN 1.5L SP.6EAT (LED)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	P520345319
Chassis No.:	MM6DL2SAAGW191121
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,729.00
Original Registration Date:	16 Jan 2017
First Registration Date:	16 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$13,729.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jan 2027
PARF Rebate Amount:	\$10,296.00

Intended COE Rebate Details

COE Expiry Date:	15 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$38,882.00
Total Rebate Amount:	\$49,178.00

The information contained herein is correct as at 11 Apr 2019

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8432651H



Name
LOO ZHONGYI JAVIER

呂忠益

Race
CHINESE

Date of birth
10-10-1984

Sex
M

Country of birth
SINGAPORE

4953812

REPUBLIC OF SINGAPORE DRIVING LICENCE

Service Number: S8432651H

Name
LOO ZHONGYI JAVIER

Birth Date: 10 Oct 1984

Issue Date: 08 Mar 2013




002158369G

lp: 9635 9353.

Email: j-zhongsyi@yahoo.com.sg

4953812



NRIC No. S8432651H



Date of issue
08-03-2013

63 BISHAN STREET 21 #10-02
SINGAPORE 57045

NRIC No: S8432651H

Date: 20/07/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B Motorcycles <= 200 cc 14 Sep 2006
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 26 Apr 2004

NP 428A



Spouse - Rina Wati (F)
Child - Chloe Loo (F)

Any
ly: No
ca: Yes

Total: 3



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2019-00000992 (Comprehensive - Executive Plan)

Car plate number: SLK3900H

Your name (As the policyholder): Loo Zhongyi Javier

Coverage start date: 16/01/2019

Coverage end date: 15/01/2020

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 20/12/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOO ZHONGYI JAVIER
 63 BISHAN STREET 21 #10-02
 SINGAPORE 574045

Estimate No: MC1900298
 Date: 11 Apr 2019
 Policy No: PNPV2019-00000992
 Veh Reg No: SLK3900H
 Make/Model: MAZDA MAZDA2
 SEDAN 1.5L SP

ATTN:

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 10/04/2019
 TP Veh Reg No: SHC7756X

Not within
 Resurvey B4 paint
 3 days

Estimate Repair Cost to Vehicle No :SLK3900H

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BOOT	BUC 1 PC	861.80	X ✓
2 REAR BOOT EMBLEM	1 PC	58.20	X
3 REAR BOOT MAZDA 2 LOGO	1 PC	67.90	X
4 REAR BOOT SKYACTIVE TECHNOLOGY	1 PC	77.60	X
5 REAR BOOT INNER LOCK	1 PC	190.90	X ✓
6 REAR BOOT INSULATOR CLIPS	10 PC	30.00	X
7 TAILAMP LH	1 PC	395.30	X
8 REAR BUMPER	1 PC	954.50	✓
9 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	45.60	X
10 REAR BUMPER CLIPS	15 PC	45.00	✓
11 END PANEL	1 PC	656.00	7X
12 END PANEL TOP GARNISH	1 PC	57.60	X
13 REAR EXHAUST PIPE	1 PC	1,026.80	X
14 REAR EXHAUST PIPE MOUNTING	3 PC	135.00	X
		4,602.20	
	Less 20%	920.44	3,681.76
Special Nett			
15 REVERSE SENSOR	2 PC	200.00	7 ✓
		200.00	200.00
LABOUR			
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
17 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	90.00	7X ++
18 TO REMOVE AND REINSTALL REVERSE CAMERA	1 PC	60.00	X
19 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	80.00	50/
20 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	X
21 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, REAR FENDER LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	440/
22 TO SPRAY REAR BOOT, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH	1 PC	1,000.00	7 600
		2,330.00	2,330.00

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting.
 • To display damaged parts during resurvey.
 • Parts price are subject to confirmation.
 • Third party liability is on a "without prejudice" basis.
 • Repairs are subject to approval.
 • Repairs are subject to approval and the repairer must be approved from Insurance Company.
 Repaired by Repairer.
 Signature
 Date

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LOO ZHONGYI JAVIER
63 BISHAN STREET 21 #10-02

SINGAPORE 574045

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/04/2019
TP Veh Reg No: SHC7756X

Estimate No: MC1900298
Date: 11 Apr 2019
Policy No: PNPV2019-00000992
Veh Reg No: SLK3900H
Make/Model: MAZDA MAZDA2
SEDAN 1.5L SP

Estimate Repair Cost to Vehicle No :SLK3900H

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 6,211.76
		Add GST @ 7%	434.82
		Total Amount Payable	S\$ 6,646.58

TOTAL: SINGAPORE DOLLAR SIX THOUSAND SIX HUNDRED FORTY SIX AND CENTS FIFTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

6336.24

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LOO ZHONGYI JAVIER
63 BISHAN STREET 21 #10-02

SINGAPORE 574045

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/04/2019
TP Veh Reg No: SHC7756X

Estimate No: MC1900298
Date: 16 Apr 2019
Policy No: PNPV2019-00000992
Veh Reg No: SLK3900H
Make/Model: MAZDA MAZDA2
SEDAN 1.5L SP

Estimate Repair Cost to Vehicle No :SLK3900H

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
SPARE PARTS			
1 REAR BOOT BUZZLE SENSOR	CM 1 PC	155.60 ✓	
		155.60	
	Less 20%	31.12	124.48
	Total		S\$ 124.48
	GST Amount		S\$ 8.71
	Total Amount Payable		S\$ 133.19

The above vehicle was surveyed by LKK - KENNETH on 16/04/2019

For AH LIM MOTOR COMPANY

AUTHORIZED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

16/4/19 10am
SURVEYOR COPY

M/S: LOO ZHONGYI JAVIER
63 BISHAN STREET 21 #10-02

SINGAPORE 574045

Estimate No: MC1900298
Date: 11 Apr 2019
Policy No: PNPV2019-00000992
Veh Reg No: SLK3900H
Make/Model: MAZDA MAZDA2
SEDAN 1.5L SP

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/04/2019
TP Veh Reg No: SHC7756X

Not Whgwh

Repair B4 paint

82229.08 3 days

*Lkl
Kenny*

Survey copy

Estimate Repair Cost to Vehicle No :SLK3900H

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BOOT	1 PC	<i>Bu</i> 861.80	<i>X</i>
2 REAR BOOT EMBLEM	1 PC	<i>nn</i> 58.20	<i>X</i>
3 REAR BOOT MAZDA 2 LOGO	1 PC	<i>nn</i> 67.90	<i>X</i>
4 REAR BOOT SKY ACTIVE TECHNOLOGY	1 PC	<i>nn</i> 77.60	<i>X</i>
5 REAR BOOT INNER LOCK	1 PC	<i>nn</i> 190.90	<i>X</i>
6 REAR BOOT INSULATOR GLIPS	10 PC	<i>nn</i> 30.00	<i>X</i>
7 TAILAMP LH	1 PC	<i>nn</i> 395.30	<i>X</i>
8 REAR BUMPER	1 PC	<i>Bu</i> 954.50	<i>X</i>
9 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	<i>nn</i> 45.60	<i>X</i>
10 REAR BUMPER CLIPS	15 PC	<i>nn</i> 45.00	<i>X</i>
11 END PANEL	1 PC	<i>nn</i> 656.00	<i>X</i>
12 END PANEL TOP GARNISH	1 PC	<i>nn</i> 57.60	<i>X</i>
13 REAR EXHAUST PIPE	1 PC	<i>Bu</i> 1,026.80	<i>X</i>
14 REAR EXHAUST PIPE MOUNTING	3 PC	<i>nn</i> 135.00	<i>X</i>
		4,602.20	
	Less 20%	920.44	3,681.76
Special Nett			
15 REVERSE SENSOR	2 PC	<i>Shan</i> 200.00	<i>7-photo</i> 200.00
		200.00	
LABOUR			
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>15/</i>
17 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	<i>nn</i> 90.00	<i>X</i>
18 TO REMOVE AND REINSTALL REVERSE CAMERA	1 PC	<i>nn</i> 60.00	<i>X</i>
19 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	80.00	<i>50/</i>
20 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	<i>nn</i> 60.00	<i>X</i>
21 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL TO KNOCK & REPAIR SPARE TYRE PANEL, REAR FENDER LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	<i>440/</i>
22 TO SPRAY REAR BOOT, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH	1 PC	<i>300</i> 1,000.00	<i>600/</i>
		2,330.00	2,330.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LOO ZHONGYI JAVIER
63 BISHAN STREET 21 #10-02

SINGAPORE 574045

ATTN:

Estimate No: MC1900298
Date: 11 Apr 2019
Policy No: PNPV2019-00000992
Veh Reg No: SLK3900H
Make/Model: MAZDA MAZDA2
SEDAN 1.5L SP

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/04/2019
TP Veh Reg No: SHC7756X

Estimate Repair Cost to Vehicle No :SLK3900H

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 6,211.76
		Add GST @ 7%	434.82
		Total Amount Payable	S\$ 6,646.58

TOTAL: SINGAPORE DOLLAR SIX THOUSAND SIX HUNDRED FORTY SIX AND CENTS FIFTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimunc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOO ZHONGYI JAVIER
63 BISHAN STREET 21 #10-02

SINGAPORE 574045

Estimate No: MC1900298
Date: 11 Apr 2019
Policy No: PNPV2019-00000992
Veh Reg No: SLK3900H
Make/Model: MAZDA MAZDA2
SEDAN 1.5L SP

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/04/2019
TP Veh Reg No: SHC7756X

Estimate Repair Cost to Vehicle No :SLK3900H

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT	1 PC	861.80	X
2 REAR BOOT EMBLEM	1 PC	58.20	X
3 REAR BOOT MAZDA 2 LOGO	1 PC	67.90	X
4 REAR BOOT SKY ACTIVE TECHNOLOGY	1 PC	77.60	X
5 REAR BOOT INNER LOCK	1 PC	190.90	X
6 REAR BOOT INSULATOR CLIPS	10 PC	30.00	X
7 TAIL LAMP LH	1 PC	395.30	X
8 REAR BUMPER	1 PC	954.50	X
9 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	45.60	X
10 REAR BUMPER CLIPS	15 PC	45.00	X
11 END PANEL	1 PC	656.00	X
12 END PANEL TOP GARNISH	1 PC	57.60	X
13 REAR EXHAUST PIPE	1 PC	1,026.80	X
14 REAR EXHAUST PIPE MOUNTING	3 PC	135.00	X
		4,602.20	
	Less 20%	920.44	3,681.76
Special Nett			
15 REVERSE SENSOR	2 PC	200.00	7-photo 200.00
LABOUR			
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
17 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	90.00	?
18 TO REMOVE AND REINSTALL REVERSE CAMERA	1 PC	60.00	X
19 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	80.00	50/
20 TO SPRAY ANTI-RUST GOATING ON AFFECTED AREAS.	1 PC	60.00	X
21 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, REAR FENDER LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	440/
22 TO SPRAY REAR BOOT, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH (pouch wheel away)	1 PC	700 1,000.00	7 600
		2,330.00	2,330.00

16/4/19 10am

Not within

Repair B4 paint

3 days

Like
1 month

Surveyor copy

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LOO ZHONGYI JAVIER
63 BISHAN STREET 21 #10-02

SINGAPORE 574045

ATTN:

Estimate No: MC1900298
Date: 16 Apr 2019
Policy No: PNPV2019-00000992
Veh Reg No: SLK3900H
Make/Model: MAZDA MAZDA2
SEDAN 1.5L SP

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/04/2019
TP Veh Reg No: SHC7756X

Estimate Repair Cost to Vehicle No :SLK3900H

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
SPARE PARTS			
1 REAR BOOT BUZZLE SENSOR	1 PC	155.60	
		155.60	
	Less 20%	31.12	124.48
	Total		S\$ 124.48
	GST Amount		S\$ 8.71
	Total Amount Payable		S\$ 133.19

The above vehicle was surveyed by LKK - KENNETH on 16/04/2019

For AH LIM MOTOR COMPANY

AUTHORIZED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALIZATION

M/S : LOO ZHONGYI JAVIER
63 BISHAN STREET 21 #10-02

SINGAPORE 574045

Claim No: MC1900298
No: MF1900367
Date: 21 Jun 2019
Policy No: PNPV2019-00000992
Veh Reg No: SLK3900H
Make/Model: MAZDA MAZDA2
SEDAN 1.5L SP

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/04/2019
TP Veh Reg No: SHC7756X

DRAFT FINALIZATION

Amended

Repair Cost to Vehicle No (For Finalization):SLK3900H

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT	1 PC	861.80	
2 REAR BOOT INNER LOCK	1 PC	190.90	
3 REAR BUMPER	1 PC	954.50	
4 REAR BUMPER CLIPS	15 PC	45.00	
5 REAR BOOT BUZZLE SENSOR	1 PC	155.60	
		2,207.80	
	Less 20%	441.56	1,766.24
Special Nett			
6 REVERSE SENSOR	2 PC	200.00	
		200.00	200.00
LABOUR			
7 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	15.00	
8 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	50.00	
9 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, REAR FENDER LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	440.00	
10 TO SPRAY REAR BOOT, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH	1 PC	600.00	
		1,105.00	1,105.00

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALIZATION

M/S : LOO ZHONGYI JAVIER
63 BISHAN STREET 21 #10-02
SINGAPORE 574045

Claim No: MC1900298
No: MF1900367
Date: 21 Jun 2019
Policy No: PNPV2019-00000992
Veh Reg No: SLK3900H
Make/Model: MAZDA MAZDA2
SEDAN 1.5L SP

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/04/2019
TP Veh Reg No: SHC7756X

Repair Cost to Vehicle No (For Finalization):SLK3900H

Description	Quantity	List Price	Amount
		SS	SS
		Total	SS 3,071.24
		Lump Sum Less 20%	-614.25
		Sub Total	SS 2,456.99
		Less Rounding	-6.99
		Lum Sum Repair	SS 2,450.00
		Less Excess	SS 0.00
		Amount Before GST	SS 2,450.00
		Add GST @ 7%	171.50
		Total Amount Payable	SS 2,621.50

TOTAL: SINGAPORE DOLLAR TWO THOUSAND SIX HUNDRED TWENTY ONE AND CENTS FIFTY ONLY

The above vehicle was surveyed by LKK - KENNETH on 16/04/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint Singapore 568047
AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19006669/Ktd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 01-07-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7756X	Veh. Inspected	SLK 3900H
Policy No.		Coverage (\$)	0.00
Claim No.	D19002514MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	15/04/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 2 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MM6DL2SAAGW191121	Colour	METALLIC PEARL WHITE
Odometer	45649	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R16	BRIDGESTONE	4 mm
L/H Front Tyre	195/60 R16	BRIDGESTONE	4 mm
R/H Rear Tyre	195/60 R16	BRIDGESTONE	5 mm
L/H Rear Tyre	195/60 R16	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/04/2019	Inspection Date	16/04/2019
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 3900H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	BUCKLED	861.80	861.80
1	REAR BOOT EMBLEM	NOT NECESSARY	58.20	-
1	REAR BOOT MAZDA 2 LOGO	NOT NECESSARY	67.90	-
1	REAR BOOT SKYACRIVE TECHNOLOGY	NOT NECESSARY	77.60	-
1	REAR BOOT INNER LOCK	DENTED	190.90	190.90
10	REAR BOOT INSULATOR CLIPS	NOT NECESSARY	30.00	-
1	TAILLAMP LH	SERVICEABLE	395.30	-
1	REAR BUMPER	BENT	954.50	954.50
2	REAR BUMPER SIDE RETAINERS LH & RH	SERVICEABLE	45.60	-
15	REAR BUMPER CLIPS	NECESSARY	45.00	45.00
1	END PANEL	TO REPAIR SEE LABOUR	656.00	-
1	END PANEL TOP GARNISH	SERVICEABLE	57.60	-
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	1,026.80	-
3	REAR EXHAUST PIPE MOUNTING	SERVICEABLE	135.00	-
1	REAR BOOT BUZZLE SENSOR (ADDITIONAL)	CRACKED	155.60	155.60
	LESS 20% DISCOUNT		-951.56	-441.56
			3,806.24	1,766.24
SPECIAL NETT ITEMS				
2	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00
LABOUR				
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	15.00
	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	NOT NECESSARY	90.00	-
	TO REMOVE AND REINSTALL REVERSE CAMERA.	NOT NECESSARY	60.00	-
	TO REMOVE AND REINSTALL/ REPLACE REAR BUMPER SENSORS.		80.00	50.00

Report Ref No. CS/FCI19006669/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	NOT NECESSARY	60.00	-
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, REAR FENDER LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF REPAIR OF END PANEL AND REAR EXHAUST PIPE.		1,000.00	440.00
	TO SPRAY REAR BOOT, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH.		1,000.00	600.00
			2,330.00	1,105.00
GRAND TOTAL			6,336.24	3,071.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CS/FC119006669/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.