

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LOO ZHONGYI JAVIER
63 BISHAN STREET 21 #10-02

SINGAPORE 574045

ATTN:

Estimate No: MC1900298
Date: 16 Apr 2019
Policy No: PNPV2019-00000992
Veh Reg No: SLK3900H
Make/Model: MAZDA MAZDA2
SEDAN 1.5L SP

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/04/2019
TP Veh Reg No: SHC7756X

Estimate Repair Cost to Vehicle No :SLK3900H

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
SPARE PARTS			
1 REAR BOOT BUZZLE SENSOR	CM 1 PC	155.60 ✓	
		155.60	
	Less 20%	31.12	124.48
	Total		S\$ 124.48
	GST Amount		S\$ 8.71
	Total Amount Payable		S\$ 133.19

The above vehicle was surveyed by LKK - KENNETH on 16/04/2019

For AH LIM MOTOR COMPANY

AUTHORIZED SIGNATURE

