

REPAIR ESTIMATE*

VEHICLE NO : SHD 4302L

DATE 15/4/2019 9:54

MAKE :

MODEL : HYUNDAI SONATA

L/Sum

FWD

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover — <i>cr</i>			\$ 538.80
	Front Bumper Bracket Top (LH) <i>3800</i>			\$ 22.40
	Headlamp (LH) X <i>su</i>			\$ 797.90
	Front Fender (LH) — <i>Rebuilt</i>			\$ 593.00
	Front Fender Shield (LH) — <i>tan</i>			\$ 86.00
	Front Fender Signal Lamp (LH) X <i>502</i>			\$ 45.40
	Front Fender Retainer X <i>su</i>			\$ 9.20
	Front Door (LH) — <i>Rebuilt</i>			\$ 1,345.00
	Front Door Protector (LH) — <i>on</i>			\$ 74.90
	Front Wheel Hub Cap (LH) — <i>Rebuilt</i>			\$ 145.00
	SUB TOTAL			\$ 3,657.60
	LESS 20%			\$ 731.52
	DISCOUNTED TOTAL			\$ 2,926.08
	Front Door Comfort Logo (LH) — <i>on</i>			\$ 75.00
	Labour Charge			<i>400</i>
	Panel Beating			\$ 800.00
	Spray Painting Charge			\$ 900.00 <i>600</i>
	Wiring Charge			\$ 30.00 X <i>na</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	FRT Wheel Alignment			\$ 120.00 X <i>na</i>
	TOTAL LABOUR			\$ 1,900.00
	ESTIMATE TOTAL			\$ 4,901.08
<i>Ka hui 10/14</i> <i>15/4/19 1400hr</i> <i>3 Apr.</i> <i>L/S</i> <i>After Repair photo</i> LKK Auto Consultants hence notify the Repairer of the following: • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "no fault" basis • No illegal modifications • Supplementary work is subject to the surveyor's approval Acknowledged by: _____ Signature: _____ Date: _____				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				