

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0478/2019/DY/GW
Date : 12-Apr-19

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no. : **GZ 3733 D**

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Lee Kok Hoong
Address : Blk 460 Ang Mo Kio Avenue 10
#02-1578
Singapore 560460
Telephone : (HP) + 65 83338381
Type of Claim : Third Party Claims
Policy No. : 18000136884
Vehicle No : **SMF 5167 J**
Model Code : Audi A3 SportBack 1.0 TF
Model / Year : Nov-18
Engine No : CHZ B22267
Chassis No : WAUZZZ8V6KA008700
Mileage : 4165
Date In : 12-Apr-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Apr-19
Place of Accident : Parking Lot No.3 at Ang Mo Kio-

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 5167 J

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy.	s/n \$ 360.00 ✓
2	To dismantle and renew front bumper, lhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1500 ✓ $600 \times 2.5 = 1500$
3	To rep-spray front bumper and lhs front fender.	\$ 1,500.00 1200 ✓
4	To carry out diagnostic check.	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 4,152.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 5167 J

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	
1	FRONT BUMPER <i>Replaced</i>	\$	1,698.00 ✓
2	FRONT BUMPER GUIDE SECTION-LH <i>new</i>	\$	35.00 ✕
3	FRONT BUMPER CLOSING ELEMENT-LH <i>new</i>	\$	270.00 ✕
4	FRONT FENDER-LH <i>Replaced</i>	\$	778.00 ✓
5	FRONT FENDER BRACKET-LH <i>?</i>	\$	43.00 ?
6	FRONT FENDER CLOSING ELEMENT-LH <i>new</i>	\$	56.00 ✕
7	FRONT WHEEL HOUSING LINER-LH <i>new</i>	\$	158.00 ✕
8	FRONT WHEEL HOUSING LINER ATTACHMENT PART-L <i>new</i>	\$	52.00 ✕
9	LED HEADLIGHT-LH <i>Replaced</i>	\$	5,029.00 ✓
10	LED HEADLIGHT POWER MODULE-LH <i>new</i>	2 \$	1,385.00 ✕
11	LED HEADLIGHT CONTROL UNIT-LH <i>new</i>	2 \$	1,015.00 ✕
12	LED WITH HEAT SINK-LH <i>new</i>	\$	666.00 ✕
13	LED HEADLIGHT -LIFT CYLINDER-LH <i>new</i>	\$	128.00 ✕
14	SUNDRIES <i>?</i>	\$	300.00 ?
TOTAL SPARE PARTS CHARGES		:	\$ 11,613.00
TOTAL LABOUR CHARGES			\$ 4,152.00
GRAND TOTAL			\$ 15,765.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 15/04/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 days

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant