

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6346 7400

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0207/19

DATE : 10-APR-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : M/S NORMAL STAINLESS STEEL PTE LTD
ADDRESS : 1005 TAI SENG AVENUE
#01-2578
S(534419)
TELEPHONE NO : 62808058/82910705

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : D18MTPV01016471
VEHICLE NO : SKW653P
MODEL CODE : FDRARBZJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0
ENGINE NO : MR20368545W
CHASSIS NO : SJNFBAJ11U1451453
MILEAGE : 73864 KM
DATE IN : 10/04/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 08/04/2019

- 9645 0084 elmur@tanchoy.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW653P

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR RADIATOR SUPPORT,RENEW FRT BUMPER	750.00	250
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME	600.00	200
3 ZZ/003	RENEW RH HEADLAMP AND FOCUS	48.00	/
TOTAL LABOUR CHARGES		1398.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW653P

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	FRT LICENCE PLATE <i>nn x</i>	FLP			60.00
2	SUNDRIES	NPN		20	50.00
3	RH FOGLAMP @ SGD \$ 258.00 EACH <i>nn x</i>	26150-8992B			258.00
4	RH HEADLAMP <i>SCR ✓</i>	26010-4EA0B	1617.00		
5	EMBLEM RAD GRILLE NISSAN <i>nn x</i>	62890-4EA0A	73.60		
6	GRILLE-RADIATOR <i>nnx</i>	62310-4EA1A	498.30		
7	LH STAY FRT BUMPER <i>nnx</i>	F2215-4EAMA	123.70		
8	RH STAY FRT BUMPER <i>nnx</i>	F2214-4EAMA	173.10		
9	UPPER REINFORCEMENT FRT BUMPER <i>nn x</i>	F2030-4ENMA	675.40		
10	UPPER ENERGY ABSORBER FRT BUMPER <i>nn x</i>	62090-4EA1B	195.70		
11	LOWER REINFORCEMENT FRONT BUMPER <i>nnx</i>	62030-4EJ1A	337.70		
12	LOWER ENERGY ABSORBER FRT BUMPER <i>nnx</i>	62090-4EA0C	62.20		
13	LH FOGLAMP GARNISH <i>nnx</i>	62257-4EA0C	74.70		
14	RH FOG LAMP GARNISH <i>nnx</i>	62256-4EA0C	74.70		
15	LH SIDE BRACKET FRONT BUMPER <i>nn x</i>	62223-4EA0A	20.90		
16	RH SIDE BRACKET FRT BUMPER <i>nnx</i>	62222-4EA0A	20.90		
17	CLIP FRONT BUMPER @ SGD\$1.20 EACH <i>nec ✓</i>	01553-05933	7.20		
18	FRONT BUMPER <i>DEF ✓</i>	62022-4EA0H	614.60		
SUB TOTAL			4569.70	0.00	368.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			913.94	0.00	0.00
GRAND TOTAL			3655.76	0.00	368.00
OVERALL TOTAL			4023.76		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKW653P

TOTAL LABOUR CHARGES	1398.00
TOTAL SPARE PARTS CHARGES	4023.76
GRAND TOTAL	5421.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Hwee Jie - LKK
18/4/19

P/P 3days.


hwee.jie@lkkauto.com
91803151

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: