

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9066 FAX: 6346 7400

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0207/19
DATE : 10-APR-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : M/S NORMAL STAINLESS STEEL PTE LTD
ADDRESS : 1005 TAI SENG AVENUE
#01-2578
S(534419)
TELEPHONE NO : 62808058/82910705

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : D18MTPV01016471
VEHICLE NO : SKW653P
MODEL CODE : FDRARBZJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0
ENGINE NO : MR20368545W
CHASSIS NO : SJNFBAJ11U1451453
MILEAGE : 73864 KM
DATE IN : 10/04/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 08/04/2019

- 9645 0084 elmur@tanchoong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW653P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR RADIATOR SUPPORT,RENEW FRT BUMPER	750.00	
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	600.00	
3	ZZ/003	RENEW RH HEADLAMP AND FOCUS	48.00	
		TOTAL LABOUR CHARGES	1398.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW653P

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	FRT LICENCE PLATE	FLP			60.00
2	SUNDRIES	NPN			50.00
3	RH FOGLAMP @ SGD \$ 258.00 EACH	26150-8992B			258.00
4	RH HEADLAMP	26010-4EA0B	1617.00		
5	EMBLEM RAD GRILLE NISSAN	62890-4EA0A	73.60		
6	GRILLE-RADIATOR	62310-4EA1A	498.30		
7	LH STAY FRT BUMPER	F2215-4EAMA	123.70		
8	RH STAY FRT BUMPER	F2214-4EAMA	173.10		
9	UPPER REINFORCEMENT FRT BUMPER	F2030-4ENMA	675.40		
10	UPPER ENERGY ABSORBER FRT BUMPER	62090-4EA1B	195.70		
11	LOWER REINFORCEMENT FRONT BUMPER	62030-4EJ1A	337.70		
12	LOWER ENERGY ABSORBER FRT BUMPER	62090-4EA0C	62.20		
13	LH FOGLAMP GARNISH	62257-4EA0C	74.70		
14	RH FOG LAMP GARNISH	62256-4EA0C	74.70		
15	LH SIDE BRACKET FRONT BUMPER	62223-4EA0A	20.90		
16	RH SIDE BRACKET FRT BUMPER	62222-4EA0A	20.90		
17	CLIP FRONT BUMPER @ SGD\$1.20 EACH	01553-05933	7.20		
18	FRONT BUMPER	62022-4EA0H	614.60		
SUB TOTAL			4569.70	0.00	368.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			913.94	0.00	0.00
GRAND TOTAL			3655.76	0.00	368.00
OVERALL TOTAL			4023.76		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKW653P

TOTAL LABOUR CHARGES 1398.00
TOTAL SPARE PARTS CHARGES 4023.76

GRAND TOTAL 5421.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.