4W Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770 280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773 315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSales) 64796624 (Motorrad)

Grand Total

4,080.50

GST REG. NO : M2 - 0020081 - X

ESTIMATE

15 APR 2019

Estimate No. : b1 50849 Page No. : 1 of 4 Date Estimated : 13/04/2019 Prepared By : Inthiran A/L Thurasamy - ESTIMATE REPAIR FOR -ACCOUNT -40000 Tay Chun Hui Kenneth Cash Sales - Service 81 Carlisle Road Singapore #06-01 Singapore 219647 REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE SLQ8452U 5H46348 25/07/2017 216d G TOURER 0 DESCRIPTION LKK Auto Consultants hence notify 850 1,275.00 Replace rear bumper and attachments. the Repairer of the following: · To resurvey before/after spray painting To display damaged part(s) during resurvey Painting rear bumper. Parts prices are subject to confirmation To check electrical wiring systems and lightings at the No illegal modification(s) is allowed rear section for proper function. Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Sundries. Acknowledged by Repairer Signature: Total Labour 2,570.00 Date: DESCRIPTION 1 PRIC VALUE SUPPORT 1 45.30 45.30 REAR BUMPER TRIM STRIP (CHROM) 1 108.40 108.40 REAR BUMPER PANEL PRIMED (LINES PDC 106) 1.029.50 1,029.50 SET MOUNTS PDC SENSOR REAR 60.35 60.35 Total Parts 1,243.55 / Uninsured losses / Direct Settlement Rean No. 2,570.00 Labour 1 **Authorised Date** Time 1,243.55 Parts RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Labour 2 0.00 Surveyor's E-mail Excess 0.00 No. of Working Days Recommend Total GST @ 7% 266.95

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **