

4W Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

15 APR 2019

Estimate No. : b1 50849
Date Estimated : 13/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Tay Chun Hui Kenneth
81 Carlisle Road
#06-01

Singapore 219647

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ8452U	5H46348	25/07/2017	216d G TOURER	0

DESCRIPTION

Replace rear bumper and attachments.

Painting rear bumper.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Labour 1:

VALUE

850 1,275.00

934 1,038.00

150 177.00

40 80.00

80

2,570.00

DESCRIPTION

SUPPORT

REAR BUMPER TRIM STRIP (CHROM) cut

REAR BUMPER PANEL PRIMED (LINES PDC) dx

SET MOUNTS PDC SENSOR REAR ? xsm

QTY PRIC

1 45.30

1 108.40

1 1,029.50

1 60.35

VALUE

45.30

108.40

1,029.50

60.35

Total Parts :

1,243.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. <u>03/05/19 @ 1125</u>	Claim No. _____
Quoted Time <u>9:00 AM</u>	Excess \$S _____
Surveyor's Name <u>Rashid</u>	Sign _____
Surveyor's Tel <u>9000068</u>	Authorized Yes / No _____
Authorized Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M. Yes / No	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3 days</u>	

Labour 1	:	2,570.00
Parts	:	1,243.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	266.95
Grand Total	:	4,080.50

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50849
Date Estimated : 13/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No.:

REPAIR FOR -
Tay Chun Hui Kenneth
81 Carlisle Road
#06-01

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 219647

REGN.NO.	CHASSIS NO.	REGN.DATE	MODEL	MILEAGE
SLQ8452U	5H46348	25/07/2017	216d G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00
--	--------	--	--------

To spray paint rear bumper	934.00		934.00
----------------------------	--------	--	--------

To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00
--	--------	--	--------

Sundries	80.00		80.00
----------	-------	--	-------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM STRIP (CHROM)	108.40	1.00		108.40
REAR BUMPER PANEL PRIMED (LINES PDC)	1,029.50	1.00		1,029.50

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,137.90
Total Labour & Parts :	3,151.90
Deduction for Excess :	
Total Repair Costs less Excess:	3,151.90
GST @7%:	220.63
Grand Total :	3,372.53