



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

*not authorized
 later*

15/4/2019

REG NO. : SLK 964 T
 MAKE/MODEL : BMW 535i

*2/5 @ 5000
 50%
 the photo attached
 16/4/19*

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION		AMT(\$)
	<u>LIST ITEMS</u>		
1	Rear boot lid	\$ 27	1,658.00 X
2	Rear boot lamps	\$ 17	780.00 X
1	Rear boot lock	\$ 27	272.50 X
1	Rear boot logo	\$ 17	79.00 X
1	Rear boot rubber	\$ 17	225.00 X
1	Rear boot "535i" emblem	\$ 17	89.50 X
1	Rear boot "M" emblem	\$ 17	66.70 X
2	Rear taillamps <i>665</i>	\$ n/scre	1,330.00 12c
1	Rear end panel	\$ 17	1,018.50
1	Rear end panel inner garnish	\$ 17	289.00
1	Rear bumper	Total \$ 175	1,950.00
1	Rear bumper inner pad	\$ 17	268.00
1	Rear bumper inner frame garnish	\$ 17	335.00
1	Rear bumper lower diffuser	\$ 17	785.00
2	Rear bumper reflectors	\$ 17	230.00 X
1	Rear bumper reinforcement	\$ 32	685.00
2	Rear bumper reinforcement stays	\$ 17	340.00 X
2	Rear bumper side retainers	\$ 17	279.90 X
4	Rear bumper PDC sensors <i>215</i>	\$ 364	1,436.00 12c
1	Control module for park assistant kit	\$ 17	345.00 X
1	Rear exhaust silencer	\$ 17	1,980.00 X
4	Rear exhaust mountings	\$ 17	180.00 X
		\$	14,622.10
		Less 5%	731.11
		\$	13,891.00

*50%
 Less 5%*

*6210.50
 50%
 3105.25*

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	\$	60.00	✓
1	Rear sticker (1 set)	\$	2,000.00	300
		\$	<u>2,060.00</u>	

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$	180.00	80
3	To remove and refit rear reverse sensor.	\$	150.00	50
4	To transfer boot lid mechanism and wiring assembly.	\$	80.00	X
5	To remove, refit doors fittings & replace damaged parts, transfer all fittings to new door.	\$	180.00	X
6	To apply undercoating.	\$	150.00	30
7	Panel beating.	\$	1,500.00	680
8	To re-spray painting on the affected areas.	\$	1,400.00	680
		\$	<u>3,720.00</u>	

GRAND TOTAL :

\$ 19,671.00

7788-97
 402
 6259

P-3105-25
 S.N-360
 Color-1540
 5005-25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: