



# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
#08-1339 Singapore 470130  
Tel: 9450 7920  
\* zoomautowerks@gmail.com

not Admit  
alar

16 April 2019

2/5 \$13,000

15/4/19

1 day.

REG NO.: SKE 8400 U  
MAKE/MODEL: MINI COOPER

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

| QTY | DESCRIPTION                           | AMT(\$)            |
|-----|---------------------------------------|--------------------|
|     | <u>LIST ITEMS</u>                     |                    |
| 1   | Rear windscreen moulding              | \$ per 79.50       |
| 1   | Rear tailgate                         | \$20/serf 935.50   |
| 2   | Rear tailgate dampers                 | \$ 11 230.00 X     |
| 1   | Rear tailgate inner board             | \$ 11 285.00       |
| 1   | Rear tailgate lock catch              | \$ 11 68.00        |
| 1   | Rear tailgate lock                    | \$ 11 115.00       |
| 1   | Rear tailgate logo                    | \$ rer 50.00       |
| 1   | Rear tailgate rubber                  | \$ 11 155.00 X     |
| 1   | Rear tailgate "COOPER" emblem         | \$ rer 50.00       |
| 1   | Rear taillamp -L/H                    | \$ cm 325.00       |
| 1   | Rear taillamp chrome rim -L/H         | \$ scr 85.30       |
| 1   | Rear end panel                        | \$ 1 550.00 X      |
| 1   | Rear end panel inner garnish          | \$ 11 195.00 X     |
| 1   | Rear end panel air vent               | \$ 11 95.00 X      |
| 1   | Rear bumper                           | \$ 7.5 886.00      |
| 1   | Rear bumper inner sponge              | \$ nt 88.50 X      |
| 1   | Rear bumper lower garnish             | \$ DW 321.40       |
| 1   | Rear bumper reinforcement             | \$ Ber 596.00      |
| 1   | Rear bumper clip (1 set)              | \$ rer 45.00       |
| 2   | Rear bumper side retainers            | \$ 26.30 52.60 100 |
| 1   | Rear bumper undercover                | \$ 70.1 225.00     |
| 1   | Rear third brake lamp                 | \$ cm 245.00       |
| 1   | Rocker panel side garnish             | \$ 11 445.00 X     |
| 1   | Rear exhaust silencer                 | \$ 11 785.00 X     |
| 2   | Rear exhaust mountings                | \$ 11 76.00 X      |
| 1   | Rear exhaust chrome tail pipe         | \$ 11 195.00 X     |
| 1   | Rear fender -R/H                      | \$ 60.50 900.00    |
| 1   | Rear fender inner shield              | \$ 70.1 130.00     |
| 1   | Rear fender inner shield clip (1 set) | \$ rer 45.00       |
| 1   | Rear fender inner trim                | \$ 11 195.00 X     |
| 1   | Rear fender wheel arch garnish        | \$ 7.5 165.00      |
| 1   | Rear fender quarter glass moulding    | \$ rer 86.00       |
| 1   | Rear wheel rim                        | \$ 800 800.00 X    |
| 1   | Rear wheel hub                        | \$ 27.2 333.30     |
| 1   | Rear shock absorber                   | \$ 11 198.50       |
| 1   | Rear stay arm - top                   | \$ Ber 172.90      |
| 1   | Rear stay arm -lower                  | \$ Ber 161.40      |
| 1   | Rear trailing arm with bearing        | \$ cm 636.50       |
|     |                                       | \$ 11,002.40       |

LIST ITEMS

|   |                                     |         |          |              |   |
|---|-------------------------------------|---------|----------|--------------|---|
| 1 | Front bonnet                        | 20/9/11 | \$       | 1,150.00     | ✓ |
| 1 | Front bonnet lock                   |         | \$       | 145.00       | ✓ |
| 1 | Front bonnet chrome moulding        |         | \$       | 155.00       | ✓ |
| 1 | Front bonnet logo                   |         | \$       | 90.00        | ✓ |
| 2 | Front headlamps                     | 1455    | \$       | 2,910.00     | ✓ |
| 2 | Front headlamp chrome rims          | 285     | \$       | 570.00       | ✓ |
| 1 | Front grille assy                   |         | \$       | 425.00       | ✓ |
| 1 | Front bumper                        |         | \$       | 755.00       | ✓ |
| 1 | Front bumper centre pad             |         | \$       | 195.00       | ✓ |
| 1 | Front bumper centre grille          |         | \$       | 145.00       | ✓ |
| 2 | Front bumper fog lamps              | 255     | \$       | 510.00       | ✓ |
| 1 | Front bumper lower garnish          |         | \$       | 360.00       | ✓ |
| 2 | Front bumper side arch garnishes    | 285     | \$       | 570.00       | ✓ |
| 1 | Front bumper reinforcement          |         | \$       | 440.00       | ✓ |
| 2 | Front bumper side retainers         | 58      | \$       | 116.00       | ✓ |
| 1 | Front bumper centre chrome moulding |         | \$       | 285.00       | ✓ |
| 1 | Front support panel                 |         | \$       | 750.00       | ✓ |
| 1 | Air con condenser                   |         | \$       | 800.00       | ✓ |
| 1 | Radiator                            |         | \$       | 785.00       | ✓ |
|   |                                     |         | \$       | 22,158.40    |   |
|   |                                     |         | Less 10% | \$ 2,215.84  |   |
|   |                                     |         |          | \$ 19,942.56 |   |

13631.6  
102  
1268.44

SPECIAL NETT ITEMS

|   |                                |      |    |        |     |
|---|--------------------------------|------|----|--------|-----|
| 1 | Rear windscreen sealant        |      | \$ | 80.00  | 40  |
| 1 | Rear tyre                      | 1200 | \$ | 400.00 | 50% |
| 1 | Front number plate with holder |      | \$ | 50.00  | 40  |
|   |                                |      | \$ | 530.00 |     |

180

S/N LABOUR CHARGES

|    |                                                                              |  |    |          |      |
|----|------------------------------------------------------------------------------|--|----|----------|------|
| 1  | To check wiring and reset headlamps focussing.                               |  | \$ | 80.00    | 30   |
| 2  | To remove, refit, replaced damaged lamps and check up rear electrical wiring |  | \$ | 80.00    |      |
| 3  | To remove and refit inner garnishes.                                         |  | \$ | 180.00   | 80   |
| 4  | To transfer rear tailgate mechanism and wiring assembly.                     |  | \$ | 120.00   | 60   |
| 5  | To remove and refit rear undercarriage.                                      |  | \$ | 300.00   | 120  |
| 6  | To conduct wheel alignment.                                                  |  | \$ | 180.00   | 60   |
| 7  | To remove, replace air-con condenser and conduct leakage test.               |  | \$ | 180.00   | 100  |
| 8  | To remove and refit rear windscreen glass.                                   |  | \$ | 180.00   | 120  |
| 9  | To remove and refit quarter glass to assist repair.                          |  | \$ | 150.00   | 80   |
| 10 | To remove, refit and replace exhaust silencer and mountings.                 |  | \$ | 150.00   | ✓    |
| 11 | To apply undercoating.                                                       |  | \$ | 200.00   | 100  |
| 12 | Panel beating.                                                               |  | \$ | 2,200.00 | 1400 |
| 13 | To re-spray painting on the affected areas.                                  |  | \$ | 2,000.00 | 1700 |
|    |                                                                              |  | \$ | 6,000.00 |      |

3850

16298.44

13088

\$ 26,472.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Particulars are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PAGE 2 OF 2

Acknowledged by Repairer

Signature: