



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

not Adm
dbr

2/5 @ 13,000
15/4/19
1 day.

16 April 2019

REG NO.: SKE 8400 U
MAKE/MODEL: MINI COOPER

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding	\$ per 79.50
1	Rear tailgate	\$ 20/berf 935.50
2	Rear tailgate dampers	\$ 11 230.00 X
1	Rear tailgate inner board	\$ 11 285.00 X
1	Rear tailgate lock catch	\$ 11 68.00 X
1	Rear tailgate lock	\$ 11 115.00 X
1	Rear tailgate logo	\$ per 50.00
1	Rear tailgate rubber	\$ 11 155.00 X
1	Rear tailgate "COOPER" emblem	\$ per 50.00
1	Rear taillamp -L/H	\$ cm 325.00
1	Rear taillamp chrome rim -L/H	\$ sch 85.30
1	Rear end panel	\$ 11 550.00 X
1	Rear end panel inner garnish	\$ 11 195.00 X
1	Rear end panel air vent	\$ 11 95.00 X
1	Rear bumper	\$ 7.5 886.00
1	Rear bumper inner sponge	\$ nt 88.50 X
1	Rear bumper lower garnish	\$ 0.5 321.40
1	Rear bumper reinforcement	\$ Buf 596.00
1	Rear bumper clip (1 set)	\$ per 45.00
2	Rear bumper side retainers	\$ 26.30 52.60 1pc
1	Rear bumper undercover	\$ 79.1 225.00
1	Rear third brake lamp	\$ cm 245.00
1	Rocker panel side garnish	\$ 11 445.00 X
1	Rear exhaust silencer	\$ 11 785.00 X
2	Rear exhaust mountings	\$ 11 76.00 X
1	Rear exhaust chrome tail pipe	\$ 11 195.00 X
1	Rear fender -R/H	\$ 500 900.00
1	Rear fender inner shield	\$ 100 130.00
1	Rear fender inner shield clip (1 set)	\$ per 45.00
1	Rear fender inner trim	\$ 11 195.00 X
1	Rear fender wheel arch garnish	\$ 7.5 165.00
1	Rear fender quarter glass moulding	\$ per 86.00
1	Rear wheel rim	\$ 800 800.00 X
1	Rear wheel hub	\$ 272 333.30
1	Rear shock absorber	\$ 198.50
1	Rear stay arm - top	\$ 172.90
1	Rear stay arm -lower	\$ 161.40
1	Rear trailing arm with bearing	\$ cm 636.50
		\$ 11,002.40

LIST ITEMS

1	Front bonnet	20/9/11	\$	1,150.00	✓
1	Front bonnet lock		\$	145.00	✓
1	Front bonnet chrome moulding		\$	155.00	✓
1	Front bonnet logo		\$	90.00	✓
2	Front headlamps	1455	\$	2,910.00	✓
2	Front headlamp chrome rims	285	\$	570.00	✓
1	Front grille assy		\$	425.00	✓
1	Front bumper		\$	755.00	✓
1	Front bumper centre pad		\$	195.00	✓
1	Front bumper centre grille		\$	145.00	✓
2	Front bumper fog lamps	255	\$	510.00	✓
1	Front bumper lower garnish		\$	360.00	✓
2	Front bumper side arch garnishes	285	\$	570.00	✓
1	Front bumper reinforcement		\$	440.00	✓
2	Front bumper side retainers	58	\$	116.00	✓
1	Front bumper centre chrome moulding		\$	285.00	✓
1	Front support panel		\$	750.00	✓
1	Air con condenser		\$	800.00	✓
1	Radiator		\$	785.00	✓
			\$	22,158.40	
			Less 10%	2,215.84	
			\$	19,942.56	

13631.6
102
1268.44

SPECIAL NETT ITEMS

1	Rear windscreen sealant		\$	80.00	✓
1	Rear tyre	17200	\$	400.00	✓
1	Front number plate with holder		\$	50.00	✓
			\$	530.00	

180

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focussing.		\$	80.00	✓
2	To remove, refit, replaced damaged lamps and check up rear electrical wiring		\$	80.00	✓
3	To remove and refit inner garnishes.		\$	180.00	✓
4	To transfer rear tailgate mechanism and wiring assembly.		\$	120.00	✓
5	To remove and refit rear undercarriage.		\$	300.00	✓
6	To conduct wheel alignment.		\$	180.00	✓
7	To remove, replace air-con condenser and conduct leakage test.		\$	180.00	✓
8	To remove and refit rear windscreen glass.		\$	180.00	✓
9	To remove and refit quarter glass to assist repair.		\$	150.00	✓
10	To remove, refit and replace exhaust silencer and mountings.		\$	150.00	✓
11	To apply undercoating.		\$	200.00	✓
12	Panel beating.		\$	2,200.00	✓
13	To re-spray painting on the affected areas.		\$	2,000.00	✓
			\$	6,000.00	

2820
16298.44
13038

\$ 26,472.56

Wish Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Repairs are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PAGE 2 OF 2

Acknowledged by Repairer

Signature:

Date: