

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 17 Apr 2019

Preliminary Advice

Insured Vehicle No : FBM8948X

TP Vehicle No : SMJ7213A

Make : MERCEDES-BENZ GLA45 AMG

Date of Inspection : 16/04/2019

Inspection At : MBM Wheelpower Pte Ltd (HQ)
160 Sin Ming Drive #06-02, Sin Ming AutoCity
Singapore 575722

Accident Date : 10/04/2019

Assignment Date : 15/04/2019

Est. Duration of Repair : 4 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,105.50
Revised Amount	:S\$	4,900.20
Check Items (Estimated)	:S\$	1,529.60
Total	:S\$	6,429.80

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.