

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 18 Apr 2019

## Preliminary Advice

Insured Vehicle No	:	GBH2310B		
TP Vehicle No	:	SJT1493E	Accident Date	: 15/04/2019
Make	:	Volkswagen Golf GTI 2.0L AT 5DR	Assignment Date	: 15/04/2019
Date of Inspection	:	16/04/2019	Est. Duration of Repair	: 9 days
Inspection At	:	Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre Singapore 575718		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 16,966.41
Revised Amount	:	S\$ 15,023.74
Check Items (Estimated)	:	S\$ 815.32
Total	:	S\$ 15,839.06
Lump Sum Repair	:	S\$

### **Total Loss Consideration**

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

### Remarks

- (  ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.  
Kindly let us have your authorisation.
- (  ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (  ) Other comments : TP : WP