



Case Details

Case Reference Number : TAX/04/19/2049
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB185U

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6483-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd
 Accident Date and Time : 12/04/2019 07:50 PM
 Vehicle Age(In Months) : 55

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace ▾	
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace ▾	
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	1	128.77	Replace ▾	
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Check ▾	
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair ▾	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	25.00	45.00	Replace	1	45.00	Replace ▾	
One Time Key In	Main			HINGE LOWER LHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0	Not Given ▾	
One Time Key In	Main			HINGE UPPER LHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Not Given ▾	
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Given ▾	
One Time Key In	Main			MIRROR ASSY, RH	1	1,307.10	1,307.10	25.00	980.32	Replace	0	0	Not Given ▾	
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Given ▾	

Total Spare Part Cost 3,085.42

Lump Sum Discount (%) 20.00

Final Spare Part Cost 2,468.34

Surveyor Total 755.24

Lump Sum Dis (%) 20

Final Sur Total 604.19

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MIRROR LAMP RH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Given	
One Time Key In	Main			QUARTER GLASS FRT/RH	1	234.90	234.90	25.00	176.18	Replace	0	0	Not Given	
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Given	
Total Spare Part Cost									3,085.42	Surveyor Total			755.24	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									2,468.34	Final Sur Total			604.19	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	400	
Total:			845.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
2	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
3	Main	TO RESPRAY VIEW MIRROR	180.00	0	
Total:			936.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
3	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
4	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
5	Main	TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	0	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
Total:			1,021.88	316.88	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
7	Main	TO REMOVE AND REFIT WIRE HARDESS	120.00	0	
8	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,021.88	316.88	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,468.34	604.19
Total Labour Cost	845.00	400.00
Total Spray Painting	936.00	400.00
Other	1,021.88	316.88
Overall Total	5,271.22	1,721.07
Lump Sum Repair Option	☒	☒
Lump Sum Total	5,250.00	1,700.00
Surveyor Approved Amount		1,700.00
No of Repair Days*	6	3
Remarks	-	L/S REPAIR, PHOTO AFTER PAINT.
Surveyor Name		Hwee jie
Signature		
Survey Date	16/04/2019	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: