

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0487/2019/DY
Date : 15-Apr-19

Vehicle NOT IN workshop.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Daswani Pooja Ishwar
Address : 68 Bayshore Road
Singapore 469986
Telephone : HP +65 90061921
Type of Claim : Own Damage Claims
Policy No. : 1900017227
Vehicle No : **SMJ 0794 K**
Model Code : Audi A4 SEDAN 2.0 TFSI
Model / Year : Feb-19
Engine No : CVK 071519
Chassis No : WAUZZZF4XKN000733
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Apr-19
Place of Accident : Traffic Junction at Bayshore Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 0794 K

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor headlight washer assy and front parking aid.	s/n \$ 480.00 ✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 1250.
3	To respray front bumper and rhs front fender.	\$ 1,600.00 1100
4	To renew rhs front rim and carry out wheel alignment.	s/n \$ 280.00 ✓
5	To carry out diagnostic check.	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 4,652.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 0794 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER COVER <i>Distabed</i>	\$ 1,755.00	✓
2	FRONT BUMPER FIXING PARTS <i>2</i>	\$ 531.00	✓
3	FRONT BUMPER SECURING STRIP <i>1pc</i>	\$ 57.00	✓
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>1pc</i>	\$ 171.00	✓
5	FRONT BUMPER AIR GUIDE - RH ?	\$ 67.00	?
6	FRONT BUMPER SENSOR ?	\$ 208.00	?
7	FRONT BUMPER SENSOR SEAL ?	\$ 14.00	?
8	FOAM FILLER PIECE <i>2</i>	\$ 101.00	✓
9	BUMPER CARRIER <i>1pc</i>	\$ 674.00	✓
10	FRONT BUMPER GUIDE SECTION - RH <i>2pc</i>	\$ 31.00	✓
11	FRONT FENDER - RH <i>Distabed</i>	\$ 643.00	✓
12	FRONT FENDER ATTACHEMENT PARTS ?	\$ 183.00	?
13	FRONT FENDER CLOSING ELEMENT <i>1pc</i>	\$ 27.00	✓
14	FRONT FENDER BRACKET <i>2pc</i>	\$ 29.00	✓
15	FRONT FENDER DEFORMATION ELEMENT <i>1pc</i>	\$ 42.00	✓
16	FRONT FENDER RIVET <i>1pc</i>	\$ 17.00	✓
17	FRONT FENDER BRACKET - LH FRONT AND REAR <i>Front 2pc</i>	\$ 30.00	15 ✓
18	FRONT FENDER BRACE <i>2pc</i>	\$ 100.00	✓
19	FRONT WHEEL HOUSING LINER - RH <i>torn</i>	\$ 202.00	✓
20	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$ 211.00	?
SUB - TOTAL SPARE PARTS		\$ 5,093.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 0794 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT WHEEL SPOILER - RH <i>cancel</i>	\$ 66.00	✓
22	FRONT WHEEL SPOILER TRIM - RH ?	\$ 29.00	?
23	FRONT FENDER STONE CHIP GUARD - RH <i>re</i>	\$ 46.00	✓
24	FRONT FENDER COVER TRIM - RH ?	\$ 28.00	✓
25	FRONT FENDER TOP COVER - RH <i>re</i>	\$ 19.00	✓
26	LED HEADLIGHT - RH <i>let</i>	\$ 7,861.00	✓
27	LED HEADLIGHT POWER MODULE	\$ 641.00	+
28	LED HEADLIGHT CONTROL UNIT	\$ 634.00	+
29	LED HEADLIGHT VENTILATION HOSE <i>re u</i>	\$ 29.00	+
30	LED HEADLIGHT LIFT CYLINDER - RH	\$ 180.00	+
31	FRONT TYRE RIM - RH <i>let</i>	TBC	-
32	FRONT AIR GUIDE - RHS ?	\$ 333.00	?
33	SUNDRIES ?	\$ 600.00	?

TOTAL SPARE PARTS : \$ 15,559.00

TOTAL LABOUR CHARGES : \$ 4,652.00

GRAND TOTAL : \$ 20,211.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lj*
Surveyed Date : *16/04/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, OS Rgn*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant