

INS. CASE OWNER:

CC4 / AXA160

8689

1/20/16

IDAC:

CL

ASSIGNMENT

Surveyor:

KENNETH

DOI:

04-10-16

Date / Time:

04/10/16

Registered in Merimen:

30/9/16

Pre-assign / CCU / FTE

SJR 9536 Z

Claim No.:

C0402054

Policy No.:

P1136112

Make / Model:

HONDA STREAM.

Place of Accident:

M'SIA HIGHWAY



Insured Vehicle No.:

106 / 106 K106A

Name of Insured:

HP:

42311341

Insured Tel No.:

D.O.A.:

18/9/16

Excess Sec II : \$5

Is driver the owner?

(YES / NO)

Nature of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

JPT 5831



INSRS:

WSP:

Tel:

Liability:

RMKS:

Motoexcel
make &
model.

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
11/10/16	Non-Reporting ltr (1st):	
20/10/16	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	23/11/16
	After call ltr to OI:	
11/10/16	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☐
	Final Repair Bill:	☒
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☒
	Others:	☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days) Reduction:

%

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Final Liability:

%

20

(Agreed / Assessed) BOLA S/N No.:

ML

if NO or B 28. Ass. Lia. ☒

Repair Cost:

11700.00

\$5

2340.00 (RM)

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

2400 RM 150 x 8 days

Loss of Income (LOI):

\$5

1 x days

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5

2.00 (sen dollar)

Medical:

\$5

(e.g. Tow/ Independent)

Disbursement:

\$5

Legal Cost

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$5

2+2580 (RM) = \$853.40

Email ☐Call ☐

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

\$5

853.40

Name 1:

Heng Lai Huat Motor Workshop

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

06/10/16 - SGOMYR = 2.017

Surveyor:

ASSIGNMENT

From: _____ Date: 4/10/2016

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: JPT 5831
at Workshop m/s 1 King St Auto Excel 291 1kg
of Blk 19 #01-05 Simming Trd Est

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8-8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: JPT 5831 Yr Regn: 11, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Proton Alexis c.c. 1561

Colour: M. Gold A/C: Insured / Std / NI / NA

Sp. Reading: 54481 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PLIF86YDREF122373

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45 ER17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

R/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 18/9/16

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 4/10/16

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
5/10	194 p.m. to Corhouse
	Usg 11700, 7 days
	Qel @ 17898.00, 60.1%

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC4/AXA16018689/Kza3	
8 SHENTON WAY #27-01SINGAPORE 068811		Date : 04-10-2016	
		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJR 9536Z	Veh. Inspected	JPT 5831
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/10/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/09/2016	Inspection Date	04/10/2016
Survey held at	AUTOEXCEL ENGINEERING PTE LTD		
Repairer	HENG LAI HUAT MOTOR WORKSHOP		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

AmGeneral Insurance Berhad 6872179

**POLIS DIRAJA MALAYSIA**
REPOt POLIS

Balai : TRAFIK KULAIJAYA
Daerah : KULAIJAYA
Kontinjen : JOHOR
No Repot : TRAFIK BATU PAHAT/012409/16
Tarikh : 18/09/2016
Waktu : 2224 PM
Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R111237
No Repot Bersangkut : TRAFIK BATU PAHAT/012405/16

Butir-butir Penerima Repot

Nama : ABANG AMIRUL ARRIFFIN BIN ABG. ABDILLAH.

No Personel : R196949

Pangkat : KONST/P

Butir-butir Jurubahasa (Jika Ada)

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : SELVARAJAH A/L SELLAMUTHO

No K/P (Baru) : 640507015427

No Polis/Tentera : A0114670

No Paspot : ---

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 07/05/1964

Umur : 52 tahun 4 bulan

Keturunan : India

Warganegara : Malaysia

Pekerjaan : SWASTA

Alamat Tempat Tinggal : NO 6247 JALAN NURI 14 BANDAR PUTRA 81000 JOHOR BAHRU JOHOR MALAYSIA

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 016-7962843

Emel : ---

Pengadu Menyatakan:-

PADA 18/09/2016 JAM LEBIH KURANG 1944 HRS SAYA MEMANDU MPV NO.JPT5831 JENIS P/EXORA DARI IPOH HENDAK KE JOHOR BAHRU. APABILA SAMPAI DIO KM 96 LEBUH RAYA UTARA SELATAN ARAH SELATAN, TIBA-TIBA DATANG SEBUAH M/KAR NO.SJR9536Z JENIS H/STREAM DARI ARAH BELAKANG TELAH MELANGGAR BAHAGIAN BELAKANG MPV SAYA. SAYA TIDAK CEDERA. KEROSAKAN BAHAGIAN BELAKANG MPV BUMPER, BONET, SENSOR, MUDGUARD KIRI/KANAN DAN LAIN-LAIN KEROSAKAN BELUM PASTI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada) :

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak : R196949 | 18/09/2016 10:28:19 PM

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN

NO. PENDAFTARAN: **JPT5831**

No. Sn B: **5569008**

YPMXKQ

30/11/13

641227000143
(MAL)

Nama Pemunya
Berdaftar

JOSOPHIENE A/P SINATHAMBY

Alamat

**NO 6247 JALAN NURI 14 BANDAR PUTRA
81000 KULAI JOHOR**

No. Enjin

S4PHTU7374

B.O.M/B.G.X

No. Chasis

PL1F28YDREF122373

B.T.T.

Buatan

PROTON

Berat Kerb

Nama Model

EXORA FL 1.6L CVT

B.T.M

Kapasiti Enjin

1581 S.P

B.G.1

Bahan Bakar

PETROL

B.G.2

Warna

COKLAT

B.G.3

Kelas Kegunaan

PERSENDIRIAN-MOTOKAR INDIVIDU

B.G.4

Jenis Badan

MOTOKAR PELBAGAI UTILITI

B.G.5

Tahun Dibuat

2013

B.G.6

Tarikh Pendaftaran

28/11/2013

B.G.7

Status Pemunya

PERSENDIRIAN

B.G.8

Muatan Tempet

7

B.G.9

Duduk

7

B.G.10

Kadar Lesen

7

B.G.11

Kenderaan Motor

6 bulan

12 bulan

B.G.12

RM45.00

RM90.00

Perakuan Pendaftaran ini dikeluarkan

oleh Pengerah JPJ Negeri **JPJ NEGERI JOHOR**

Tandatangan Pemunya Berdaftar

UNTUK KEGUNAAN PEJABAT

PEMANGKUAN TEMPATAN

HWAMILIK DITUNTUT OLAH: MALAYAN BANKING BERHAD NO 3101 FEB702013P0700

NOTA PENTING

1. Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengerah Jabatan Pengangkutan Jalan (JPJ).
2. Semak butiran kenderaan di muka ini dan laporkan dengan segera kepada Pengerah JPJ jika terdapat sebarang perubahan.
3. Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membariskan lesen 60 hari sebelum tempohnya tamat.
4. Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengerah JPJ sekiranya kenderaan anda tidak berlesen.
5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJKBUPK3A kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran lesen bilik disertipulatkan dan kenderaan telah didaftarkan dengan nama pemilik baru.
7. Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

...CLAIM SUBFOLDER...(New Assignment)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Sep 2016		04 Oct 2016 09:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LEE KOK KIONG, NRIC: S8080866F, Tel: +6592311341, Email: 8911goo@gmail.com		
Main Claimant:	-		
Vehicle Reg. No.:	JPT5831	Date of Loss:	18/09/2016 19:00 - :59
Claim Type:	TP / C0402054	Policy/Cover Note No.:	P1636112 (Comprehensive)
Vehicle Reg. No. (Insured):	SJR9536Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Autoexcel Engineering Pte Ltd (HQ) Blk 19 Sector A #01-05, Sin Ming Industrial Estate, 575677 Sin Ming - Tel:		
Handling Insurer:	AXA Insurance Singapore Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/10/2016]		
Adj Asg. Remarks:	XS NIL		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AXA_SG (04/10/2016): C0402054/P1636112 - NON MCF
- AXA_SG (04/10/2016): New TP Assignment - C0402054/P1636112

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

4/10/2016 @ 9.45am
Pgan
vehicle in
Kenneth

View Sent Message

This mail is associated with :

***JPT5831 (C0402054)**
[SJR9536Z]

TP
JOSOPHIENE A/P SINATHAMBY
Sep 18 2016 7:00PM
[LEE KOK KIONG]
Autoexcel Engineering Pte Ltd

Resend

View Recipients

Print Message

Delete Message

Forward

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **06/10/2016 15:23 PM.**
To AXA_SG; cynthia.loh@axa.com.sg
CC vivianlau@lkkauto.com; chewht@lkkauto.com; zayyer@lkkauto.com; admin-a@lkkauto.com
Subject **Re: C0402054/P1636112 - NON MCF**

Dear Cynthia,

Thank you for your email.

As per instruction, we will proceed direct settlement for this case.

Please note that :-

- We survey TP vehicle at M/s. Autoexcel Engineering Pte Ltd - Sin Ming.
- TP will send vehicle to M/s Heng Lai Huat Motor Workshop - Johor Bahru (Malaysia) for repair
- Repair costs in Ringgit Malaysia (RM)

Kindly take note that the case handler in-charge is Zayyer and he can be contacted at DID: 6841 2409.

Thank you.

Best Regards,
Mei Kwan | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AXA_SG
To: LKK_HQ;sur@lkkauto.com;assignments@lkkauto.com
CC: AXA_SG
Sent On: 04/10/2016 09:19 AM
Subject: C0402054/P1636112 - NON MCF



redefining / insurance

AXA INSURANCE SINGAPORE PTE LTD
☎ (65) 6338 7288
☎ (65) 6338 2522
🌐 www.axa.com.sg

Dear LKK Auto Consultants Pte Ltd,

Please take note that the chain collision is a Non-MCF case.

Regards,
Cynthia Loh

DOCUMENTS SUMMARY

There are no documents.

K2
HENG LIM HUAT MOTOR WORKSHOP
(JMD076000-M)
No. 3, Jalan Austin Heights 1/15,
Taman Mount Austin,
81100 Johor Bahru, Johor.

Not Authorised
21 Sep & 11,700 RM
Recovery After Paint

Date : 02/10/2016

QUOTATION - THIRD PARTY CLAIM

7 days

AXA INSURANCE SINGAPORE PTE LTD

Attn: Motor Claim Department, Officer In Charge

Claim : Third Party Claim
Veh. No : JPT 5831
Model : PROTON EXORA
Insured Ins: AM GENERAL

Accident on : 18/09/2016

QTY	PARTICULARS	AMOUNT	SURVEYOR
Your Insurer Vehicle No : SJR 9536 Z			
1	TAILGATE	\$ 2,585.60	✓
1	TAILGATE LOCK	\$ 784.50	✓
1	TAILGATE TRIM BOARD	\$ 1,708.56	✓
1	TAILGATE CENTRE LOGO	\$ 180.00	✓
1	TAILGATE EXORA EMBLEM	\$ 144.50	✓
1	TAILGATE EFE EMBLEM	\$ 144.50	✓
1	TAILLAMP LH	\$ 1,343.20	X
1	TAILLAMP PANEL LH	REPAIR	
1	TAILLAMP APRON PANEL LH	\$ 424.60	X
1	REAR FENDER LH	REPAIR	
1	REAR FENDER INNER SIDE TRIM	\$ 980.65	X
1	REAR BUMPER	\$ 2,213.50	✓
1	REAR BUMPER BEAM	\$ 980.00	✓
2	REAR BUMPER BRACKETS	\$ 280.00	✓
2	REAR BUMPER SIDE RETAINERS	\$ 240.00	✓
1	REAR BUMPER TOW COVER	\$ 142.00	X
2	REAR BUMPER REFLECTORS	\$ 680.00	n/s X X X
1	END PANEL	\$ 1,888.45	✓
1	END PANEL TOP GARNISH	\$ 685.00	✓
1	END PANEL TOP LATCH	\$ 120.00	X
1	FLOOR PANEL	\$ 1,988.45	X
1	FLOOR PANEL TOP BOARD	\$ 1,480.60	✓
1	SPARE TYRE BRACKET	\$ 1,114.60	✓
1	REAR EXHAUST ASSY	\$ 1,955.60	✓
1	REAR EXHAUST MOUNTING	\$ 140.00	X
TOTAL RINGIT :		RM 22,204.31	
AMT AFTER LESS 10%		RM 19,983.88	
S/NETT PARTS			
3TUBE	TAILGATE SELANT	\$ 180.00	400n
1SET	REAR No PLATE WITH HOLDER	\$ 55.00	X
1SET	REVERSE SENSOR	\$ 200.00	✓
1SET	REVERSE CAMERA	\$ 600.00	X
1	REAR BUMPER LOWER SKIRTING	\$ 1,400.00	X
1	SPARE TYRE	\$ 980.00	200n
TOTAL S/N IN RINGIT		RM 3,415.00	
TOTAL PARTS IN RINGIT :		RM 23,398.00	

HENG LAI HUAT MOTOR WORKSHOP
(JMP676600-M)
No. 3, Jalan Austin Heights 1/15,
Taman Mount Austin,
81100 Johor Bahru, Johor.

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	RM 23,398.00	
	Labour charges to replace, repair, cutting, welding, align adjust on rear accident damage	\$ 2,000.00	8000
	To do spray painting on accident damage area	\$ 1,800.00	10000
	To check rear wiring system, replace sensors, camera	\$ 500.00	1200
	Transfer tailgate parts to another tailgate	\$ 200.00	600
	To do anti rust tuff coating	\$ 200.00	600
	To do sealant, seal gap on welding, accident area	\$ 400.00	300
	Remove refix replace garnish, side trim, car seat upholstery etc	\$ 500.00	1000
	Labour to remove refix w/screen	\$ 250.00	1200
	To do chassis body alignment	\$ 350.00	2500
	Total Labour :	RM 6,200.00	
	Total	RM 29,598.00	

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

HENG LAI HUAT MOTOR WORKSHOP
(JM0676600-M)
No. 3, Jalan Austin Heights 1/15,
Taman Mount Austin,
81100 Johor Bahru, Johor.

*Not Authorized
21 Sep 8?
Recovery After Paint*

Date : 02/10/2016

QUOTATION -THIRD PARTY CLAIM

AXA INSURANCE SINGAPORE PTE LTD

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim
Veh. No : JPT 5831
Model : PROTON EXORA
Insured Ins: AM GENERAL

Accident on : 18/09/2016

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SJR 9536 Z		
1	TAILGATE <i>B</i>	\$ 2,585.60	✓
1	TAILGATE LOCK <i>P</i>	\$ 784.50	✓
1	TAILGATE TRIM BOARD <i>Sm</i>	\$ 1,708.56	X
1	TAILGATE CENTRE LOGO <i>me</i>	\$ 180.00	—
1	TAILGATE EXORA EMBLEM <i>me</i>	\$ 144.50	—
1	TAILGATE EFE EMBLEM <i>me</i>	\$ 144.50	✓
1	TAILLAMP LH <i>Sm</i>	\$ 1,343.20	X
1	TAILLAMP PANEL LH	REPAIR	
1	TAILLAMP APRON PANEL LH <i>R</i>	\$ 424.60	X
1	REAR FENDER LH	REPAIR	
1	REAR FENDER INNER SIDE TRIM <i>Sm</i>	\$ 980.65	X
1	REAR BUMPER <i>B</i>	\$ 2,213.50	✓
1	REAR BUMPER BEAM	\$ 980.00	?
2	REAR BUMPER BRACKETS	\$ 280.00	?
2	REAR BUMPER SIDE RETAINERS <i>D.I</i>	\$ 240.00	✓
1	REAR BUMPER TOW COVER <i>Sm</i>	\$ 142.00	X
2	REAR BUMPER REFLECTORS <i>discovered n/s ?</i>	\$ 680.00	n/s ?
1	END PANEL	\$ 1,888.45 <i>B</i>	✓
1	END PANEL TOP GARNISH <i>R</i>	\$ 685.00	✓
1	END PANEL TOP LATCH	\$ 120.00 <i>R</i>	X
1	FLOOR PANEL	\$ 1,988.45	?
1	FLOOR PANEL TOP BOARD	\$ 1,480.60	?
1	SPARE TYRE BRACKET	\$ 1,114.60	?
1	REAR EXHAUST ASSY	\$ 1,955.60	?
1	REAR EXHAUST MOUNTING	\$ 140.00	?
	TOTAL RINGIT :	RM 22,204.31	
	AMT AFTER LESS 10%	RM 19,983.88	
	S/NETT PARTS		
3TUBE	TAILGATE SELANT <i>me</i>	\$ 180.00	4cin
1SET	REAR No.PLATE WITH HOLDER <i>Sm</i>	\$ 55.00	X
1SET	REVERSE SENSOR <i>CRM</i>	\$ 200.00	✓
1SET	REVERSE CAMERA <i>Sm</i>	\$ 600.00	X
1	REAR BUMPER LOWER SKIRTING <i>ASP</i>	\$ 1,400.00	X
1	SPARE TYRE	\$ 980.00	?
	TOTAL S/N IN RINGIT	RM 3,415.00	
	TOTAL PARTS IN RINGIT :	RM 23,398.00	

HENG LAI HUAT MOTOR WORKSHOP
(JMD676600-M)
No. 3, Jalan Austin Heights 1/15,
Taman Mount Austin,
81100 Johor Bahru, Johor.

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	RM 23,398.00	
	Labour charges to replace, repair, cutting, welding, align adjust on rear accident damage	\$ 2,000.00	8000
	To do spray painting on accident damage area	\$ 1,800.00	10000
	To check rear wiring system, replace sensors, camera	\$ 500.00	1200
	Transfer tailgate parts to another tailgate	\$ 200.00	600
	To do anti rust tuff coating	\$ 200.00	600
	To do sealant, seal gap on welding, accident area	\$ 400.00	500
	Remove refix replace garnish, side trim, car seat upholstery etc	\$ 500.00	1000
	Labour to remove refix w/screen	\$ 250.00	1200
	To do chassis body alignment	\$ 350.00	7
	Total Labour :	RM 6,200.00	
	Total	RM 29,598.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HENG LAI HUAT MOTOR WORKSHOP
(JM0676600-M)
No. 3, Jalan Austin Heights 1/15,
Taman Mount Austin,
81100 Johor Bahru, Johor.

Date : 02/10/2016

**QUOTATION -THIRD PARTY CLAIM
SUPPLEMENTARY PARTS**

AXA INSURANCE SINGAPORE PTE LTD

Attn: Motor Claim Department, Officer In Charge

Accident on : 18/09/2016

Claim : Third Party Claim
Veh. No : JPT 5831
Model : PROTON EXORA
Insured Ins: AM GENERAL

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SJR 9536 Z		
	SUPPLEMENTARY PARTS		
2	REAR FENDER UNDERSHIELDS <i>dis / m</i>	\$ 460.60	✓
2	FLOOR PANEL TRAY	\$ 890.50	✓
	TOTAL RINGIT :	RM 1,351.10	
	AMT AFTER LESS 10%	RM 1,215.99	
	TOTAL PARTS IN RINGIT :	RM 1,215.99	

Malaysian Ringgit to Singapore Dollar exchange rate on 18 September 2016 (18/09/2016)

On the 18th September 2016 the inter-bank SGD to MYR spot rate was:

Below is a table showing the **average rate** for **Singapore Dollar (SGD) to Malaysian Ringgit (MYR)** on 18 September 2016 (18/09/2016)

Singapore Dollar to Malaysian Ringgit	Malaysian Ringgit to Singapore Dollar	Date
1 SGD = 3.0222 MYR	0.3309 SGD = 1 MYR	on 18/09/2016
5 SGD = 15.111 MYR	1.6544 SGD = 5 MYR	on 18/09/2016
10 SGD = 30.222 MYR	3.3088 SGD = 10 MYR	on 18/09/2016
15 SGD = 45.333 MYR	4.9633 SGD = 15 MYR	on 18/09/2016
20 SGD = 60.444 MYR	6.6177 SGD = 20 MYR	on 18/09/2016
25 SGD = 75.555 MYR	8.2721 SGD = 25 MYR	on 18/09/2016
50 SGD = 151.11 MYR	16.5442 SGD = 50 MYR	on 18/09/2016
100 SGD = 302.22 MYR	33.0885 SGD = 100 MYR	on 18/09/2016
500 SGD = 1511.1 MYR	165.4424 SGD = 500 MYR	on 18/09/2016
1000 SGD = 3022.2 MYR	330.8848 SGD = 1000 MYR	on 18/09/2016
2500 SGD = 7555.5 MYR	827.212 SGD = 2500 MYR	on 18/09/2016
5000 SGD = 15111 MYR	1654.4239 SGD = 5000 MYR	on 18/09/2016
10000 SGD = 30222 MYR	3308.8479 SGD = 10000 MYR	on 18/09/2016
25000 SGD = 75555 MYR	8272.1196 SGD = 25000 MYR	on 18/09/2016
50000 SGD = 151110 MYR	16544.2393 SGD = 50000 MYR	on 18/09/2016
100000 SGD = 302220 MYR	33088.4786 SGD = 100000 MYR	on 18/09/2016
250000 SGD = 755550 MYR	82721.1965 SGD = 250000 MYR	on 18/09/2016
500000 SGD = 1511100 MYR	165442.393 SGD = 500000 MYR	on 18/09/2016
1000000 SGD = 3022200 MYR	330884.7859 SGD = 1000000 MYR	on 18/09/2016

For full historical data please visit [SGD/MYR exchange rate history page](#)

Choose currency...



Choose country...



ATTN : MOTOR CLAIM DEPARTMENT (T.P)

WITHOUT PREJUDICE

ATTN : AXA Insurance Singapore Pte Ltd
Your Ref : C0402054 MC/CL

Dear Sir/ Mdm,

Accident involving our vehicle No : JPT 5831 & your insure vehicle SJR 9536 Z

Date of Accident : 18/09/2016 : Along / At : Malaysia Highway

Refer to the matter. The accident was caused solely by the negligence of your insured and as a result the following costs and losses had incurred. :

		AMOUNT
1	FINAL REPAIR BILL INCLUDE GST	S\$ <u>Rm 11,700 /2</u>
2	SURVEYOR REPORT FEE	S\$ <u>LKK</u>
3	RENTAL BILL	S\$ <u>-</u>
	L.O.U	S\$ <u>-</u>
4	T.P INSURANCE SEARCH	S\$ <u>Rm 2000 /2</u>
5	OTHER DOCUMENT	S\$ <u>\$2 /2</u>
		S\$ <u>-</u>
	TOTAL :	S\$ <u>Rm 13,700 /2</u>

Please kindly let us have your confirmation to settle our claim within 30 days
Kindly contact Ryan Soh regarding the above matter.

Ryan Soh

Tel : 645435654
HP : 93825367



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

3 November 2016

LEE KOK KIONG
Blk 782E Woodlands Crescent
#04-381
Singapore 735782

Dear Sir/Madam,

OUR REF : CC4/AXA16018692/Kza3
YOUR REF : SJR 9536Z

**ACCIDENT INVOLVING SJR 9536Z AND JPT 5831 ALONG / AT MALAYSIA
HIGHWAY ON 18/09/2016**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s **HENG LAI HUAT MOTOR WORKSHOP** acting on behalf of the owner of **JPT 5831** against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties (3 vehicles chain collision) where your vehicle was the 2nd vehicle, we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) will be withheld for the time being, pending for the final allocation of liability.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to zayyer@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2409 or email us at zayer@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

Zayer

LKK Auto Consultants Pte Ltd

Cc AXA Insurance Singapore Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORITY & INDEMNITY

Heng Lai Huat Motor Workshop
No. 3, Jalan Austin Heights 1/15,
Taman Mount Austin,
81100 Johor Bahru, Johor

Your ref: SJR9536Z

ACCIDENT CLAIM FOR DAMAGE TO MY/OUR VEHICLE JPT 5831 ("the Vehicle") ON 18/09/2016

It is hereby declared and agreed that:

- 1 I/We hereby instruct and authorize you to commence repairs to the Vehicle.
- 2 You are further authorised to appoint a firm of solicitors on my/our behalf ("the Lawyers") and give the Lawyers full instructions as if the appointment is made and instructions are given by me/us with respect to the conduct of my/our claim against the third party driver and/or his insurers including if necessary, to commence legal proceedings in Court in my/our name against the third party(ies).
- 3 I/we shall **render all cooperation** as requested by you or the Lawyers (which shall include, attending at the Lawyers' office and/or in Court personally and/or with the driver for signing of documents, providing statements, perusing and signing Affidavits, and giving evidence, executing any Discharge Vouchers/Settlement Agreement/Release or such other document as required by the third party/ third party insurers before you or the Lawyers upon settlement of my/our claim with the third party/third party insurers). I/We understand that should I/we fail or neglect to render all co-operation to the Lawyers and as a result of which legal costs is ordered against me/us by the Court, I/we shall be personally liable to bear the said costs.
- 4 You have my/our full authority to instruct my/our Lawyers to negotiate a settlement with the third party and/or his insurers on such terms as you deem fit. Upon settlement of my/our claim, I/we hereby irrevocably authorize you to sign any Discharge Voucher or any document to confirm my/our acceptance of the settlement as full and final discharge of my claim, on my/our behalf.
- 5 Upon resolving my/our claim, you are authorised to agree with my/our Lawyers on the amount of their professional costs and disbursements for acting for me/us and to receive payment of the balance of the settlement sum on my/our behalf directly.
- 6 I/We duly authorise you to receive payment of the compensation/settlement monies on my behalf. I/We further confirm that if I/we receive the compensation/settlement monies in respect of my/our claim from the third party/third party insurers, I/we will inform you of the same and I/we will attend at my Lawyers' office or at your workshop to make payment of the costs of repairs, rental, survey fees, legal costs and disbursements within 7 days of receipt of the compensation/settlement monies. I/we understand that in the event that I/we fail to do so, you have the right to commence legal proceedings against us for the full sum of the costs of repair, rental, survey fees and legal costs and disbursements as a liquidated sum debt and to further claim interests from the date of the accident to the date of full payment at the rate of 6% per annum and costs on an indemnity basis (whether before or after Judgment, award or order) for taking any action to recover the amount owing to you/ the Lawyers.
- 7 I/We agree to pay you and the Lawyers the costs of repair, rental, survey fees and legal costs within 7 days of you giving me/us written notice of the same in the event that my/our claim against the third party and/or his insurers is not successful or cannot be proceeded with for any of the following reasons:
 - (a) I/we or my/our driver fail, neglect and/or refuse to provide any cooperation required by you or the Lawyers.

- (b) I/we or my/our driver fail, neglect and/or refuse to attend any Court hearings or mediations as required by the Court or other relevant authorities.
- (c) the driver of the Vehicle is given a warning by the relevant authorities or is fined or jailed or has committed a traffic offence or driving related offence with respect to the above referenced accident.
- (d) The driver of the Vehicle is not my/our authorized driver, servant or agent.
- (e) The third party driver or owner is uninsured or fails to report the accident to his/her insurers or fails to co-operate with his/her insurers or commits a breach of policy conditions resulting in his/her insurers refusing to entertain my/our claim.
- (f) I/we or the driver of the Vehicle makes a false report about the accident.
- (g) the Court finds me/us/ the driver of the Vehicle liable for more than 50% of the claim,

but otherwise, we confirm that you will waive any further claims against me/us for any costs incurred by you in this matter.

Dated 04 day of 10 2016

Owner

HENG LAI HUAT MOTOR WORKSHOP

↓ Jos
Name: Josephine Alp. SINATHAMBY Company Stamp
NRIC No: 641227-08-5548

HENG LAI HUAT MOTOR WORKSHOP

PRO - FORMA

(JM0676600-M)

No. 3, Jalan Austin Heights 1/15, Taman Mount Austin,
81100 Johor Bahru, Johor.
Tel / Fax : 07-361 0318

DATE : 02/12/2016

INVOICE NO : TP 1081


TO : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 , AXA TOWER
SINGAPORE 068811

VEH. NO : JPT 5831
MODEL : PROTON
EXORA

* *	DESCRIPTION	AMOUNT RM
	Accident Date : 18/09/2016	
	Lump Sum Repair, Supply Parts Labour , Spray Painting , etc	RM 11,700.00
	Sub - Total	RM 11,700.00
	TOTAL	RM 11,700.00

NOTE : All cheques must be crossed and make
payable to Heng Lai Huat Motor Workshop

for HENG LAI HUAT MOTOR WORKSHOP





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-16-114766
Date of Request: 28/09/2016

Your Ref No: Online Purchase

Autoexcel Engineering Pte Ltd
Blk 19 Sector A #01-05
Sin Ming Industrial Estate
Singapore 575677

Dear Sir/Madam,

Enquiry Date 28/09/2016
Enquiry By AUTOEXCEL
TP Vehicle No. SJR9536Z
Accident Date 18/09/2016

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJR9536Z	AXA Insurance Singapore Pte Ltd	23/07/2016-22/07/2017	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-16-114766

Date of Request: 28/09/2016

Your Ref No:

Online Purchase

Autoexcel Engineering Pte Ltd
Blk 19 Sector A #01-05
Sin Ming Industrial Estate
Singapore 575677

Dear Sir/Madam,

Enquiry Date 28/09/2016
Enquiry By AUTOEXCEL
TP Vehicle No. SJR9536Z
Accident Date 18/09/2016

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Sep 2016		04 Oct 2016 09:17 Edit Adj Rpt	S\$11,700.00 Edit Estimates	S\$11,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LEE KOK KIONG, NRIC: S8080866F, Tel: +6592311341, Email: 8911goo@gmail.com									
Main Claimant: JOSOPHIENE A/P SINATHAMBY, NRIC: 641227085548									
Vehicle Reg. No.: JPT5831		Date of Loss:	18/09/2016 19:00 - :59						
Claim Type: TP / C0402054		Policy/Cover Note No.:	P1636112 (Comprehensive)						
Vehicle Reg. No. (Insured): SJR9536Z		Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer: Heng Lai Huat Motor Workshop (HQ) NO 3 JALAN AUSTIN HEIGHTS 1/15, TAMAN MOUNT AUSTIN, 81100 Johor Bahru - Tel:									
Handling Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/10/2016]									
Adj Asg. Remarks: XS NIL									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- LKK_HQ (14/02/2017): TP's repairer purchase Survey report - AXA_SG (21/12/2016): Re: TP rejected 10% offer and proposed 30% - AXA_SG (04/10/2016): C0402054/P1636112 - NON MCF - AXA_SG (04/10/2016): New TP Assignment - C0402054/P1636112									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JPT5831 (C0402054)
[SJR9536Z]
TP
JOSOPHIENE A/P SINATHAMBY
Sep 18 2016 7:00PM
[LEE KOK KIONG]
Heng Lai Huat Motor Workshop

Upload Documents		Upload Photos		Compose New Letter		View Use Viewer	
Letters/Correspondences						1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown					Edit
Assessment Reports						1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	05/10/16 16:49	Adjuster Immediate Advice					Load HTM
Documentation						1 per page	
No	Finalized On	AXA Insurance Pte Ltd (HQ)				Thumbnail	Print
1	30/09/16 11:16	EMAIL_ABS					Load PDF
2	30/09/16 11:16	DRIVING LICENSE_ABS					Load PDF
3	30/09/16 11:16	SJR9536Z INSD GIA REPORT_ABS					Load PDF
4	03/10/16 16:09	EMAIL_ABS					Load PDF
5	03/10/16 16:09	POLICE REPORT_ABS					Load PDF
6	04/10/16 09:14	TO LKK					Load TIF
7	17/10/16 16:20	Police Investigation Result - PIR (DRIVER OF 3RD/LAST VEH WAS CHARGED)					Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	06/10/16 15:28	TP POLICE REPORT					Load PDF
2	06/10/16 15:28	TP ESTIMATE - MARKED					Load PDF
3	06/10/16 15:28	SUPPLEMENTARY ESTIMATE					Load PDF
4	06/10/16 15:28	CI					Load PDF
5	06/10/16 15:28	LOG CARD					Load PDF
6	11/11/16 13:13	email from workshop.pdf					Load PDF
7	02/02/17 11:15	exchange rate					Load PDF
8	17/02/17 14:11	EMAIL TO AXA					Load PDF
9	17/02/17 14:11	WORKSHOP INVOICE					Load PDF
10	17/02/17 14:11	AUTHORISATION TO ACT FORM					Load PDF
11	17/02/17 14:11	LETTER TO OI					Load PDF
12	17/02/17 14:11	GIA SEARCH					Load PDF
13	17/02/17 14:11	LOD					Load PDF

Documents Checklist

Reset Save Print
DOCUMENTS CHECKLIST There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJR9536Z (Insd veh)	Model:	PROTON EXORA 1.6 (A)
	JPT5831 (TP veh)		
Date of Accident:	18/09/2016		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$		29,598.88
Final Repair Cost	:	\$		853.40
Loss of Use	:	\$		8.00 days at \$150.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum	:	\$		853.40
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability <u>20</u> (%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No:		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Heng Lai Huat Motor Workshop	:	\$ 853.40
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Feb
2017

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16018689/KZA3Q2

Date: 17/02/2017

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1636112
Claimant Vehicle No :	JPT5831	Insured Vehicle No :	SJR9536Z
Date of Loss:	18/09/2016	Nature of Claim:	TP
		Claim No:	C0402054

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JPT5831	Engine No:	S4PHTU7374
Make & Model:	PROTON EXORA, 1.6 (A)	Chassis No:	PL1FZ6YDREF122373
Reg. Date:	28/11/2013 (Man. Year: 2013)	Odometer:	54481 km
Colour:	Metallic Gold		
Engine Capacity:	1561 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Falken 2 mm	Rear Left Side:	Falken 3 mm
Front Right Side:	Falken 2 mm	Rear Right Side:	Falken 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	23,398.88	13,729.16	9,669.72	41.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,200.00	2,560.00	3,640.00	58.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,598.88	16,289.16	13,309.72	44.97
Approved Total (Overridden) (S\$)		11,700.00		
Nett Amount (S\$)	29,598.88	11,700.00	17,898.88	60.47
+ Loss of Use (8.0 x S\$150.00/day) (S\$)		1,200.00		
		(S\$) 12,900.00		
Liabe Amount (20.00%) (S\$)		2,580.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,582.00		

INSPECTION

Date of Assignment:	04/10/2016	
Date Inspected:	04/10/2016 Inspected At:	Heng Lai Huat Motor Workshop (HQ) NO 3 JALAN AUSTIN HEIGHTS 1/15, TAMAN MOUNT AUSTIN 81100 Johor Bahru, Johor Darul Takzim
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG

Manager: ZAY YER LYNN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2017)
Parts: M1-MPV	PROTON EXORA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for JPT5831)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE (CONSISTENT)	Bent	2,585.60 FL	*2,585.60 FL
2	1		*TAILGATE LOCK (CONSISTENT)	Dented	784.50 FL	*784.50 FL
3	1		*TAILGATE TRIM BOARD (CONSISTENT)	Serviceable	1,708.56 FL	*- FL
4	1		*TAILGATE CENTRE LOGO (CONSISTENT)	Necessary	180.00 FL	*180.00 FL
5	1		*TAILGATE EXORA EMBLEM (CONSISTENT)	Necessary	144.50 FL	*144.50 FL
6	1		*TAILGATE EFE EMBLEM (CONSISTENT)	Necessary	144.50 FL	*144.50 FL
7	1		*TAILLAMP LH (CONSISTENT)	Serviceable	1,343.20 FL	*- FL
8	1		*TAILLAMP PANEL LH (NPA)(CONSISTENT)	Repair	0.00 FL	*- FL
9	1		*TAILLAMP APRON PANEL LH (CONSISTENT)	Repair	424.60 FL	*- FL
10	1		*REAR FENDER LH (CONSISTENT) (NPA)	Repair	0.00 FL	*- FL
11	1		*REAR FENDER INNER SIDE TRIM (CONSISTENT)	Serviceable	980.65 FL	*- FL
12	1		*REAR BUMPER (CONSISTENT)	Bent	2,213.50 FL	*2,213.50 FL
13	1		*REAR BUMPER BEAM (CONSISTENT)	Bent	980.00 FL	*980.00 FL
14	2		*REAR BUMPER BRACKETS (CONSISTENT)	Bent	280.00 FL	*280.00 FL
15	2		*REAR BUMPER SIDE RETAINERS (CONSISTENT)	Distorted	240.00 FL	*240.00 FL
16	1		*REAR BUMPER TOW COVER (CONSISTENT)	Serviceable	142.00 FL	*- FL
17	2		*REAR BUMPER REFLECTORS (CONSISTENT)	Serviceable	680.00 FL	*- FL
18	1		*END PANEL (CONSISTENT)	Bent	1,888.45 FL	*1,888.45 FL
19	1		*END PANEL TOP GARNISH (CONSISTENT)	Dented	685.00 FL	*685.00 FL
20	1		*END PANEL TOP LATCH (CONSISTENT)	Repair	120.00 FL	*- FL
21	1		*FLOOR PANEL (CONSISTENT)	Repair	1,988.45 FL	*- FL
22	1		*FLOOR PANEL TOP BOARD (CONSISTENT)	Dented / Distorted	1,480.60 FL	*1,480.60 FL
23	1		*SPARE TYRE BRACKET (CONSISTENT)	Distorted / Bent	1,114.60 FL	*1,114.60 FL
24	1		*REAR EXHAUST ASSY (CONSISTENT)	Bent	1,955.60 FL	*1,955.60 FL
25	1		*REAR EXHAUST MOUNTING (CONSISTENT)	Serviceable	140.00 FL	*- FL
26	1		*TUBE TAILGATE SELANT (CONSISTENT)	Necessary	180.00 FS	*40.00 FS
27	1		*SET REAR NO.PLATE WITH HOLDER (CONSISTENT)	Serviceable	55.00 FS	*- FS
28	1		*SET REVERSE SENSOR (CONSISTENT)	Cracked	200.00 FS	*200.00 FS
29	1		*SET REVERSE CAMERA (CONSISTENT)	Serviceable	600.00 FS	*- FS
30	1		*REAR BUMPER LOWER SKIRTING (CONSISTENT)	No such part	1,400.00 FS	*- FS
31	1		*SPARE TYRE (CONSISTENT)	Cut	980.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 25,619.31 15,196.85
 - List Item Discount on L Items 10.00/10.00% (S\$) 2,220.43 1,467.69

Total Parts (S\$) 23,398.88 13,729.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REPLACE ,REPAIR ,CUTTING ,WELDING ,ALIGN ADJUST ON REAR ACCIDENT DAMAGE	New	2,000.00	800.00
2	TO DO SPRAY PAINTING ON ACCIDENT DAMAGE AREA	New	1,800.00	1,000.00
3	TO CHECK REAR WIRING SYSTEM ,REPLACE SENSORS ,CAMERA	New	500.00	120.00
4	TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE	New	200.00	60.00
5	TO DO ANTI RUST TUFF COATING	New	200.00	60.00
6	TO DO SEALANT , SEAL GAP ON WELDING ,ACCIDENT AREA	New	400.00	50.00
7	REMOVE ,REFIX REPLACE GARNISH ,SIDE TRIM ,CAR SEAT UPHOLSTERY ETC	New	500.00	100.00
8	LABOUR TO REMOVE REFIX W/SCREEN	New	250.00	120.00
9	TO DO CHASSIS BODY ALIGNMENT	New	350.00	250.00
Gross Labour Cost (S\$)			6,200.00	2,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >