

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

THE CARHUB
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

TPEQ

16th APRIL 2019

Xiao Tony

NZT2403033174

Accident date: 12th APRIL 2019
Estimated repair cost for vehicle no: SJM6413R TOYOTA ALLION 1.5

S/n	Qty	Items	U/price	Amount	
				\$624.80	✓
1	1	Front Bumper <i>Del'd</i>		\$263.50	58
2	2	Front Bumper Side Bracket <i>RH Dmgd</i>	\$131.75	\$103.20	30
3	8	Front bumper clips <i>new</i>	\$12.90	\$235.20	105.70
4	1	Front bumper <i>sponge</i>		\$165.00	✓
5	1	Front inner shield -RH <i>new</i>		\$765.10	✓
6	1	headlamp -RH <i>lt</i>		\$381.20	✓
7	1	Front bumper fog lamp-RH <i>could</i>		\$156.00	✓
8	1	front bumper fog lamp cover -RH <i>missing</i>		\$50.00	✓
9	1	Front Bumper Number Plate		\$61.00	✓
10	1	Front Bumper emblem logo		\$128.30	✓
11	1	Front Bumper Grille Chrome		\$465.00	325
12	1	Front Bumper Reinforcement <i>sent</i>		\$325.00	124
13	1	Front RH water tank <i>could</i>		\$645.00	✓
14	1	Front RH fender <i>dented</i>		\$153.55	✓
15	1	Front R/H fender cowling <i>new</i>	\$5.00	\$50.00	✓
16	10	Front R/H fender cowling clips		\$316.20	✓
17	1	Front R/H lower arm <i>sent</i>		\$395.60	✓
18	1	Front R/H knuckle arm <i>2nd</i>		\$182.25	✓
19	1	Front R/H knuckle arm bearing <i>2nd</i>		\$381.80	✓
20	1	Front R/H shock absorber <i>new</i>		\$1,712.80	✓
21	1	Front R/H drive shaft <i>new</i>		\$450.00	✓
22	1	Front Tire <i>new</i>		\$500.00	350.00
23	1	front rim <i>lt</i>			

Subtotal :- \$8,530.50

410855 SW 350
308163

Labour charges

To Remove & refix front undercarriage , drive shaft

~~\$480.00~~ 220

Tuff kote

~~\$100.00~~ X

To remove & refix cushion

~~\$100.00~~ X

To check wheel alignment computer

~~\$150.00~~ 80

Towing charges

~~\$100.00~~ X

Panel beating

~~\$800.00~~ 400

Spray painting

~~\$800.00~~ 600

Subtotal :- \$2,530.00

Total:- \$11,060.50

total : 4731.63

4/s : 3750

05 Pages

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: