

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

16th APRIL 2019

THE CARHUB
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

Accident date: 12th APRIL 2019

Estimated repair cost for vehicle no: SJM6413R TOYOTA ALLION 1.5

S/n	Qty	Items	U/price	Amount
				\$624.80
1	1	Front Bumper		\$263.50
2	2	Front Bumper Side Bracket	\$131.75	\$103.20
3	8	Front bumper clips	\$12.90	\$235.20
4	1	Front bumper center lower garnish		\$165.00
5	1	Front inner shield -RH		\$765.10
6	1	headlamp -RH		\$381.20
7	1	Front bumper fog lamp-RH		\$156.00
8	1	front bumper fog lamp cover -RH		\$50.00
9	1	Front Bumper Number Plate		\$61.00
10	1	Front Bumper emblem logo		\$128.30
11	1	Front Bumper Grille Chrome		\$485.00
12	1	Front Bumper Reinforcement		\$325.00
13	1	Front RH water tank		\$645.00
14	1	Front RH fender		\$153.55
15	1	Front R/H fender cowling		\$50.00
16	10	Front R/H fender cowling clips	\$5.00	\$316.20
17	1	Front R/H lower arm		\$395.60
18	1	Front R/H knuckle arm		\$182.25
19	1	Front R/H knuckle arm bearing		\$381.80
20	1	Front R/H shock absorber		\$1,712.80
21	1	Front R/H drive shaft		\$450.00
22	1	Front Tire		\$500.00
23	1	front rim		
Subtotal :-				\$8,530.50

Labour charges

To Remove & refix front undercarriage , drive shaft

\$480.00

Tuff kote

\$100.00

To remove & refix cushion

\$100.00

To check wheel alignment computer

\$150.00

Towing charges

\$100.00

Panel beating

\$800.00

Spray painting

\$800.00

Subtotal :-

\$2,530.00

Total:-

\$11,060.50