

**Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

AXA

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
ACCIDENT DATE : 11/04/2019@0720HRS
VRN : SKQ5487B
MODEL : Toyota Estima
TP VRN : WC7004E

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
--	------------	-----------------	----------------	------------------

PARTS REPLACEMENT

1. Body Repair

1 Front Bumper	1	\$ 604.00	\$ 604.00	di ✓
2 Front Bumper Clips	10	\$ 5.50	\$ 55.00	ne ✓
3 Front Bumper Outer Bracket LH/RH	1	\$ 70.00	\$ 70.00	RH-dis ✓
4 Headlamp RH	1	\$ 1,985.00	\$ 1,985.00	int ✓
5 Front Fender RH	1	\$ 650.00	\$ 650.00	ht ✓
6 Front Fender Shield RH	1	\$ 90.00	\$ 90.00	m ✓
7 Front Fender Shield Clips RH	10	\$ 5.50	\$ 55.00	ue ✓
8 Front Door RH	Repair 1	\$ -	\$ -	

Discount 25% \$ (877.25)

TOTAL \$ 2,631.75

2. Labor Charges

1 Panel beat, cut, weld, re-align and replace damaged of affected area	3500	\$ 750.00
2 Spray painting on front portion of affected area	500	\$ 750.00
3 Check wiring, re-align headlamps and ensure proper function	30	\$ 80.00

Sub Total : \$ 1,580.00

Grand Total : \$ 4,211.75
Add 7% GST : \$ 294.82
Nett Total : \$ 4,506.57

No. of repair days:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjin 97495749
"up"
16/4/19 @ 333pm
03-0# days
sunclhntn.com
Resurvey before paint

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)