

# 來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No .....: EST0022004  
Fan Chongzhi

Page .....: 1 of 2  
Your ref. ....: TP-SLA 2519K AXA  
Job No. ....: 70421  
Our ref. ....: 19.04.24  
Payment .....  
Date .....: 16/4/2019

Attn .....

Vehicle No ....: SME 5417T  
Vehicle Model : Honda Odyssey  
Accident on ...: 12/4/2019

*NOT Authorized  
U/Survey @?  
Resurvey After Paint  
6 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Set	Rear windscreen mouldings	<i>Nu</i> 114.80	20.00	91.84 <i>✓</i>
1.00	Pc	Rear tailgate	<i>B1</i> 1,068.30	20.00	854.64 <i>✓</i>
1.00	Pc	Rear bumper	<i>Bul/cm</i> 751.00	20.00	600.80 <i>✓</i>
1.00	Pc	Rear bumper side retainer RH	<i>DIV</i> 27.20	20.00	21.76 <i>✓</i>
1.00	Pc	Rear end panel	<i>B1</i> 494.00	20.00	395.20 <i>✓</i>
1.00	Pc	Rear end panel trim garnish	<i>M3 cm</i> 285.60	20.00	228.48 <i>✓</i>
1.00	Pc	Rear spare tyre covering	<i>CM</i> 418.60	20.00	334.88 <i>✓</i>
1.00	Pc	Odyssey emblem	<i>Nu</i> 45.50	20.00	36.40 <i>✓</i>
Labour & Misc:					
1.00		To dismantle + refix rear windscreen	160.00		160.00 <i>1200</i>
1.00		To supply sealant	40.00		40.00 <i>Nu</i> <i>✓</i>
1.00		To dismantle + refix rear fender inner trim garnish (x2), etc	120.00		120.00 <i>1000</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Date:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车壳及给予快速与准确的测量方式和大小铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

# 來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No .....: EST0022004  
Fan Chongzhi

Page .....: 2 of 2  
Your ref. ....: TP-SLA 2519K AXA  
Job No. ....: 70421  
Our ref. ....: 19.04.24  
Payment .....  
Date .....: 16/4/2019

Attn .....

Vehicle No ....: SME 5417T  
Vehicle Model : Honda Odyssey  
Accident on ...: 12/4/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To apply anti rust chemical	80.00		80.00 <i>60%</i>
1.00		To transfer rear reversing sensor	60.00		60.00 <i>50%</i>
1.00		To straighten rear body including cutting and welding, to knock dents on rear spare tyre panel and renew of parts	750.00		750.00 <i>65%</i>
1.00		To spray paint (including rear tailgate outer garnish)	800.00		800.00 <i>72%</i>

*Supplementary*

*\* Rear Bumper Reinforcement*

*207-70 20. \$166.16 /Bt.*

Sub-Total ..... 4,574.00  
GST 7.00% ..... 320.18  
Total ..... S\$ 4,894.18

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."