

INS. CASE OWNER:

Wang Peter

CC 4, Asm 1900 6763, E 903

LKK:
IDAC:

110790

Surveyor:

Steve

DOI:

ASSIGNMENT

6/5/19

Date / Time:

16/4/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

S7A 507P

Name of Insured:

TLC INS PTL

Insured Tel No.:

HP:

Excess Sec II :SS

5,500.00

D.O.A.:

15/4/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kah Motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: E-mail only

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

Steve

Email ☐ Call ☐

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

P/P

S\$ 6,118.44

(5 days)

Reduction:

\$10,448.78%

by

FINAL SETTLEMENT

Date/Time:

24/4/19

Confirm with

Sim Hui

Desmond

Email ☒Call ☐

Final Liability:

S\$ 100

(Agreed / Assessed)

BOLA S/N No.:

27

Repair Cost: (W/GST)

S\$ 6,546.72

Loss of Rental (LOR):

S\$ 535.00

(5 days)

x \$107

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

Legal Cost

S\$ -

Total:

S\$ 7081.72

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

S\$ 7081.72

Name 1:

Kah Motor Co. Sdn. Bhd.

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP \$350/-

Surveyor **Steve**

REF: **ASM (AxA)**

67631 (S)

ASSIGNMENT

From: _____ Date: **6 May 2019**

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SJF 5332J**

at Workshop m/s **Kah motor**

of **NO 255 Alexandra Road**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: **10.000.m (owner waiting)**

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **82,000**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **5** days Res.: Yes or No

Lum Sum: **1.471** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rwpr

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SJF 5332J**

Yr Regn: **11/5/18**

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda HRV**

c.c. **1496**

Colour: **white**

A/C: Insured / Std / NI / NA

Sp.Reading: **016320**

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JHMRU 1830GX 203842**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **215/60R16**

R: **"**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. **7** mm

R/Bal. **7** mm

L/Bal. **7** mm

L/Bal. **7** mm

D.O.A. **15/4/19**

D.O.I. **6/5/19**

Survey held at **Kah motor**

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rebate: \$49,500

Date / Time Action / Instruction

MV - 82K

14-5-19 P/P \$6,118.44

(Red = \$10,448.78 / 63%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJF5332J
Chassis No : JHMRU1830GX203842
Model : HRV LX-SIN CVT YM 2016
Owner's Name : NAY LIN TUN
Ins Policy No :
Date of Accident :

Document No. : SQT19001949
Date : 6. May 2019
Customer No. : WZA006
Svc Advisor :
Engine No : L15B4533841
Date | Time : 6. May 2019 9:26:48 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BOSUN ①	SUNDRIES	net 1	100.00	30	100.00	7.00	107.00
BA02R ②	REMOVE & RENEW REVERSE SENSORS-4 PCS (H)	1	180.00	/	180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00	X	80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00	X	80.00	5.60	85.60
BOJSE ③	SEALANT FOR TAILGATE	net 1	80.00	/	80.00	5.60	85.60
BML02I ④	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	/	180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES (H)	1	560.00	X	560.00	39.20	599.20
BMI02D ⑤	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00	280	560.00	39.20	599.20
BKTG02R ⑥	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00	/	560.00	39.20	599.20
BG02D ⑦	REMOVE & INSTALL RR. WINDSCREEN (H)	1	560.00	/	560.00	39.20	599.20
BODAMKIT ⑧	WINDSCREEN DAM KIT.	net 1	100.00	/	100.00	7.00	107.00
BKRP02M ⑨	CUT OFF & RENEW RR PANEL. 3	1	5000.00	1680	5000.00	350.00	5350.00
BP06R ⑩	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00	1350	3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR (H)	1	450.00	X	450.00	31.50	481.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00	X	480.00	33.60	513.60
BP00R	APPLY BODY UNDERSIDE COATING (H)	1	450.00	X	450.00	31.50	481.50
Sum Labor					12420.00	869.40	13,289.40

Printed on 6/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJF5332J

Chassis No : JHMRU1830GX203842

Model : HRV LX-SIN CVT YM 2016

Owner's Name : NAY LIN TUN

Ins Policy No. :

Date of Accident :

Document No. : SQT19001949

Date : 6. May 2019

Customer No. : WZA006

Svc Advisor :

Engine No : L15B4533841

Date | Time : 6. May 2019 9:26:48 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
RS-TMP3040L	VPC 4PCS REAR SENSORS ? X NAI	1	320.00		320.00	22.40	342.40
33502-T7A-J01	LAMP UNITR. X NAI	1	441.50	25	331.12	23.18	354.30
33552-T7A-J01	LAMP UNITL. X NAI	1	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY.R LID X NAI	1	269.90	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSYL LID X NAI	1	269.90	25	202.42	14.17	216.59
68100-T7A-J20ZZ	① TAIL GATE COMP / 00	1	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE X NAI	1	98.70	25	74.02	5.18	79.20
74800-T7A-J02	LOCK ASSYTAILGATE X NAI	1	78.90	25	59.17	4.14	63.31
84431-T7A-J01ZA	LINING ASSYTAILGATE X NAI	1	136.00	25	102.00	7.14	109.14
75722-T7W-A01	② EMBLEMRR. / NAI	1	13.30	25	9.97	0.70	10.67
33505-T7A-J01	REFLECTOR ASSYR.RR. ? X NAI	1	156.30	25	117.22	8.21	125.43
33555-T7A-J01	REFLECTOR ASSYLRR. X NAI	1	156.30	25	117.22	8.21	125.43
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER X NAI	1	94.10	25	70.57	4.94	75.51
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER X NAI	1	94.10	25	70.57	4.94	75.51
71593-T7A-000	③ SPACER,R.RR.BUMPER SIDE X NAI	1	17.20	25	12.90	0.90	13.80
71598-T7A-000	④ SPACER,L.RR.BUMPER SIDE / NAI	1	17.20	25	12.90	0.90	13.80
91505-TM8-003	⑤ CLIP,BUMPER / NAI	8	2.30	25	13.80	0.97	14.77
66100-T7A-300ZZ	PANEL COMPRR X R	1	373.10	25	279.82	19.59	299.41
84640-T7A-J01ZA	LINING ASSYRR PANEL X NAI	1	43.90	25	32.92	2.30	35.22
04655-T7A-310ZZ	PANEL SETRR.FLOOR X NAI	1	675.50	25	506.62	35.46	542.08
72841-SH3-315	OILSHEET X NAI	3	40.70	25	91.57	6.41	97.98
73214-T7J-H01	⑥ RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	⑦ DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	⑧ RUBBER CL.WINDSHIELD DAMPER X NAI	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	⑨ CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	⑩ FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	⑪ FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	⑫ FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10

Printed on 5/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJF5332J
Chassis No : JHMRU1830GX203842
Model : HRV LX-SIN CVT YM 2016
Owner's Name : NAY LIN TUN
Ins Policy No. :
Date of Accident :

Document No. : SQT19001949 Page 3
Date : 6. May 2019
Customer No. : WZA006
Svc Advisor :
Engine No : L15B4533841
Date | Time : 6. May 2019 9:25:48 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
BO-WS-SEALANT	WINDSCREEN SEALANT 4MT <i>SAEC X NM 2</i>		60.00		120.00	8.40	128.40
Sum Item					3788.58	265.20	4,053.78

Survey By

Date & Time

Excess

Status

Signature

Sten CLKKJ

6/5/19 10.20am

W/L Prejudice

P/P

Ry bel spy
5 Days

Total Amount 16,208.58 1,134.60 17,343.18

Total (Inclusive of GST) 17,343.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 6/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

16567.22 #

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: *****3839H / NAY LIN TUN
Chassis No: JHMRU1830GX203842
License No: SJF5332J
Mileage: 8926
Engine No: L15B4533841

Document No: SVO19028380
Printed By: SHNG
Order Date: 6. May 2019
Order Time: 12:09:37 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
75725-T8N-T00	SUPPLEMENTARY EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
SUM PARTS:					358.64	25.10	383.74
TOTAL SGD					358.64	25.10	383.74

Total Payable (SGD)**383.74**

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
 Chassis No: JHMRU1830GX203842
 License No: SJF5332J
 Mileage: 8926
 Engine No: L15B4533841

Document No: SVO19028380
 Printed By: SHNG
 Order Date: 6. May 2019
 Order Time: 12:09:37 PM
 Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO:)							
	OWNER:NAY LIN TUN							
	OWNER INSURER:AVIVA							
	ACC DATE:15/04/2019							
	SURVEYED BY:STEVE							
	DATE:06/05/2019							
	REF NO:							
	TP INSURER:AXA							
	TP VEH:SHD507P							
	SUPPLEMENTARY							
68100-T7A-J20ZZ	① TAIL GATE COMP	1	855.70	25	641.77	44.92	686.69	
75722-T7W-A01	② EMBLEMRR.	1	13.30	25	9.97	0.70	10.67	
71593-T7A-000	③ SPACER,R.RR.BUMPER SIDE	1	17.20	25	12.90	0.90	13.80	
71598-T7A-J00	④ SPACER,L.RR.BPR S	1	17.20	25	12.90	0.90	13.80	
91505-TM8-003	⑤ CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77	
73214-T7J-H01	⑥ RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48	
73226-SZW-000	⑦ DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82	
73254-T7J-H01	⑧ RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48	
76711-T6A-003	⑨ CAPPVOT	1	4.80	25	3.60	0.25	3.85	
91501-S70-003	⑩ FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01	
91502-S70-003	⑪ FASTENER B	2	5.30	25	7.95	0.56	8.51	
91536-SS0-J01	⑫ FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10	
75725-T8N-T00	⑬ EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76	11.63	
04715-T7A-900ZZ	⑭ FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11	
	SUM PARTS:				1,118.44	78.28	1,196.72	
BOSUN	0701	1	30.00		30.00	2.10	32.10	
	① SUNDRIES <i>nee</i>							
BA02R	1729	1	180.00		180.00	12.60	192.60	
	② REMOVE & RENEW REVERSE SENSORS-4 PCS-(N)-							
BOJSE	1718	1	80.00		80.00	5.60	85.60	
	③ SEALANT FOR TAILGATE <i>nee</i>							
BML02I	1718	1	180.00		180.00	12.60	192.60	
	④ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST-(N)-							
BMI02D	1718	1	280.00		280.00	19.60	299.60	
	⑤ REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC-(N)-							
BKTG02R	1729	1	560.00		560.00	39.20	599.20	
	⑥ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)							
BG02D	1438	1	560.00		560.00	39.20	599.20	
	⑦ REMOVE & INSTALL RR. WINDSCREEN. (N)-							
BODAMKIT	1438	1	100.00		100.00	7.00	107.00	
	⑧ WINDSCREEN DAM KIT. <i>nee</i>							

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMRU1830GX203842
License No: SJF5332J
Mileage: 8926
Engine No: L15B4533841

Document No: SVO19028380
Printed By: SHNG
Order Date: 6. May 2019
Order Time: 12:09:37 PM
Service Advisor: NG SIN HAI

BKRP02M	1729	1	1,680.00	1,680.00	117.60	1,797.60
	(9) CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.					
BP06R	1718	1	1,350.00	1,350.00	94.50	1,444.50
	(10) SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION					
			SUM LABOUR:	5,000.00	350.00	5,350.00
			TOTAL SGD	6,118.44	428.28	6,546.72

Total Payable (SGD)**6,546.72**

GST Amount is calculated from individual line(s)

K.A. Consultants hence notify
the insurer of the following:
• Survey before/after spray painting
• Survey damaged part(s) during resurvey
• All repairs are subject to confirmation
• Resurvey is on a "Without Prejudice" basis
• Any modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Knownledged by Repairer:
Signature:
Date:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	: SQT19001949	Page	1
	8 SHENTON WAY	Date	: 6. May 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	:		
Registration No	: SJF5332J	Engine No	: L15B4533841		
Chassis No	: JHMRU1830GX203842	Date Time	: 6. May 2019 9:26:48 AM		
Model	: HRV LX-SIN CVT YM 2016	Surveyor Name	:		
Owner's Name	: NAY LIN TUN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	/	180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00	X	80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00	X	80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00	/	80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	/	180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00	X	560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00	280	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00	/	560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00	/	560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	/	100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL. 3	1	5000.00	1680	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00	1350	3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00	X	450.00	31.50	481.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00	/	480.00	33.60	513.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00	X	450.00	31.50	481.50
Sum Labor					12420.00	869.40	13,289.40

Printed on 6/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJF5332J

Chassis No : JHMRU1830GX203842

Model : HRV LX-SIN CVT YM 2016

Owner's Name : NAY LIN TUN

Ins Policy No. :

Date of Accident :

Document No. : SQT19001949

Date : 6. May 2019

Customer No. : WZA006

Svc Advisor :

Engine No : L15B4533841

Date | Time : 6. May 2019 9:26:48 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
RS-TMP3040L	VPC 4PCS REAR SENSORS ?	1	320.00		320.00	22.40	342.40
33502-T7A-J01	LAMP UNITR. X	1	441.50	25	331.12	23.18	354.30
33552-T7A-J01	LAMP UNITL. X	1	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R.LID X	1	269.90	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSYL.LID X	1	269.90	25	202.42	14.17	216.59
68100-T7A-J20ZZ	TAIL GATE COMP. / 00	1	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE X	1	98.70	25	74.02	5.18	79.20
74800-T7A-J02	LOCK ASSYTAILGATE ?	1	78.90	25	59.17	4.14	63.31
84431-T7A-J01ZA	LINING ASSYTAILGATE X	1	136.00	25	102.00	7.14	109.14
75722-T7W-A01	EMBLEMRR. / Nec	1	13.30	25	9.97	0.70	10.67
33505-T7A-J01	REFLECTOR ASSYR.RR. ?	1	156.30	25	117.22	8.21	125.43
33555-T7A-J01	REFLECTOR ASSYL.RR. X	1	156.30	25	117.22	8.21	125.43
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER X	1	94.10	25	70.57	4.94	75.51
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER X	1	94.10	25	70.57	4.94	75.51
71593-T7A-000	SPACER,R.RR.BUMPER SIDE 2 / Nec	1	17.20	25	12.90	0.90	13.80
71598-T7A-000	SPACER,L.RR.BUMPER SIDE / Nec	1	17.20	25	12.90	0.90	13.80
91505-TM8-003	CLIP,BUMPER / Nec	8	2.30	25	13.80	0.97	14.77
66100-T7A-300ZZ	PANEL COMPRR. X R	1	373.10	25	279.82	19.59	299.41
84640-T7A-J01ZA	LINING ASSYRR.PANEL X	1	43.90	25	32.92	2.30	35.22
04655-T7A-310ZZ	PANEL SETRR.FLOOR X	1	675.50	25	506.62	35.46	542.08
72841-SH3-315	OILSHEET X	3	40.70	25	91.57	6.41	97.98
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER } NEC /	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10

Printed on 6/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJF5332J
Chassis No : JHMRU1830GX203842
Model : HRV LX-SIN CVT YM 2016
Owner's Name : NAY LIN TUN
Ins Policy No. :
Date of Accident :

Document No. : SQT19001949
Date : 6. May 2019
Customer No. : WZA006
Svc Advisor :
Engine No : L15B4533841
Date | Time : 6. May 2019 9:26:48 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>AKC</i>	2	60.00		120.00	8.40	128.40
Sum Item					3788.58	265.20	4,053.78

Survey By

Date & Time

Excess

Status

Signature

*Steve CLKK**6/5/19 10.20am**with prejudice**P/P**Reg bel spy**5 Days*

Total Amount 16,208.58 1,134.60 17,343.18

Total (Inclusive of GST) **17,343.18**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 6/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3839H
Vehicle Details	
Vehicle No.:	SJF5332J
Vehicle to be Exported:	No
Intended Deregistration Date:	06 May 2019
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 LX CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	L15B4533841
Chassis No.:	JHMRU1830GX203842
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,077.00
Original Registration Date:	11 May 2018
First Registration Date:	11 May 2018
Transfer Count:	0
Actual ARF Paid:	\$21,508.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 May 2028
PARF Rebate Amount:	\$16,131.00
Intended COE Rebate Details	
COE Expiry Date:	10 May 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,000.00
COE Rebate Amount:	\$33,339.00
Total Rebate Amount:	\$49,470.00

The information contained herein is correct as at 06 May 2019

OK

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself. Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Cde Renewal Honda Stream 1.8A



3.98% p.a. 10 Admin Fee
Finance 2 Years Warranty \$2500
Down Monthly From \$878
GV Credit Pte Ltd. [Spend](#)



Browse by Category

« Back (1 2) Next »

Sort by Date Posted 20 results/page

26 vehicles

Honda Vezel

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Vel Type	Status
Search Selection	Honda Vezel	Any	Any	2018	Any	Any	Any	Available
	Honda Vezel 1.5A X Honda Sensing	\$78,800	\$8,280 /yr	28-Feb-2018	1,496 cc	-	SUV	Available
Honda Sensing Technology, Sporty Looking 1 Year Old Only! Rare In The Market! 1 Owner, Well Maintained Condition As Good As New, 100% Accident-Free, Beautiful Interior Leather And Lighting. In House L...								
Posted: 23-Apr-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X Honda Sensing	\$81,888	\$8,500 /yr	13-Apr-2018	1,496 cc	-	SUV	Available
Only \$800/Mth To Drive Away The Latest Facelifted Honda Vezel With Full Honda Sensing Safety Features! Highly Sought After White On Black Unit! Full Leather Seats For Easy Upkeep! 3 Free Servicing Pac...								
Car Buyer's Automotive Pte Ltd								
Posted: 21-Apr-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X	\$91,988	\$9,470 /yr	26-Apr-2018	1,496 cc	60 km	SUV	Available
3 Years Warranty Provided. Loan Available, Flawless And Pristine Condition, Perfect Paintwork, View To Believe. Hurry Up, Arrange An Appointment With Us Now.								
Posted: 20-Apr-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel Hybrid 1.5A X	\$95,888	\$9,760 /yr	14-May-2018	1,496 cc	50 km	SUV	Available
Fuel Type: Petrol-Electric Condition Like New, Warranty 3 Years In House Workshop, 5 Years Hybrid Motor And Battery, 1 Owner Only, In House Loan And Bank Available. Call Us To View Now!								
Posted: 07-Apr-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Multi Matic Fluid Vehicle Servicing Genuine Honda HMMF Fluid for all CVT gearbox models. Find out more!							
	Honda Vezel 1.5A X	\$85,800	\$8,840 /yr	05-Jun-2018	1,496 cc	-	SUV	Available
Banks/In House Available, Please Call For Financial And Latest Update Price. The Car Agency, Subsidiy Of Thong Lee Trading Is Established Since 1969, And Has Been Awarded As A Premium Dealer By sgCarM...								
Posted: 04-May-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X Honda Sensing	\$86,600	\$8,820 /yr	14-Jun-2018	1,496 cc	4,915 km	SUV	Available
Hitachi Warranty And Free Servicing. Like Brand New.								
Posted: 10-Apr-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X	\$91,988	\$9,400 /yr	23-Jun-2018	1,496 cc	70 km	SUV	Available
3 Years Warranty Provided, Loan Available, Flawless And Pristine Condition, Perfect Paintwork, View To Believe. Hurry Up, Arrange An Appointment With Us Now.								
Posted: 21-Apr-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel Hybrid 1.5A RS Honda Sensing (OPC)	\$85,000	\$8,010 /yr	25-Jun-2018	1,496 cc	42 km	SUV	Available
Fuel Type: Petrol-Electric Why Wait? CDE Is Expected To Sky Rocket. Cat B CDE, Not Cat A, Super High PARF Of \$11,755. Comes With Honda Sensing. Original Condition From Day 1. Almost New Unit That Has Been Unused. Genuine Mileag...								
Posted: 12-Mar-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X	\$79,888	\$8,030 /yr	26-Jun-2018	1,496 cc	-	SUV	Available
3 Years Or 100k Km Warranty, High Trade In. In-house Loan Available.								

Compare

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 16 April 2019 11:13 AM
To: assignments
Subject: RE: 3rd party direct settlement SJF5332J/ & your insured SHD507P/DOA:15/04/2019/Est \$ // S9M01KC8 // WANG Peter // 110790 //
Attachments: TP GIA REPORT.PDF; OI GIA REPORT.PDF

TP SMART

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

12.32pm @ 16/4/19
Sin Hai
vehicle not in

16/4/19 9:57 AM

--- Liability clear - pls proceed DS with quantum to

Message

TP EXcess: \$5000.

- WANG Peter

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Sent: Monday, 15 April, 2019 7:19 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Subject: RE: 3rd party direct settlement SJF5332J/ & your insured SHD507P/DOA:15/04/2019/Est \$

Dear Motor Claims,

Please refer to the attached pdf, we are assisting our insured vehicle SJF5332J to file a 3rd party claim against your insured vehicle SHD507P and to request for direct settlement.

Please assist and expedite to check the claim liability soonest.

Thank you and have a nice day, ☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



GIVE SKIES FOR
OUR CHILDREN



Visit our
Facebook page

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 19/9/2019

Survey Details:

Date of loss	15-Apr-19
Date of appointment	16-Apr-19
Date of survey	6-May-19
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SJF5332J
Make and Model	HONDA HRV 1.5 LX CVT
Date of registration	11-May-18
Parf Rebate	
Market Value	\$ 82,000.00
Parf Rebate	\$ 45,731.00
Nett Loss	\$ 36,269.00

Repair details:

Initial Estimate	\$ 16,208.58
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 1,118.44
Check items (estimate)	\$ -
Labour	\$ 5,000.00
Total	\$ 6,118.44
Lump Sum(if applicable)	\$ -

Number of days for repair	5
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 6,546.72	W/GST
Loss of use	\$ -	
Loss of rental (W/GST)	\$ 535.00	5days x \$107.00
Loss of income	\$ -	
LTA search fees	\$ -	
Others	\$ -	
Proposed Total	\$ 7,081.72	



<MANDATE IA> - S9M01KC8 { ACCIDENT INVOLVING SHD 507P(OI) & SJF 5332J(TP) ON 15/04/2019}

Type

Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$7,081.72 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply



Pls proceed DS with quantum as proposed

Type

🔗 Question

Message

LOR is subject to rental receipt. TP Excess: \$5000.

Reply



Kah Motor Co. Sdn. Bhd.
A Member of Oriental Holdings Berhad
Body Repair & Paint Centre
6A Mandai Estate
Singapore 729903
Tel : +65 6841 3838
Fax : +65 6362 5015
www.honda.com.sg

M/s: AXA Insurance Singapore Pte Ltd

Date : 5/9/2019

8 Shenton Way
#27-01
Singapore 068811

Attn: Motor Claims Department

Your ref : SHD507P

Our ref : SJF5332J

Dear All,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SJF5332J AND SHD507P ON 15/04/2019.

We refer to the item(s) marked (✓) below:

- (✓) We refer to your email dated 23/04/2019
- (✓) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- () Kindly forward the discharge voucher for our client's signature within **2 weeks** via email to : desmondtoh@honda.com.sg
- (✓) We return your discharge voucher duly completed.
- (✓) Kindly expedite settlement the following :-
 - Repair Cost **S\$6,546.72** payable to **Kah Motor Co. Sdn. Bhd.**
 - Loss of RENTAL **S\$107.00 X 05 days=S\$535.00** payable to **NAY LIN TUN**

Loss of Use


(INCLUDING 01 SAT 01 SUN 01 PRI)

LTA Search

- (✓) Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.
- (✓) Letter of Authority

Thank you.

Yours faithfully,


Ng Sin Hai



Service Tax Invoice

Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
6A Mandal Estate, SINGAPORE 729903
Mandal Parts Centre
Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223
Company Ref. No. S60FC1380G

AXA INSURANCE S'PORE PTE LTD
MOTOR CLAIMS DEPT
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE, 068811

Customer Code : CU0129734
Payment Term : 30 Days

Invoice No. : SINV-BM19001426
Invoice Date : 27/08/19
Order No. : SVO19028380
Reference :
Job Card No. : 10567
Date/Time Received : 06/05/19 / 9:26:48 AM
Licence No. : SJF5332J
Model : HRV LX-SIN CVT YM 2016
Car Chassis No. : JHMRU1830GX203842
Car Engine No. : L15B4533841
Mileage : 8926
Service Advisor : NG SIN HAI 1596
Served By : SHNG
Page : 1

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO:)							
	OWNER:NAY LIN TUN							
	OWNER INSURER:AVIVA							
	ACC DATE:15/04/2019							
	SURVEYED BY:STEVE							
	DATE:06/05/2019							
	REF NO:							
	TP INSURER:AXA							
	TP VEH:SHD507P							
BOSUN	0701 SUNDRIES	1	Hours	30.00		30.00	2.10	32.10
BA02R	1729 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	Hours	180.00		180.00	12.60	192.60
BOJSE	1718 SEALANT FOR TAILGATE	1	Hours	80.00		80.00	5.60	85.60
BML02I	1718 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	Hours	180.00		180.00	12.60	192.60
BMI02D	1718 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	Hours	280.00		280.00	19.60	299.60
BKTG02R	1729 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	Hours	560.00		560.00	39.20	599.20
BG02D	1438 REMOVE & INSTALL RR. WINDSCREEN.(N)	1	Hours	560.00		560.00	39.20	599.20
BODAMKIT	1438 WINDSCREEN DAM KIT.	1	Hours	100.00		100.00	7.00	107.00
BKRP02M	1729 CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	Hours	1,680.00		1,680.00	117.60	1,797.60
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	Hours	1,350.00		1,350.00	94.50	1,444.50
68100-T7A-J20ZZ	TAIL GATE COMP	1	Each	855.70	25	641.77	44.92	686.69
75722-T7W-A01	EMBLEMRR.	1	Each	13.30	25	9.97	0.70	10.67
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	Each	17.20	25	12.90	0.90	13.80
71598-T7A-J00	SPACER,L.RR.BPR S	1	Each	17.20	25	12.90	0.90	13.80
91505-TM8-003	CLIP,BUMPER	8	Each	2.30	25	13.80	0.97	14.77
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	Each	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	Each	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	Each	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	Each	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	Each	3.80	25	5.70	0.40	6.10

Printed by SHNG on 27 Aug 2019 at 3:25:26 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.
Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.
Interest will be charged at 2% per month on overdue amounts.

Please give us your feedback by scanning the QR Code using mobile device.





Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE S'PORE PTE LTD
MOTOR CLAIMS DEPT
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE, 068811

Customer Code : CU0129734

Payment Term : 30 Days

Service Tax Invoice

GST Reg No. M200050223
Company Ref. No. S60FC1380G

Invoice No. : SINV-BM19001426
Invoice Date : 27/08/19
Order No. : SVO19028380
Reference :
Job Card No. : 10567
Date/Time Received : 06/05/19 / 9:26:48 AM
Licence No. : SJF5332J
Model : HRV LX-SIN CVT YM 2016
Car Chassis No. : JHMRU1830GX203842
Car Engine No. : L15B4533841
Mileage : 8926
Service Advisor : NG SIN HAI 1596
Served By : SHNG
Page : 2

No.	Description	Qty.	UoM	U.	Price	Disc %	7% GST Amount Incd	
							Amount	GST
75725-T8N-T00	SUPPLEMENTARY EMBLEM,RR. I-VTEC	1	Each	14.50	25		10.87	0.76
04715-T7A-900ZZ	FACE,RR.BUMPER	1	Each	463.70	25		347.77	24.34
Sum Labor							5,000.00	350.00
Sum Item							1,118.44	78.28
Total SGD							6,118.44	428.28
Total Payable (SGD)							6,546.72	

Printed by SHNG on 27 Aug 2019 at 3:25:26 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.
Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.
Interest will be charged at 2% per month on overdue amounts.

Please give us your
feedback by scanning
the QR Code using
mobile device.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19006763/Ega3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: PETER WANG

Date : 14-10-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 507P	Veh. Inspected	SJF 5332J
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01KC8	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	16/04/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA HRV	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMRU1830GX203842	Colour	WHITE
Odometer	016320	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	7 mm
L/H Front Tyre	215/60 R16	DUNLOP	7 mm
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/04/2019	Inspection Date	06/05/2019
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 5332J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
4	REAR SENSORS (SN) (CONSISTENT)	NOT NECESSARY	320.00	-
1	LAMP UNITR. (SN) (CONSISTENT)	NOT NECESSARY	331.12	-
1	LAMP UNITL. (SN) (CONSISTENT)	NOT NECESSARY	331.12	-
1	LIGHT ASSY.R.LID (SN) (CONSISTENT)	NOT NECESSARY	202.42	-
1	LIGHT ASSYL.LID (SN) (CONSISTENT)	NOT NECESSARY	202.42	-
1	TAIL GATE COMP (SN) (CONSISTENT)	DENTED	641.77	641.77
1	WEATHERSTRIP TAILGATE (SN) (CONSISTENT)	NOT NECESSARY	74.02	-
1	LOCK ASSY TAILGATE (SN) (CONSISTENT)	NOT NECESSARY	59.17	-
1	LINING ASSY TAILGATE (SN) (CONSISTENT)	NOT NECESSARY	102.00	-
1	EMBLEMRR. (SN) (CONSISTENT)	NECESSARY	9.97	9.97
1	REFLECTOR ASSYR.RR. (SN) (CONSISTENT)	NOT NECESSARY	117.22	-
1	REFLECTOR ASSYL.RR. (SN) (CONSISTENT)	NOT NECESSARY	117.22	-
1	FACER.RR.BUMPER CORNER (SN) (CONSISTENT)	NOT NECESSARY	70.57	-
1	FACEL.RR.BUMPER CORNER (SN) (CONSISTENT)	NOT NECESSARY	70.57	-
1	SPACER,R.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	12.90	12.90
1	SPACER,L.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	12.90	12.90
8	CLIP, BUMPER (SN) (CONSISTENT)	NECESSARY	13.80	13.80
1	PANEL COMPRR (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	279.82	-
1	LINING ASSYRR.PANEL (SN) (CONSISTENT)	NOT NECESSARY	32.92	-
1	PANEL SETRR. FLOOR (SN) (CONSISTENT)	NOT NECESSARY	506.62	-
3	OILSHEET (SN) (CONSISTENT)	NOT NECESSARY	91.57	-
1	RUBBER CR.WINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	14.47	14.47
1	DAMPERSTD 5X5 (SN) (CONSISTENT)	NECESSARY	6.37	6.37
1	RUBBER CL.WINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	14.47	14.47
1	CAPPIVOT (SN) (CONSISTENT)	NECESSARY	3.60	3.60
4	FASTENER BW/SHIELD (SN) (CONSISTENT)	NECESSARY	15.90	15.90
2	FASTENER B (SN) (CONSISTENT)	NECESSARY	7.95	7.95
2	FASTENER AW/SHIELD (SN) (CONSISTENT)	NECESSARY	5.70	5.70
2	WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	30.00

Report Ref No. CC4/ASM19006763/Ega3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SEALANT FOR TAILGATE (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	WINDSCREEN DAM KIT (SN) (CONSISTENT)	NECESSARY	100.00	100.00
1	SEALANT FOR REAR END PANEL (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	SEALANT FOR REAR FLOOR PANEL (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	EMBLEM,RR. I-VTEC (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	10.87	10.87
1	FACE,RR.BUMPER (SN) (CONSISTENT) (ADDITIONAL)	DENTED	347.77	347.77
			4,587.22	1,328.44
	LABOUR			
	REMOVE & RENEW REVERSE SENSORS.		180.00	180.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		180.00	180.00
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK.		560.00	280.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.		560.00	560.00
	REMOVE & INSTALL RR. WINDSCREEN.		560.00	560.00
	CUT OFF & RENEW RR PANEL. INCLUSIVE OF THE REPAIR OF PANEL COMPRR.		5,000.00	1,680.00
	RREMOVE & INSTALL FUEL TANK FUEL PIPES.	NOT NECESSARY	560.00	-
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		3,000.00	1,350.00
	REMOVE & RENEW RR FLOOR INSULATOR.	NOT NECESSARY	450.00	-
	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA.	NOT NECESSARY	480.00	-
	APPLY BODY UNDERSIDE COATING.	NOT NECESSARY	450.00	-
			11,980.00	4,790.00
	GRAND TOTAL		16,567.22	6,118.44
	RECOMMENDED COST OF REPAIRS			6,118.44

Report Ref No. CC4/ASM19006763/Ega3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.