

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJF5332J

Chassis No : JHMRU1830GX203842

Model : HRV LX-SIN CVT YM 2016

Owner's Name : NAY LIN TUN

Ins Policy No. :

Date of Accident :

Document No. : SQT19001949 Page 1

Date : 6. May 2019

Customer No. : WZA006

Svc Advisor :

Engine No : L15B4533841

Date | Time : 6. May 2019 9:26:48 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	/	180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00	X	80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00	X	80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00	/	80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	/	180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00	X	560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00	280	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00	/	560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00	/	560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	/	100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL. 3	1	5000.00	1680	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) 3	1	3000.00	1350	3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00	X	450.00	31.50	481.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00	/	480.00	33.60	513.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00	X	450.00	31.50	481.50
Sum Labor					12420.00	869.40	13,289.40

Printed on 6/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJF5332J

Chassis No : JHMRU1830GX203842

Model : HRV LX-SIN CVT YM 2016

Owner's Name : NAY LIN TUN

Ins Policy No. :

Date of Accident :

Document No. : SQT19001949

Date : 6. May 2019

Customer No. : WZA006

Svc Advisor :

Engine No : L15B4533841

Date | Time : 6. May 2019 9:26:48 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
RS-TMP3040L	VPC 4PCS REAR SENSORS ?	1	320.00		320.00	22.40	342.40
33502-T7A-J01	LAMP UNITR. X	1	441.50	25	331.12	23.18	354.30
33552-T7A-J01	LAMP UNITL. X	1	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R.LID X	1	269.90	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSYL,LID X	1	269.90	25	202.42	14.17	216.59
68100-T7A-J20ZZ	TAIL GATE COMP / 00	1	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE X	1	98.70	25	74.02	5.18	79.20
74800-T7A-J02	LOCK ASSYTAILGATE ?	1	78.90	25	59.17	4.14	63.31
84431-T7A-J01ZA	LINING ASSYTAILGATE X	1	136.00	25	102.00	7.14	109.14
75722-T7W-A01	EMBLEMRR. / Nec	1	13.30	25	9.97	0.70	10.67
33505-T7A-J01	REFLECTOR ASSYR.RR. ?	1	156.30	25	117.22	8.21	125.43
33555-T7A-J01	REFLECTOR ASSYL.RR. X	1	156.30	25	117.22	8.21	125.43
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER X	1	94.10	25	70.57	4.94	75.51
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER X	1	94.10	25	70.57	4.94	75.51
71593-T7A-000	SPACER,R.RR.BUMPER SIDE a / Nec	1	17.20	25	12.90	0.90	13.80
71598-T7A-000	SPACER,L.RR.BUMPER SIDE / Nec	1	17.20	25	12.90	0.90	13.80
91505-TM8-003	CLIP,BUMPER / Nec	8	2.30	25	13.80	0.97	14.77
66100-T7A-300ZZ	PANEL COMPRR. X R	1	373.10	25	279.82	19.59	299.41
84640-T7A-J01ZA	LINING ASSYRR.PANEL X	1	43.90	25	32.92	2.30	35.22
04655-T7A-310ZZ	PANEL SETRR.FLOOR X	1	675.50	25	506.62	35.46	542.08
72841-SH3-315	OILSHEET X	3	40.70	25	91.57	6.41	97.98
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER } NEC	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10

Printed on 6/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJF5332J
Chassis No : JHMRU1830GX203842
Model : HRV LX-SIN CVT YM 2016
Owner's Name : NAY LIN TUN
Ins Policy No. :
Date of Accident :

Document No. : SQT19001949
Date : 6. May 2019
Customer No. : WZA006
Svc Advisor :
Engine No : L15B4533841
Date | Time : 6. May 2019 9:26:48 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>AKC</i>	2	60.00		120.00	8.40	128.40
Sum Item					3788.58	265.20	4,053.78

Survey By

Steve CLKK

Date & Time

6/5/19 10.20am

Excess

Status

Signature

Total Amount 16,208.58 1,134.60 17,343.18

Total (Inclusive of GST) **17,343.18**

*W/L Prejudice
P/P
Reg bef spy
5 Days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 6/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.