

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
 Chassis No: JHMRU1830GX203842
 License No: SJF5332J
 Mileage: 8926
 Engine No: L15B4533841

Document No: SVO19028380
 Printed By: SHNG
 Order Date: 6. May 2019
 Order Time: 12:09:37 PM
 Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NAY LIN TUN OWNER INSURER: AVIVA ACC DATE: 15/04/2019 SURVEYED BY: STEVE DATE: 06/05/2019 REF NO: TP INSURER: AXA TP VEH: SHD507P SUPPLEMENTARY						
68100-T7A-J20ZZ ①	TAIL GATE COMP	1	855.70	25	641.77	44.92	686.69
75722-T7W-A01 ②	EMBLEM RR.	1	13.30	25	9.97	0.70	10.67
71593-T7A-000 ③	SPACER, R.R. BUMPER SIDE	1	17.20	25	12.90	0.90	13.80
71598-T7A-J00 ④	SPACER, L.R.R. BPR S	1	17.20	25	12.90	0.90	13.80
91505-TM8-003 ⑤	CLIP, BUMPER	8	2.30	25	13.80	0.97	14.77
73214-T7J-H01 ⑥	RUBBER CR. WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000 ⑦	DAMPER STD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01 ⑧	RUBBER CL. WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003 ⑨	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003 ⑩	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003 ⑪	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01 ⑫	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
75725-T8N-T00 ⑬	EMBLEM, RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
04715-T7A-900ZZ ⑭	FACE, RR. BUMPER	1	463.70	25	347.77	24.34	372.11
	SUM PARTS:				1,118.44	78.28	1,196.72
BOSUN	0701	1	30.00		30.00	2.10	32.10
	① SUNDRIES						
BA02R	1729	1	180.00		180.00	12.60	192.60
	② REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BOJSE	1718	1	80.00		80.00	5.60	85.60
	③ SEALANT FOR TAILGATE						
BML02I	1718	1	180.00		180.00	12.60	192.60
	④ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST (N)						
BMI02D	1718	1	280.00		280.00	19.60	299.60
	⑤ REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC. (N)						
BKTG02R	1729	1	560.00		560.00	39.20	599.20
	⑥ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE. (N)						
BG02D	1438	1	560.00		560.00	39.20	599.20
	⑦ REMOVE & INSTALL RR. WINDSCREEN. (N)						
BODAMKIT	1438	1	100.00		100.00	7.00	107.00
	⑧ WINDSCREEN DAM KIT.						



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMRU1830GX203842
License No: SJF5332J
Mileage: 8926
Engine No: L15B4533841

Document No: SVO19028380
Printed By: SHNG
Order Date: 6. May 2019
Order Time: 12:09:37 PM
Service Advisor: NG SIN HAI

BKRP02M	1729	1	1,680.00	1,680.00	117.60	1,797.60
	(9) CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.					
BP06R	1718	1	1,350.00	1,350.00	94.50	1,444.50
	(19) SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION					
			SUM LABOUR:	5,000.00	350.00	5,350.00
			TOTAL SGD	6,118.44	428.28	6,546.72
Total Payable (SGD)						6,546.72

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: ****3839H / NAY LIN TUN
Chassis No: JHMRU1830GX203842
License No: SJF5332J
Mileage: 8926
Engine No: L15B4533841

Document No: SVO19028380
Printed By: SHNG
Order Date: 6. May 2019
Order Time: 12:09:37 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
75725-T8N-T00	SUPPLEMENTARY	1	14.50	25	10.87	0.76	11.63
04715-T7A-900ZZ	EMBLEM,RR. I-VTEC	1	463.70	25	347.77	24.34	372.11
	FACE,RR.BUMPER						
	SUM PARTS:				358.64	25.10	383.74
	TOTAL SGD				358.64	25.10	383.74

Total Payable (SGD)

383.74

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJF5332J

Chassis No : JHMRU1830GX203842

Model : HRV LX-SIN CVT YM 2016

Owner's Name : NAY LIN TUN

Ins Policy No. :

Date of Accident :

Document No. : SQT19001949

Date : 6. May 2019

Customer No. : WZA006

Svc Advisor :

Engine No : L15B4533841

Date | Time : 6. May 2019 9:26:48 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BOSUN ①	SUNDRIES	1	100.00 30		100.00	7.00	107.00
BA02R ②	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 /		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00 X		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00 X		80.00	5.60	85.60
BOJSE ③	SEALANT FOR TAILGATE	1	80.00 /		80.00	5.60	85.60
BML02I ④	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 /		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES (N)	1	560.00 X		560.00	39.20	599.20
BMI02D ⑤	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00 280		560.00	39.20	599.20
BKTG02R ⑥	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 /		560.00	39.20	599.20
BG02D ⑦	REMOVE & INSTALL RR. WINDSCREEN (N)	1	560.00 /		560.00	39.20	599.20
BODAMKIT ⑧	WINDSCREEN DAM KIT.	1	100.00 /		100.00	7.00	107.00
BKRP02M ⑨	CUT OFF & RENEW RR PANEL 3	1	5000.00 1680		5000.00	350.00	5350.00
BP06R ⑩	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) 3	1	3000.00 1350		3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR (N)	1	450.00 X		450.00	31.50	481.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00 /		480.00	33.60	513.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00 X		450.00	31.50	481.50
Sum Labor					12420.00	869.40	13289.40

Printed on 6/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJF5332J
Chassis No : JHMRU1830GX203842
Model : HRV LX-SIN CVT YM 2016
Owner's Name : NAY LIN TUN
Ins Policy No :
Date of Accident :

Document No. : SQT19001949
Date : 6. May 2019
Customer No. : WZA006
Svc Advisor :
Engine No : L15B4533841
Date | Time : 6. May 2019 9:26:48 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
RS-TMP3040L	VPC 4PCS REAR SENSORS ? X NAI	1	320.00		320.00	22.40	342.40
33502-T7A-J01	LAMP UNITR X NAI	1	441.50	25	331.12	23.18	354.30
33552-T7A-J01	LAMP UNITL X NAI	1	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R LID X NAI	1	269.90	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSYLID X NAI	1	269.90	25	202.42	14.17	216.59
68100-T7A-J20ZZ	① TAIL GATE COMP / 00	1	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE X NAI	1	98.70	25	74.02	5.18	79.20
74800-T7A-J02	LOCK ASSYTAILGATE X NAI	1	78.90	25	59.17	4.14	63.31
84431-T7A-J01ZA	LINING ASSYTAILGATE X NAI	1	136.00	25	102.00	7.14	109.14
75722-T7W-A01	② EMBLEMRR. / NAI	1	13.30	25	9.97	0.70	10.67
33505-T7A-J01	REFLECTOR ASSYR.RR. ? X NAI	1	156.30	25	117.22	8.21	125.43
33555-T7A-J01	REFLECTOR ASSYL.RR. X NAI	1	156.30	25	117.22	8.21	125.43
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER X NAI	1	94.10	25	70.57	4.94	75.51
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER X NAI	1	94.10	25	70.57	4.94	75.51
71593-T7A-000	③ SPACER,R.RR.BUMPER SIDE 2 / NAI	1	17.20	25	12.90	0.90	13.80
71598-T7A-000	④ SPACER,L.RR.BUMPER SIDE / NAI	1	17.20	25	12.90	0.90	13.80
91505-TM8-003	⑤ CLIP,BUMPER / NAI	8	2.30	25	13.80	0.97	14.77
66100-T7A-300ZZ	PANEL COMPRR. X R NAI	1	373.10	25	279.82	19.59	299.41
84640-T7A-J01ZA	LINING ASSYRR PANEL X NAI	1	43.90	25	32.92	2.30	35.22
04655-T7A-310ZZ	PANEL SETRR.FLOOR X NAI	1	675.50	25	506.62	35.46	542.08
72841-SH3-315	OILSHEET X NAI	3	40.70	25	91.57	6.41	97.98
73214-T7J-H01	⑥ RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	⑦ DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	⑧ RUBBER CL.WINDSHIELD DAMPER NAI	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	⑨ CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	⑩ FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	⑪ FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	⑫ FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10

Printed on 6/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJF5332J
Chassis No : JHMRU1830GX203842
Model : HRV LX-SIN CVT YM 2016
Owner's Name : NAY LIN TUN
Ins Policy No. :
Date of Accident :

Document No. : SQT19001949
Date : 6. May 2019
Customer No. : WZA006
Svc Advisor :
Engine No : L15B4533841
Date | Time : 6 May 2019 9:26:48 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>SATC X NNI</i>	2	60.00		120.00	8.40	128.40
Sum Item					3788.58	265.20	4,053.78

Survey By : *Steve CLKK*
Date & Time : *6/5/19 10.20am*
Excess :
Status :
Signature :

with Prejudice
PIP
Req bef 5 Days
SPY

Total Amount 16,208.58 1,134.60 17,343.18
Total (Inclusive of GST) 17,343.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 6/5/2019 9:33:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.