



2/5 @ 12,000

Bedok Motor Engineering Pte Ltd
30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
+65 6286 3032

Estimate To Repair CB6725G YUTONG ZK6100H

Chassis No : LZYTBD63B1007081

S/No	Quantity	Description	Amount
LIST ITEMS			
1	1pc	Front windshield glass <i>120 2500</i>	\$ 3,133.43
2	1pc	Front side view mirror assy with arm R/H <i>one</i>	\$ 1,942.21
3	1pc	Front wiper arm R/H <i>3y</i>	\$ 299.42
4	1pc	Front wiper blade R/H <i>11</i>	\$ 69.74
5	1pc	Front wiper arm L/H <i>11</i>	\$ 321.74
6	1pc	Front wiper blade L/H <i>11</i>	\$ 74.42
7	1pc	Front body panel <i>22/magub</i>	\$ 2,942.74
8	1pc	Front body panel badge <i>her</i>	\$ 169.42
9	2pcs	Head lamp @2 \$ 1047.21 <i>0/5 one</i>	\$ 2,094.42
10	1pc	Front body centre reflector garnish <i>one</i>	\$ 647.24
11	1pc	Front bumper <i>21</i>	\$ 2,872.79
12	1pc	Front bumper stay @2 \$247.79 <i>1</i>	\$ 495.58
13	1pc	Front licence plate panel <i>2</i>	\$ 178.24
14	1pc	Front bumper spot lamp @2 \$282.22 <i>0/5 one</i>	\$ 564.44
<i>Not Authorized</i> <i>here tel. 62863581</i> <i>2/5 3 12,000 7 day.</i> <i>17/4/19</i> <i>the phc. Adh. up.</i>			\$ 15,805.83
Less 10%			\$ 1,580.58
			\$ 14,225.25
SPECIAL NETT ITEAMS			
15	1pc	Front windshield glass repair kit <i>her</i>	\$ 500.00
16	1pc	Front licence plate <i>11</i>	\$ 50.00
			\$ 550.00
LABOUR & MISC CHARGE			
1		To remove/refit front windshield glass.	\$ 550.00
2		To remove/ refit instrument dashloard assy to facilitate repairs.	\$ 700.00
3		Check lightings and focussing head-lamp.	\$ 80.00
4		Panel beating.	\$ 3,000.00
5		Spray painting.	\$ 2,200.00
6		To check aircond assy , vaccum and charge in aircond gas.	\$ 280.00
			\$ 6,810.00
Total			\$ 21,585.25

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: