



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLU 1102 E

| | | | |
|-------------------------|-----------------------------|----|-----------------|
| Parts | (a) Cost / List Price Items | \$ | 1,513.10 |
| | Plus/Less 25% | \$ | 378.28 |
| | Total of Cost / List | \$ | 1,134.83 |
| | (b) Nett Price Items | | |
| | Less | | |
| | Total of Nett Item | | |
| | (c) Special Nett Items | \$ | 200.00 |
| Total Parts Cost | | \$ | 1,334.83 |
| Labour | | \$ | 1,050.00 |
| Total | | \$ | 2,384.83 |

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

*Not Authorized
 Resurvey By paint*

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 24/3/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is not authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature] Date: 23/4/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLU 1102 E
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU703579968

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. :

Cost / List

| S/No. | Part Description | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|---|-----|------------|-------|-------------------------|
| 1 | Reverse sensor <i>Sn</i> | 1 | \$200.00 | S.N | X |
| 2 | Rear bumper <i>Bu</i> | 1 | \$497.50 | | ✓ |
| 3 | Rear bumper clip <i>cu</i> | 10 | \$40.00 | | ✓ |
| 4 | Rear bumper side retainer LH <i>Sn</i> | 1 | \$112.70 | | X |
| 5 | Rear bumper side retainer RH <i>dis</i> | 1 | \$112.70 | | ✓ |
| 6 | Rear bumper reinforcement | 1 | \$398.90 | | ? |
| 7 | Rear bumper lower garnish RH <i>mje m</i> | 1 | \$149.70 | | ✓ |
| 8 | Rear bumper under cover RH | 1 | \$187.60 | | ? |
| 9 | Rear bumper under cover clip | 4 | \$14.00 | | ? |
| 10 | | | | | |
| 11 | | | | | |
| 12 | | | | | |
| 13 | | | | | |
| 14 | | | | | |
| 15 | | | | | |
| 16 | | | | | |
| 17 | | | | | |
| 18 | | | | | |
| 19 | | | | | |
| 20 | | | | | |
| 21 | | | | | |
| 22 | | | | | |
| 23 | | | | | |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

