

ASS. REC. BY:

REF:

CS/INC19006782/T1sd387

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Annie Koh

of

INC

Date/Time:

16/4/19 @ 9.47am

Estimated Cost:

Bill to:

OD / ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 4505Z

Insured:

SKA 5008K

at Workshop n/s

Munich Automobile

Tel:

9051 5581

of

30 Jeeban Gardens Crescent

Policy No:

Claim No:

MT/1034482002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/3/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9.55am @ 16/4/19

Person Contacted:

Mr. Tan

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLM 4505Z - X

SKA 5008K - X ...

Surveyor

Tanji

REF: INC

ASSIGNMENT

From: _____ Date: **16/4/19**
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SLM 4505Z**
 at Workshop m/s **Munich Automobile**
 of **30 Jeban Gardens Crescent**
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: **2-3pm**
Mr. Tan @ 9051 9581

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **lup**

Date: _____ Person Contacted: **16/4/19**
 Vehicle: IN / OUT

Veh No: **SLM 4505Z** Yr Regn: **2017, March**
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **BMW M3** C.C. **2979**
 Colour: **white** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **20548** T/Radio: **Insured / Std / NI / NA**
 Eng/No: **WB58M920505F71543**
 C/No: _____
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modi: **Nil** (S/Rim) / STD A/Rim or
 Tyre Size: **F: 285 / 30 R20**
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **1** mm
 D.O.A. _____ D.O.I. **16/4/19**
 Survey held at **Munich Auto**

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
26/4/19	\$4634.74, 1 days, e-mail to 16/4/19
	(\$3,623.66 Redn 44%)

Date/Time, File Pass to?

1) **26/04/19**
Typisp

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ **4,634.74**)

Days Of Repair: **4**

Resurvey No. of Trip: **32**

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation: _____

_____ S + RS, _____ SI

Photos

Others

TOTAL

290

290

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 16 April 2019 9:55 AM
To: 'assignments@lkkauto.com'
Cc: Thio Tse Kiat; Teng Ken Leong
Subject: RE: TP CASES FARMED OUT TO LKK ON 16/04/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 16 April 2019 9:47 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 16/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1040072-002	SMJ1436M	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	/ 6266 0555		SDA8856S	12/4/19	
2	Muhammad Airwan	MT/1032714-002	SKW3185D	HUA HONG PTE LTD	25D SUNGEI KADUT STREET 1 SINGAPORE 729332	Jerleen / Mrs Tan / 6661 9688	14:00- 16:00	YP130C	18/2/19	
3	David Phua	MT/1034482-002	SLM4505Z	MUNICH AUTOMOBILES PTE LTD	30 TEBAN GARDENS CRESCENT SINGAPORE 608927	Tan Kok Ting / 6566 7666	13:00- 15:00	SKA5008K	2/3/19	9051 5581

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

• **Annie Koh**

Senior Admin Assistant, Motor Insurance

T +65 6430 7899

www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shirley Hiew (LKK Auto)

From: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Sent: Friday, 26 April 2019 10:39 AM
To: 'Tan Kok Ting'
Cc: Shirley Hiew (LKK Auto)
Subject: RE: MT/1034482-002 = SKA5008K / SLM4505Z on 2 Mar 2019= Munich Automobiles (2018), Est COR: \$8836.49 - finalize

Hi Kok Ting,

COR \$4634.74 , 4 days.

Regards
Taufikh
Lkk Auto

From: Tan Kok Ting [mailto:kok.ting@munichauto.com.sg]
Sent: Friday, 26 April 2019 10:26 AM
To: 'Taufikh (LKKAuto)'
Subject: RE: MT/1034482-002 = SKA5008K / SLM4505Z on 2 Mar 2019= Munich Automobiles (2018), Est COR: \$8836.49 - finalize

From: Tan Kok Ting [mailto:kok.ting@munichauto.com.sg]
Sent: Friday, April 26, 2019 10:06 AM
To: 'Taufikh (LKKAuto)'
Subject: RE: MT/1034482-002 = SKA5008K / SLM4505Z on 2 Mar 2019= Munich Automobiles (2018), Est COR: \$8836.49 - finalize

Resend

From: Tan Kok Ting [mailto:kok.ting@munichauto.com.sg]
Sent: Thursday, April 25, 2019 7:08 PM
To: 'Taufikh (LKKAuto)'; 'SUR'
Subject: RE: MT/1034482-002 = SKA5008K / SLM4505Z on 2 Mar 2019= Munich Automobiles (2018), Est COR: \$8836.49 - finalize

Hi Taufikh ,

Attached is for finalize. Hope we can finalize this by next Monday.
Please let me know if I can provide additional information.

Regards
Kok Ting

From: MTSurvey [mailto:MTSurvey@income.com.sg]
Sent: Monday, April 15, 2019 3:04 PM
To: Tan Kok Ting
Subject: RE: MT/1034482-002 = SKA5008K / SLM4505Z on 2 Mar 2019= Munich Automobiles (2018), Est COR: \$8836.49

Dear Workshop,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/03/2019 14:36
Date Of Accident	02/03/2019 12:40
Exact Location Of Accident	LORNIE ROAD LANE 1
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLM4505Z
Insured/Policyholder	
Name Of Registered Owner	LIM YONG LI, IRWIN
NRIC No	S8423110Z
Email Address	IRWINLIM@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-94799310
Alternative Phone No	OFFICE-94799310
Vehicle Particulars	
Manufacturer	BMW
Model	M3-3.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M0010744
Cover Note Number	
Driver	
Name of Driver	LIM YONG LI, IRWIN
NRIC No	S8423110Z
Date Of Birth	10/08/1984
Occupation	INDOOR
Date Of Driving Pass	04/04/2003
Driving Experience	15 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94799310
Fax Number	
Contact Number	OFFICE-94799310
EMail Address	IRWINLIM@HOTMAIL.COM

Address	12 PLATINA ROAD SINGAPORE 758620
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA5008A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

after moving off

I was driving on Lone Rd Lane 1. ~~When I moved off~~ I changed lane from 1 to 2 as I am heading towards Thames Rd. Upon completing my lane change, about 5 secs later I was hit by Driver of SKA 5002A from the right side. As I turned into Thames Rd properly to ~~stop~~ stop so that we can exchange particulars, the driver of SKA 5002A kept to the extreme right line and did not have intention to stop. As there was a traffic light ahead, I managed to inform her that ~~it is~~ instead run is an offence. We both turned into SLC Complex to exchange details.

It should also be noted that prior to the accident, the Driver of SKA 5002A ~~changed~~ moved from lane 1 on upper Thames Road ~~and~~ ~~at~~ ~~to~~ ~~lane~~ ~~4~~ to lane 4 to take the exit to Lone Road abruptly. This abrupt moving is captured on the video.

Accident occurred on Saturday, 2nd March Approx. 12:40 PM

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 4 March 2017
11:40 AM

Driver's Signature

(If driver is not the policyholder)
Date & Time: 4 March 2017
10:50 AM

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

Munich Automobiles (2018) Pte Ltd

Company Reg No: 201813033K
GST Reg No: 201813033K
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **C0002**

Invoice Name & Address:
Mr Irwin Lim Yong Li
12 Platina Eroad

Customer Name & Address:

Mr Irwin Lim Yong Li
12 Platina Eroad

758620

758620

Email: irwinlim@hotmail.com

Inv. Printed By: TKT Service Advisor:

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 13110	0	0		08/03/2019	09:51	1
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SLM4505Z	5E21543	M3 Sedan LCI	30/03/2017		0	
Job Description						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
1	GEN	Remove damaged body parts and replaced affected body part		192.00	12.50		0.00	2,400.00
2	GEN	Knock rear right fender and both right door		96.00	12.50		0.00	1,200.00
3	GEN	Painting both right door, right sill cover and rear right fender		320.00	12.50		0.00	4,000.00
4	SUN	Sundry items		150.00	1.00		0.00	150.00
Menu Subtotal:								7,750.00
5		B021011 Side sill, p		1.00	419.20 EACH		0.00	419.20
6		A061276 Protective f		1.00	89.20 EACH		0.00	89.20
								84.74

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.

Munich Automobiles (2018) Pte Ltd

Company Reg No: 201813033K
GST Reg No: 201813033K
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **C0002**

Invoice Name & Address:

Mr Irwin Lim Yong Li
12 Platina Eroad

Customer Name & Address:

Mr Irwin Lim Yong Li
12 Platina Eroad

758620

758620

Email: irwinlim@hotmail.com

Inv. Printed By: TKT Service Advisor:

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 13110	0	0		08/03/2019	09:51	2
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SLM4505Z	5E21543	M3 Sedan LCI	30/03/2017		0	
Job Description						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
Menu Subtotal:								508.40
7	NOTES	Third party claim against Etiqa (SKA5008A) D.O.A : 2/March/2019 1240hrs		0.00	0.00		0.00	0.00
Menu Subtotal:								0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

18/4/19
Tanfer 97495744
16/4/19 0230pm
& Resurvey after repair.
4 days
Tanfer@lkkauto.com

Parts 508.40
Surcharge 0.00
Labour 7,750.00
Sublet 0.00
Menus 0.00

V	Rate	Service/Goods	GST	Net	
S	7.00	8258.40	578.09	G.S.T.	578.09
				Total	8,836.49
				Deposit	0.00
				Owing	8,836.49

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.

Munich Automobiles (2018) Pte Ltd

Company Reg No: 201813033K
GST Reg No: 201813033K
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. N0001

Invoice Name & Address:

NTUC Income Insurance Co-operative
75 Bras Basah Road
NTUC Income Centre
Singapore 189557

Customer Name & Address:

Mr Irwin Lim Yong Li
12 Platina Eroad

758620

Email: irwinlim@hotmail.com

Inv. Printed By: TKT Service Advisor: Tan Kok Ting

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
B 13110	26958	0	INS	26/04/2019	10:25	1
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SLM4505Z	5E21543	M3 Sedan LCI	30/03/2017	16/04/2019	20548	
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
1	GEN	Remove damaged body parts and replaced affected body part		96.00	12.50		0.00	1,200.00
2	GEN	Knock rear right fender and rear right door		48.00	12.50		0.00	600.00
3	GEN	Repair and re-Paint right door, right sill cover rear right fender and blend front right door		216.00	12.50		0.00	2,700.00
4	SUN	Sundry items		50.00	1.00		0.00	50.00
Menu Subtotal:								4,550.00
5		Protective film, whe		1.00	89.20 EACH		5.00	84.74

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No.

N.B. Goods sold are not returnable.

Munich Automobiles (2018) Pte Ltd

Company Reg No: 201813033K
GST Reg No: 201813033K
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **N0001**

Invoice Name & Address:

NTUC Income Insurance Co-operative
75 Bras Basah Road
NTUC Income Centre
Singapore 189557

Customer Name & Address:

Mr Irwin Lim Yong Li
12 Platina Eroad

758620

Email: irwinlim@hotmail.com

Inv. Printed By: TKT Service Advisor: Tan Kok Ting

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
B 13110	26958	0	INS	26/04/2019	10:25	2
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SLM4505Z	5E21543	M3 Sedan LCI	30/03/2017	16/04/2019	20548	
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
		Menu Subtotal:						84.74
6	NOTES	Third party claim against NTUC(SKA5008K) D.O.A : 2/March/2019 1240hrs		0.00	0.00		0.00	0.00
		Menu Subtotal:						0.00

	V	Rate	Service/Goods	GST	Net	
Parts		84.74			4,634.74	
Surcharge	S	0.00	4634.74	324.43	G.S.T.	324.43
Labour		4,550.00			Total	4,959.17
Sublet		0.00			Deposit	0.00
Menus		0.00			Owing	4,959.17

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No

N.B. Goods sold are not returnable.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19006782/T1sd3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 26-04-2019



ATTN : DAVID PHUA

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKA 5008K	Veh. Inspected	SLM 4505Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1034482-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	16/04/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. M3	c.c	2979
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBS8M920505E21543	Colour	WHITE
Odometer	20548 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	285/30 R20	MICHELIN	6 mm
L/H Front Tyre	285/30 R20	MICHELIN	6 mm
R/H Rear Tyre	285/30 R20	MICHELIN	6 mm
L/H Rear Tyre	285/30 R20	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/03/2019	Inspect Date / Time	16/04/2019 (02:30 PM)
Survey held at	MUNICH AUTOMOBILES PTD LTD 30 TEBAN GARDENS CRESCENT SINGAPORE 608927		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 4505Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUNDRY ITEMS (SN)	NECESSARY	150.00	50.00
1	B021011 SIDE SILL, P (SN)	TO REPAIR SEE LABOUR	419.20	-
1	A061276 PROTECTIVE F (SN)	NECESSARY	89.20	84.74
			658.40	134.74
<u>LABOUR</u>				
	REMOVE DAMAGED BODY PARTS AND REPLACED AFFECTED BODY PART. INCLUSIVE OF THE REPAIR OF B021011 SIDE SILL, P.		2,400.00	1,200.00
	KNOCK REAR RIGHT FENDER AND BOTH RIGHT DOOR.		1,200.00	600.00
	PAINTING BOTH RIGHT DOOR, RIGHT SILL COVER AND REAR RIGHT FENDER.		4,000.00	2,700.00
			7,600.00	4,500.00
GRAND TOTAL			8,258.40	4,634.74
RECOMMENDED COST OF REPAIRS (CONFIRMED)				4,634.74

Report Ref No. CS/INC19006782/T1sd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.