

22/03/2013

ASS. REC. BY:

REF: CS/CT219006784/R1Vd31

Special Instructions:

SURVEYOR: RASUL

ASSIGNMENT (Office)

mbrinn

From (Person): Ong Chin Kiat

of CT2

Date/Time: 16-4-19 16:47 PM

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SF2 318B

Insured: PC5433X

at Workshop m/s Goldbell Engineering

Tel: 97396452

of BK K, Pandan Loop Industrial Estate # 01-12

Policy No: DMBLSN1708941902

Claim No: SNM19D201685102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14.4.19

17.4.19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 16-4-19 4:59 PM

Person Contacted: Andy

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SF2 318B - CS/TM/1401/1413 / M/V BW2
	PC5433X - X
23/4/19	LS \$2800 confirmed by email (Ref 2490.80, 47/1)

Pavan

ASSIGNMENT

56.62
008 XPMY. 2027/may

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFZ 318B

at Workshop m/s: GOLDALL ENGINEERING

of: PANDAN LAMP

Insured: CTL

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No


Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Veh No: SFZ 318B Yr Regn: 2007 mpc

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MERCEDES BENZ S300L c.c: 2997

Colour: GOLD A/C: Insured / Std / NI / NA

Sp. Reading: 199683 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 221 542 A 099 159

Gen. Cond: Good Far / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 5/Rim / STD A/Rim or

Tyre Size: F: 255/352R20 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA MK / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 14/04/19 D.O.L: 17/04/19

Survey held at: GOLDALL

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or REAR N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 23 APR 2019

Date/Time, File Pass to? ☐ : Prel. Report

if ☐ : Final Report

Date/Time, File Return to?

23/4 - typist

Report Format: merimen

Lump Sum / I.B.I: (\$) 2800/-

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

Site Insp. (\$)

Interview (\$)

Others (\$)

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2019		16 Apr 2019 16:47 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant: CHAN MEN WAI, ID: S1615606Z

Vehicle Reg. No.: SFZ318B

Date of Loss: 14/04/2019 15:00 - :59

Claim Type: TP / SNM19D201685C02

Policy/Cover Note No.: DMB15N1708941902

Vehicle Reg. No. (Insured): PC5433X

Policy No. (Claimant): 18-MY004471-R05

Excess: S\$2,000.00

Repairer: Goldbell Engineering Pte Ltd (Pandan) Blk K, Pandan Loop Industrial Estate, #01-12, 128219 Tues - Tel:

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]

Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/04/2019]

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: 18-MY004471-R05 (Private Motor Car)

1. Index Mark and Registration Number of Vehicle: SFZ318H Chassis No.: WDD2211542A099159
2. Name of Policyholder: MR CHAN MEN WAI
3. Effective date of the Commencement of Insurance for the purposes of the Act: 18/08/2018
4. Date of Expiry of Insurance: 15/09/2019
5. Persons or Class of Persons entitled to drive*
 - (a) The Policyholder;
 - (b) Any other person who is driving on the Policyholder's order or with his permission.

* Provided that the Person driving is permitted in accordance with the Licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*
 Use only for social domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered operative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy in which this Certificate is issued is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the Insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the Insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost or destroyed, you must make a statutory declaration to that effect. Failure to comply with this rule is an offence under Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: 0751DDA

Insurance Plan: Third Party, Fire & Theft
 Limit for total loss or theft: Prevailing Market Value
 Financial Interest: UNITED OVERSEAS BANK LTD

Tokio Marine Insurance Singapore Ltd.

Authorised Signature



Identity Card No. S7976450G



25-02-2004

Address

51 EWE BOON ROAD
#02-09
SINGAPORE 258342

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 2 Motor cars $\leq$ 3000 kg with $\leq$ 7 passengers, exclusive of the driver; and motor tractors / vehicles $\leq$ 2500 kg

19 Nov 2004



SP 4284

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7976450G



Name

WANG XUELIN

王 雪 林

Race

CHINESE

Date of birth

16-05-1979

Country of birth

CHINA

Sex

M

S7976450G

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7976450G

Name

WANG XUELIN

Birth Date: 16 May 1979

Issue Date: 19 Nov 2004



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the forwarding of this report to the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 15/04/2019 16:37
Date Of Accident 14/04/2019 15:00
Exact Location Of Accident WHITEY RD SLIP RD TO DUNEARN RD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFZ318B
Insured/Policyholder
Name Of Registered Owner CHAN MEN WA
NRIC No S78158082
Email Address WANGXUELIN@YAHOO.COM
Mobile Phone No (LOCAL) +65-93879716
Alternative Phone No OFFICE-93879716

Vehicle Particulars

Manufacturer MERCEDES-BENZ
Model S300-3.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 18-WYD04471-R05
Cover Note Number

Driver

Name of Driver WANG XUE LIN
NRIC No S78794500
Date Of Birth 18/05/1979
Occupation INDICOR
Date Of Driving Pass 18/11/2004
Driving Experience 14 YEARS AND 4 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-93879716
Fax Number
Contact Number
EMail Address WCEMAIL

Address 51 EWE BOON RD #02-09
 Postcode 259345
 Was driver an employee of the Insured's Company? NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle
 Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance? NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME : DAUGHTER
 GENDER : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLANS

Attachment(s)


Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC5433X
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

WHITLEY ROAD



DUNEARN ROAD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened at slip road exit from
Whitley Rd to Dunearn Rd.
While stationary at the slip road waiting for
traffic to clear along Dunearn Rd to clear, suddenly
Veh No PC5433X collided on to the rear of
my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:



SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638884
Tel: +65 6861 0017 Fax: +65 6861 3076 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No: 199603963G

Page 1 / 2

ESTIMATE

Date	: 16/04/2019	Reg No	: SFZ318B
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: S300L
Attn.	:	Chassis No	: WDD2211542A099159
Office / Mobile	:	Engine No	: 27294630497422
Email Address	:	Quotation No.	: 85810
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 14/04/2019
Attn.	: ANDYOOILK	Policy No.	: 18-MY004471-R05
Office / Mobile	: +65 67730073	Claim Type	: THIRD PARTY CLAIM
Email / Fax No.	: AndyOilK@goldbell.com.sg	Workshop	: PANDAN

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		REAR BUMPER <i>DE ✓</i>	1	1,898.00	-10	1,708.20	1,708.20
2		REAR BUMPER REINFORCEMENT <i>1 XSC</i>	1	720.00	-10	648.00	648.00
3		REAR BUMPER REVERSE SENSOR LH-2PCS <i>MIS/</i>	2	186.00	-10	167.40	334.80
4		TAIL LAMP ASST LH <i>CRS ✓</i>	1	650.00	-10	585.00	585.00
5		REAR BUMPER REVERSE SENSOR RH-2PCS <i>XSC</i>	2	186.00	-10	167.40	334.80
PARTS TOTAL :							3,610.80

LABOUR CHARGES

1	TO REMOVE AND REPLACED DAMAGED PARTS , CUT , WELD , STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	400 750.00
2	TO PUTTY , CLEAN , SPRAY PAINT AND POLISHING ON REAR BUMPER , BOOT LID GARNISH	400 800.00
3	TO REMOVE AND REPLACED REAR BUMPER SENSOR	50 80.00
4	SUNDRIES <i>New</i>	20 50.00

LABOUR TOTAL :	1,680.00
SUB-TOTAL :	5,290.80
GST @ 7% for \$ 5,290.80	370.36
GRAND TOTAL (S\$) :	5,661.16



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 10 Singapore 336894
Tel: +65 6861 0007 Fax: +65 6861 3079 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No.: 188003963G

Page 2 / 2

ESTIMATE

Date	: 16/04/2019	Reg No	: SFZ3188
To	: CHINA TAIPIING INSURANCE (SINGAPORE) PTE. LTD.	Model	: S300L
Attn.	:	Chassis No	: WDD2211542A099159
Office / Mobile	:	Engine No	: 27294630497422
Email Address	:	Quotation No.	: 85810
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 14/04/2019
Attn.	: ANDYOOILK	Policy No.	: 18-MY004471-R05
Office / Mobile	: +65 67730073	Claim Type	: THIRD PARTY CLAIM
Email / Fax No.	: AndyOilK@goldbell.com.sg	Workshop	: PANDAN

PREPARED BY : ANDYOOILK

DATE / TIME : 17/04/19 @ 105K

SURVEYOR : RASUE

MOBILE NO : 90010068

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

[Signature]
18/4/19

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / **COMBINE**

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT **AFTER PAINT**

NO. OF DAYS : 4 days

REMARKS : _____

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Authorised by Repairer

Signature

Date

biSAFE
STAR

AIA
SINGAPORE
LICENSURE NO. AA010000200

AIA
SINGAPORE
LICENSURE NO. AA010000200



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 630894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No. 108003561C

Page 1 / 2

ESTIMATE

Date :	16/04/2019	Reg No :	SFZ318B
To :	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model :	S300L
Attn. :		Chassis No :	WDD2211542A099159
Office / Mobile :		Engine No :	27294630497422
Email Address :		Quotation No. :	85810
		Ref. No. :	GBE/SVC/SALES
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	14/04/2019
Attn. :	ANDYOOILK	Policy No. :	18-MY004471-R05
Office / Mobile :	+65 67730073	Claim Type :	THIRD PARTY CLAIM
Email / Fax No. :	AndyOilK@goldbell.com.sg	Workshop :	PANDAN

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		REAR BUMPER <i>VE</i>	1	1,898.00	-10	1,708.20	1,708.20
2		REAR BUMPER REINFORCEMENT <i>1</i>	1	720.00	-10	648.00	648.00 <i>X</i>
3		REAR BUMPER REVERSE SENSOR LH- 2PCS <i>MIS</i>	2	186.00	-10	167.40	334.80
4		TAILGATE ASSY LH <i>CR</i>	1	650.00	-10	585.00	585.00
5		REAR BUMPER REVERSE SENSOR RH-2PCS <i>X</i>	2	186.00	-10	167.40	334.80 <i>X</i>
PARTS TOTAL :							3,610.80

LABOUR CHARGES

1	TO REMOVE AND REPLACED DAMAGED PARTS , CUT , WELD , STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	400	750.00
2	TO PUTTY , CLEAN , SPRAY PAINT AND POLISHING ON REAR BUMPER , BOOT LID GARNISH	400	800.00
3	TO REMOVE AND REPLACED REAR BUMPER SENSOR	50	80.00
4	SUNDRIES	20	50.00

LABOUR TOTAL : 1,680.00

SUB-TOTAL : 5,290.80

GST @ 7% for \$ 5,290.80 370.36

GRAND TOTAL (S\$) : 5,661.16

P- 2628.00

L- 870.00

FINALISE 3498.00 - 20% = 2800.00 4/5 repair
with 7 days

bizSAFE
STARS





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3570 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co Reg No. 156030630

Page 2 / 2

ESTIMATE

Date :	16/04/2019	Reg No :	SFZ318B
To :	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model :	S300L
Attn. :		Chassis No :	WDD2211542A099159
Office / Mobile :		Engine No :	27294630497422
Email Address :		Quotation No. :	85810
		Ref. No. :	GBE/SVC/SALES
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	14/04/2019
Attn. :	ANDYOOILK	Policy No. :	18-MY004471-R05
Office / Mobile :	+65 67730073	Claim Type :	THIRD PARTY CLAIM
Email / Fax No. :	AndyOilK@goldbell.com.sg	workshop :	PANDAN

PREPARED BY : ANDYOOILK

DATE / TIME : 17/04/19 @ 1056

SURVEYOR : Rasue

MOBILE NO : 90010068

OFFICE FAX NO :

EMAIL ADDRESS :

EXCESS AMOUNT :

REPAIR TYPE : PART-BY-PART / IMPULSE

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT AFTER PAINT

NO. OF DAYS : 4 days

REMARKS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE
STARS



CLAIMS HANDLING AUTHORITY

CLAIMS HANDLING AUTHORITY

CLAIMS HANDLING AUTHORITY

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 23 April 2019 11:11 AM
To: Andy Ooi Lee Keong; SUR
Cc: Rasul (LKKAUTO)
Subject: RE: PLEASE CONFIRMED FINALISED AMOUNT - SFZ318B

Dear Andy,

WITHOUT PREJUDICE

Confirmed Lump Sum \$2800/ @ 4 working days.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING, their ref: SNM19D201685102

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Andy Ooi Lee Keong <AndyOoiLK@goldbell.com.sg>
Sent: Monday, 22 April 2019 9:45 AM
To: SUR <sur@lkkauto.com>
Cc: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: PLEASE CONFIRMED FINALISED AMOUNT - SFZ318B

Hi Rasul,

Kindly find the above attached After paint photo ,
Please closed Lump sum Repairs @ \$2800.00 before 7% Gst with 04 days

Thanks & regards



GOLDBELL
ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

Andy Ooi Lee Keong | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6458 9596 | Tel: +65 6773 0073 | Fax: +65 6458 7172 |
Mobile: +65 8816 2798 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Pandan)
Blk K, Pandan Loop Ind. Estate, #01-12 Singapore 128230

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2019		16 Apr 2019 16:47 Edit Adj Rpt	S\$2,800.00 Edit Estimates	S\$2,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: ~ ID: -									
Main Claimant: CHAN MEN WAI , ID: S1615606Z									
Vehicle Reg. No.: SF2318B		Date of Loss: 14/04/2019 15:00 - :59 [144 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D201685C02		Policy/Cover Note No.: DMB1SN1708941902							
Vehicle Reg. No. (Insured): PC5433X		Policy No. (Claimant): 18-MY004471-R05							
		Excess: S\$2,000.00							
Repairer: Goldbell Engineering Pte Ltd (Pandan) Blk K, Pandan Loop Industrial Estate, #01-12, 128219 Tuas - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]									
Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/04/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFZ318B (SNM19D201685C02)
[PC5433X]
TP
CHAN MEN WAI
Apr 14 2019 3:00PM
[-]
Goldbell Engineering Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
1	15/04/19 16:46	Accident Statement		Load HTM	

Photos/Images

3 per page

No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
1	15/04/19 16:45	Accident Photo [Linked Accident Report Documents]		Load JPG	
2	15/04/19 16:45	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	15/04/19 16:45	Accident Photo [Linked Accident Report Documents]		Load JPG	
4	15/04/19 16:45	Accident Photo [Linked Accident Report Documents]		Load JPG	
5	15/04/19 16:45	Accident Photo [Linked Accident Report Documents]		Load JPG	
6	15/04/19 16:45	Accident Photo [Linked Accident Report Documents]		Load JPG	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/04/19 10:58	General View		Load PDF	
2	23/04/19 10:58	Reinspection Photo		Load PDF	

Documentation

1 per page

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/04/19 16:47	PRS - SFZ318B		Load PDF	
2	16/04/19 16:49	EMAIL - SFZ318B		Load PDF	

No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
1	15/04/19 16:45	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	15/04/19 16:45	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

View View in Browser

Assessment Reports				1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
1	15/04/19 16:46	Accident Statement	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
1	15/04/19 16:45	Accident Photo	1	Load JPG	☒
2	15/04/19 16:45	Accident Photo	1	Load JPG	☒
3	15/04/19 16:45	Accident Photo	1	Load JPG	☒
4	15/04/19 16:45	Accident Photo	1	Load JPG	☒
5	15/04/19 16:45	Accident Photo	1	Load JPG	☒
6	15/04/19 16:45	Accident Photo	1	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
Documentation				
			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
1	15/04/19 16:45	Sketch Plan	 Load TIF	
2	15/04/19 16:45	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19006784/T1VD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SN1708941902

Claimant Vehicle
No: SFZ318BInsured Vehicle
No: PC5433X

Date of Loss: 14/04/2019

Nature of Claim: TP

Claim
No: SNM19D201685C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFZ318B

Make & Model: MERCEDES-BENZ S300, 3.0 (A)

Engine No: 27294630497422

Reg. Date: 16/03/2007 (Man. Year: 2006)

Chassis No: WDD2211542A099159

Colour: Gold

Odometer: 199643 km

Engine Capacity: 2997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35Z R20

Rear Tyre Size: 255/35Z R20

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,660.80	2,648.00	1,012.80	27.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	850.00	780.00	47.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,290.80	3,498.00	1,792.80	33.89
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	5,290.80	2,800.00	2,490.80	47.08
+ GST 7.00/7.00% (S\$)	370.36	196.00	174.36	47.08
Nett Amount (S\$)	5,661.16	2,996.00	2,665.16	47.08

INSPECTION

Date of Assignment: 16/04/2019

Date Inspected: 17/04/2019 Inspected At:

Goldbell Engineering Pte Ltd (Pandan)
Blk K, Pandan Loop Industrial Estate, #01-12
Singapore 128219

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts:	143	MERCEDES-BENZ S300 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFZ318B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,898.00 FL	*1,898.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	720.00 FL	*- FL
3	2		*REAR BUMPER REVERSESENSOR LH	Missing	372.00 FL	*372.00 FL
4	1		*TAILLAMP ASSY LH	Cracked	650.00 FL	*650.00 FL
5	2		*REAR BUMPER REVERSE SENSOR RH	Serviceable	372.00 FL	*- FL
6	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,062.00	2,940.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	401.20	292.00
Total Parts (\$\$)	3,660.80	2,648.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACED DAMAGED PARTS ,CUT ,WELD ,STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	750.00	400.00
2	TO PUTTY,CLEANE ,SPRAY PAINT AND POLISHING ON REAR BUMPER ,BOOT LID GARNISH	New	800.00	400.00
3	TO REMOVE AND REPLACED REAR BUMPER SENSOR	New	80.00	50.00
Gross Labour Cost (\$\$)			1,630.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >