

ASS. REC. BY:

REF: CS/MSG 190067861 Kq/d3ⁿ²

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

MUMH

From (Person): Irene Tan Gek Ing of MS16

Date/Time: 16.4.19 16:38 pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGT 1716Z

Insured: SGU 9732T

at Workshop m/s Chung Hoe Motor

Tel: 64812001

of 10 Ang Mo Kio Ind Park 2A, # 01-04

Policy No: 28729747

Claim No: 590640

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 16.4.19

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGT 1716Z - X
	SGU 9732T - X
18/4-	reused preli advice via menmen

ASS. REC. BY:

REF:

MSG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SG717168 Yr Regn: 04, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy ⁴ ~~Aris~~ c.c. 1598

Colour: M. Gold A/C: Insured / Std / NI / NA

Sp. Reading: 65235 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR053 E EG07130320

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/70R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 13/4/11

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 17/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

117 61 Lp & 20301 Confirm E funds (Red to 93223, 317)

RECEIVED 04 JUL 2019

4/7/2019

Date/Time, File Pass to?



: Prel. Report

1) 04/7 2019



: Final Report

Date/Time, File Return to?

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + R.S. SI

Fuels

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

MER-TP

7050

150

11

161

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 18 Apr 2019

Preliminary Advice

Insured Vehicle No	: SGU9732T	Accident Date	: 13/04/2019
TP Vehicle No	: SGT1716Z	Assignment Date	: 16/04/2019
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 6.00
Date of Inspection	: 17/04/2019		
Inspection At	: CHENG HOE MOTOR PTE LTD (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,982.23
Revised Amount	:S\$	2,568.98
Check Items (Estimated)	:S\$	203.25
Total	:S\$	2,772.23
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2019		16 Apr 2019 16:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TENG HENG YEW, ID: S1828534G, Tel: +6597609606, Email: AVAD.TENG@GMAIL.COM								
Main Claimant:	PENG CHEE SENG (PENG ZHICHENG), ID: S7600650D								
Vehicle Reg. No.:	SGT1716Z	Date of Loss:	13/04/2019 16:00 - :59 [144 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 590640	Policy/Cover Note No.:	28729747 (TP, Fire & Theft) Coverage: 30/05/2018 - 29/05/2019						
Vehicle Reg. No. (Insured):	SGU9732T	Policy No. (Claimant):							
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/04/2019]								
Driver/Custodian (Insured):	TENG HENG YEW (51 / Male), NRIC: S1828534G, Tel: +6597609606 Email: AVAD.TENG@GMAIL.COM								
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK (KENNETH KONG). LIABILITY:100% CONTACT: DORLYN LI 6481 2001								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
☐ ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	0650D

Vehicle Details

Vehicle No.:	SGT1716Z
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Gold
Manufacturing Year:	2006
Engine No.:	3ZZ4600243
Chassis No.:	MR053ZEC107130320
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,498.00
Original Registration Date:	02 Apr 2007
First Registration Date:	02 Apr 2007
Transfer Count:	1
Actual ARF Paid:	\$14,601.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Mar 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$24,715.00
COE Rebate Amount:	\$14,629.00
Total Rebate Amount:	\$14,629.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Apr 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO 201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 13/04/2019

TP Veh Reg No: SGU9732T

Estimate No: ES1991406/AMK

Date: 15 Apr 2019

Policy No: 5108405273

Veh Reg No: SGT1716Z

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Chassis No: MR053ZEC107130320

Engine No: 3ZZ4600243

Reg. Date: 02/04/2007

Estimate Repair Cost to Vehicle No :SGT1716Z

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	384.90	1 PC	CM 384.90	✓
2 REAR BUMPER LH SIDE RETAINER	9.60	1 PC	DT 9.60	✓
3 REAR BUMPER CLIP	3.50	5 PC	2 17.50	✓
4 LH TAILLAMP	271.00	1 PC	2 271.00	✓
5 LH TAILLAMP LOWER PANEL	94.00	1 PC	2 94.00	✓
6 LH TAILLAMP LOWER PANEL RIVET	2.00	4 PC	2 8.00	✓
7 REAR LH FENDER	718.20	1 PC	2 718.20	✓
8 REAR WINDSCREEN GLASS MOULDING	50.82	1 PC	2 50.82	✓
9 REAR BOOT EMBLEM 'COROLLA'	13.09	1 PC	2 13.09	✓
10 REAR BOOT EMBLEM 'ALTIS'	13.58	1 PC	2 13.58	✓
11 REAR BOOT EMBLEM '1.5'	32.91	1 PC	2 32.91	✓
12 REAR BOOT EMBLEM 'E'	30.94	1 PC	2 30.94	✓
13 REAR BOOT EMBLEM 'VVT-I'	38.43	1 PC	2 38.43	✓
			1,682.97	
		Less 25%	420.74	1,262.23
Special Net				
14 REAR WINDSCREEN GLASS SEALANT	40.00	1 UNIT	2 40.00	✓
			40.00	40.00
Labour				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
16 REMOVE & REFIX REAR BUMPER, TAILLAMP & LOWER PANEL, REAR BOOT & ATTACHMENTS, TO CUT, WELD & RENEW REAR LH FENDER, KNOCKING & REPAIR REAR END PANEL & REALIGN THE SAME	700.00	1 LA	700.00	600
17 PUTTY & RESPRAY REAR BUMPER, REAR BOOT, TAILLAMP LOWER PANEL, REAR LH FENDER, REAR END PANEL & ALL AFFECTED AREAS	700.00	1 LA	700.00	600
18 REMOVE & REFIX REAR SEAT, CARPET TO FACILITATE REPAIR	100.00	1 LA	100.00	✓
19 RUSTPROOFING	60.00	1 LA	60.00	50
			1,680.00	1,680.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK
Claim Type: Third Party
Accident Date: 13/04/2019
TP Veh Reg No: SGU9732T

Estimate No: ES1991406/AMK
Date: 15 Apr 2019
Policy No: 5108405273
Veh Reg No: SGT1716Z
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chassis No: MR053ZEC107130320
Engine No: 3ZZ4600243
Reg. Date: 02/04/2007

Estimate Repair Cost to Vehicle No :SGT1716Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 2,982.23
			Add GST @ 7%	208.76
			Total Amount Payable	<u>S\$ 3,190.99</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19006786/KQD3N2

Date: 10/07/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28729747
Claimant Vehicle No :	SGT1716Z	Insured Vehicle No :	SGU9732T
Date of Loss:	13/04/2019	Nature of Claim:	TP
		Claim No:	590640

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT1716Z	Engine No:	3ZZ4600243
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEC107130320
Reg. Date:	02/04/2007 (Man. Year: 2006)	Odometer:	65235 km
Colour:	Metallic Gold		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70R14	Rear Tyre Size:	185/70R14
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,302.23	1,098.98	203.25	15.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,470.00	210.00	12.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,982.23	2,568.98	413.25	13.86
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	2,982.23	2,050.00	932.23	31.26
+ GST 7.00/7.00% (S\$)	208.76	143.50	65.26	31.26
Nett Amount (S\$)	3,190.99	2,193.50	997.49	31.26

INSPECTION

Date of Assignment: 16/04/2019

Date Inspected: 17/04/2019 Inspected At:

10 ANG MO KIO IND PARK 2A
 #01-04 ANG MO KIO AUTOPOINT
 SINGAPORE 568047
 REPAIRER : CHENG HOE MOTOR
 PTE LTD

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2019)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT1716Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	384.90 FL	*384.90 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Distorted	9.60 FL	*9.60 FL
3	5		*REAR BUMPER CLIP	Necessary	17.50 FL	*17.50 FL
4	1		*LH TAILLAMP	Serviceable	271.00 FL	*- FL
5	1		*LH TAILLAMP LOWER PANEL	Bent	94.00 FL	*94.00 FL
6	4		*LH TAILLAMP LOWER PANEL RIVET	Necessary	8.00 FL	*8.00 FL
7	1		*REAR LH FENDER	Buckled	718.20 FL	*718.20 FL
8	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	50.82 FL	*50.82 FL
9	1		*REAR BOOT EMBLEM COROLLA	Necessary	13.09 FL	*13.09 FL
10	1		*REAR BOOT EMBLEM ALTIS	Necessary	13.58 FL	*13.58 FL
11	1		*REAR BOOT EMBLEM 1.5	Necessary	32.91 FL	*32.91 FL
12	1		*REAR BOOT EMBLEM E	Necessary	30.94 FL	*30.94 FL
13	1		*REAR BOOT EMBLEM VVT-I	Necessary	38.43 FL	*38.43 FL
14	1		*UNIT REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,722.97	1,451.97
- List Item Discount on L Items 25.00/25.00% (\$\$)	420.74	352.99
Total Parts (\$\$)	1,302.23	1,098.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER, TAILLAMP & LOWER PANEL, REAR BOOT & ATTACHMENTS. TO CUT, WELD & RENEW REAR LH FENDER; KNOCKING & REPAIR REAR END PANEL & REALIGN THE SAME	New	700.00	600.00
3	PUTTY & RESPRAY REAR BUMPER, REAR BOOT, TAILLAMP LOWER PANEL, REAR LH FENDER, REAR END PANEL & ALL AFFECTED AREAS	New	700.00	600.00
4	REMOVE & REFIX REAR SEAT, CARPET TO FACILITATE REPAIR	New	100.00	100.00
5	RUSTPROOFING	New	60.00	50.00
Gross Labour Cost (\$\$)			1,680.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >