

ASS. REC. BY:

REF: CS/MSG19006787/0vd3

Special Instruction:

Surveior: MARCUS

ASSIGNMENT (Office)

From (Person): Katherine Wong

of MSG

Date/Time: 16.4.19 16.33pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBA 2948Z

Insured: GBD 883H

at Workshop m/s Lui's Brother Auto

Tel: 67411730

of No 1 Kati Bukit 6 A 01-01 Autobay

Policy No: 28736449mkc

Claim No: 590604

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11.4.2019

(Client's Record)

17.4.2019 ✓

CA / REV / REP. / REV 24 HRS

"rwp"

H.O.D. Endorsement:

Date/Time: 16.4.19 4.39p.m

Person Contacted: Susan

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	GBA 2948Z - X
	GBD 883H - X
17/4/19	Informed Katherine Wong pending workshop est via merimen
28/4/19	Send preli revised via merimen

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c

Colour:

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 29/4 - typist

Report Format:

Merimen

Lump Sum / I.B.I: (\$

3400 1/2

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

RECEIVED 29 APR 2019

29/4/2019

29/4/19 4/5 to 3400 confirmed with Susan. (Ref 5968.70, 6490)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Apr 2019		16 Apr 2019 16:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TAI HUA FOOD INDUSTRIES PTE LTD, Co. Reg. No.: NA								
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001195N								
Vehicle Reg. No.:	GBA2948Z	Date of Loss:	11/04/2019 00:00 - :59 [142 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 590604	Policy/Cover Note No.:	28736449MKC (Comprehensive) Coverage: 03/06/2018 - 02/06/2019						
Vehicle Reg. No. (Insured):	GBD8183H	Policy No. (Claimant):							
		Excess:							
Repairer:	Lul's Brother Auto Engineering Workshop (HQ) NO 1 KAKI BUKIT 6 #01-01 AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/04/2019]								
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY: DISPUTE (OI NON-REPORTING) CONTACT: SUSAN LOW 6741 1730. on WP								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 29 Apr 2019

Preliminary Advice

Insured Vehicle No	: GBD8183H	Accident Date	: 11/04/2019
TP Vehicle No	: GBA2948Z	Assignment Date	: 16/04/2019
Make	: TOYOTA HIACE	Est. Duration of Repair	: 4
Date of Inspection	: 16/4/2019		
Inspection At	: LIU'S BROTHER AUTO ENGINEERING WORKSHOP		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,368.70
Revised Amount	:S\$	3,400.00 (Lump Sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,400.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***GBA2948Z (590604)**
[GBDB183H]

TP
GOLDBELL LEASING PTE LTD
Apr 11 2019 12:00AM
[TAI HUA FOOD INDUSTRIES PTE LTD]
Lui's Brother Auto Engineering Workshop

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 17/04/2019 15:19 PM.
To MSI_WCS
Subject TP SURVEY GBA 2948Z

Dear Katherine,

Please be informed that we have inspected the vehicle GBA 2948Z on 16/4/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 1196N

Vehicle Details

Vehicle No.: GBA2948Z
Vehicle to be Exported: No
Intended Deregistration Date: 15 Apr 2019
Vehicle Make: TOYOTA
Vehicle Model: HIACE MANUAL
Primary Colour: White
Manufacturing Year: 2007
Engine No.: 1KD1615522
Chassis No.: JTFHT02P000003380
Maximum Power Output: -
Open Market Value: \$24,590.00
Original Registration Date: 15 May 2007
First Registration Date: 15 May 2007
Transfer Count: 1
Actual ARF Paid: \$0.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 14 May 2022
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$22,263.00
COE Rebate Amount: \$13,710.00
Total Rebate Amount: \$13,710.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.
The information contained herein is correct as at 15 Apr 2019

OK

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[F](#)

hiace

Price Range

Depreciation

> 10 year(s)

Vehicle Type

[Home](#) » [Used Cars](#) » [SG Motor Link Pte Ltd](#) » [Toyota Hiace 3.0M \(COE till 01/2022\)](#)

Toyota Hiace 3.0M (COE till 01/2022)

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$23,800	Lifespan	24-Jan-2027
Depreciation ⓘ	\$8,570 /yr	Reg Date	25-Jan-2007 (2yrs 9mths 8days COE left)
Mileage	N.A.	Manufactured ⓘ	2006
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$13,520 as of today (change)	OMV ⓘ	\$24,590
COE ⓘ	\$24,334	No. of Owners ⓘ	2
Engine Cap	2,982 cc		
Curb Weight ⓘ	1,780 kg		
Type of Vehicle	Van		

Features[View specs of the Toyota Hiace](#)**Accessories**

DVD Player, Reverse Camera, New Cushion Seat

Description

Good Condition, Servicing Done, Vehicle Well Maintained, Bank/In-House Available, Welcome Trade-In, Price Negotiable. Call Now For Viewing.

Category

COE Car, Premium Ad Car

Sta[Compare](#)[Shortlist](#)[Com](#)[Report Error](#)[M](#)**Seller Information**

Company	SG M » deal » 66 v
Address	15 Yis Search
Location	Win 5
Office No	62506
Contact Person(s)	Berna Jamer

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

hiace

Price Range

Depreciation

> 10 year(s)

Vehicle Type


[Home](#) » [Used Cars](#) » [Direct Owners](#) » Toyota Hiace 3.0M (COE till 02/2022)

Toyota Hiace 3.0M (COE till 02/2022)

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price	\$18,000	Fuel Type	Diesel
Depreciation ⓘ	\$6,260 /yr	Reg Date	14-Oct-2004 (2yrs 10mths 12days COE left)
Mileage	N.A.	Manufactured ⓘ	2004
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$13,940 as of today (change)	OMV ⓘ	\$21,926
COE ⓘ	\$24,252	ARF ⓘ	\$1,097
Engine Cap	2,986 cc	No. of Owners ⓘ	2
Curb Weight ⓘ	1,500 kg		
Type of Vehicle	Van		

Category

COE Car, Direct Owner Sale

Status

Available

Resources


Car Valuation - Free
Find out the market value of your existing car for free. [Get started](#)
Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)

Posted on: 02-Apr-2019 | Last Updated on: 10-Apr-2019

Upfront Payment

Transfer Fee ⓘ

\$25

Down P:

\$1,800 (change)

Maximum 90% Loan

[Compare](#)

Based on 4.5% interest rate

[» more Financial info](#)

[Shortlist](#)
[Com](#)
[Report Error](#)
[M](#)

Seller Information

Contact Person(s)
Contact No.
Enquiry

ESSENTIAL TRANSACTION

» Indemnity form

» Receipt

» Ownership Transfer


**GET HELP WITH
PAPERWORK**

sgCarMart Connect handles all your paperwork - send us your original documents and we'll help with **Car Loan & Ownership Transfer**. For **Advertised Vehicles**.

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROH No: 538917931. Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liushbro@gmail.com

Invoice/Ref No: GBA2948Z190471

Estimate

Customer

Name: MSIG Insurance (Singapore) Pte Ltd

Date: 15-04-19

Address: Motor Claims Department

Vehicle No: GBA2948Z

4 Shenton Way #21-01

Model/Make: Toyota Hiace

SGX Centre 2

Singapore 068807

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>body</i>	\$ 1,456.00	
2	Tailgate Weatherstrip <i>11</i>	\$ 395.10	X
3	Tailgate Inner Lock <i>721</i>	\$ 359.00	
4	Tailgate "Toyota Logo" Motif <i>rec 68.50</i>	\$ 70.50	
5	Tailgate "70 KM/H" Sticker <i>rec</i>	\$ 15.00	SN 10.5.11
6	Tailgate "Corporate" Advertisement Sticker <i>rec</i>	\$ 500.00	SN 380.5.11
7	Tailgate Inner Aluminium Plate <i>rec</i>	\$ 480.00	SN X 5.11
8	Tailgate Inner Aluminium Plate Rivet <i>rec</i>	\$ 50.00	SN X 5.11
9	Number Plate "Metal" <i>rec</i>	\$ 28.00	SN 15.5.11
10	Reverse Sensor <i>1 set</i>	\$ 250.00	SN 200.5.11
11	Bumper <i>De 428.10</i>	\$ 599.30	
12	Bumper Side Bracket 02 pcs (@ \$598.10) <i>3 set</i>	\$ 196.20	
13	Bumper Clips 1 set <i>rec</i>	\$ 48.00	SN
14	End Panel Outer <i>rec</i>	\$ 566.10	X
15	End Panel Inner <i>rec</i>	\$ 936.20	X
16	End Panel Sealant <i>11</i>	\$ 50.00	SN X
17	Tail Lamp 02 pcs (@ \$5303.10) <i>rec</i>	\$ 606.20	X
18	Tailgate Windscreen Moulding <i>11</i>	\$ 219.00	X
19	Tailgate Windscreen Sealant <i>rec</i>	\$ 50.00	SN 40
	To check all wiring & electrical component for proper function	\$ 60.00	20
	Remove and refix rear tailgate components & wiper mechanism	\$ 100.00	60
	Remove & reinstall Tailgate Glass to facilitate repairs	\$ 120.00	1
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 880.00	580
	To putty & spray painting & including touch up paint on accident affect	\$ 800.00	450

Total Parts & Labour of estimate for damaged vehicle

\$ 8,914.60

Total amount in Lump Sum Basis for repaired vehicle



SDLS:

M/s Liu's Brother Auto Engrg Wks

P-2555.80

258
1916.88

2/5 3100

4 day

When p/b After repair
16/4/19

1. To check all wiring & electrical component for proper function

2. To remove and refix rear tailgate components & wiper mechanism

3. To remove & reinstall Tailgate Glass to facilitate repairs

4. To apply Rust Proofing, reseal tuff-coating treatment on accident area

5. Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc

6. To putty & spray painting & including touch up paint on accident affect

Address: 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

Telephone: 6741-1730 / 731

Fax: 6744-5746

Email: liushbro@gmail.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/04/2019 21:51
Date Of Accident	11/04/2019 09:55
Exact Location Of Accident	ALONG PIE (CHANGI)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBA2948Z
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942833
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090757MFCV
Cover Note Number	
Driver	
Name of Driver	CHUA WEI RONG
NRIC No	S9429545I
Date Of Birth	13/08/1994
Occupation	OUTDOOR
Date Of Driving Pass	16/01/2015
Driving Experience	4 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90914105
Fax Number	
Contact Number	
Email Address	KENNETH.ONG@KIMPARADISE.COM.SG

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 5329791 Tel: 6744-1791 / 79 Fax: 6744-5746 Email: liushb@gmail.com

Invoice/Ref No: GBA2948Z190411

Estimate

Customer		Date:	15-04-19
Name:	MSIG Insurance (Singapore) Pte Ltd	Vehicle No:	GBA2948Z
Address:	Motor Claims Department	Model/Make:	Toyota Hiace
	4 Shenton Way #21-01		Manual
	SGX Centre 2		
	Singapore 068807		

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate	\$ 1,910.10	
2	Tailgate Weatherstrip	\$ 395.10	
3	Tailgate Inner Lock	\$ 359.00	
4	Tailgate "Toyota Logo" Motif	\$ 70.50	
5	Tailgate "70 KM/H" Sticker	\$ 15.00	SN 105.00
6	Tailgate "Corporate" Advertisement Sticker	\$ 500.00	SN 400.00
7	Tailgate Inner Aluminium Plate	\$ 480.00	SN X
8	Tailgate Inner Aluminium Plate Rivet	\$ 50.00	SN 5.00
9	Number Plate "Metal"	\$ 28.00	SN 15.00
10	Reverse Sensor	\$ 250.00	SN 200.00
11	Bumper	\$ 509.30	
12	Bumper Side Bracket 02 pcs (@ \$508.10)	\$ 106.20	
13	Bumper Clips 1 set	\$ 48.00	
14	End Panel Outer	\$ 566.10	
15	End Panel Inner	\$ 916.20	
16	End Panel Sealant	\$ 50.00	SN X
17	Tail Lamp 02 pcs (@ \$5303.10)	\$ 606.20	
18	Tailgate Windscreen Moulding	\$ 219.00	
19	Tailgate Windscreen Sealant	\$ 50.00	SN 405.00
	To check all wiring & electrical component for proper function	\$ 60.00	20
	Remove and refix rear tailgate components & wiper mechanism	\$ 100.00	60
	Remove & reinstall Tailgate Glass to facilitate repairs	\$ 120.00	
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 880.00	580
	To putty & spray painting & including touch up paint on accident aff	\$ 800.00	450

Total Parts & Labour of estimate for damaged vehicle

\$9,168.70

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

1. To check all wiring & electrical component for proper function
 2. Remove and refix rear tailgate components & wiper mechanism
 3. Remove & reinstall Tailgate Glass to facilitate repairs
 4. To apply Rust Proofing, reseal tuff-coating treatment on accident area
 5. Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc
 6. To putty & spray painting & including touch up paint on accident aff

Approved by:
 Signature:
 Date:

P-3009.9
 257
 2257.42
 4252.42
 3401

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Apr 2019		16 Apr 2019 16:33 Edit Adj Rpt	\$3,400.00 Edit Estimates	\$3,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAI HUA FOOD INDUSTRIES PTE LTD, Co. Reg. No.: NA								
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	GBA2948Z	Date of Loss:	11/04/2019 00:00 - :59 [142 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 590604	Policy/Cover Note No.:	28736449MKC (Comprehensive) Coverage: 03/06/2018 - 02/06/2019						
Vehicle Reg. No. (Insured):	GBD8183H	Policy No. (Claimant):							
		Excess:							
Repairer:	Lui's Brother Auto Engineering Workshop (HQ) NO 1 KAKI BUKIT 6 #01-01 AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/05/2019]								
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY: DISPUTE (OI NON-REPORTING) CONTACT: SUSAN LOW 6741 1730. on WP								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBA2948Z (590604)
 [GBD8183H]
 TP
 GOLDBELL LEASING PTE LTD
 Apr 11 2019 12:00AM
 [TAI HUA FOOD INDUSTRIES PTE LTD]
 Lui's Brother Auto Engineering Workshop

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	29/04/19 08:40	Adjuster Immediate Advice							1	Load HTM				
Photos/Images									3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	16/04/19 17:53	Odometer Reading							1	Load JPG	☒			
2	16/04/19 17:53	Chassis Number							1	Load JPG	☒			
3	16/04/19 17:54	General View							1	Load JPG	☒			
4	16/04/19 17:54	General View							1	Load JPG	☒			
5	16/04/19 17:54	General View							1	Load JPG	☒			
6	16/04/19 17:54	General View							1	Load JPG	☒			
7	16/04/19 17:54	General View							1	Load JPG	☒			
8	16/04/19 17:54	General View							1	Load JPG	☒			
9	16/04/19 17:54	General View							1	Load JPG	☒			
10	16/04/19 17:54	General View							1	Load JPG	☒			
11	16/04/19 17:54	General View							1	Load JPG	☒			
12	16/04/19 17:54	General View							1	Load JPG	☒			
13	16/04/19 17:54	General View							1	Load JPG	☒			
14	16/04/19 17:54	General View							1	Load JPG	☒			
15	16/04/19 17:54	General View							1	Load JPG	☒			
16	16/04/19 17:54	General View							1	Load JPG	☒			
17	16/04/19 17:54	General View							1	Load JPG	☒			
18	16/04/19 17:54	General View							1	Load JPG	☒			
19	16/04/19 17:54	General View							1	Load JPG	☒			
20	16/04/19 17:54	General View							1	Load JPG	☒			
21	16/04/19 17:54	General View							1	Load JPG	☒			
22	16/04/19 17:54	General View							1	Load JPG	☒			
23	16/04/19 17:54	General View							1	Load JPG	☒			
24	16/04/19 17:54	General View							1	Load JPG	☒			
25	16/04/19 17:54	General View							1	Load JPG	☒			
26	16/04/19 17:54	General View							1	Load JPG	☒			
27	16/04/19 17:54	General View							1	Load JPG	☒			
28	16/04/19 17:54	General View							1	Load JPG	☒			
29	16/04/19 17:54	General View							1	Load JPG	☒			
30	16/04/19 17:54	General View							1	Load JPG	☒			
31	16/04/19 17:54	General View							1	Load JPG	☒			
32	16/04/19 17:54	General View							1	Load JPG	☒			
33	16/04/19 17:54	General View							1	Load JPG	☒			
34	16/04/19 17:54	General View							1	Load JPG	☒			

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	16/04/19 17:54	General View	 Load JPG	☒
36	16/04/19 17:54	General View	 Load JPG	☒
37	16/04/19 17:54	General View	 Load JPG	☒
38	16/04/19 17:54	General View	 Load JPG	☒
39	16/04/19 17:54	General View	 Load JPG	☒
40	16/04/19 17:54	General View	 Load JPG	☒
41	16/04/19 17:54	General View	 Load JPG	☒
42	16/04/19 17:54	General View	 Load JPG	☒
43	16/04/19 17:54	General View	 Load JPG	☒
44	16/04/19 17:54	General View	 Load JPG	☒
45	16/04/19 17:54	General View	 Load JPG	☒
46	16/04/19 17:54	General View	 Load JPG	☒
47	16/04/19 17:54	General View	 Load JPG	☒
48	16/04/19 17:54	General View	 Load JPG	☒
49	16/04/19 17:54	General View	 Load JPG	☒
50	16/04/19 17:54	General View	 Load JPG	☒
51	16/04/19 17:54	General View	 Load JPG	☒
52	16/04/19 17:54	General View	 Load JPG	☒
53	16/04/19 17:54	General View	 Load JPG	☒
54	16/04/19 17:54	General View	 Load JPG	☒
55	16/04/19 17:54	General View	 Load JPG	☒
56	16/04/19 17:54	General View	 Load JPG	☒
57	16/04/19 17:54	General View	 Load JPG	☒
58	16/04/19 17:54	General View	 Load JPG	☒
59	16/04/19 17:54	General View	 Load JPG	☒
60	16/04/19 17:54	General View	 Load JPG	☒
61	16/04/19 17:54	General View	 Load JPG	☒
62	16/04/19 17:54	General View	 Load JPG	☒
63	16/04/19 17:54	General View	 Load JPG	☒
64	16/04/19 17:54	General View	 Load JPG	☒
65	16/04/19 17:54	General View	 Load JPG	☒
66	16/04/19 17:54	General View	 Load JPG	☒
67	16/04/19 17:54	General View	 Load JPG	☒
68	16/04/19 17:54	General View	 Load JPG	☒
69	29/04/19 07:53	Reinspection Photo	 Load JPG	☒
70	29/04/19 07:53	Reinspection Photo	 Load JPG	☒
71	29/04/19 07:53	Reinspection Photo	 Load JPG	☒
72	29/04/19 07:53	Reinspection Photo	 Load JPG	☒
73	29/04/19 07:53	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/04/19 18:55	TP ACCDT REPORT	 Load PDF	
2	16/04/19 13:54	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19006787/UVD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28736449MKC

Claimant Vehicle No : GBA2948Z

Insured Vehicle No : GBD8183H

Date of Loss: 11/04/2019

Nature of Claim: TP

Claim No: 590604

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA2948Z**

Make & Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 1KD1615522

Reg. Date: 15/05/2007 (Man. Year: 2007)

Chassis No: JTFHT02P000003380

Colour: Yellow

Odometer: 557303 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Austone 5 mm

Rear Left Side: Austone 5 mm

Front Right Side: Austone 5 mm

Rear Right Side: Austone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,328.70	2,972.42	4,356.28	59.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,280.00	760.00	37.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,368.70	4,252.42	5,116.28	54.61
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	9,368.70	3,400.00	5,968.70	63.71

INSPECTION

Date of Assignment: 16/04/2019

Date Inspected: 16/04/2019 Inspected At:

Lui's Brother Auto Engineering Workshop
(HQ)

NO 1 KAKI BUKIT 6 #01-01

AUTOBAY@KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 May 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA2948Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,910.10 F	*1,910.10 FL
2	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	395.10 F	*- FL
3	1		*REAR TAILGATE INNER LOCK	Jammed /Twisted	359.00 F	*359.00 FL
4	1		*REAR TAILGATE TOYOTA LOGO MOTIF	Necessary	70.50 F	*68.50 FL
5	1		*REAR TAILGATE 70KM/H STICKER	Missing	15.00 FS	*10.00 FS
6	1		*REAR TAILGATE CORPORATEADVERTISEMNT STICKER	Necessary	500.00 FS	*400.00 FS
7	1		*REAR TAILGATE INNER ALUMINIUM PLATE	Serviceable	480.00 FS	*- FS
8	1		*REAR TAILGATE INNER ALUMINIUM PLATE RIVET	Necessary	50.00 FS	*50.00 FS
9	1		*REAR NUMBER PLATE METAL	Bent	28.00 FS	*15.00 FS
10	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
11	1		*REAR BUMPER	Deformed	599.30 F	*428.10 FL
12	2		*REAR BUMPER SIDE BRACKET	Bent	196.20 F	*196.20 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	48.00 F	*48.00 FL
14	1		*REAR END PANEL OUTER	Repair	566.10 F	*- FL
15	1		*REAR END PANEL INNER	Repair	936.20 F	*- FL
16	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
17	2		*REAR TAIL LAMP	Serviceable	606.20 F	*- FL
18	1		*REAR TAILGATE WINDSCREEN MOULDING	Not Necessary	219.00 F	*- FL
19	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	7,328.70	3,724.90
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	752.48
Total Parts (\$\$)	7,328.70	2,972.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	20.00
2	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	100.00	60.00
3	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	120.00	120.00
4	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	50.00
5	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	880.00	580.00
6	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	800.00	450.00
Gross Labour Cost (S\$)			2,040.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >